

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875



Date : 27/03/2019
TP Vehicle No. : SMD-8820-Y
To : AIG ASIA PACIFIC INSURANCE PTE LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : PHEE CHWEE KIAT
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5094020313-01
Vehicle No. : SJJ-7959-S
Make & Model : TOYOTA ESTIMA 2.4 AERAS (A)

Accident Date: 26/03/2019

NOT Affected
28/3/19 The photo taken
1/5 @ 3000 5 day

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE	<i>n</i> \$1,950.60	<i>X</i>
1	TAILGATE WEATHERSTRIP MOULDING	<i>11</i> \$395.60	<i>X</i>
1	TAILGATE LOCK	<i>11</i> \$415.60	<i>X</i>
1	TAILGATE EMBLEM " AERAS"	<i>ser</i> \$65.60	<i>—</i>
1	TAILGATE EMBLEM " ESTIMA"	<i>ser</i> \$65.60	<i>—</i>
1	TAILGATE EMBLEM LOGO	<i>ser</i> \$68.90	<i>—</i>
1	REAR WINDSCREEN MOULDING	<i>11</i> \$185.90	<i>X</i>
1	TAILGATE HINGE LH	<i>11</i> \$78.70	<i>X</i>
1	TAILGATE HINGE RH	<i>11</i> \$78.70	<i>X</i>
1	TAILLAMP RH	<i>11</i> \$350.60	<i>X</i>
1	TAILLAMP LH	<i>11</i> \$350.60	<i>X</i>
1	REAR BUMPER	<i>De</i> \$650.20	<i>—</i>
1	REAR BUMPER RETAINER RH	<i>11</i> \$65.60	<i>X</i>
1	REAR BUMPER RETAINER LH	<i>11</i> \$65.60	<i>X</i>
1	REAR BUMPER REINFORCEMENT	<i>ns</i> \$385.60	<i>X</i>
1	REAR BUMPER SPONGE	<i>Ter</i> \$95.60	<i>?</i>
10	REAR BUMPER CLIPS	<i>ser</i> \$65.00	<i>—</i>
1	REAR END PANEL	<i>sooty</i> \$750.60	<i>?</i>
1	REAR END PANEL TOP GARNISH	<i>tw</i> \$385.60	<i>?</i>
10	REAR END PANEL TOP GARNISH CLIPS	<i>11</i> \$70.00	<i>X</i>
1	SPARE TYRE COMPARTMENT	<i>11</i> \$950.60	<i>X</i>
1	SPARE TYRE PANEL	<i>R</i> \$850.60	<i>X</i>
1	RH REAR FENDER INNER SHIELD	<i>11</i> \$150.60	<i>X</i>
10	RH REAR FENDER INNER SHIELD CLIPS	<i>11</i> \$65.00	<i>X</i>
1	RH REAR FENDER	<i>n</i> \$850.60	<i>X</i>
	Sub Total	\$9,407.60	
	Discount 25% on Parts	(\$2,351.90)	
		\$7,055.70	

P-2147-1
252
1610.32

Date : 27/03/2019
 TP Vehicle No. : SMD-8820-Y
 To : **AIG ASIA PACIFIC INSURANCE PTE LTD**
 Attn : **Motor Claim Department**

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Owner : PHEE CHWEE KIAT
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5094020313-01
 Vehicle No. : SJJ-7959-S
 Make & Model : TOYOTA ESTIMA 2.4 AERAS (A)

Accident Date: 26/03/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

Special Nett

1	REAR WINSSCREEN SEALANT	11 \$65.00	X
1 set	REAR BUMPER REVERSE SENSOR	one \$450.00	200
1	REAR NUMBER PLATE & CASEING	11 \$65.00	X
	Sub Total	\$580.00	

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,800.00	900
TO SPRAY PAINT ON AFFECTED AREAS	\$1,800.00	980
TO TRANSFER & INSTALL REAR WINDSCREEN FITTING	11 \$250.00	X
TO TRANSFER ALL REAR TAILGATE, RH REAR FENDER FITTING TO NEW & upholstery	\$250.00	80
Sub Total	\$4,100.00	

Sub Total \$11,735.70
GST 7% \$821.50
Total \$12,557.20

3770

L&K Auto Consultants hence notify the Repairer of the following:

- To return vehicle after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary parts must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: