

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

Not Allowed
LH
P/P 2737.28
4/4/19
to the relevant party.
3 dy.

ABWIN 諭輝

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 28/03/2019
TP Vehicle No. : SLZ-2149-M
To : **AIG ASIA PACIFIC INSURANCE PTE LTD**
Attn : **Motor Claim Department**

Owner : CHEE HIANG CHUAN
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5079694184-02
Vehicle No. : SLC-1499-E
Make & Model : HONDA VEZEL 1.5X CVT

Accident Date: 26/03/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE <i>Boddy</i>	\$972.40	/
1	TAILGATE LOCK <i>11</i>	\$187.10	X
1	TAILGATE LOCK CATCH <i>11</i>	\$35.50	X
1	TAILGATE EMBLEM LOGO <i>11</i>	\$35.70	X
1	TAILGATE EMBLEM "VEZEL" <i>see</i>	\$45.00	/
1	TAILGATE WEATHERSTRIPE <i>11</i>	\$96.80	X
1	REAR WINDSCREEN MOULDING <i>see</i>	\$150.00	/
1	REAR BUMPER <i>see/cut</i>	\$516.70	/
1	REAR BUMPER RETAINER RH <i>11</i>	\$25.00	X
1	REAR BUMPER RETAINER LH <i>11</i>	\$25.00	X
10	REAR BUMPER CLIPS <i>see</i>	\$50.00	/
1	REAR BUMPER LOWER GARNISH <i>11</i>	\$250.00	X
1	RH TAILLAMP <i>11</i>	\$450.70	X
1	LH TAILLAMP <i>11</i>	\$450.70	X
1	REAR END PANEL <i>see</i>	\$450.90	X
1	REAR END PANEL TOP GARNISH <i>11</i>	\$120.30	X
10	REAR END PANEL TOP GARNISH CLIPS <i>11</i>	\$50.00	X

Sub Total

\$3,911.80

Discount 20% on Parts

(\$782.36)

\$3,129.44

P-1734.1
20%
1387.28

Special Nett

1	REAR WINDSCREEN SEALANT <i>see</i>	\$65.00	40
1	REAR WINDSCREEN SEAL <i>see</i>	\$65.00	30
1	REAR NUMBER PLATE WITH CASING <i>11</i>	\$65.00	X
1	REAR BUMPER REVERSE SENSOR <i>shut</i>	\$450.00	200
1	REAR REVERSE CAMERA <i>11</i>	\$450.00	X
Sub Total		\$1,095.00	

Date : 28/03/2019
 TP Vehicle No. : SLZ-2149-M
 To : AIG ASIA PACIFIC INSURANCE PTE LTD
 Attn : Motor Claim Department

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Owner : CHEE HIANG CHUAN
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5079694184-02
 Vehicle No. : SLC-1499-E
 Make & Model : HONDA VEZEL 1.5X CVT

Accident Date: 26/03/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,500.00	400
TO SPRAY PAINT ON AFFECTED AREAS	\$1,500.00	400
TO TRANSFER ALL REAR TAILGATE, FITTING TO NEW	\$150.00	60
TO APPLY TUFF KOTE ON AFFECTED AREA.	\$150.00	30
TO CHECK LIGHTING AND FOCUS TAILAMP	\$150.00	20
TO INSTALL REAR WINDSCREEN	\$150.00	120
TO INSTALL REVERSE CAMERA AND CHECK FUNCTIONALITY	\$150.00	50
TO DETACH & RENEW REVERSE SENSOR	\$250.00	
Sub Total	\$4,000.00	

Sub Total \$8,224.44
GST 7% \$575.71
Total \$8,800.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: