

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 595Z**AAD1903-199***Not Authenik
C/Bmp 8320d*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF 595Z

VF1ABL15AUC278434

RENAULT

LATITUDE

22.3.2019

AIG

20/6/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>Dis</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77 X
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP LH	\$	<i>mgem</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT LH	\$	<i>Bu</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	AIR CLEANER BOX	\$	<i>Sn</i> 464.20
1	AIR CLEANER HOSE	\$	<i>Sn</i> 175.85

Trans-cab Auto Services Pte Ltd**AAD1903-199**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 595Z

TOTAL	\$	18,891.00
10%	\$	1,889.10
	\$	17,001.90

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>na</i> 66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i> 12.00	} X
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i> 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i> 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i> 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i> 30.00	
1SET	WHEELARCH CLIP FRT RH	\$	<i>na</i> 30.50	}
1	FRONT LEFT TYRE RIM	\$	<i>sh</i> 330.00	
1	FRONT LEFT TYRE	\$	<i>sh</i> 300.00	
		\$	938.00	

TOTAL PARTS	\$	17,939.90
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00 <i>4001</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>4401</i>
To rust-proofing of the affected areas.	\$	170.00 <i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>

Trans-cab Auto Services Pte Ltd**AAD1903-199**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 595Z

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i> 170.00 X

TOTAL	\$	8,710.00
--------------	-----------	-----------------

Over All Total	\$	26,649.90
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)~~10 DAYS~~*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: