

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50622
Date Estimated : 27/03/2019
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Au Shao Xian, Harold
815B UPPER EAST COAST ROAD

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

SINGAPORE 466610

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL2697H	J215020	22/10/2013	116iA/5	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To make good the front LH door, front bumper include replacement of damaged part and knocking out dents caused by the accident	1700.00	10.00	1,530.00	
To spray paint front LH door and front bumper	1730.00	10.00	1,557.00	
To check electrical wiring systems at the front section for proper function	150.00	10.00	135.00	
Sundries	80.00	0.00	80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
PLAQUE 82MM	71.25	1.00	3.00	69.11

SUPPLEMENTARY ITEMS

Total Labour :	3,302.00
Total Parts :	69.11
Total Labour & Parts :	3,371.11
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,371.11
GST @7%:	235.98
Grand Total :	3,607.09

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)Exit 14 day
cancel notice13/5/2019
any & repair
Rgn
cancel
Service
21/8/2019
repairing

GST REG. NO : M2 - 0020081 - X

27 MAR 2019

E S T I M A T E

Estimate No.	: b1 50622	Page No. : 1 of 5
Date Estimated	: 27/03/2019	
Prepared By	: Chua Kee Sin	

- ESTIMATE REPAIR FOR - Au Shao Xian, Harold 815B UPPER EAST COAST ROAD SINGAPORE 466610	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL2697H	J215020	22/10/2013	116iA/5	0

DESCRIPTION	VALUE
Replace front bumper, left front door and remove attachment etc include repair on accident damage area	1700 2,550.00
Spray painting left front door and front bumper	1730 1,923.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To carry out body cavity preservation. (Per panel).	111 X 118.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).	111 X 531.00
Sundries.	? 150.00 80
Total Labour 1:	5,449.00

DESCRIPTION	QTY	PRIC	VALUE
FRT LH DOOR repair	1	1,077.40	1,077.40
FRT LH SIDE PANEL SUPPORT ? } Xn	1	12.50	12.50
FRT RH SIDE PANEL SUPPORT ? } Xn	1	12.50	12.50
FRT BUMPER LH INSERT ?	1	7.55	7.55
FRT BUMPER RH INSERT ?	1	7.60	7.60
FRT BUMPER PANEL PRIMED (SRA) repair	1	862.90	862.90
EMBLEM GROMMET Xn	2	0.80	1.60
FRONT DOOR BRAKE ?	1	71.00	71.00
FRT DOOR JOINT SEAL ?	1	38.00	38.00
Sealing ?	1	21.80	21.80
FRT LH DOOR WINDOW GUIDE ?	1	105.85	105.85
FRT LH DOOR INSIDE CHANNEL SEALING ?	1	60.95	60.95
FRT LH DOOR CHANNEL SEALING ?	1	71.70	71.70
FRT DOOR EDGE PROTECTOR ?	1	152.50	152.50
PLAQUE 82MM	1	71.25	71.25

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50622		Page No. : 2 of 5	
Date Estimated : 27/03/2019			
Prepared By : Chua Kee Sin			

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL2697H	J215020	22/10/2013	116iA/5	0

Total Parts : 2,575.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Claims OD / Third Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 21/05/19 @ 1320 Excess S\$ _____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PMI Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 4 days

Labour 1	:	5,449.00
Parts	:	2,575.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	561.69
Grand Total	:	8,585.79

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **