

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. NO. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E13/5/2019
Shuy & repair
8am
conduct
Service
21/8/2019
morning

27 MAR 2019

Page No. : 1 of 5

Estimate No. : b1 50622
Date Estimated : 27/03/2019
Prepared By : Chua Kee Sin**- ESTIMATE REPAIR FOR -**
Au Shao Xian, Harold
815B UPPER EAST COAST ROAD**SINGAPORE 466610****- ACCOUNT - 40000**
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL2697H	J215020	22/10/2013	116iA/5	0

DESCRIPTIONVALUE

Replace front bumper, left front door and remove attachment etc include repair on accident damage area

1700 2,550.00

Spray painting left front door and front bumper

1730 1,923.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To carry out body cavity preservation.
(Per panel).

X 118.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

X 531.00

Sundries.

? 150.00

Total Labour 1: **5,449.00**DESCRIPTIONQTYPRICVALUE

FRT LH DOOR repair	1	1,077.40	1,077.40
FRT LH SIDE PANEL SUPPORT ?	1	12.50	12.50
FRT RH SIDE PANEL SUPPORT ?	1	12.50	12.50
FRT BUMPER LH INSERT ?	1	7.55	7.55
FRT BUMPER RH INSERT ?	1	7.60	7.60
FRT BUMPER PANEL PRIMED (SRA) repair	1	862.90	862.90
EMBLEM GROMMET	2	0.80	1.60
FRONT DOOR BRAKE ?	1	71.00	71.00
FRT DOOR JOINT SEAL ?	1	38.00	38.00
Sealing ?	1	21.80	21.80
FRT LH DOOR WINDOW GUIDE ?	1	105.85	105.85
FRT LH DOOR INSIDE CHANNEL SEALING ?	1	60.95	60.95
FRT LH DOOR CHANNEL SEALING ?	1	71.70	71.70
FRT DOOR EDGE PROTECTOR ?	1	152.50	152.50
PLAQUE 82MM	1	71.25	71.25

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Page No. : 2 of 5

Estimate No. : b1 50622
Date Estimated : 27/03/2019
Prepared By : Chua Kee Sin

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL2697H	J215020	22/10/2013	116iA/5	0

Total Parts : 2,575.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 21/05/11 @ 1320 Excess S\$ _____Surveyor's Name Rasul Sign _____Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 4 days

Labour 1	:	5,449.00
Parts	:	2,575.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	561.69
Grand Total	:	8,585.79

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **