

FIRST

AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 26/3/2019

To Whom It May Concern

Dear Sir,

Reference: SDF8896A

Make: CHEVROLET ORLANDO

RE: VEHICLE .:SDF8896A
CHASSIS NO.: KL1YA7589FK022400
ENGINE NO.: A14NET143550053

Name of insured .: Lee Han Siang Joseph
Date of accident.: 20/03/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts			
No.	Qty	Part Description	Price (SGD)
<u>1</u>	1	REAR BUMPER STEP PLATE	160.00
<u>2</u>	1	REAR BUMPER UPPER	1730.00
<u>3</u>	1	REAR BUMPER LOWER	760.00
<u>4</u>	1	REAR BUMPER SILL PLATE(SILVER)	390.00
<u>5</u>	1	REAR BUMPER TOWING COVER	25.00
<u>6</u>	1	LHR BUMPER REFLECTOR	65.00
<u>7</u>	1	RHR BUMPER REFLECTOR	65.00
<u>8</u>	1	REAR REVERSE LIGHT AND BRAKE LIGHT	320.00
<u>9</u>	1	REVERSE SENSOR WIRING HARNESS	325.00
<u>10</u>	1	CHEVROLET LETTERING	50.00
<u>11</u>	1	ORLANDO LETTERING	40.00
<u>12</u>	1	LS LETTERING	30.00
<u>13</u>	1	CHEVROLET EMBLEM	120.00
<u>14</u>	1	REAR TAILGATE	1850.00
<u>15</u>	1	LHR TAILLAMP	729.00
<u>16</u>	1	RHR TAILLAMP	729.00
<u>17</u>	1	REAR END PANEL	770.00
<u>18</u>	1	REAR END PANEL TRIM	125.00
<u>19</u>	1	REAR FLOOR BOARD	490.00
<u>20</u>	1	REAR BUMPER CENTRE GUIDE	50.00
<u>21</u>	1	RHR BUMPER GUIDE, OTR	40.00
<u>22</u>	1	LHR BUMPER GUIDE, OTR	40.00
<u>23</u>	1	REAR BUMPER LEFT CENTRE GUIDE, INR	45.00
<u>24</u>	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	45.00
<u>25</u>	1	REAR BUMPER ABSORBER	120.00
<u>26</u>	1	REAR BUMPER BEAM	860.00
Parts Total:			9973.00
Less10%:			997.30
Total :			8975.70

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion,to panel beating,reshape,straighten,orientate and align repair /replacement parts.	2800.00
<u>2</u>	Carry out spray painting on accident affected area	2280.00
<u>3</u>	To conduct anti rust of under carriage tuff coat	120.00
<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs,reconnect and check electrical function after repair	80.00
<u>5</u>	To remove and refix reverse sensor and conduct test	180.00
<u>6</u>	To remove and refix reverse camera and conduct test	180.00
<u>7</u>	To conduct transfer of parts from old tailgate to new tailgate	350.00
<u>8</u>	To conduct water leakage test after repairs of vehicle	30.00
<u>9</u>	To remove and refix rear tail gate windscreen	180.00
Labour Total :		6200.00

Others

<u>No.</u>	<u>Qty</u>	<u>Other Description</u>	<u>Price (SGD)</u>
<u>Rear portion</u>			
1	1	Rear number plate	45.00
2	10	Rear bumper clip	65.00
3	8	Fender Protector Clip	52.00
4	1	Rear reverse camera	350.00
5	1	Reverse sensor(1 set)	460.00
6	1	Turbo Logo	30.00
Other Total:			1002.00

Total : \$16,177.70
Gst (7%) : \$1,132.44
GRAND TOTAL: \$17,310.14

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Service Adviser
Ronnie Tan
HP : 8298 8933 Fax:6844 5185