

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North, #01-18,**  
**628457**

**Insurer Reference: CC4/ASM19005536/GB3**  
**Repairer Reference: GBF3741U-TP AXA**  
**Date calculated: 02/09/2019 11:48 AM**

**Full Report**  
**Registration: GBF3741U**  
**Printed: 02/09/2019 11:48 AM**

### Summary Information

#### Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:	CC4/ASM19005536/GB3	Date of Incident:	26/03/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

#### Vehicle

Manufacturer:	TOYOTA
Model:	DYNA
Sub Model:	BASE MODEL
Model Sheet Number:	70 1C 01
Registration:	GBF3741U
VIN number:	JTFAT35YX0K206885
Odometer:	

#### Model Specs

FROM 07/2016	WHEELBASE 2525MM	"WIDE CAB"
PREPARE OFF VEHICLE		

*Taught 97495749*  
*WP'*  
*2/9/19 @ 420pm*  
*#Resurvey new parts*  
*Est 3-4 days*  
*taught e/handover*  
**TWO COAT METALLIC**


### Vehicle Condition

#### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

All ☐  
Underbody ☐



**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Labour**

Time Base 10 WU/h

Price = 45.00 SGD/h

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North, #01-18,**  
**628457**

Insurer Reference: CC4/ASM19005536/GB3  
 Repairer Reference: GBF3741U-TP AXA  
 Date calculated: 02/09/2019 11:48 AM

Full Report  
 Registration: GBF3741U  
 Printed: 02/09/2019 11:48 AM

Code	Description	WU	Price SGD
811011	R + R LEFT TAIL LAMP	3.0	13.50
NO NUMBER	RENEW REAR NUMBER PLATE (REMOVED)	1.0	4.50
NO NUMBER	RENEW REAR NUMBER PLATE	1.0	4.50
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>0.50</b>	<b>5.0</b>
<b>Total of Labour</b>			<b>22.50</b>

**Spare Parts**

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2702	REAR NUMBER PLATE	KNPL6		b/v ✓ 0.00
3281	L/R LAMP ASSY	81560 37270		cut - 90.00
1000	RR BOX DOOR LOCK	BAR x 2PCS		RX 1,100.00
f: OEM Parts				<b>Savings</b> 0.00
n: Non-OEM Parts				<b>Subtotal</b> 1,190.00
u: Used parts				<b>Addition(+15.00%)</b> 178.50
<b>Total</b>				<b>1,368.50</b>

**Extras**

Code	Description	Price SGD
1001	RR REVERSE SENSOR REVERSE SENSOR	1w ✓ 180.00*
1002	REDRAW COMPANY LOGO COMPANY LOGO	200. 400.00*
1003	TO KNOCK,WELD,REMOVE &FIX ABOVE PART	200. 300.00*
1004	TO SPRAY ABOVE PARTS	300. 600.00*
1005	RR NUMBER PLATE NUMBER PLATE	b/v ✓ 35.00*
1006	REAR BOOX 70KM STICKER	rec ✓ 20.00*
<b>Total Extras</b>		<b>1,535.00</b>

**Sng Ah Tee Motor Pte Ltd**  
**Blk 3 Pioneer Road North, #01-18,**  
**628457**

**Insurer Reference: CC4/ASM19005536/GB3**  
**Repairer Reference: GBF3741U-TP AXA**  
**Date calculated: 02/09/2019 11:48 AM**

**Full Report**  
**Registration: GBF3741U**  
**Printed: 02/09/2019 11:48 AM**

### **Final Calculation**

	SGD	SGD
<b>Parts</b>	1,190.00	
Addition(+15.00%)	178.50	
<b>Total Parts</b>		<b>1,368.50</b>
<b>Labour Time Base 10 WU/h</b>		
Total 5.0 WU X 45.00 SGD/h	22.50	
<b>Total of Labour</b>		<b>22.50</b>
<b>Total Of Extras</b>		<b>1,535.00</b>
<b>Repair Cost Excludes GST</b>		<b>2,926.00</b>
GST (+7.0%)		<b>204.82</b>
<b>Repair Cost Included GST</b>		<b>3,130.82</b>

### **Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

### **Assessment Note**

**No assessment notes entered.**