

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference: CC4/ASM19005536/GB3
Repairer Reference: GBF3741U-TP AXA
Date calculated: 05/11/2019 5:55 PM

Full Report
Registration: GBF3741U
Printed: 05/11/2019 5:55 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:	CC4/ASM19005536/GB3	Date of Incident:	26/03/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	DYNA
Sub Model:	BASE MODEL
Model Sheet Number:	70 1C 01
Registration:	GBF3741U
VIN number:	JTFAT35YX0K206885
Odometer:	

Model Specs

FROM 07/2016	WHEELBASE 2525MM	"WIDE CAB"	TWO COAT METALLIC
PREPARE OFF VEHICLE			


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 45.00 SGD/h

Code	Description	WU	Price SGD
811011	R + R LEFT TAIL LAMP	3.0	13.50
NO NUMBER	RENEW REAR NUMBER PLATE (REMOVED)	1.0	4.50
NO NUMBER	RENEW REAR NUMBER PLATE	1.0	4.50
1000	RR BOX DOOR LOCK BAR x 2PCS	5.0*	22.50
Labour Cost		Hrs	WU
Panel / Mechanical Labour		1.00	10.0
Total of Labour			45.00

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
2702	REAR NUMBER PLATE	KNPL6			0.00
3281	L/R LAMP ASSY	81560 37270			90.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				90.00
u: Used parts	Addition(+ 15.00%)				13.50
Total					103.50

Extras

Code	Description	Price SGD
1001	RR REVERSE SENSOR REVERSE SENSOR	180.00*
1002	REDRAW COMPANY LOGO COMPANY LOGO	200.00*
1003	TO KNOCK,WELD,REMOVE &FIX ABOVE PART	200.00*
1004	TO SPRAY ABOVE PARTS	300.00*
1005	RR NUMBER PLATE NUMBER PLATE	35.00*
1006	REAR BOOX 70KM STICKER	20.00*
1007	AUDATEX FEE NEC (ADD)	42.00*
Total Extras		977.00

Final Calculation

	SGD	SGD
Parts	90.00	
Addition(+15.00%)	13.50	
Total Parts		103.50
Labour Time Base 10 WU/h		
Total 10.0 WU X 45.00 SGD/h	45.00	
Total of Labour		45.00
Total Of Extras		977.00
Repair Cost Excludes GST		1,125.50
GST (+7.0%)		78.79
Repair Cost Included GST		1,204.29
Deductions (Excludes GST)		
Repair Cost Discount (+15.00%)	-168.83	
Total Of Deductions (Excludes GST)		-168.83
Grand Total Excludes GST		956.67
GST (+7.0%)		66.97
Grand Total Included GST		1,023.64

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.