



新福德車廠私人有限公司

Lonpac - Adnan Lkk

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

08/01/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 03/01/2019

Estimated repair cost for vehicle no: CB7672T TOYOTA HIACE COMMUTER 3.0 A '15

CHASSIS: KDH2230025945

FP Lonpac, Joy

S/n	Qty	Items	U/price	Amount
1	1	Rear L/H Tail Lamp <i>new</i>		\$374.45 +
2	1	Rear L/H Tail Lamp Chrome <i>lt</i>		\$182.20 +
3	1	Rear L/H Fender <i>Repis</i>		\$1,912.10 +
4	1	Rear L/H Fender Glass Seal <i>3mm</i>		\$55.00 +
5	1	Rear L/H Fender Glass Moulding		\$74.00 +

Subtotal :- \$2,597.75

Labour charges

To remove & refit seat cushion & trim board	\$180.00 +
To remove & refit rear L/H fender glass (Small)	\$100.00 +
Gum	\$50.00 +
To remove & refit rear L/H fender glass (Big)	\$120.00 +
Gum	\$50.00 +
To check wiring	\$60.00 <i>30.</i>
Tuff kote	\$80.00 +
Panel beating	\$1,400.00 <i>200</i>
Spray painting	\$1,400.00 <i>250.</i>

\$700

*total: 480 (P/P)
02 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$3,440.00

Total:- \$6,037.75