

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

CHENG KEK NGUANG

26-03-2019

REPAIR ESTIMATE FOR TOYOTA COROLLA 1.6 - ALTIS - SFR 6811 X

<u>List items</u>			
1 pc. Front bumper	Bumper	\$ 395.40	✓
1 pc. Front bumper RH side retainer	Bit	23.90	✓
1 set. Front bumper clips	m	30.00	✓
1 pc. Front bumper inner reinforcement	n	297.10	x
1 pc. Front fender	Bu	275.10	✓
1 pc. Headlamp RH	cn	385.40	✓
		1,406.90	
	Less 25%	281.38	
		\$ 1,125.52	\$ 1,125.52

<u>Labour</u>	
1. Labour charges for remove/refit, panel beating, cutting/welding and replacement of damages.	500.00 <i>400</i>
2. To putty and spray Spray Paintings charges.	600.00 <i>400</i>
3. To check wirings & lightings.	30.00 <i>20</i>
	<u>\$ 2,255.52</u>

Not Notarized
1/100 & 1300
Repair After Rain
3days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: