



Steve (CLKK) Wn 26/3/19 5.15 pm Pte Ltd

Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

M/s India International Insurance
64 Cecil Street #04-02
IOB Building
Singapore 049711

Vehicle number SLL366P
Make / Model HONDA ODYSSEY
Chassis number JHMRC1890GC208559
Accident date 23/3/19
Reference 1903-40

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER / OD	823.20 /
1	FRONT BUMPER LOWER GARNISH LH / CRW	186.00 /
1	FRONT BUMPER REINFORCEMENT X / OD	342.00 265.30 /
1	FRONT BUMPER LH RETAINER / BR	28.50 /
1	FRONT GRILLE X NN	330.00 X
1	FRONT EMBLEM - LOGO X NN	33.60 X
1	FRONT UPPER GRILLE X NN	210.00 X
1	FRONT LH HEADLAMP ? BR /	2684.40 2237.00 /
1	FRONT LOWER GRILLE X NN	180.30 X
1	FRONT LH HEADLAMP BRACKET ? - BR	72.00 /
1	FRONT FOG LAMP COVER / CHT	126.00 /
1	FRONT FOG LAMP ? - BR	342.00 182.30 /
1	FRONT FENDER INNER SHIELD ? - TN	186.00 /
1	FRONT LH SHOCK ABSORBER X NN	366.00 X
1	FRONT LH KNUCKLE ARM X NN	342.00 X
1	FRONT LH KNUCKLE ARM BEARING X NN	210.00 X
1	FRONT LH LOWER ARM X NN	680.40 X
		7142.40
Less 20%		1428.48
Subtotal		5713.92
Balance C/F		5713.92
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	FRONT BUMPER CLIP / A/E	30 60.00
1 SET	FRONT GRILLE CLIP / NE	20 80.00
1 SET	FRONT FENDER INNER SHIELD CLIP / A/E	20 80.00
Subtotal		220.00
Balance C/F		5933.92
LABOUR AND MISCELLANEOUS CHARGES		
S/No		Balance B/F
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	150.00 30
2	CHECK WHEEL ALIGNMENT	200.00 X
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	200.00 X
4	PANEL BEATING ON AFFECTED AREAS	900.00 250
5	SPRAY PAINTING ON AFFECTED AREAS	900.00 300
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00 20
Subtotal		2500.00
Grand total		8433.92

Poh Kin

4106.30

-20%

3285.04 /

70 /

600 /



Teamwork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
 REPAIR PERFORMA INVOICE

M/s India International Insurance P
64 Cecil Street #04-02
IOB Building
Singapore 049711 (Supp)

Vehicle number	SLL366P
Make / Model	HONDA ODYSSEY
Chassis number	JHMRC1890GC208559
Accident date	23/3/19
Reference	1903-40

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	AIR DUCT BOX ✓ CRU	390.12 318.50 ✓
		390.12 - 7%
	Less 20%	78.02
	Subtotal	312.10 254.80 ✓
	Balance C/F	312.10

P- 3285.04
 Supp - 254.80
 NI - 70
 L - 600
 4209.84

 L/S - 3367.87
 = 3350 ✓

Steve Chen (LKK Auto)

From: claims@teamworkgarage.com
Sent: Tuesday, July 09, 2019 3:46 PM
To: Steve Chen (LKK Auto)
Cc: 'TEAMWORK GARAGE CLAIMS'
Subject: RE: SLL366P Finalize

We confirm COR @ \$3350 AND DOR @ 3 DAYS

Thank you and have a nice day! 😊

Letitia

Teamwork Garage Pte Ltd

Blk 53 Ubi Avenue 1 #01-24 Paya Ubi Industrial Park
Singapore (408934)
Tel: 6844 2475 | Fax: 6844 2474

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Thursday, May 9, 2019 8:44 AM
To: Darren <claims@teamworkgarage.com>
Subject: SLL366P Finalize

Dear Darren,

Kindly refer our finalize \$3350 (L/S, before GST). 3 days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Darren [mailto:claims@teamworkgarage.com]
Sent: Wednesday, May 08, 2019 11:08 AM
To: Steve Chen (LKK Auto)
Subject: RE: SLL366P Supplementary

Hi Steve,

Please see attached.

Please let us have the finalise amount soonest

Darren