

1/1/2020

INS. FARE OWNER

CC 3 /AIG1900

5550, A 203

LRK
IDAC

Surveyor:

K. Arim

DOI:

ASSIGNMENT

26/2/19

Date / Time:

29/2/19

Registered in Merimen:

28/2/19

Pre-assign / CCU / FTE

SKR 2900P



Insured Vehicle No.

THANAR EUN KRISHNA

Name of Insured

Insured Tel No.

HP:

24/2/19

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

RAJEEVI 610 MURUGAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.

778715405454

Policy No.

700401051-04

Make / Model:

YOLVO

Place of Accident:

2nd FLOOR 1st Floor Heights

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKR 23U



INSRS:
WSP:
Tel:
Liability:
RMKS:

premium
outstanding



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

29/2/19

SKR 23U - 1st floor view.

STAGE	DATE / PIC
Non-Reporting 1st (1st)	
Non-Reporting 1st (2nd)	
Non-Reporting 1st (Final)	
Notification 1st (if non-pickup)	
Call 01	29/2/19
After call 1st to 01	
Documentation Check List: Handler Typist	
Notification 1st (if non-pickup)	☒
After call 1st to 01	☒
Authorisation To Act	☒
Release Voucher	☒
Final Repair Bill	☒
Car Rental Invoice	☐
Towing Invoice	☐
LTA / GIA	☒
Medical Bill	☐
PIR	☐
Mandate/Reject Instruction	☒
LOD	☒
Payment Breakdown Form	☐
Post-Repair Photos	☐
Others	☐

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____	
FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: WSP	
Repair Cost: 552,799.28 (2 days) Reduction: 58 %	Email ☒ Call ☐
FINAL SETTLEMENT Date/Time: 08.01.20 Confirm with: KEE SURVEY Email ☒ Call ☐	
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 7	If NO or B 28, Ans. Lja:
Repair Cost: 552,799.28	
Loss of Rental (LOR): \$5 - (1 days)	
Loss of Use (LOU): \$5 900.00 (5100 x 9 days)	
Loss of Income (LOI): \$5 - (5 x 9 days)	
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOU ☐ [Tick only one]	
GIA/LTA Search: 551.75	
Medical: \$5 -	
Disbursement: \$5 - (e.g. Tow/ Independent)	
Legal Cost: \$5 -	
Total: 553,650.68 Global Sum \$5:	
FINAL PAYMENT Date/Time: 08.01.20 Confirm with: KEE SURVEY Email ☒ Call ☐	
Payee 1: 553,650.68 Name 1: PREMIUM AUTOMOBILES PTE LTD	
Payee 2: (Strike if N.A.) \$5 Name 2:	
Payee 3: (Strike if N.A.) \$5 Name 3:	

COPY SENT 8/1/2020

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO / TP / WS / TP RES / OO RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 hrs days Res.: Yes or NoLum Sum: - % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____Veh No: SKP 23U Yr Regn: 2017 MayType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q7 c.c. 1984Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 35025 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAU2224M2HD045845Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SR / STD A/Rim orTyre Size: F: 255/55R19R: 255/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.L. 28/03/19Survey held at: PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPAIG.</u>
	<u>FF: +31,199.28 (RED: +31,463.73 58%)</u>
	<u>MV:</u>
	<u>PV:</u>
	<u>Nett:</u>
	<u>4875G.</u>

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, GI

Photos

Others

TOTAL

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 0023 U

S/N	Nature of Jobs	Estimated Charges		
1	To remove and reinstall all front wire harness for headlights, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓	✓
2	To remove and transfer rear parking aid and rear kick sensor and renew according to damage.	S/N \$ 360.00	✓	✓
3	To dislodge and reinstall lhs A- Pillar, lhs front and rear doors harness, multi-lock system and power window devices. Inspect for damages.	S/N \$ 1,400.00	✓	✓
4	To remove and reinstall front seat assy, back rest, ABCD pillar trims, sill trims, carpets, electronic components and fuse trays.	S/N \$ 1,800.00	✗	
5	To renew front windscreen.	S/N \$ 480.00	✗	
6	To remove center console and dashboard assy for A-pillar renewal. Inspect for damages.	S/N \$ 3,200.00	✗	
SUB-TOTAL LABOUR CHARGES		:	\$ 7,720.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 0023 U

S/N	Nature of Jobs	Estimated Charges
7	To disassemble front bumper, lhs front fender, lhs front door, lhs rear doors and rear bumper assy. Cut out and reweld lhs A-pillar, lhs sill panel and lhs B-pillar. Renew lhs front fender, lhs front and rear doors and rear bumper assy. Reinstall all parts removed.	$\begin{matrix} \text{2 door} \\ \text{2 bumper} \\ \text{1 Fender} \end{matrix} \times 600 = 3600$ $\$ 11,200.00$ 3600.
8	To respray lhs front fender, lhs front and rear doors, door covers, both front wheel arch trims, lhs A-pillar, lhs sill panel, lhs B-pillar, door entrances, lhs rear fender, rear bumper, rear lower bumper and both rear wheel arch trims.	$7 \times 600 = 4200$ $\text{Wheel Cover} \times 4 = 800$ (200) $\text{Door Covers} \times 2 = 500.$ $\$ 10,000.00$ 5500.
9	To remove and renew lhs side step.	S/N \$ 400.00 ✓ ✓
10	To renew lhs front and rear trims. To carry out wheel alignment.	S/N \$ 320.00 ✓ ✓
11	To carry out diagnostic check.	S/N \$ 384.00 ✓ ✓
TOTAL LABOUR CHARGES		: \$ 30,024.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 0023 U

S/N	Parts Description	Damage Pa S/NETT	
1	FRONT FENDER-LH <i>Dented</i>	\$ 1,481.00	✓ 1,184.80
2	FRONT FENDER ATTACHEMENT PARTS-LH <i>Not Nec</i>	\$ 69.00	✗
3	FRONT FENDER BRACKET-LH <i>new</i>	\$ 56.00	+
4	FRONT FENDER CENTER BRACKET-LH <i>new</i>	\$ 59.00	+
5	FRONT FENDER BRACE-LH <i>new</i>	\$ 93.00	+
6	FRONT FENDER CLOSING ELEMENT-LH <i>new</i>	\$ 30.00	+
7	FRONT WHEEL COVER-LH/RH <i>new</i>	2 \$ 1,044.00	✓ 834.40
8	FRONT PILLAR A/B-LH <i>Repair</i>	\$ 4,162.00	✗
9	FRONT WINDSCREEN <i>new</i>	\$ 1,451.00	+
10	FRONT WINDSCREEN RAIN SENSOR <i>Not nec</i>	\$ 749.00	+
11	FRONT DOOR-LH <i>Dented</i>	\$ 3,570.00	✓ 2,856.00
12	FRONT OUTER DOOR SEAL-LH <i>new</i>	\$ 229.00	✓ 182.80
13	BONDING AGENT <i>new</i>	\$ 45.00	✗
14	CLEANING SOLUTION <i>new</i>	\$ 65.00	✗
15	APPLICATOR <i>Not Nec</i>	\$ 7.00	✗
16	FRONT DOOR ATTACHMENT PARTS-LH <i>Not Nec</i>	\$ 89.00	✗
17	FRONT DOOR CATCH -LH <i>new</i>	\$ 117.00	+
18	FRONT DOOR CATCH COVER-LH <i>new</i>	\$ 16.00	+
19	FRONT DOOR HINGE HALF UPPER PART-LH UPPER <i>new</i>	\$ 41.00	✗
20	FRONT DOOR HINGE HALF LOWER PART-LH UPPER <i>new</i>	\$ 41.00	✗
SUB-TOTAL SPARE PARTS		\$ 13,414.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 0023 U

S/N	Parts Description	Damage Pa S/NETT
21	FRONT DOOR HINGE HALF UPPER PART-LH LOWER <i>Not Nee</i>	\$ 54.00 X
22	FRONT DOOR HINGE HALF LOWER PART-LH LOWER <i>Not Nee</i>	\$ 41.00 X
23	FRONT DOOR COVER-LH <i>Distorted</i>	\$ 632.00 ✓ 505.60
24	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-LH <i>Not Nee</i>	\$ 344.00 +
25	FRONT DOOR GUIDE COVER TRIM ALUMINIUM-LH <i>Distorted</i>	\$ 354.00 ✓ 282.80
26	FRONT SILL TRIM STRIP-LH OUTER <i>Not</i>	\$ 167.00 ✓ 133.60
27	FRONT SILL TRIM STRIP-LH INNER	\$ 188.00 ✓ 150.00
28	REAR DOOR-LH <i>Distorted</i>	\$ 3,570.00 ✓ 2856.00
29	REAR OUTER DOOR SEAL-LH <i>Not</i>	\$ 229.00 ✓ 182.80
30	BONDING AGENT	\$ 45.00 X
31	CLEANING SOLUTION <i>Not Nee</i>	\$ 65.00 X
32	APPLICATOR <i>Not</i>	\$ 7.00 X
33	REAR DOOR ATTACHMENT PARTS-LH <i>Not Nee</i>	\$ 89.00 X
34	REAR DOOR CATCH-LH <i>Not Nee</i>	\$ 96.00 ✓ 76.16
35	REAR DOOR CATCH COVER-LH <i>Distorted</i>	\$ 16.00 ✓ 12.32
36	REAR DOOR SEAL OUTER-LH <i>Not Nee</i>	\$ 174.00 ✓ 138.80
37	REAR WHEATHER STRIP-LH <i>Not Nee</i>	\$ 234.00 ✓
38	REAR DOOR COVER-LH <i>Distorted</i>	\$ 545.00 ✓ 436.00
39	REAR WINDOW SLOT SEAL WITH TRIM STIP ALUMINIUM-LH <i>Not</i>	\$ 337.00 +
40	REAR COVER TRIM ALUMINIUM-LH <i>Distorted</i>	\$ 273.00 ✓ 218.40
SUB-TOTAL SPARE PARTS		\$ 7,460.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 0023 U

S/N	Parts Description		Damage Pa S/NETT
41	FRONT PILLAR B TRIM-LH <i>3 New</i>	\$	203.00 +
42	REAR PILLAR B TRIM-LH <i>2 New</i>	\$	204.00 +
43	REAR UPPER BUMPER <i>Repair</i>	\$	1,121.00 +
44	REAR LOWER BUMPER <i>Repair</i>	\$	1,677.00 +
45	REAR BUMPER FIXING PARTS <i>New</i>	\$	188.00 +
46	REAR BUMPER GUIDE SECTION-LH <i>New</i>	\$	58.00 +
47	REAR BUMPER TAIL LIGHT BULB -LH <i>New</i>	\$	326.00 +
48	REAR DOOR WHEEL COVER-LH <i>New</i>	\$	179.00 ✓ 143.20
49	REAR WHEEL COVER-LH <i>New</i>	\$	344.00 ✓ 275.20
50	LH ALUMINIUM RIM-FRONT/REAR <i>Lot</i>	2 \$	2,232.00 ✓ 1,785.60
51	RUBBER VALVE <i>New</i>	4 \$	13.00 +
52	REAR WINDOW REGULATOR WITHOUT MOTOR-LH <i>New</i>	\$	257.00 +
53	REAR WINDOW REGULATOR MOTOR-LH <i>New</i>	\$	278.00 +
54	REAR DOOR CONTROL UNIT-LH <i>New</i>	\$	685.00 +
55	SIDE STEP (RUNNING BOARD)-LH <i>Lot</i>	\$	1,315.00 ✓ 1,142.90
56	ACRYLIC SEALANT <i>3</i>	S/N \$	180.00 +
57	CAVITY WAX <i>2</i>	S/N \$	140.00 +
58	STONE CHIP <i>2</i>	S/N \$	180.00 +
59	FRONT WINDSCREEN SEALANT <i>New</i>	S/N \$	200.00 +
60	SUNDRIES <i>New</i>	\$	1,200.00 ✓ 39.36
TOTAL SPARE PARTS		:	\$ 31,854.00
TOTAL LABOUR CHARGES		:	\$ 30,024.00
GRAND TOTAL		:	\$ 61,878.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian King

Surveyed Date

:

28/03/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 08 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0392/2019/DY 15-Apr-19 Kee Siang 1 of 1 SKP 0023 U Q7 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
Parts			
1	Window Guide <i>Damaged</i>	\$ 461.00	\$ 368.80
2	Door Hinge Left Lower <i>2 Bad</i>	\$ 39.00	\$ 32.32
3	Door Hinge Left Lower	\$ 41.00	\$ 42.72
4	Rear Wheel Cover-RH <i>4 up</i>	\$ 344.00	\$ 275.20
GRAND TOTAL		\$ 885.00	\$ 719.04

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0392/2019/DY 16-Apr-19 Kee Siang 1 of 1 SKP 0023 U Q7 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>labour</u>			
1	Repair LHS sill panel & B-pillar.	\$ 1,200.00	\$ 600.00 ✓
2	To respray LHS sill panel and B-pillar	\$ 1,500.00	\$ 600.00 ✓
<u>Parts</u>			
GRAND TOTAL		\$ 2,700.00	\$ 1,200.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0392/2019/DY
Date : 28-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKR 2900 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

8 days exclude 1 Sunday - jlb

9-Sep-19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Poh Lay Mui
Address : 23 Tai Hwan Lane
Singapore 555340

Telephone : 98623323/98533333
Type of Claim : Third Party Claim
Policy No. : DHOM12003498180
Vehicle No : **SKP 0023 U**
Model Code : Q7 2.0 TFSI QU
Model / Year : 31/5/2017
Engine No : CYR 036651
Chassis No : WAUZZZ4M2HD045845
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By :
Accident Date : 27-Mar-19
Place of Accident : Junction of Tai Hwan Heights and Jin Pacheli

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 0023 U

S/N	Nature of Jobs	Estimated Charges			
1	To remove and reinstall all front wire harness for headlights, outside temperature sensor, headlight washer assy and fornt parking aid.	S/N	\$	480.00	\$ 480.00
2	To remove and transfer rear parking aid and rear kick sensor and renew according to damage.	S/N	\$	360.00	\$ 360.00
3	To dislodge and reinstall lhs A- Pillar, lhs front and rear doors harness, multi-lock system and power window devices. Inspect for damages.	S/N	\$	1,400.00	\$ 1,400.00
4	To remove and reinstall front seat assy, back rest, ABCD pillar trims, sill trims, carpets, electronic components and fuse trays.	S/N	\$	1,800.00	na
5	To renew front windscreen.	S/N	\$	480.00	
6	To remove center console and dashboard assy for A-pillar renewal. Inspect for damages.	S/N	\$	3,200.00	na
SUB-TOTAL LABOUR CHARGES		:	\$	7,720.00	\$ 2,240.00

Tel : 6366 2323 Fax : 6841 1183

Estimated Labour Charges for Accident Vehicle SKP 0023 U

S/N	Nature of Jobs	Estimated Charges		
		<i>c/f</i>	\$	2,240.00
7	To disassemble front bumper, lhs front fender, lhs front door, lhs rear doors and rear bumper assy. Cut out and reweld lhs A-pillar, lhs sill panel and lhs B-pillar. Renew lhs front fender, lhs front and rear doors and rear bumper assy. Reinstall all parts removed.	\$ 11,200.00	\$	3,600.00
8	To respray lhs front fender, lhs front and rear doors, door covers, both front wheel arch trims, lhs A-pillar, lhs sill panel, lhs B-pillar, door entrances, lhs rear fender, rear bumper, rear lower bumper and both rear wheel arch trims.	\$ 10,000.00	\$	5,500.00
9	To remove and renew lhs side step.	S/N \$ 400.00	\$	400.00
10	To renew lhs front and rear trims. To carry out wheel alignment.	S/N \$ 320.00	\$	320.00
10A	Added labour charge - see attached	\$ 2,700.00	\$	1,200.00
11	To carry out diagnostic check.	S/N \$ 384.00	\$	384.00
TOTAL LABOUR CHARGES		:	\$ 32,724.00	\$ 13,644.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 0023 U

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT FENDER-LH	\$ 1,481.00	\$ 1,184.80
2	FRONT FENDER ATTACHEMENT PARTS-LH	\$ 69.00	
3	FRONT FENDER BRACKET-LH	\$ 56.00	
4	FRONT FENDER CENTER BRACKET-LH	\$ 59.00	
5	FRONT FENDER BRACE-LH	\$ 93.00	
6	FRONT FENDER CLOSING ELEMENT-LH	\$ 30.00	
7	FRONT WHEEL COVER-LH/RH	2 \$ 1,044.00	\$ 834.40
8	FRONT PILLAR A/B-LH	\$ 4,162.00	
9	FRONT WINDSCREEN	\$ 1,451.00	
10	FRONT WINDSCREEN RAIN SENSOR	\$ 749.00	
11	FRONT DOOR-LH	\$ 3,570.00	\$ 2,856.00
12	FRONT OUTER DOOR SEAL-LH	\$ 229.00	\$ 182.80
13	BONDING AGENT	\$ 45.00	
14	CLEANING SOLUTION	\$ 65.00	
15	APPLICATOR	\$ 7.00	
16	FRONT DOOR ATTACHMENT PARTS-LH	\$ 89.00	
17	FRONT DOOR CATCH -LH	\$ 117.00	
18	FRONT DOOR CATCH COVER-LH	\$ 16.00	
19	FRONT DOOR HINGE HALF UPPER PART-LH UPPER	\$ 41.00	
20	FRONT DOOR HINGE HALF LOWER PART-LH UPPER	\$ 41.00	
SUB-TOTAL SPARE PARTS		\$ 13,414.00	\$ 5,058.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 0023 U

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
	c/f	\$	5,058.00
21	FRONT DOOR HINGE HALF UPPER PART-LH LOWER	\$ 54.00	
22	FRONT DOOR HINGE HALF LOWER PART-LH LOWER	\$ 41.00	
23	FRONT DOOR COVER-LH	\$ 632.00	\$ 505.60
24	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-LH	\$ 344.00	
25	FRONT DOOR GUIDE COVER TRIM ALUMINIUM-LH	\$ 354.00	\$ 282.80
26	FRONT SILL TRIM STRIP-LH OUTER	\$ 167.00	\$ 133.60
27	FRONT SILL TRIM STRIP-LH INNER	\$ 188.00	\$ 150.00
28	REAR DOOR-LH	\$ 3,570.00	\$ 2,856.00
29	REAR OUTER DOOR SEAL-LH	\$ 229.00	\$ 182.80
30	BONDING AGENT	\$ 45.00	
31	CLEANING SOLUTION	\$ 65.00	
32	APPLICATOR	\$ 7.00	
33	REAR DOOR ATTACHMENT PARTS-LH	\$ 89.00	
34	REAR DOOR CATCH-LH	\$ 96.00	\$ 76.16
35	REAR DOOR CATCH COVER-LH	\$ 16.00	\$ 12.32
36	REAR DOOR SEAL OUTER-LH	\$ 174.00	\$ 138.80
37	REAR WHEATHER STRIP-LH	\$ 234.00	
38	REAR DOOR COVER-LH	\$ 545.00	\$ 436.00
39	REAR WINDOW SLOT SEAL WITH TRIM STIP ALUMINII	\$ 337.00	
40	REAR COVER TRIM ALUMINIUM-LH	\$ 273.00	\$ 218.40
SUB-TOTAL SPARE PARTS		\$ 7,460.00	\$ 10,050.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 0023 U

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	10,050.48
41	FRONT PILLAR B TRIM-LH		\$ 203.00	
42	REAR PILLAR B TRIM-LH		\$ 204.00	
43	REAR UPPER BUMPER		\$ 1,121.00	
44	REAR LOWER BUMPER		\$ 1,677.00	
45	REAR BUMPER FIXING PARTS		\$ 188.00	
46	REAR BUMPER GUIDE SECTION-LH		\$ 58.00	
47	REAR BUMPER TAIL LIGHT BULB -LH		\$ 326.00	
48	REAR DOOR WHEEL COVER-LH		\$ 179.00	\$ 143.20
49	REAR WHEEL COVER-LH		\$ 344.00	\$ 275.20
50	LH ALUMINIUM RIM-FRONT/REAR	2	\$ 2,232.00	\$ 1,785.60
51	RUBBER VALVE	4	\$ 13.00	
52	REAR WINDOW REGULATOR WITHOUT MOTOR-LH		\$ 257.00	
53	REAR WINDOW REGULATOR MOTOR-LH		\$ 278.00	
54	REAR DOOR CONTROL UNIT-LH		\$ 685.00	
55	SIDE STEP (RUNNING BOARD)-LH		\$ 1,315.00	\$ 1,142.40
56	ACRYLIC SEALANT	S/N	\$ 180.00	
57	CAVITY WAX	S/N	\$ 140.00	
58	STONE CHIP	S/N	\$ 180.00	
59	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00	
60	<i>Added parts - see attached</i>		\$ 885.00	\$ 719.04
61	SUNDRIES		\$ 1,200.00	\$ 39.36
TOTAL SPARE PARTS		:	\$ 32,739.00	\$ 14,155.28
TOTAL LABOUR CHARGES		:	\$ 32,724.00	\$ 13,644.00
GRAND TOTAL		:	\$ 65,463.00	\$ 27,799.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0392/2019/DY
Date	:	28-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKR 2900 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Poh Lay Mui
Address	:	23 Tai Hwan Lane Singapore 555340

Telephone	:	98623323/98533333
Type of Claim	:	Third Party Claim
Policy No.	:	DHOM12003498180
Vehicle No	:	SKP 0023 U
Model Code	:	Q7 2.0 TFSI QU
Model / Year	:	31/5/2017
Engine No	:	CYR 036651
Chassis No	:	WAUZZZ4M2HD045845
Mileage	:	
Date In	:	
Liability	:	
Excess Cost	:	
Estimated By	:	
Accident Date	:	27-Mar-19
Place of Accident	:	Junction of Tai Hwan Heights and Jln Pacheli

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 Mar 2019 16:02	Cim Dtl Modified	Claimant's Name: -> POH LAY MUI. Claimant's ID: -> S6904875G.	[A] Lau Shu Pei
2	28 Mar 2019 16:02	Cim Veh Model Changed	(204926) AUDI Q7 2.0 TFSI QU (A).	[A] Lau Shu Pei
3	28 Mar 2019 16:02	Cim Created	Reg No: SKP23U. Acct Date: 2019/03/27. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: United Overseas Insurance Ltd (HQ). Workshop: Premium Automobiles Pte Ltd (UBI)	[A] Lau Shu Pei
4	28 Mar 2019 16:02	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); Suggested Adj. : LKK Auto Consultants Pte Ltd.	[A] Lau Shu Pei
5	28 Mar 2019 16:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/08	[A] Lau Shu Pei
6	28 Mar 2019 16:02	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Lau Shu Pei
7	28 Mar 2019 16:02	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	28 Mar 2019 16:03	Label Added	(23):Express.	[A] Lau Shu Pei
9	28 Mar 2019 16:03	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
10	23 Oct 2019 10:34	Adj Rpt Initiated		[A] HUEY YON
11	23 Oct 2019 10:34	Cim Dtl Modified	JPJ Reg. Date: -> 2017/05/31.	[A] HUEY YON
12	23 Oct 2019 10:34	Cim Details Notified		[A] HUEY YON
13	23 Oct 2019 16:00	Adj Mandate Request	Cur.Reg:30652.68:LIABILITY: 100% B:7 OLD MAKE A RIGHT TURN AT UNCONTROLLED JUNCTION	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type: None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2322200	23 Oct 2019 10:34:21	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKP23U	SKR2900P	11.77

Print Received Message

This mail is associated with :

***SKP23U (2256734587SG)
[SKR2900P]**

TP
POH LAY MUI
Mar 27 2019 11:00AM
[THANGAVELU KRISHNA]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 03/01/2020 12:22 PM
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$30652.68) - SKP23U - Claim Handler: Foo, Chit Yan

Approved:30652.68:Above mandate subj to Damage Photos furnished (per email dated 03/01/20), Final Repair Bill, LTA Bill in order



MEMBER OF THE UOB GROUP

United Overseas Insurance Limited

3 Anson Road
#28-01 Springleaf Tower
Singapore 079909Tel (65) 6222 7733
Fax (65) 6327 3869 / 6327 3870
Email: ContactUs@uoi.com.sg
uoi.com.sg

Co. Reg. No. 197100152R

ORIGINALUNIDRIVE
THE SCHEDULE

Agency	A000401	Class of Policy	MOTOR UNIDRIVE	Policy Number	 DHOM12003498180
Account	A000401	Issued on	 07/06/2018 in UOI		
Client	0388078	Acceptance Date	04/06/2018	Replacing Cover Note	19832

Period of insurance from 1038 hours on 04/06/2018 to 2400 hours on 30/05/2019

Insured's Name....	MDM POH LAY MUI
Mailing Address...	23 TAI HWAN LANE TAI HWAN GARDEN SINGAPORE 555340

Business/Occupn...	INDOOR
Financial interest	UNITED OVERSEAS BANK LIMITED

Premium	ANNUAL PREMIUM	SGD1,019.69		
	Total Annual Premium	SGD1,019.69	Premium Due	SGD1,008.1
			Premium GST	SGD70.1
			Total Due	SGD1,079.1

EXCESS FOR NAMED DRIVER
REFER TO DRIVER AGE MUST BE ABOVE 25 YEAR AND OR DRIVING EXPERIENCE MORE THAN
THREE (3) YEARS

Risk No. 001	UNIDRIVE			
1. Registration	SKP23U	Make/Model ..	AUDI Q7 2.0 TFSI QU	
Type of Cover	COMPREHENSIVE	No. of seats	4	Body Type STATION WAGON
Engine No. ..	CYR036651	Capacity cc's	1984	Yr of Manuf/Regn 2017/2017
Chassis No. .	WAUZZZ4M2HDO45845			NCB%..... 50.00
				Certificate Ref. PVI
INDEMNITY FOR TOTAL LOSS.....		MARKET VALUE		
OTHERS		SGD1,500.00		
APPL TO <25 YRS & OR <3YRS EXP		SGD3,000.00		
WINDSCREEN DAMAGE CLAIM		SGD100.00		
NAMED DRIVERS - OPTION 2		SGD750.00		
Named Drivers POH LAY MUI		PETER TAY KWONG LAIN		

THE FOLLOWING CLAUSES AND ENDORSEMENTS APPLY TO THIS POLICY

2 - EXCESS - DAMAGE CLAIMS

AN EXCESS OF \$100 (BEFORE GST) APPLIES FOR EACH WINDSCREEN CLAIM

15 - HIRE PURCHASE

PAYMENT BEFORE COVER WARRANTY

TERRORISM EXCLUSION ENDORSEMENT

CONTRACTS (RIGHT OF THIRD PARTIES) ACT 2001

25 - STRIKE RIOT AND CIVIL COMMOTION

SECTION III - MEDICAL EXPENSES

SECTION IV - PERSONAL ACCIDENT BENEFITS

2 E - YOUNG AND INEXPERIENCED DRIVERS

2 F - (A) THE INSURED

BREAKDOWN OF PAYMENT

Vehicle No: SKP 23 U

Accident on 27/3/2019 at Juntion Of Tai Hwan Heights And Jln Pacheli

Involving vehicle/s SKR 2900 P

1) Repair cost \$ 29,745.23 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 7.45 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 900 Payable to: Poh Lay Mui

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express	Help Contents
	Feedback/Requests
	Take Screenshot (Ctrl+Shift+S)
	Language

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2019 Edit Reg		28 Mar 2019 00:00 Edit Adj Rpt	S\$27,799.28 Edit Estimates	S\$27,799.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	THANGAVELU KRISHNA, ID: S10497588, Tel: +6599999999								
Main Claimant:	POH LAY MUI, ID: S6904875G								
Vehicle Reg. No.:	SKP23U	Date of Loss:	27/03/2019 11:00 - :59 [21 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2256734587SG	Policy/Cover Note No.:	2100401051 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKR2900P	Policy No. (Claimant):	DHOM12003498180						
	Excess:								
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	United Overseas Insurance Ltd (HQ) - Tel: 64909318								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (03/01/2020): Alert - Adj Mandate Approved (S\$30652.68) - SKP23U - Claim Handler: Foo, Chit Ya...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKP23U (22567345875G)
[SKR2900P]
TP
POH LAY MUI
Mar 27 2019 11:00AM
[THANGAVELU KRISHNA]
Premium Automobiles Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	

Assessment Reports

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/03/19 11:12	Accident Statement From: SC - Reg. No: SKR2900P, Claimant: THANGAVELU KRISHNA	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/10/19 11:52	General View	Load JPG	☒
2	04/10/19 11:52	General View	Load JPG	☒
3	04/10/19 11:52	General View	Load JPG	☒
4	04/10/19 11:52	General View	Load JPG	☒
5	04/10/19 11:52	General View	Load JPG	☒
6	04/10/19 11:52	General View	Load JPG	☒
7	04/10/19 11:52	General View	Load JPG	☒
8	04/10/19 11:52	General View	Load JPG	☒
9	04/10/19 11:52	General View	Load JPG	☒
10	04/10/19 11:52	General View	Load JPG	☒
11	04/10/19 11:52	General View	Load JPG	☒
12	04/10/19 11:52	General View	Load JPG	☒
13	04/10/19 11:52	General View	Load JPG	☒
14	04/10/19 11:52	General View	Load JPG	☒
15	04/10/19 11:52	General View	Load JPG	☒
16	04/10/19 11:52	General View	Load JPG	☒
17	04/10/19 11:52	General View	Load JPG	☒
18	04/10/19 11:52	General View	Load JPG	☒
19	04/10/19 11:52	General View	Load JPG	☒
20	04/10/19 11:52	General View	Load JPG	☒
21	04/10/19 11:52	General View	Load JPG	☒
22	04/10/19 11:52	General View	Load JPG	☒
23	04/10/19 11:52	General View	Load JPG	☒
24	04/10/19 11:52	General View	Load JPG	☒
25	04/10/19 11:52	General View	Load JPG	☒
26	04/10/19 11:52	General View	Load JPG	☒
27	04/10/19 11:52	General View	Load JPG	☒
28	04/10/19 11:52	General View	Load JPG	☒
29	04/10/19 11:52	General View	Load JPG	☒
30	04/10/19 11:52	General View	Load JPG	☒
31	04/10/19 11:52	General View	Load JPG	☒
32	04/10/19 11:52	General View	Load JPG	☒
33	04/10/19 11:52	General View	Load JPG	☒
34	04/10/19 11:52	General View	Load JPG	☒
35	04/10/19 11:52	General View	Load JPG	☒
36	04/10/19 11:52	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
37	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
38	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
39	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
40	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
41	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
42	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
43	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
44	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
45	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
46	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
47	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
48	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
49	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
50	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
51	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
52	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
53	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
54	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
55	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
56	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
57	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
58	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
59	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
60	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
61	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
62	04/10/19 11:52	Reinspection Photo	 Load JPG	☒
63	02/01/20 15:53	General View	 Load JPG	☒
64	02/01/20 15:53	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/19 16:03	TP GIA REPORT	 Load PDF	
2	29/03/19 16:35	TP ESTIMATE- MARKED	 Load PDF	
3	23/10/19 15:56	TP LOD	 Load PDF	
4	23/10/19 15:58	LETTER TO OI	 Load PDF	
5	09/01/20 09:31	WORKSHOP INVOICE	 Load PDF	
6	09/01/20 09:31	AUTHORISATION TO ACT FORM	 Load PDF	
7	09/01/20 09:31	Release Voucher	 Load PDF	
8	09/01/20 09:31	LTA SEARCH	 Load PDF	
9	09/01/20 09:31	LOD	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/11/19 14:49	Clear Report	 Load XLSX	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKR2900P (Insd veh)	Model:	AUDI Q7 2.0 TFSI QU (A)
	SKP23U (TP veh)		
Date of Accident:	27/03/2019		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$	69,867.83	
Final Repair Cost	: \$	29,745.23	
Loss of Use	: \$	900.00	9.00 days at \$100.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	30,652.68	

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 7

BOLA Liability: 100 (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	: \$	30,652.68
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

09 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19005550/AEA3Q2

Date: 09/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100401051
 Claimant: SKP23U Insured Vehicle No: SKR2900P
 Vehicle No: SKP23U
 Date of Loss: 27/03/2019 Nature of Claim: TP Claim No: 2256734587SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP23U
 Make & Model: AUDI Q7, 2.0 TFSI QU (A) Engine No: CYR036651
 Reg. Date: 31/05/2017 (Man. Year: 2017) Chassis No: WAUZZZ4M2HD045845
 Colour: Grey Odometer: 35025 km
 Engine Capacity: 1984 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55R19 Rear Tyre Size: 255/55R19
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,573.04	14,155.28	18,417.76	56.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	32,724.00	13,644.00	19,080.00	58.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	65,297.04	27,799.28	37,497.76	57.43
+ GST 7.00/7.00% (S\$)	4,570.79	1,945.95	2,624.84	57.43
Nett Amount (S\$)	69,867.83	29,745.23	40,122.60	57.43
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		30,652.68		

INSPECTION

Date of Assignment: 28/03/2019
 Date Inspected: 28/03/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -LH	Dented	1,481.00 FS	*1,184.80 FS
2	1		*FRONT FENDER ATTACHMENT PARTS -LH	Not Necessary	69.00 FS	*- FS
3	1		*FRONT FENDER BRACKET -LH	Not Necessary	56.00 FS	*- FS
4	1		*FRONT FENDER CENTER BRACKET -LH	Not Necessary	59.00 FS	*- FS
5	1		*FRONT FENDER BRACE -LH	Not Necessary	93.00 FS	*- FS
6	1		*FRONT FENDER CLOSING ELEMENT -LH	Not Necessary	30.00 FS	*- FS
7	2		*FRONT WHEEL COVER -LH/RH	Necessary	1,044.00 FS	*834.40 FS
8	1		*FRONT PILLAR A/B -LH	Repair	4,162.00 FS	*- FS
9	1		*FRONT WINDSCREEN	Not Necessary	1,451.00 FS	*- FS
10	1		*FRONT WINDSCREEN RAIN SENSOR	Not Necessary	749.00 FS	*- FS
11	1		*FRONT DOOR -LH	Dented	3,570.00 FS	*2,856.00 FS
12	1		*FRONT OUTER DOOR SEAL -LH	Necessary	229.00 FS	*182.80 FS
13	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
14	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
15	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
16	1		*FRONT DOOR ATTACHMENT PARTS -LH	Not Necessary	89.00 FS	*- FS
17	1		*FRONT DOOR CATCH -LH	Not Necessary	117.00 FS	*- FS
18	1		*FRONT DOOR CATCH COVER -LH	Not Necessary	16.00 FS	*- FS
19	1		*FRONT DOOR HINGE HALF UPPER PART -LH UPPER	Not Necessary	41.00 FS	*- FS
20	1		*FRONT DOOR HINGE HALF LOWER PART -LH UPPER	Not Necessary	41.00 FS	*- FS
21	1		*FRONT DOOR HINGE HALF LOWER PART -LH LOWER	Not Necessary	41.00 FS	*- FS
22	1		*FRONT DOOR HINGE HALF UPPER PART -LH LOWER	Not Necessary	54.00 FS	*- FS
23	1		*FRONT DOOR COVER -LH	Distorted	632.00 FS	*505.60 FS
24	1		*FRONT WIDDOW SLOT SEAL WITH TRIM STRIP -LH	Not Necessary	344.00 FS	*- FS
25	1		*FRONT DOOR GUIDE COVER TRIM ALUMINIUM -LH	Distorted	354.00 FS	*282.80 FS
26	1		*FRONT SILL TRIM STRIP -LH OUTER	Cut	167.00 FS	*133.60 FS
27	1		*FRONT SILL TRIM STRIP -LH INNER	Cut	188.00 FS	*150.00 FS
28	1		*REAR DOOR -LH	Dented	3,570.00 FS	*2,856.00 FS
29	1		*REAR OUTER DOOR SEAL -LH	Necessary	229.00 FS	*182.80 FS
30	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
31	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
32	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
33	1		*REAR DOOR ATTACHMENT PARTS -LH	Not Necessary	89.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*REAR DOOR CATCH -LH	Necessary	96.00 FS	*76.16 FS
35	1		*REAR DOOR CATCH COVER -LH	Deformed	16.00 FS	*12.32 FS
36	1		*REAR DOOR SEAL OUTER-LH	Necessary	174.00 FS	*138.80 FS
37	1		*REAR WEATHERSTRIP -LH	Not Necessary	234.00 FS	*- FS
38	1		*REAR DOOR COVER -LH	Deformed	545.00 FS	*436.00 FS
39	1		*REAR WINDOW SLOT SEAL WITH TRIM STIP ALUMINIUM -LH	Not Necessary	337.00 FS	*- FS
40	1		*REAR COVER TRIM ALUMINIUM -LH	Deformed	273.00 FS	*218.40 FS
41	1		*FRONT PILLAR B TRIM -LH	Not Necessary	203.00 FS	*- FS
42	1		*REAR PILLAR B TRIM -LH	Not Necessary	204.00 FS	*- FS
43	1		*REAR UPPER BUMPER	Repair	1,121.00 FS	*- FS
44	1		*REAR LOWER BUMPER	Repair	1,677.00 FS	*- FS
45	1		*REAR BUMPER FIXING PARTS	Not Necessary	188.00 FS	*- FS
46	1		*REAR BUMPER GUIDE SECTION -LH	Not Necessary	58.00 FS	*- FS
47	1		*REAR BUMPER TAIL LIGHT BULB -LH	Not Necessary	326.00 FS	*- FS
48	1		*REAR DOOR WHEEL COVER -LH	Necessary	179.00 FS	*143.20 FS
49	1		*REAR WHEEL COVER -LH	Necessary	344.00 FS	*275.20 FS
50	2		*LH ALUMINIUM RIM-FRONT /REAR	Cut	2,232.00 FS	*1,785.60 FS
51	4		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
52	1		*REAR WINDOW REGULATOR WITHOUT MOTOR -LH	Not Necessary	257.00 FS	*- FS
53	1		*REAR WINDOW REGULATOR MOTOR -LH	Not Necessary	278.00 FS	*- FS
54	1		*REAR DOOR CONTROL UNIT -LH	Not Necessary	685.00 FS	*- FS
55	1		*SIDE STEP (RUNNING BOARD)-LH	Cut	1,315.00 FS	*1,142.40 FS
56	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
57	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
58	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
59	1		*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
60	1		*SUNDRIES	Necessary	1,200.00 FS	*39.36 FS
61	1		*WINDOW GUIDE	Damaged	368.80 FS	*368.80 FS
62	1		*DOOR HINGE LEFT LOWER	Bent	32.32 FS	*32.32 FS
63	1		*DOOR HINGE LEFT LOWER	Bent	42.72 FS	*42.72 FS
64	1		*REAR WHEEL COVER -RH	Cut	275.20 FS	*275.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 32,573.04 14,155.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL ALL FRONT WIRE HARNESS FOR HEADLIGHTS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR KICK SENSOR AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
3	TO DISLODGE AND REINSTALL LHS A-PILLAR ,LHS FRONT AND REAR DOORS HARNESS ,MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES .INSPECT FOR DAMAGES	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL FRONT SEAT ASSY ,BACK REST,ABCD PILLAR TRIMS, SILL TRIMS ,CARPETS ,ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	0.00
5	TO RENEW FRONT WINDSCREEN	New	480.00	0.00
6	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR RENEWAL .INSPECT FOR DAMAGES	New	3,200.00	0.00
7	TO DISMANTLE FRONT BUMPER ,LHS FRONT FENDER ,LHS FRONT DOOR ,LHS REAR DOORS AND REAR BUMPER ASSY.CUT OUT AND REWELD LHS A-PILLAR ,LHS SILL PANEL AND LHS B-PILLAR .RENEW LHS FRONT FENDER ,LHS FRONT AND REAR DOORS AND REAR BUMPER ASSY .REINSTALL ALL PARTS REMOVED	New	11,200.00	3,600.00
8	TO RESPRAY LHS FRONT FENDER ,LHS FRONT AND REAR DOORS,DOOR COVERS ,BOTH FRONT WHEEL ARCH TRIMS,LHS A-PILLAR ,LHS SILL PANEL ,LHS B-PILLAR ,DOOR ENTRANCES ,LHS REAR FENDER ,REAR BUMPER ,REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	10,000.00	5,500.00
9	TO REMOVE AND RENEW LHS SIDE STEP	New	400.00	400.00
10	TO RENEW LHS FRONT AND REAR TRIMS .TO CARRY OUT WHEEL ALIGNMENT	New	320.00	320.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
12	REPAIR LHS SILL PANEL & B-PILLAR	New	1,200.00	600.00
13	TO RESPRAY LHS SILL PANEL AND B-PILLAR	New	1,500.00	600.00
Gross Labour Cost (S\$)			32,724.00	13,644.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >