

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0392/2019/DY
Date : 28-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKR 2900 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Poh Lay Mui
Address : 23 Tai Hwan Lane
Singapore 555340

Telephone : 98623323/98533333
Type of Claim : Third Party Claim
Policy No. : DHOM12003498180
Vehicle No : **SKP 0023 U**
Model Code : Q7 2.0 TFSI QU
Model / Year : 31/5/2017
Engine No : CYR 036651
Chassis No : WAUZZZ4M2HD045845
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By :
Accident Date : 27-Mar-19
Place of Accident : Junction of Tai Hwan Heights and Jln Pacheli

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 0023 U

S/N	Nature of Jobs		Estimated Charges	
1	To remove and reinstall all front wire harness for headlights, outside temperature sensor, headlight washer assy and fornt parking aid.	S/N \$	480.00	✓
2	To remove and transfer rear parking aid and rear kick sensor and renew according to damage.	S/N \$	360.00	✓
3	To dislodge and reinstall lhs A- Pillar, lhs front and rear doors harness, multi-lock system and power window devices. Inspect for damges.	S/N \$	1,400.00	✓
4	To remove and reinstall front seat assy, back rest, ABCD pillar trims, sill trims, carpets, electronic components and fuse trays.	S/N \$	1,800.00	✗
5	To renew front windscreen.	S/N \$	480.00	✗
6	To remove center console and dashboard assy for A-pillar renewal. Inspect for damages.	S/N \$	3,200.00	✗
SUB-TOTAL LABOUR CHARGES		:	\$	<u><u>7,720.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKP 0023 U

S/N	Nature of Jobs	Estimated Charges
7	To disassemble front bumper, lhs front fender, lhs front door, lhs rear doors and rear bumper assy. Cut out and reweld lhs A-pillar, lhs sill panel and lhs B-pillar. Renew lhs front fender, lhs front and rear doors and rear bumper assy. Reinstall all parts removed.	$(4+1) \times 600 = 3000$ $2 \text{ door} \leftarrow$ $2 \text{ bumper} \leftarrow$ $1 \text{ Fender} \leftarrow$ $11,200.00$ 3600.
8	To respray lhs front fender, lhs front and rear doors, door covers, both front wheel arch trims, lhs A-pillar, lhs sill panel, lhs B-pillar, door entrances, lhs rear fender, rear bumper, rear lower bumper and both rear wheel arch trims.	$7 \times 600 = 4200$ $\text{Wheel Cover} \times 4 = 800$ (200) $\text{Door Cover} \times 2 = 400$ $10,000.00$ 5600.
9	To remove and renew lhs side step.	S/N \$ 400.00 ✓
10	To renew lhs front and rear trims. To carry out wheel alignment.	S/N \$ 320.00 ✓
11	To carry out diagnostic check.	S/N \$ 384.00 ✓
TOTAL LABOUR CHARGES		: \$ 30,024.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 0023 U

S/N	Parts Description	Damage Pa S/NETT
1	FRONT FENDER-LH <i>Dented</i>	\$ 1,481.00 ✓
2	FRONT FENDER ATTACHEMENT PARTS-LH ?	\$ 69.00 ?
3	FRONT FENDER BRACKET-LH <i>new</i>	\$ 56.00 ✕
4	FRONT FENDER CENTER BRACKET-LH <i>new</i>	\$ 59.00 ✕
5	FRONT FENDER BRACE-LH <i>new</i>	\$ 93.00 ✕
6	FRONT FENDER CLOSING ELEMENT-LH <i>new</i>	\$ 30.00 ✕
7	FRONT WHEEL COVER-LH/RH <i>new</i>	2 \$ 1,044.00 ✓
8	FRONT PILLAR A/B-LH <i>Repair</i>	\$ 4,162.00 ✕
9	FRONT WINDSCREEN <i>new</i>	\$ 1,451.00 ✕
10	FRONT WINDSCREEN RAIN SENSOR <i>Not in</i>	\$ 749.00 ✕
11	FRONT DOOR-LH <i>Dented</i>	\$ 3,570.00 ✓
12	FRONT OUTER DOOR SEAL-LH <i>new</i>	\$ 229.00 ✓
13	BONDING AGENT ?	\$ 45.00 ?
14	CLEANING SOLUTION ?	\$ 65.00 ?
15	APPLICATOR ?	\$ 7.00 ?
16	FRONT DOOR ATTACHMENT PARTS-LH ?	\$ 89.00 ?
17	FRONT DOOR CATCH -LH <i>new</i>	\$ 117.00 ✕
18	FRONT DOOR CATCH COVER-LH <i>new</i>	\$ 16.00 ✕
19	FRONT DOOR HINGE HALF UPPER PART-LH UPPER <i>new</i> ?	\$ 41.00 ✕ ?
20	FRONT DOOR HINGE HALF LOWER PART-LH UPPER <i>new</i> ?	\$ 41.00 ✕ ?
SUB-TOTAL SPARE PARTS		: \$ 13,414.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Parts & Prices

REMARKS

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 0023 U

S/N	Parts Description	Damage Pa S/NETT
21	FRONT DOOR HINGE HALF UPPER PART-LH LOWER ?	\$ 54.00 ?
22	FRONT DOOR HINGE HALF LOWER PART-LH LOWER ?	\$ 41.00 ?
23	FRONT DOOR COVER-LH Distal	\$ 632.00 ✓
24	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-LH new	\$ 344.00 +
25	FRONT DOOR GUIDE COVER TRIM ALUMINIUM-LH Distal	\$ 354.00 ✓
26	FRONT SILL TRIM STRIP-LH OUTER } ut	\$ 167.00 ✓
27	FRONT SILL TRIM STRIP-LH INNER	\$ 188.00 ✓
28	REAR DOOR-LH Bent	\$ 3,570.00 ✓
29	REAR OUTER DOOR SEAL-LH new	\$ 229.00 ✓
30	BONDING AGENT ?	\$ 45.00 ?
31	CLEANING SOLUTION ?	\$ 65.00 ?
32	APPLICATOR ?	\$ 7.00 ?
33	REAR DOOR ATTACHMENT PARTS-LH ?	\$ 89.00 ?
34	REAR DOOR CATCH-LH new	\$ 96.00 +
35	REAR DOOR CATCH COVER-LH Bent	\$ 16.00 ✓
36	REAR DOOR SEAL OUTER-LH new	\$ 174.00 +
37	REAR WHEATHER STRIP-LH new	\$ 234.00 +
38	REAR DOOR COVER-LH Bent	\$ 545.00 ✓
39	REAR WINDOW SLOT SEAL WITH TRIM STIP ALUMINIUM-LH	\$ 337.00 +
40	REAR COVER TRIM ALUMINIUM-LH Bent	\$ 273.00 ✓
SUB-TOTAL SPARE PARTS		\$ 7,460.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Items & Prices

REMARKS

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKP 0023 U

S/N	Parts Description	Damage Pa S/NETT
41	FRONT PILLAR B TRIM-LH <i>3</i>	\$ 203.00 <i>+</i>
42	REAR PILLAR B TRIM-LH <i>2</i>	\$ 204.00 <i>+</i>
43	REAR UPPER BUMPER <i>Repair</i>	\$ 1,121.00 <i>+</i>
44	REAR LOWER BUMPER <i>Repair</i>	\$ 1,677.00 <i>+</i>
45	REAR BUMPER FIXING PARTS <i>new</i>	\$ 188.00 <i>+</i>
46	REAR BUMPER GUIDE SECTION-LH <i>new</i>	\$ 58.00 <i>+</i>
47	REAR BUMPER TAIL LIGHT BULB -LH <i>new</i>	\$ 326.00 <i>+</i>
48	REAR DOOR WHEEL COVER-LH <i>new</i>	\$ 179.00 <i>✓</i>
49	REAR WHEEL COVER-LH <i>new</i>	\$ 344.00 <i>✓</i>
50	LH ALUMINIUM RIM-FRONT/REAR <i>lot</i>	2 \$ 2,232.00 <i>✓</i>
51	RUBBER VALVE <i>new</i>	4 \$ 13.00 <i>+</i>
52	REAR WINDOW REGULATOR WITHOUT MOTOR-LH <i>new</i>	\$ 257.00 <i>+</i>
53	REAR WINDOW REGULATOR MOTOR-LH <i>new</i>	\$ 278.00 <i>+</i>
54	REAR DOOR CONTROL UNIT-LH <i>new</i>	\$ 685.00 <i>+</i>
55	SIDE STEP (RUNNING BOARD)-LH <i>lot</i>	\$ 1,315.00 <i>✓</i>
56	ACRYLIC SEALANT <i>2</i>	S/N \$ 180.00 <i>+</i>
57	CAVITY WAX <i>new</i>	S/N \$ 140.00 <i>+</i>
58	STONE CHIP <i>new</i>	S/N \$ 180.00 <i>+</i>
59	FRONT WINDSCREEN SEALANT <i>new</i>	S/N \$ 200.00 <i>+</i>
60	SUNDRIES <i>?</i>	\$ 1,200.00 <i>?</i>
TOTAL SPARE PARTS		: \$ 31,854.00
TOTAL LABOUR CHARGES		: \$ 30,024.00
GRAND TOTAL		: \$ 61,878.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Parts & Prices

REMARKS

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 28/03/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant