

# MEGA SWIFT AUTO

176 Sin Ming Drive #05-11

Sin Ming Autocare Singapore 575721

Tel No. : HP:97511604

Buss. Reg. No. : 52950829W

← Steve ask change to (CA) wrongly write.

Can Authorise

OD - Not Authorise (Revett)

29/3/19 12-15p m

EXCISE - \$509

6 days

Steve (LKK)

8322 8813

Cash

Ry AL spy & change PL  
L/S

Quotation : WO000138

Date Printed : 28/03/2019

Vehicle Num. : SLB5489M

Make/Model : HONDA

Mileage(Km) :

P.O.R.O No. :

Ref./Remark :

| S/N | Quantity | Particular                       | Unit Price | Amount S\$ |
|-----|----------|----------------------------------|------------|------------|
| 1.  | 1pc      | Front Fender ✓ OD                | 813.30     | 813.30     |
| 2.  | 1pc      | Front Bumper ✓ CRV               | 1,067.90   | 1,067.90   |
| 3.  | 1pc      | Front Bumper Lower Lip ✓ R       | 990.22     | 990.22     |
| 4.  | 1pc      | Drive Shaft Assy ✓ BR            | 1,379.14   | 1,379.14   |
| 5.  | 1pc      | Front Knuckle ?                  | 459.67     | 459.67     |
| 6.  | 1pc      | Steering Rack Assy ?             | 2,298.61   | 2,298.61   |
| 7.  | 1pc      | Steering Tie Rod ?               | 88.46      | 88.46      |
| 8.  | 1pc      | Steering Rack Link ?             | 109.91     | 109.91     |
| 9.  | 1pc      | Wheel Bearing ?                  | 174.36     | 174.36     |
| 10. | 1pc      | Front Shock Absorbers ?          | 482.27     | 482.27     |
| 11. | 1pc      | Front Lower Arm ✓ BR             | 433.22     | 433.22     |
| 12. | 1pc      | Front Upper Arm ?                | 300.00     | 300.00     |
| 13. | 1pc      | Front Cross Member ?             | 1,768.00   | 1,768.00   |
| 14. |          | 4 Wheel Computer Alignment ✓ MEC | 60 150.00  | 150.00     |
| 15. |          | checking wiring ✓ MEC            | 80 100.00  | 100.00     |
|     |          | Labour Charge"                   |            |            |
|     |          | To remove parts repair & replace | 1200       | 1,500.00   |
|     |          | To spray bumper                  | 200        | 250.00     |
|     |          | To spray lip                     | ✓          | 150.00     |
|     |          | To spray fender                  | 200        | 250.00     |

Supp - Headlamp RH - Cut  
Safety belt RH - Jammed  
Passenger air bag LH - BR

SingDollars : Twelve Thousand Seven Hundred Sixty-Five & Cents Six Only

E. & O.E.

Total S\$ : 12,765.06

Terms : Cash

Customer's Signature/Co. Stamp

for MEGA SWIFT AUTO

N.B. : Cheque should be crossed and made payable to MEGA SWIFT AUTO

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: