



Poh kin

Section A - Accident Details

Registration Number	SHC4094S
Case Reference Number	TAX/03/19/2129
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LIM TECK HENG
Type of Accident	Head to Rear
Accident Date and Time	26/3/2019 12:51 PM
Accident Reported Date and Time	26/3/2019 3:46 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100777
Special Instruction to ARC, if any	AIG - LKK
Prepared Date and Time	27/3/2019 1:15 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Location

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$1,098.00	\$200.00
Total Spare Part Cost	\$2,856.99	\$543.68
Total Other Cost	\$500.00	\$20.00
TOTAL COST	\$5,130.99	\$963.68 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	27/03/2019 1:44 PM	27/03/2019 2:42 PM
Signature		
Remarks	P/P REPAIR, PHOTO BEFORE PAINT.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0071	Invoice Number	
Quotation Date	05.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,098.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$500.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		5246247030	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247020	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757708
 FAX Number : 63655502
 Estimator Telephone Number : 65652623
 Accident Reporting Number : 58502672

Date Generated : 09/04/2019
 User ID : PohSuan

	9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X	nn
	5256647900	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X	nn
	5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X	nn
	5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	✓	DEF
	5216947020	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X	nn
	5246147010	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace	✓	rec
	5839947030	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X	nn
	5839847050	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X	nn
	6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Check	X	nn
	8218347020	WIRE, LUGGAGE ROOM	0.00	\$143.50	0.00	\$0.00	Replace	Not Given	X	nn
	8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X	nn
	5830747090	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Not Given	X	nn
4006314		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	nn
Total				\$3,549.40		\$543.68				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

543.68
 + 200.00
 + 220.00

 963.68