



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 27/03/2019

Attn: The Motor Claims Department

Your Insured veh no : GBF 5911 H

ERGO Insurance Pte Ltd

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Vic

WITHOUT PREJUDICE

LKK

(By Email Only)

Tel : 6829 9199

Fax : 6829 9247

Dear Sir / Madam

Estimate Cost repair Bill To Toyota Dyna NO GY 6966 J & GBF 5911 H on 22/03/2019 @07:30:00

To Supply :-

1pc	Front head lamp RH <i>anchd</i>	<i>1642.80</i>	\$ 752.30	✓
1pc	Front grille <i>anchd</i>		\$ 395.00	✓
1pc	Front bumper <i>filld</i>	<i>1232.10</i>	\$ 495.50	✓
			\$ 1,642.80	
		less	25% \$ 410.70	
			\$ 1,232.10	

1pc Front number plate *Bent* *30* \$ ~~55.00~~ ³⁰ s/nett

To dismanlte & replace damage parts,panel beat where necessaey.

700

\$ ~~480.00~~ ³⁵⁰

To putty,apply primer & spray paint on the affecte portion.

\$ ~~400.00~~ ³⁵⁰

To check wiring functions.

\$ 60.00

\$ 2,227.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 1962.10 *Adrian Lj*
L/S: 1550 ✓ *L/S 28/03/19.*
03 days.