

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

25-Mar-19

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8494 A

1 pc	Rear bumper <i>— Ahl</i>	\$	696.00
1 pc	Rear bumper lower cover <i>— ct</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X see</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>X see</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>X see</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X see</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X see</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X see</i>	\$	36.00
		\$	1,861.00
Less 10%		\$	186.10
		\$	1,674.90

### S/NETT

1 set	Rear bumper clips <i>— huc</i>	\$	48.00
1 set	Reverse sensor <i>— sldd</i>	\$	<del>280.00</del> <i>200</i>
1 pc	Rear bumper top protector <i>— ne</i>	\$	<del>80.00</del> <i>50</i>
Sundry		\$	<del>50.00</del> <i>X n/c</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$	<del>120.00</del> <i>30</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	<del>180.00</del> <i>X</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc		\$	<del>850.00</del> <i>200</i>
To putty and spray painting on rear bumper, end panel <i>X</i>		\$	<del>400.00</del> <i>180</i>
To apply rustproofing on the repaired and replaced panels.		\$	<del>120.00</del> <i>X 2</i>
		\$	3,602.90

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*Kahin Ullay*  
*27/3/19 1700h*  
*2 Pops*  
*4/5*  
*After Repair photo*