

KAY MOTOR
BLOCK 9 SIN MING INDUSTRIAL ESTATE
#01-46
SINGAPORE 575644
Tel: 6458 2283 Fax: 6459 8863
Email:kayautosg@yahoo.com

*Not Authorised
Resurvey before
4 days*

Color Play Enterprise Pte Ltd

04 April 2019

Estimate To Repair Toyota Hiace – GBF 4104C

1pc	front bumper
1pc	front bumper reinforcement
1pc	front bumper o/s bracket
1pc	front bumper o/s cover
1pc	front grille
1pc	o/s head lamp
1pc	air filter housing

CM	\$ 418.50	✓
	374.45	✓
DM	178.85	✓
DM	181.10	✓
CM	561.60	✓
CM	781.70	✓
	975.10	✓

less 25%

3471.30
867.83

2603.35

To putty & spray painting
To repair & panelbeat o/s door pillar,
front inner panel,
remove & fit the above parts

580.00 *500*
650.00 *400*

Total: \$ 3833.48

(Dollars Three Thousand Three Hundred Thirty Three & Cents Forty Eight Only)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: