

Winnipeg CC 4 / Asm 1900 5572, Epa352

100907

## ASSIGNMENT

Surveyor:

Steve

DOI:

28/3/19

Date / Time:

28/03/2019

Registered in Meriten:

Pre-assign / CCU / FTE

SmG7723K

Claim No.:

Sgm01I4B



Insured Vehicle No.:

Name of Insured:

Who Han Xuan

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

28/03/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SJK6370R



INSRS:

WSP:

Tel:

Liability:

RMKS:

SK Automobile



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

9/8  
CNC

SJK6370R-X ; SmG7723K-X

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 10/6/19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

\* video uploaded on smobit by AXA. (BOLA 27)

10/6/19 No body pick-up

1/price / SmG 7723K / 12 video footage

BOLA 27, 100%, send letter to OI

10/6/19 OI call back confirmed BOLA 27, agree to settle and return

HOD issue

17/10 - to seek mandate

18/10 - pending mandate approval

22/10 - offer GTS \$1200 (pending acceptance)

20/10 - TP reject offer RE - offer GTS \$1400

- TP reject offer, seek AXA instructions

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by: Steve

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Steve

Repair Cost:

US

SS 7200.00

(12 days)

Reduction: 48257.40

% 53

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

(W/GST)

SS 7704.00

Loss of Rental (LOR):

SS 1200.00

(12 days)

x 4100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 8900.00

Global Sum SS:

8900

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS 8900.00

Name 1:

SK Automobile Pte Ltd

Payee 2: (Strike if N.A.)

SS -

Name 2:

Payee 3: (Strike if N.A.)

SS -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4350/-

COPY SENT  
4/11/19

## REFERENCE NUMBER

DATE / TIME

ACTIONS / REMARKS

30/10

- Re-offer GTS \$8900 (pending acceptance)

31/10

- Settle @ GTS \$8900, File pass Suhi send dv.



**SK Automobile Pte. Ltd.**  
**(Co Reg. No. 201500047H)**  
**23 Kaki Bukit Ave 4, #03-01**  
**Vicom Inspection Centre (S415933)**  
**Tel: 6789 5155 Fax : 6783 5155**

|                                                 |                                 |
|-------------------------------------------------|---------------------------------|
| TO : AXA                                        | DATE : 26/3/2019                |
| ATTENTION : MOTOR CLAIMS DEPARTMENT             | JOB TYPE : T/P CLAIMS           |
| ESTIMATE REPORT :                               | 28/3/19 12:30pm                 |
| <i>Step (LKK) wh pmul</i><br><i>8327807 L/S</i> |                                 |
| <b>OWNER PARTICULAR</b>                         | <b>VEHICLE DETAILS</b>          |
| NAME :                                          | VEHICLE NO. : SJK6370R          |
| ADDRESS :                                       | MODEL / MAKE : TOYOTA VIOS      |
| TEL. NO. :                                      | CHASSIS NO. : MR053HY9305081566 |
| OWNER INSURANCE : CN TAIPING                    | <b>ACCIDENT DETAIL</b>          |
| POLICY NO. : DMPCSN3073801800                   | DATE : 26/3/2019                |
|                                                 | TIME : 08:00 HRS                |
| PERSON INCHARGE :                               |                                 |

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

| S/N | DESCRIPTION                                             | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---------------------------------------------------------|-----|-----------------|------------------|
| 1   | REAR BOOT LID / DD                                      | 1   | \$ 625.70       | \$ 625.70 /      |
| 2   | REAR BOOT LID LOGO EMBLEM / NEC                         | 1   | \$ 47.20        | \$ 47.20 /       |
| 3   | REAR BOOT LID E EMBLEM / NEC                            | 1   | \$ 36.71        | \$ 36.71 /       |
| 4   | REAR BOOT LID OUTER GARNISH / CR4                       | 1   | \$ 153.80       | \$ 153.80 /      |
| 5   | REAR BOOT LID OUTER KEY LOCK X NN                       | 1   | \$ 95.70        | \$ 95.70 X       |
| 6   | REAR NUMBER PLATE LAMP LH / RH X NN                     | 2   | \$ 45.80        | \$ 91.60 X       |
| 7   | REAR BOOT LID HINGES LH / RH / RH LH DD                 | 2   | \$ 75.21        | \$ 150.42 /      |
| 8   | REAR BOOT LID RUBBER GUIDE STOPPER X NN                 | 2   | \$ 25.10        | \$ 50.20 X       |
| 9   | REAR BOOT LID MECHANISM LOCK / DD                       | 1   | \$ 119.01       | \$ 119.01 /      |
| 10  | REAR BOOT LID WEATHERSHIP / CR4                         | 1   | \$ 185.30       | \$ 185.30 /      |
| 11  | REAR TAILLAMP LH / RH / RH LH DR                        | 2   | \$ 256.10       | \$ 512.20 /      |
| 12  | REAR TAILLAMP BACK RUBBER GASKET LH / RH / NEC          | 2   | \$ 28.20        | \$ 56.40 /       |
| 13  | REAR TAILLAMP INNER PANEL LH / RH / RH LH DD            | 2   | \$ 205.24       | \$ 410.48 /      |
| 14  | REAR BUMPER / DD                                        | 1   | \$ 527.15       | \$ 527.15 /      |
| 15  | REAR BUMPER REFLECTOR LH / RH X NN                      | 2   | \$ 98.25        | \$ 196.50 X      |
| 16  | REAR BUMPER RETAINER LH / RH / LH RH DR                 | 2   | \$ 85.00        | \$ 170.00 /      |
| 17  | REAR BUMPER CORNER RETAINER LH / RH / RH LH DR          | 2   | \$ 85.10        | \$ 170.20 /      |
| 18  | REAR BUMPER INNER SIDE SHIELD LH / RH X NN              | 2   | \$ 48.60        | \$ 97.20 X       |
| 19  | REAR END PANEL / DD                                     | 1   | \$ 617.10       | \$ 617.10 /      |
| 20  | REAR END PANEL INNER TOP GARNISH / DR                   | 1   | \$ 182.50       | \$ 182.50 /      |
| 21  | REAR END PANEL LOCK STRIKER X NN                        | 1   | \$ 36.80        | \$ 36.80 X       |
| 22  | REAR ENG PANEL BRACKET PLATE LH / RH X R                | 2   | \$ 38.20        | \$ 76.40 X       |
| 23  | SPARE TYRE PANEL / DD                                   | 1   | \$ 657.20       | \$ 657.20 /      |
| 24  | SPRAY TYRE PANEL INNER TOP CARD BOARD / CR4             | 1   | \$ 135.70       | \$ 135.70 /      |
| 25  | SPARE TYRE PANEL INNER TOP SPONGE X NN                  | 1   | \$ 125.60       | \$ 125.60 X      |
| 26  | SPARE TYRE SIDE PANEL LH / RH X NN                      | 2   | \$ 105.70       | \$ 211.40 X      |
| 27  | SPARE TYRE SIDE PANEL INNER TOP SPONGE LH / RH / LH 2/3 | 2   | \$ 95.10        | \$ 190.20 /      |

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

| S/N | SPARE | DESCRIPTION                                             | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|-------|---------------------------------------------------------|-----|-----------------|------------------|
| 28  | SPRAY | TYRE RETAINER LOCK / CRV                                | 1   | \$ 45.60        | \$ 45.60         |
| 29  |       | REAR FENDER LH / RH LH - RH DO                          | 2   | \$ 826.10       | \$ 1,652.20      |
| 30  |       | REAR FENDER INNER AIR VENT LH X N/A                     | 1   | \$ 123.50       | \$ 123.50        |
| 31  |       | REAR FENDER INNER UPHOLSTERY TRIM LH / RH / LH / RH CRV | 2   | \$ 213.60       | \$ 427.20        |
| 32  |       | REAR WINDSCREEN GLASS MOULDING / MEC                    | 1   | \$ 28.60        | \$ 28.60         |
| 33  |       | REAR EXHAUST SILENCER BOX ? X N/A                       | 1   | \$ 298.60       | \$ 298.60        |
| 34  |       | REAR EXHAUST END CHROME PIPE / DO                       | 1   | \$ 125.70       | \$ 125.70        |
| 35  |       | REAR EXHAUST GASKET / MEC                               | 1   | \$ 35.80        | \$ 35.80         |
| 36  |       | REAR EXHAUST RUBBER MOUNTING / TN                       | 2   | \$ 28.90        | \$ 86.70         |
| 37  |       | REAR EXHAUST ALUMINIUM HEAT SHIELD ? X N/A              | 1   | \$ 185.70       | \$ 185.70        |
| 38  |       | REAR SUB CHAISIS FRAME LH / RH X R                      | 2   | \$ 455.80       | \$ 911.60        |

TOTAL PRICE \$ 9,849.87  
 LESS -25% \$ (2,462.47)  
 SUB TOTAL PRICE \$ 7,387.40

57.80  
 7320.17  
 -25%  
 5490.12

CLAIMS DETAIL : PARTS LIST

| S/N | DESCRIPTION                                               | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|-----------------------------------------------------------|-----|-------------|--------------|
| 1   | REAR BOOTG LID OUTER GARNISH CLIPS SET / MEC              | 1   | \$ 30.00    | \$ 30.00     |
| 2   | REAR BOOT NUMBER PLATE WITH GARNISH BR /                  | 1   | \$ 60.00    | \$ 60.00     |
| 3   | REAR TAILLAMP CLIPS SET LH / RH / MEC                     | 2   | \$ 30.00    | \$ 60.00     |
| 4   | REAR TAILLAMP BRAKE BULB LH / RH ? X N/A                  | 2   | \$ 15.00    | \$ 30.00     |
| 5   | REAR TAILLAMP SIGNAL BULB LH / RH X N/A                   | 2   | \$ 15.00    | \$ 30.00     |
| 6   | REAR TAILLAMP REVERSE BULB LH / RH X N/A                  | 2   | \$ 15.00    | \$ 30.00     |
| 7   | REAR BUMPER REVERSE SENSOR / BR                           | 1   | \$ 280.00   | \$ 280.00    |
| 8   | REAR BUMPER CLIPS SET / MEC                               | 1   | \$ 60.00    | \$ 60.00     |
| 9   | REAR END PANEL INNER TOP GARNISH CLIPS SET / MEC          | 1   | \$ 40.00    | \$ 40.00     |
| 10  | SPRAY TYRE PANEL INSULATOR MAT X N/A                      | 1   | \$ 380.00   | \$ 380.00    |
| 11  | SPRAY TYRE PANEL INNER TOP JACKING TOOL X N/A             | 1   | \$ 180.00   | \$ 180.00    |
| 12  | SPRAY TYRE PANEL INNER TOP BREAK SOWN X N/A               | 1   | \$ 150.00   | \$ 150.00    |
| 13  | REAR FENDER INSULATOR MAT LH / RH / MEC - RPT             | 2   | \$ 180.00   | \$ 360.00    |
| 14  | REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH / RH / MEC | 2   | \$ 60.00    | \$ 120.00    |
| 15  | REAR WINDSCREEN INNER GARNISH CLIPS SET LH / RH / MEC     | 2   | \$ 30.00    | \$ 60.00     |
| 16  | REAR WINDSCREEN SEALANT WITH PRIMER / MEC                 | 1   | \$ 100.00   | \$ 100.00    |

TOTAL \$ 1,970.00

455

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

|                                                                                                     |                              |                      |  |
|-----------------------------------------------------------------------------------------------------|------------------------------|----------------------|--|
| TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION                                 | \$ 2,400.00                  | 1540                 |  |
| TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA                                | \$ 2,000.00                  | 1100                 |  |
| TO APPLY ANTI-RUST & TUFF KOTE                                                                      | \$ 200.00                    | 50                   |  |
| TO PERFORM LIGHTING & WIRING CHECK                                                                  | \$ 80.00                     | 30                   |  |
| TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION                                 | \$ 280.00                    | X                    |  |
| TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR                                     | \$ 220.00                    | ? X                  |  |
| TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST                               | \$ 150.00                    | 100<br><del>30</del> |  |
| TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION           | \$ 150.00                    | 30                   |  |
| TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING                            | \$ 80.00                     | 20                   |  |
| TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING   | \$ 180.00                    | <del>50</del> 80     |  |
| TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR | \$ 280.00                    | 50                   |  |
| TOWING SERVICE ACCIDENT SCENE TOW TO WORKSHOP                                                       | <del>80.00</del><br>\$ 80.00 | /                    |  |

TOTAL

\$ 6,100.00

3040

P- 5490.12  
 A- 455  
 L- 3040  
 8985.12  
 L/S- 7188.09  
 = 7200

12 repair days

## QUOTATION SUMMARY

PAGE 04

### ESTIMATE REPORT

|                   |   |    |                  |
|-------------------|---|----|------------------|
| TOTAL PARTS COST  | : | \$ | 9,357.40         |
| TOTAL LABOUR COST | : | \$ | 6,100.00         |
| TOTAL REPAIR COST | : | \$ | <u>15,457.40</u> |

### APPROVED DETAILS

EXCESS :  
NO. OF REPAIR DAYS :  
RE-SURVEY :  
P / P OR L / S :

DATE / TIME OF SURVEY :  
SURVEYED BY / FROM :  
CONTACT NUMBER :  
FAX NUMBER :  
EMAIL ADDRESS :

**Steve Chen (LKK Auto)**

---

**From:** Pioneer Workshop <pioneer@skauto.com.sg>  
**Sent:** Monday, June 03, 2019 10:06 AM  
**To:** Steve Chen (LKK Auto)  
**Subject:** Re: Finalized SJK6370R

Dear Steve,

Please confirm finalized @ COR \$7,200.00.

On Sat, Jun 1, 2019 at 4:13 PM Pioneer Workshop <pioneer@skauto.com.sg> wrote:

## Reminder

Dear Mr Steve,

Kindly help top finalized below vehicle. The after photo attached.

|        |          |         |            |
|--------|----------|---------|------------|
| TP AXA | SJK6370R | Lumpsum | \$7,670.00 |
|--------|----------|---------|------------|

Repair days: 13 Days

On Sat, May 25, 2019 at 3:01 PM Pioneer Workshop <pioneer@skauto.com.sg> wrote:

Dear LKK

Kindly help to finalized abovementioned case ASAP.

Understand YOUR surveyor very busy, but those case pending TWO months already. We also need to give a result to our customers.

--

Thanks & Regards,

*Yvette Zhao*

SK Automobile Pte Ltd

48 Toh Guan Road East # 01-121  
Enterprise Hub, Singapore 608586  
D: +65 6266 0555 | F: +65 6266 3155 | [pioneer@skauto.com.sg](mailto:pioneer@skauto.com.sg)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                                                                                                                                                                                                         |                          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>                                                                                                                                                                                        |                          |
| Owner ID Type:                                                                                                                                                                                                          | Singapore NRIC           |
| Owner ID:                                                                                                                                                                                                               | 9286G                    |
| <b>Vehicle Details</b>                                                                                                                                                                                                  |                          |
| Vehicle No.:                                                                                                                                                                                                            | SJK6370R                 |
| Vehicle to be Exported:                                                                                                                                                                                                 | No                       |
| Intended Deregistration Date:                                                                                                                                                                                           | 28 Mar 2019              |
| Vehicle Make:                                                                                                                                                                                                           | TOYOTA                   |
| Vehicle Model:                                                                                                                                                                                                          | VIOS E AUTO              |
| Primary Colour:                                                                                                                                                                                                         | Silver                   |
| Manufacturing Year:                                                                                                                                                                                                     | 2008                     |
| Engine No.:                                                                                                                                                                                                             | 1NZX807897               |
| Chassis No.:                                                                                                                                                                                                            | MR053HY9305081566        |
| Maximum Power Output:                                                                                                                                                                                                   | 80.0 kW (107 bhp)        |
| Open Market Value:                                                                                                                                                                                                      | \$11,834.00              |
| Original Registration Date:                                                                                                                                                                                             | 29 Oct 2008              |
| First Registration Date:                                                                                                                                                                                                | 29 Oct 2008              |
| Transfer Count:                                                                                                                                                                                                         | 2                        |
| Actual ARF Paid:                                                                                                                                                                                                        | \$11,834.00              |
| <b>Intended PARF Rebate Details</b>                                                                                                                                                                                     |                          |
| PARF Eligibility:                                                                                                                                                                                                       | Forfeited                |
| PARF Eligibility Expiry Date:                                                                                                                                                                                           | -                        |
| PARF Rebate Amount:                                                                                                                                                                                                     | \$0.00                   |
| <b>Intended COE Rebate Details</b>                                                                                                                                                                                      |                          |
| COE Expiry Date:                                                                                                                                                                                                        | 28 Oct 2023              |
| COE Category:                                                                                                                                                                                                           | A - Car (1600cc & below) |
| COE Period(Years):                                                                                                                                                                                                      | 5                        |
| PQP Paid:                                                                                                                                                                                                               | \$15,142.00              |
| COE Rebate Amount:                                                                                                                                                                                                      | \$13,880.00              |
| <b>Total Rebate Amount:</b>                                                                                                                                                                                             | <b>\$13,880.00</b>       |
| <b>Message</b>                                                                                                                                                                                                          |                          |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                          |

The information contained herein is correct as at 28 Mar 2019

OK



Toyota Vios

Price Range

Depreciation

Year Reg

Vehicle Type

Advance Search

Home » Used Cars » Creative Auto » Toyota Vios 1.5A E (COE till 11/2023)

## Toyota Vios 1.5A E (COE till 11/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$24,666

Depreciation ⑦ \$5,290 /yr

Reg Date 26-Nov-2008  
(4yrs 7mths 28days COE left)

Mileage 114,400 km (11.1k /yr)

Manufactured ⑦ 2008

Road Tax ⑦ \$752 /yr

Transmission Auto

Dereg Value ⑦ \$13,843 as of today (change)

OMV ⑦ \$11,834

COE ⑦ \$14,835

ARF ⑦ \$11,834

Engine Cap 1,497 cc

Power 80.0 kW (107 bhp)

Curb Weight ⑦ 1,095 kg

No. of Owners ⑦ 2

Type of Vehicle Mid-Sized Sedan

## Features

Fuel Efficient And Reliable 1.5L Toyota VVT-i Engine, 5 Speed Auto Transmission, ABS, EBD, Dual SRS Airbags, 4 Disc Brakes, Knockdown Rear Seats, Etc. View specs of the Toyota Vios (2007-2013)

## Accessories

Sports Rims, Leather Seats, Original Factory Sound System, Retractable Side Mirror With Indicator, Reverse Sensors, Solar Films, Etc.

## Description

Full Loan Amount Stated, Car Is Beautifully Maintained With Solid Engine And Gear Transmission, Smooth And Responsive, Rare Good Condition, Don't Miss, Call Or Sms For Viewing Appointment.

## Category

COE Car

## Status


Available

Compare



Location Map

## Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

## Seller Information

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resour

- The Perfect Storm of the Stock Market II
- LG/Samsung/Sony TVs
- Ah Tiong dumb ass!

Toyota Vios

Price Range ▼

Depreciation ▼

Year Reg ▼

Vehicle Type ▼



Advanced Search

Home » Used Cars » Steven Mobile » Toyota Vios 1.5A E (COE till 05/2023)

## Toyota Vios 1.5A E (COE till 05/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

**Price** \$23,500**Depreciation** ⓘ \$5,620 /yr**Reg Date** 04-Jun-2008  
(4yrs 2mths 3days COE left)**Mileage** N.A.**Manufactured** ⓘ 2008**Road Tax** ⓘ \$752 /yr**Transmission** Auto**Dereg Value** ⓘ \$15,957 as of today (change)**OMV** ⓘ \$12,344**COE** ⓘ \$19,096**ARF** ⓘ \$12,344**Engine Cap** 1,497 cc**Power** 80.0 kW (107 bhp)**Curb Weight** ⓘ 1,095 kg**No. of Owners** ⓘ 3**Type of Vehicle** Mid-Sized Sedan**Features**

View specs of the Toyota Vios (2007-2013)

**Category**

COE Car

**Status**

Available

**Resources****Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more

**Car Valuation - Free**

Find out the market value of your existing car for free. Get started



Shortlist

Compare

Add note

Report Error

More Actions

**Seller Information****Company****Steven Mobile**

» dealer's pricelist

» 27 vehs sold | 11 vehs availab

**Address**

8 Kaki Bukit Avenue 4 #07-16

Search cars nearby this location

**Location**

Premier @ Kaki Bukit

**Office No**

63489909

**Contact Person(s)**

Steven

96788;

Louise

91908;

Posted on: 28-Mar-2019 | Last Updated on: 28-Mar-2019

**Upfront Payment**

» more Financial info

**Transfer Fee** ⓘ \$25**Down Payment** ⓘ \$7,050 (change)

Maximum 70% Loan

**1st Compare** \$380

Based on 3.75% interest rate

SK Automobile Pte. Ltd.  
(Co Reg. No. 201500047H)  
23 Kaki Bukit Ave 4, #03-01  
Vicom Inspection Centre (S415933)  
Tel: 6789 5155 Fax : 6783 5155

|                         |                                            |                        |                     |
|-------------------------|--------------------------------------------|------------------------|---------------------|
| TO                      | : AXA                                      | DATE                   | : 26/3/2019         |
| ATTENTION               | : MOTOR CLAIMS DEPARTMENT                  | JOB TYPE               | : T/P CLAIMS        |
| ESTIMATE REPORT         | : <i>Step (LKK) Wk Pmt 28/3/19 12.39pm</i> |                        |                     |
| <b>OWNER PARTICULAR</b> |                                            | <b>VEHICLE DETAILS</b> |                     |
| NAME                    | : <i>83278873 L/S R1 AF RY 11 dgs</i>      | VEHICLE NO.            | : SJK6370R          |
| ADDRESS                 | :                                          | MODEL / MAKE           | : TOYOTA VIOS       |
| TEL. NO.                | :                                          | CHASSIS NO.            | : MR053HY9305081566 |
| <b>OWNER INSURANCE</b>  |                                            | <b>ACCIDENT DETAIL</b> |                     |
| POLICY NO.              | : CN TAIPING                               | DATE                   | : 26/3/2019         |
|                         | : DMPCSN3073801800                         | TIME                   | : 08:00 HRS         |
| PERSON INCHARGE :       |                                            |                        |                     |

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

| S/N | DESCRIPTION                                                      | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|------------------------------------------------------------------|-----|-----------------|------------------|
| 1   | REAR BOOT LID / <i>DD</i>                                        | 1   | \$ 625.70       | \$ 625.70        |
| 2   | REAR BOOT LID LOGO EMBLEM / <i>NEC</i>                           | 1   | \$ 47.20        | \$ 47.20         |
| 3   | REAR BOOT LID E EMBLEM / <i>NEC</i>                              | 1   | \$ 36.71        | \$ 36.71         |
| 4   | REAR BOOT LID OUTER GARNISH / <i>CR4</i>                         | 1   | \$ 153.80       | \$ 153.80        |
| 5   | REAR BOOT LID OUTER KEY LOCK X <i>NN</i>                         | 1   | \$ 95.70        | \$ 95.70         |
| 6   | REAR NUMBER PLATE LAMP LH / RH X <i>NN</i>                       | 2   | \$ 45.80        | \$ 91.60         |
| 7   | REAR BOOT LID HINGES LH / RH / <i>RT - LH DD</i>                 | 2   | \$ 75.21        | \$ 150.42        |
| 8   | REAR BOOT LID RUBBER GUIDE STOPPER X <i>NN</i>                   | 2   | \$ 25.10        | \$ 50.20         |
| 9   | REAR BOOT LID MECHANISM LOCK / <i>DD</i>                         | 1   | \$ 119.01       | \$ 119.01        |
| 10  | REAR BOOT LID WEATHERSHIP / <i>CR4</i>                           | 1   | \$ 185.30       | \$ 185.30        |
| 11  | REAR TAILLAMP LH / RH / <i>RH - LH</i>                           | 2   | \$ 256.10       | \$ 512.20        |
| 12  | REAR TAILLAMP BACK RUBBER GASKET LH / RH / <i>NEC</i>            | 2   | \$ 28.20        | \$ 56.40         |
| 13  | REAR TAILLAMP INNER PANEL LH / RH / <i>RH - LH DD</i>            | 2   | \$ 205.24       | \$ 410.48        |
| 14  | REAR BUMPER / <i>DD</i>                                          | 1   | \$ 527.15       | \$ 527.15        |
| 15  | REAR BUMPER REFLECTOR LH / RH                                    | 2   | \$ 98.25        | \$ 196.50        |
| 16  | REAR BUMPER RETAINER LH / RH / <i>LH - RH DD</i>                 | 2   | \$ 85.00        | \$ 170.00        |
| 17  | REAR BUMPER CORNER RETAINER LH / RH                              | 2   | \$ 85.10        | \$ 170.20        |
| 18  | REAR BUMPER INNER SIDE SHIELD LH / RH                            | 2   | \$ 48.60        | \$ 97.20         |
| 19  | REAR END PANEL / <i>DD</i>                                       | 1   | \$ 617.10       | \$ 617.10        |
| 20  | REAR END PANEL INNER TOP GARNISH / <i>OR</i>                     | 1   | \$ 182.50       | \$ 182.50        |
| 21  | REAR END PANEL LOCK STRIKER X <i>NN</i>                          | 1   | \$ 36.80        | \$ 36.80         |
| 22  | REAR ENG PANEL BRACKET PLATE LH / RH X <i>R</i>                  | 2   | \$ 38.20        | \$ 76.40         |
| 23  | SPARE TYRE PANEL / <i>DD</i>                                     | 1   | \$ 657.20       | \$ 657.20        |
| 24  | SPRAY TYRE PANEL INNER TOP CARD BOARD / <i>CR4</i>               | 1   | \$ 135.70       | \$ 135.70        |
| 25  | SPARE TYRE PANEL INNER TOP SPONGE                                | 1   | \$ 125.60       | \$ 125.60        |
| 26  | SPARE TYRE SIDE PANEL LH / RH X <i>NN</i>                        | 2   | \$ 105.70       | \$ 211.40        |
| 27  | SPARE TYRE SIDE PANEL INNER TOP SPONGE LH / RH / <i>CR4 LH 2</i> | 2   | \$ 95.10        | \$ 190.20        |

# QUOTATION SUMMARY

PAGE 02

## CLAIMS DETAIL : PARTS LIST

| S/N             | DESCRIPTION                                             | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----------------|---------------------------------------------------------|-----|-----------------|------------------|
| 28              | SPRAY TYRE RETAINER LOCK / CR4                          | 1   | \$ 45.60        | \$ 45.60         |
| 29              | REAR FENDER LH / RH LH - RH DO                          | 2   | \$ 826.10       | \$ 1,652.20      |
| 30              | REAR FENDER INNER AIR VENT LH                           | 1   | \$ 123.50       | \$ 123.50        |
| 31              | REAR FENDER INNER UPHOLSTERY TRIM LH / RH / LH / RH CR4 | 2   | \$ 213.60       | \$ 427.20        |
| 32              | REAR WINDSCREEN GLASS MOULDING / MEC                    | 1   | \$ 28.60        | \$ 28.60         |
| 33              | REAR EXHAUST SILENCER BOX ?                             | 1   | \$ 298.60       | \$ 298.60        |
| 34              | REAR EXHAUST END CHROME PIPE / DO                       | 1   | \$ 125.70       | \$ 125.70        |
| 35              | REAR EXHAUST GASKET / MEC                               | 1   | \$ 35.80        | \$ 35.80         |
| 36              | REAR EXHAUST RUBBER MOUNTING / TN                       | 23  | \$ 28.90        | \$ 86.70         |
| 37              | REAR EXHAUST ALUMINIUM HEAT SHIELD ?                    | 1   | \$ 185.70       | \$ 185.70        |
| 38              | REAR SUB CHAISIS FRAME LH / RH X R                      | 2   | \$ 455.80       | \$ 911.60        |
| TOTAL PRICE     |                                                         |     |                 | \$ 9,849.87      |
| LESS -25%       |                                                         |     |                 | \$ (2,462.47)    |
| SUB TOTAL PRICE |                                                         |     |                 | \$ 7,387.40      |

## CLAIMS DETAIL : PARTS LIST

| S/N | DESCRIPTION                                            | QTY | UNIT S/NETT | TOTAL S/NETT  |
|-----|--------------------------------------------------------|-----|-------------|---------------|
| 1   | REAR BOOTG LID OUTER GARNISH CLIPS SET                 | 1   | \$ 30.00    | \$ 10 30.00   |
| 2   | REAR BOOT NUMBER PLATE WITH GARNISH BR ✓               | 1   | \$ 60.00    | \$ 35 60.00   |
| 3   | REAR TAILLAMP CLIPS SET LH / RH                        | 2   | \$ 30.00    | \$ 10 60.00   |
| 4   | REAR TAILLAMP BRAKE BULB LH / RH ?                     | 2   | \$ 15.00    | \$ 30.00      |
| 5   | REAR TAILLAMP SIGNAL BULB LH / RH X                    | 2   | \$ 15.00    | \$ 30.00      |
| 6   | REAR TAILLAMP REVERSE BULB LH / RH ✓                   | 2   | \$ 15.00    | \$ 30.00      |
| 7   | REAR BUMPER REVERSE SENSOR / BR                        | 1   | \$ 280.00   | \$ 200 280.00 |
| 8   | REAR BUMPER CLIPS SET / MEC                            | 1   | \$ 60.00    | \$ 25 60.00   |
| 9   | REAR END PANEL INNER TOP GARNISH CLIPS SET             | 1   | \$ 40.00    | \$ 10 40.00   |
| 10  | SPRAY TYRE PANEL INSULATOR MAT X                       | 1   | \$ 380.00   | \$ 380.00     |
| 11  | SPRAY TYRE PANEL INNER TOP JACKING TOOL X              | 1   | \$ 180.00   | \$ 180.00     |
| 12  | SPRAY TYRE PANEL INNER TOP BREAK SOWN X                | 1   | \$ 150.00   | \$ 150.00     |
| 13  | REAR FENDER INSULATOR MAT LH/ RH / MEC - RH            | 2   | \$ 180.00   | \$ 50 360.00  |
| 14  | REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH / RH ME | 2   | \$ 60.00    | \$ 20 120.00  |
| 15  | REAR WINDSCREEN INNER GARNISH CLIPS SET LH / RH / MEC  | 2   | \$ 30.00    | \$ 20 60.00   |
| 16  | REAR WINDSCREEN SEALANT WITH PRIMER / MEC              | 1   | \$ 100.00   | \$ 80 100.00  |

TOTAL

\$ 1,970.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

|                                                                                                     |             |                      |  |
|-----------------------------------------------------------------------------------------------------|-------------|----------------------|--|
| TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION                                 | \$ 2,400.00 | 1540                 |  |
| TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA                                | \$ 2,000.00 | 1100                 |  |
| TO APPLY ANTI-RUST & TUFF KOTE                                                                      | \$ 200.00   | 50                   |  |
| TO PERFORM LIGHTING & WIRING CHECK                                                                  | \$ 80.00    | 30                   |  |
| TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION                                 | \$ 280.00   | X                    |  |
| TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR                                     | \$ 220.00   | ?                    |  |
| TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST                               | \$ 150.00   | 100<br><del>30</del> |  |
| TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION           | \$ 150.00   | 30                   |  |
| TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING                            | \$ 80.00    | 20                   |  |
| TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING   | \$ 180.00   | 50                   |  |
| TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR | \$ 280.00   | 50                   |  |
| TOWING SERVICE ACCIDENT SCENE TOW TO WORKSHOP                                                       | \$ 80.00    | Bill /               |  |

TOTAL

\$ 6,100.00

**QUOTATION SUMMARY**

PAGE 04

**ESTIMATE REPORT**

|                   |   |    |                  |
|-------------------|---|----|------------------|
| TOTAL PARTS COST  | : | \$ | 9,357.40         |
| TOTAL LABOUR COST | : | \$ | 6,100.00         |
| TOTAL REPAIR COST | : | \$ | <u>15,457.40</u> |

**APPROVED DETAILS**

EXCESS :  
NO. OF REPAIR DAYS :  
RE-SURVEY :  
P / P OR L / S :

DATE / TIME OF SURVEY :  
SURVEYED BY / FROM :  
CONTACT NUMBER :  
FAX NUMBER :  
EMAIL ADDRESS :



ROC No.: 201500047H  
23 Kaki Bukit Ave 4, #03-01  
Vicom Inspection Centre (South Wing) S415933  
Tel: 6789 5155 Fax: 6783 5155

To: AXA Insurance Pte Ltd

Dear Sir/Madam

Accident involving SJK 6370R and SMA 7723K on 26/3/2019  
At/along Clementi Ave 6 (Pandan Flyover) Towards AYE (Tuas)

I/We, Selvaraju Subramaniam, am the registered  
owner of the motor vehicle no. SJK 6370R.

Please note that I have assigned all compensation monies due to me/us in the above said accident to  
M/S SK Automobile Pte Ltd.

I/We, hereby authorized you to release all compensation monies pertaining to the above-mentioned  
accident to M/S SK Automobile Pte Ltd and forward your settlement cheque to M/S SK Automobile  
Pte Ltd whom I have authorized to collect the said compensation/monies.

Signature of Claimant

Witness



## Nivitha (LKK Auto)

---

**From:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>  
**Sent:** Thursday, 28 March 2019 11:12 AM  
**To:** assignments  
**Subject:** FW: Arrange survey for SJK6370R (Your vehicle SMG7723K) D.O.A 26/03/2019  
**Attachments:** SJK6370R GIA.pdf; SJK6370R PRI.pdf; OI GIA REPORT.pdf

Hi team

*Tp smart. Kindly assist.*

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Pioneer Workshop <pioneer@skauto.com.sg>

**Sent:** Wednesday, 27 March, 2019 11:28 AM

**To:** SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

**Subject:** Arrange survey for SJK6370R (Your vehicle SMG7723K) D.O.A 26/03/2019

Dear Motor Claim Department,

Kindly arrange survey for following vehicle,

### Survey Before Repair

Your Vehicle No.:SMG7723K

Our Vehicle No.: SJK6370R

D.O.A: 26/03/2019

Location: 48 Toh Guan Road East # 01-121, Enterprise Hub, Singapore 608586

--

Thanks & Regards,

*Yvette Zhao*

SK Automobile Pte Ltd

48 Toh Guan Road East # 01-121

Enterprise Hub, Singapore 608586

D: +65 6266 0555 | F: +65 6266 3155 | [pioneer@skauto.com.sg](mailto:pioneer@skauto.com.sg)

11.12am @ 28/3/19  
vehicle in  
prior @ Yvonne



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/10/2019

### Survey Details:

|                     |                       |
|---------------------|-----------------------|
| Date of loss        | 26-Mar-19             |
| Date of appointment | 28-Mar-19             |
| Date of survey      | 28-Mar-19             |
| Location of survey  | SK AUTOMOBILE PTE LTD |

### Vehicle Details:

|                      |                    |
|----------------------|--------------------|
| Claim Type:          | THIRD PARTY CLAIM  |
| Vehicle number       | SJK6370R           |
| Make and Model       | TOYOTA VIOS E AUTO |
| Date of registration | 29-Oct-08          |
| Parf Rebate          |                    |
| Market Value         | \$ 26,000.00       |
| Parf Rebate          | \$ 13,880.00       |
| Nett Loss            | \$ 12,120.00       |

### Repair details:

|                  |           |
|------------------|-----------|
| Initial Estimate | 15,457.40 |
|------------------|-----------|

### Proposed/Revised repair cost:

|                         |             |
|-------------------------|-------------|
| Parts                   | \$ 5,945.13 |
| Check items (estimate)  | \$ -        |
| Labour                  | \$ 3,040.00 |
| Total                   | \$ 8,985.13 |
| Lump Sum(if applicable) | \$ 7,200.00 |

|                           |    |
|---------------------------|----|
| Number of days for repair | 12 |
|---------------------------|----|



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

12 RECOMMENDED REPAIR DAYS + 1 SUNDAY + 1PRS= 14DAYS

**Mandate:**

| Liability(TP)        |    | 100%                    |
|----------------------|----|-------------------------|
| Proposed repair cost | \$ | 7,704.00 W/GST          |
| Loss of use          | \$ | -                       |
| Loss of rental       | \$ | 1,400.00 14days x \$100 |
| Loss of income       | \$ | -                       |
| LTA search fees      | \$ | 2.00                    |
| Others               |    | -                       |
| Proposed Total       |    | 9,106.00                |



## <MANDATE IA> - S9M01I4B {ACCIDENT INVOLVING SMG 7723K(OI) & SJK 6370R(TP) ON 26/03/2019}

Type

Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$9,106.00 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

Reply



<MANDATE IA> - S9M01I4B {ACCIDENT INVOLVING  
SMG 7723K(OI) & SJK 6370R(TP) ON 26/03/2019}

Type

🔗 Question

Message

Hi Cecilia, propose \$8200 to \$8400 (global) full and final. Tks

Reply



**RE: <MANDATE IA> - S9M01I4B {ACCIDENT INVOLVING  
SMG 7723K(OI) & SJK 6370R(TP) ON 26/03/2019}**

Type

🔗 Question

Message

Dear Winnie, TP reject offer. Kindly let us have your instruction. Thanks - CCL

Reply



SK AUTOMOBILE PTE LTD ROC: 201500047H  
48 Toh Guan Road East #01-121, Enterprise Hub, Singapore 608586  
Tel: 6266 0555 Fax: 6266 3155 Email: [pioneer@skauto.com.sg](mailto:pioneer@skauto.com.sg)

Your ref: SMG7723K  
Our Ref: SJK6370R

WITHOUT PERJUDICE

June 10, 2019

AXA INSURANCE PTE LTD  
8 Shenton Way #27-01  
Singapore 06881

Attn: Motor Claim Dept

Dear Sir/Mdm

Accident involving SJK6370R and SMG7723K on 26/03/2019

We refer to the above said accident.

Based on the information we got from your insurance, we knew you are the insurer of vehicle no: **SMG7723K** at the material time of the accident, and the said accident was cause solely by the negligence of the driver of your company.

We enclosed herewith the relevant documents as stated below: -

1. Accident report of SJK6370R ✓
2. Certificate of insurance ✓
3. Repairing tax invoice ✓
3. Letter authorization ✓
4. LTA Search Enquiry ✓
5. Rental agreement & Invoice ✓

As instructed, we are claiming the following as stated below:

|                                                          |    |          |
|----------------------------------------------------------|----|----------|
| 1. Cost of repair (Include GST) 1/19 - 90275             | \$ | 7,704.00 |
| 2. Loss of rental (14 D X \$ 140.00) 26/03/19 - 09/04/19 | \$ | 1,960.00 |
| 3. LTA search fees                                       | \$ | 2.00     |
| Total:                                                   | \$ | 9,666.00 |

Please kindly let us know whether you are prepared to settle our client's claim and we look forward to hear from you soonest.

Thanks & regards

*Yvette Ang*



Yvette  
Tel: 6266 0555  
Fax: 6266 3155  
Email: [pioneer@skauto.com.sg](mailto:pioneer@skauto.com.sg)

23 Kaki Bukit Ave 4 #03-01

Phone +65 6789-5155 Fax +65 6783-5155

CO Reg No. 201500047H GST Reg No. 201500047H

DATE: 10-Jun-19

**INVOICE #** IV19-90275

VEH REG NO: SJK 6370 R

**Bill To:**

AXA INSURANCE PTE LTD

8 SHENTON WAY

**#24-01 AXA TOWER**

SINGAPORE 068811

Make all cheques payable to "SK AUTOMOBILE PTE LTD"

**THANK YOU FOR YOUR BUSINESS!**





## <MANDATE IA> - S9M01I4B {ACCIDENT INVOLVING SMG 7723K(OI) & SJK 6370R(TP) ON 26/03/2019}

Type

🔗 Question

Message

Hi Cecilia, COR-proceed @ \$7704 (include GST) LOR - propose @ 12 days, max 13 days. pls note LOU benchmark rate is different LTA - proceed. Tks

Reply



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                       |                                 |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------|---------------------------------|-------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD                                                                                                                     |                                                                       | Ref : CC4/ASM19005572/Ega3s2    |                                                                                     |
| 8 SHENTON WAY #24-01<br>AXA TOWERS SINGAPORE 068811<br>ATTN: WINNIE HO                                                                    |                                                                       | Date : 13-11-2019<br>Code : ASM |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                       |                                 |                                                                                     |
| Insured Veh.                                                                                                                              | SMG 7723K                                                             | Veh. Inspected                  | SJK 6370R                                                                           |
| Policy No.                                                                                                                                | VPA/P2234797                                                          | Coverage (\$)                   | 0.00                                                                                |
| Claim No.                                                                                                                                 | S9M01I4B                                                              | Excess (\$)                     | 0.00                                                                                |
| Assign From                                                                                                                               | WINNIE HO                                                             | Assign Date                     | 28/03/2019                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                       |                                 |                                                                                     |
| Make & Model                                                                                                                              | TOYOTA VIOS                                                           | c.c                             | 1497                                                                                |
| Engine No.                                                                                                                                | HIDDEN                                                                | Year of Reg.                    | 2008                                                                                |
| Chassis No.                                                                                                                               | MR053HY9305081566                                                     | Colour                          | BLUE                                                                                |
| Odometer                                                                                                                                  | 152767                                                                | Steering                        | IN ORDER                                                                            |
| Brakes                                                                                                                                    | IN ORDER                                                              | Modification                    | SPORTS RIM                                                                          |
| General                                                                                                                                   | FAIR                                                                  |                                 |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                       |                                 |                                                                                     |
|                                                                                                                                           | Size                                                                  | Make                            | Balance                                                                             |
| R/H Front Tyre                                                                                                                            | 185/60 R15                                                            | MICHELIN                        | 5 mm                                                                                |
| L/H Front Tyre                                                                                                                            | 185/60 R15                                                            | MICHELIN                        | 5 mm                                                                                |
| R/H Rear Tyre                                                                                                                             | 185/60 R15                                                            | MICHELIN                        | 5 mm                                                                                |
| L/H Rear Tyre                                                                                                                             | 185/60 R15                                                            | MICHELIN                        | 5 mm                                                                                |
| <b>4. Description of Damages</b>                                                                                                          |                                                                       |                                 |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                                |                                                                       |                                 |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                       |                                 |                                                                                     |
| Accident Date                                                                                                                             | 26/03/2019                                                            | Inspection Date                 | 28/03/2019                                                                          |
| Survey held at                                                                                                                            | SK AUTOMOBILE PTE LTD<br>23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933 |                                 |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                       |                                 |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                       |                                 |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                        |                                                                       |                                 |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                       |                                                                       | 12 Working Days                 |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 6370R

| Qty                         | Description of Parts                                            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-----------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                                 |                      |                           |                   |
| 1                           | REAR BOOT LID (CONSISTENT)                                      | DENTED               | 625.70                    | 625.70            |
| 1                           | REAR BOOT LID LOGO EMBLEM (CONSISTENT)                          | NECESSARY            | 47.20                     | 47.20             |
| 1                           | REAR BOOT LID E EMBLEM (CONSISTENT)                             | NECESSARY            | 36.71                     | 36.71             |
| 1                           | REAR BOOT LID OUTER GARNISH (CONSISTENT)                        | CRUSHED              | 153.80                    | 153.80            |
| 1                           | REAR BOOT LID OUTER KEY LOCK (CONSISTENT)                       | NOT NECESSARY        | 95.70                     | -                 |
| 2                           | REAR NUMBER PLATE LAMP LH / RH @ \$45.80 (CONSISTENT)           | NOT NECESSARY        | 91.60                     | -                 |
| 2                           | REAR BOOT LID HINGES LH / RH @ \$75.21 (CONSISTENT)             | DENTED               | 150.42                    | 150.42            |
| 2                           | REAR BOOT LID RUBBER GUIDE STOPPER @ \$25.10 (CONSISTENT)       | NOT NECESSARY        | 50.20                     | -                 |
| 1                           | REAR BOOT LID MECHANISM LOCK (CONSISTENT)                       | DENTED               | 119.01                    | 119.01            |
| 1                           | REAR BOOT LID WEATHERSTRIP (CONSISTENT)                         | CRUSHED              | 185.30                    | 185.30            |
| 2                           | REAR TAILLAMP LH / RH @ \$256.10 (CONSISTENT)                   | BROKEN               | 512.20                    | 512.20            |
| 2                           | REAR TAILLAMP BACK RUBBER GASKET LH / RH @ \$28.20 (CONSISTENT) | NECESSARY            | 56.40                     | 56.40             |
| 2                           | REAR TAILLAMP INNER PANEL LH / RH @ \$205.24 (CONSISTENT)       | DENTED               | 410.48                    | 410.48            |
| 1                           | REAR BUMPER (CONSISTENT)                                        | DENTED               | 527.15                    | 527.15            |
| 2                           | REAR BUMPER REFLECTOR LH / RH @ \$98.25 (CONSISTENT)            | NOT NECESSARY        | 196.50                    | -                 |
| 2                           | REAR BUMPER RETAINER LH / RH @ \$85.00 (CONSISTENT)             | BROKEN               | 170.00                    | 170.00            |
| 2                           | REAR BUMPER CORNER RETAINER LH / RH @ \$85.10 (CONSISTENT)      | BROKEN               | 170.20                    | 170.20            |
| 2                           | REAR BUMPER INNER SIDE SHIELD LH / RH @ \$48.60 (CONSISTENT)    | NOT NECESSARY        | 97.20                     | -                 |
| 1                           | REAR END PANEL (CONSISTENT)                                     | DENTED               | 617.10                    | 617.10            |
| 1                           | REAR END PANEL INNER TOP GARNISH (CONSISTENT)                   | BROKEN               | 182.50                    | 182.50            |
| 1                           | REAR END PANEL LOCK STRIKER (CONSISTENT)                        | NOT NECESSARY        | 36.80                     | -                 |
| 2                           | REAR END PANEL BRACKET PLATE LH / RH @ \$38.20 (CONSISTENT)     | TO REPAIR SEE LABOUR | 76.40                     | -                 |
| 1                           | SPARE TYRE PANEL (CONSISTENT)                                   | DENTED               | 657.20                    | 657.20            |
| 1                           | SPARE TYRE PANEL INNER TOP CARD BOARD (CONSISTENT)              | CRUSHED              | 135.70                    | 135.70            |

Report Ref No. CC4/ASM19005572/Ega3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty                       | Description of Parts                                                  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---------------------------|-----------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| 1                         | SPARE TYRE PANEL INNER TOP SPONGE (CONSISTENT)                        | NOT NECESSARY        | 125.60                    | -                 |
| 2                         | SPARE TYRE SIDE PANEL LH / RH @ \$105.70 (CONSISTENT)                 | NOT NECESSARY        | 211.40                    | -                 |
| 2                         | SPARE TYRE SIDE PANEL INNER TOP SPONGE LH / RH @ \$95.10 (CONSISTENT) | CRUSHED              | 190.20                    | 190.20            |
| 1                         | SPARE TYRE RETAINER LOCK (CONSISTENT)                                 | CRUSHED              | 45.60                     | 45.60             |
| 2                         | REAR FENDER LH / RH @ \$826.10 (CONSISTENT)                           | DENTED               | 1,652.20                  | 1,652.20          |
| 1                         | REAR FENDER INNER AIR VENT LH (CONSISTENT)                            | NOT NECESSARY        | 123.50                    | -                 |
| 2                         | REAR FENDER INNER UPHOLSTERY TRIM LH / RH @ \$213.60 (CONSISTENT)     | CRUSHED              | 427.20                    | 427.20            |
| 1                         | REAR WINDSCREEN GLASS MOULDING (CONSISTENT)                           | NECESSARY            | 28.60                     | 28.60             |
| 1                         | REAR EXHAUST SILENCER BOX (CONSISTENT)                                | NOT NECESSARY        | 298.60                    | -                 |
| 1                         | REAR EXHAUST END CHROME PIPE (CONSISTENT)                             | DENTED               | 125.70                    | 125.70            |
| 1                         | REAR EXHAUST GASKET (CONSISTENT)                                      | NECESSARY            | 35.80                     | 35.80             |
| 3                         | REAR EXHAUST RUBBER MOUNTING @ \$28.90 (CONSISTENT)                   | TORN 2PCS ONLY       | 86.70                     | 57.80             |
| 1                         | REAR EXHAUST ALUMINIUM HEAT SHIELD (CONSISTENT)                       | NOT NECESSARY        | 185.70                    | -                 |
| 2                         | REAR SUB CHASSIS FRAME LH / RH @ \$455.80 (CONSISTENT)                | TO REPAIR SEE LABOUR | 911.60                    | -                 |
|                           | LESS 25% DISCOUNT                                                     |                      | -2,462.47                 | -1,830.04         |
|                           |                                                                       |                      | 7,387.40                  | 5,490.13          |
| <b>SPECIAL NETT ITEMS</b> |                                                                       |                      |                           |                   |
| 1                         | SET REAR BOOT LID OUTER GARNISH CLIPS (SN) (CONSISTENT)               | NECESSARY            | 30.00                     | 20.00             |
| 1                         | REAR BOOT NUMBER PLATE WITH GARNISH (SN) (CONSISTENT)                 | BROKEN               | 60.00                     | 35.00             |
| 2                         | SET REAR TAILLAMP CLIPS LH / RH @ \$30.00 (SN) (CONSISTENT)           | NECESSARY            | 60.00                     | 20.00             |
| 2                         | REAR TAILLAMP BRAKE LH / RH @ \$15.00 (SN) (CONSISTENT)               | NOT NECESSARY        | 30.00                     | -                 |
| 2                         | REAR TAILLAMP SIGNAL BULB LH / RH @ \$15.00 (SN) (CONSISTENT)         | NOT NECESSARY        | 30.00                     | -                 |
| 2                         | REAR TAILLAMP REVERSE BULB LH / RH @ \$15.00 (SN) (CONSISTENT)        | NOT NECESSARY        | 30.00                     | -                 |
| 1                         | REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)                          | BROKEN               | 280.00                    | 200.00            |

Report Ref No. CC4/ASM19005572/Ega3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts                                                                                                                                                     | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | SET REAR BUMPER CLIPS (SN) (CONSISTENT)                                                                                                                                  | NECESSARY     | 60.00                     | 30.00             |
| 1   | SET REAR END PANEL INNER TOP GARNISH CLIPS (SN) (CONSISTENT)                                                                                                             | NECESSARY     | 40.00                     | 20.00             |
| 1   | SPARE TYRE PANEL INSULATOR MAT (SN) (CONSISTENT)                                                                                                                         | NOT NECESSARY | 380.00                    | -                 |
| 1   | SPARE TYRE PANEL INNER TOP JACKING TOOL (SN) (CONSISTENT)                                                                                                                | NOT NECESSARY | 180.00                    | -                 |
| 1   | SPARE TYRE PANEL INNER TOP BREAK SOWN (SN) (CONSISTENT)                                                                                                                  | NOT NECESSARY | 150.00                    | -                 |
| 2   | REAR FENDER INSULATOR MAT LH / RH @ \$180.00 (SN) (CONSISTENT)                                                                                                           | O/S NECESSARY | 360.00                    | 50.00             |
| 2   | SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS LH / RH @ \$60.00 (SN) (CONSISTENT)                                                                                          | NECESSARY     | 120.00                    | 20.00             |
| 2   | SET REAR WINDSCREEN INNER GARNISH CLIPS LH / RH @ \$30.00 (SN) (CONSISTENT)                                                                                              | NECESSARY     | 60.00                     | 20.00             |
| 1   | REAR WINDSCREEN SEALANT WITH PRIMER (SN) (CONSISTENT)                                                                                                                    | NECESSARY     | 100.00                    | 40.00             |
|     |                                                                                                                                                                          |               | 1,970.00                  | 455.00            |
|     | <b>LABOUR</b>                                                                                                                                                            |               |                           |                   |
|     | TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF REAR END PANEL BRACKET PLATE LH / RH AND REAR SUB CHASSIS FRAME LH / RH. |               | 2,400.00                  | 1,500.00          |
|     | TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.                                                                                                    |               | 2,000.00                  | 1,100.00          |
|     | TO APPLY ANTI-RUST & TUFF KOTE.                                                                                                                                          |               | 200.00                    | 50.00             |
|     | TO PERFORM LIGHTING & WIRING CHECK.                                                                                                                                      |               | 80.00                     | 30.00             |
|     | TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION.                                                                                                     | NOT NECESSARY | 280.00                    | -                 |
|     | TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR.                                                                                                         | NOT NECESSARY | 220.00                    | -                 |
|     | TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST.                                                                                                   |               | 150.00                    | 100.00            |
|     | TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION.                                                                               |               | 150.00                    | 30.00             |
|     | TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING.                                                                                                |               | 80.00                     | 20.00             |

Report Ref No. CC4/ASM19005572/Ega3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

| Qty                                                                  | Description of Parts                                                                                 | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                                                                      | TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING.   |           | 180.00                    | 80.00             |
|                                                                      | TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR. |           | 280.00                    | 50.00             |
|                                                                      | TOWING SERVICE ACCIDENT SCENE TOW TO WORKSHOP.                                                       |           | 80.00                     | 80.00             |
|                                                                      |                                                                                                      |           | 6,100.00                  | 3,040.00          |
| GRAND TOTAL                                                          |                                                                                                      |           | 15,457.40                 | 8,985.13          |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                                                                      |           |                           | 7,200.00          |

Report Ref No. CC4/ASM19005572/Ega3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.