



Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

GST / ROC Company No : 201101753C
Third Party Insurer : AXA
Insured's Veh No : SGQ7770S
Date of accident : 23/03/2019
Estimate To Repair : MAZDA 5
Vehicle No : SLV1874E
Chassis No : JM6CW1071H0127178
Quotation No : AR/QO19/03-1007
Quotation Date : 27/03/2019

NOT AVAL
25/6/19
Thylo de hamply
40

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1PC	FRT RH DOOR	\$1,265.00
2	1SET	FRT RH DOOR TOP STICKER	\$105.60
3	1SET	REAR RH DOOR TOP STICKER	\$105.60
4	1PC	REAR RH DOOR	\$1,364.50
5	1PC	RH SIDE SKIRTS	\$32.50
			\$2,873.20
LESS 20%			\$574.64
			\$2,298.56
LABOUR CHARGES			
1		WIRE CHECKING	\$20.00
2		TRANSFER 2 DOORS COMPONENT FROM OLD TO NEW	\$200.00
3		LABOUR CHARGE	\$700.00
4		SPRAY PAINTING	\$850.00
TOTAL			\$1,770.00
Sub Total			\$4,068.56
GST (7.00%)			\$284.80
Total			\$4,353.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please conduct the survey at
Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883
GARY 8338 8418