



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

General Details

Involving	1 2009 BMW 525 I (SJU1135J)
Date of Loss	7 March 2019
Time of Loss	20.30
Loss Description	SJU1135J (INSD) C/W SLE4141G (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="27830"/>
Nett Loss Amount	\$5,170.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	<input type="text" value="38"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJU1135J

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

18/11/2009



Mileage

216427

Age of Vehicle

9

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2009	2009
Make	BMW	B.M.W.
Model	525 I	525I XL

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	MAHADEVAN RAMASAMY	
Date of Birth	6 May 1970	dd/mm/yyyy
Age	48	



CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	WBANU52040C229202	<input type="text" value="WBANU52040C2"/>
Engine No	07047238N52B25AF	<input type="text" value="07047238N52B2"/>
Engine Capacity		<input type="text" value="2497"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="33000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	23	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 
Address	SINGAPORE, Singapore	<input type="text"/>
Address type	Residential	<input type="text"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text" value=""/>
Marital status	Married	<input type="text" value=""/>
Identification #	S7015463C	<input type="text" value=""/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

29/03/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

245/45R17

Rear Tyre Size

245/45R17

Front left side

PIRELLI5mm

Rear left side

PIRELLI5mm

Front right side

PIRELLI5mm

Rear right side

PIRELLI5mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		1	1			LH FRONT FENDER			Repair	0	0	0	0	0	Deny	
<input type="checkbox"/>		2	1			LH FRONT FENDER INNER SHIELD			Deformed	167		5		158.65	Reviewing	
<input type="checkbox"/>		3	1			SET LH FRONT FENDER INNER SHIELD CLIP			Necessary	45		5		42.75	Reviewing	
<input type="checkbox"/>		4	1			LH FRONT FENDER SIGNAL LAMP			Damaged	68		5		64.6	Reviewing	
<input type="checkbox"/>		5	1			LH SIDE SKIRT			Damaged	432		5		410.4	Reviewing	
<input type="checkbox"/>		6	1			LH FRONT DOOR			Buckled	1805		5		1714.75	Reviewing	
<input type="checkbox"/>		7	1			LH FRONT DOOR OUTER HANDLE			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		8	1			LH FRONT DOOR OUTER HANDLE CAP			Serviceable	0	0	0	0	0	Deny	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	9	1			LH FRONT DOOR WINDOW LOWER CHROME MOULDING			Serviceable	0	0	0	0	0	Deny	
	10	1			LH FRONT DOOR WINDOW UPPER CHROME MOULDING			Serviceable	0	0	0	0	0	Deny	
	11	1			LH FRONT DOOR WINDOW OUTER VERTICAL GARNISH			Necessary	71		5		67.45	Reviewing	
	12	1			LH FRONT DOOR LOCK			Serviceable	0	0	0	0	0	Deny	
	13	1			LH FRONT DOOR LOCK STRIKER			Serviceable	0	0	0	0	0	Deny	
	14	2			LH FRONT DOOR HINGE			Serviceable	0	0	0	0	0	Deny	
	15	1			LH FRONT FENDER CENTRE CHECKER			Serviceable	0	0	0	0	0	Deny	
	16	1			LH FRONT DOOR INNER TRIM BOARD			Cracked	1711.2		5		1625.64	Reviewing	
	17	1			SET LH FRONT DOOR INNER TRIM BOARD CLIP			Necessary	60		5		57	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		18	1			LH FRONT DOOR SPEAKER ASSY			Serviceable	0	0	0	0	0	Deny	
		19	1			LH FRONT DOOR POWER WINDOW REGULATOR			Serviceable	0	0	0	0	0	Deny	
		20	1			LH FRONT DOOR POWER WINDOW REGULATOR MOTOR			Serviceable	0	0	0	0	0	Deny	
		21	1			LH FRONT DOOR WEATHERSTRIP			Damaged	176		5		167.2	Reviewing	
		22	1			LH FRONT TYRE (NPA)			Serviceable	0	0	0	0	0	Deny	
		23	1			LH FRONT SHOCK ABSORBER			Serviceable	0	0	0	0	0	Deny	
		24	1			LH FRONT SHOCK ABSORBER TOP MOUNTING			Serviceable	0	0	0	0	0	Deny	
		25	1			LH FRONT STABILISER LINKAGE ROD			Serviceable	0	0	0	0	0	Deny	
		26	1			LH FRONT WHEEL BEARING			Serviceable	0	0	0	0	0	Deny	
		27	1			LH FRONT KNUCKLE ARM			Serviceable	0	0	0	0	0	Deny	
		28	1			LH FRONT LOWER ARM			Serviceable	0	0	0	0	0	Deny	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	29	1			LH FRONT STEERING TIE ROD			Serviceable	0	0	0	0	0	Deny	
	30	1			LH FRONT CONTROL ARM			Serviceable	0	0	0	0	0	Deny	
	31	1			LH FRONT ABS SENSOR			Serviceable	0	0	0	0	0	Deny	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		LABOUR TO PANEL BEAT AND REPLACE PARTS	600	0	0	Reviewing		
	2		TO PUTTY, RESPRAY AND POLISH AFFECTED PORTION	700	0	0	Reviewing		
	3		CHECK AND RECTIFY WIRING SYSTEM	30	0	0	Reviewing		
	4		REMOVE AND INSTALL FRONT DOOR COMPONENT	60	0	0	Reviewing		
	5		REMOVE AND INSTALL FRONT UNDERCARRIAGE	0	0	0	Deny		
	6		RUSTPROOF AFFECTED PORTION	40	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add Approve Deny Submit All



1

DAYS OF REPAIR : 5 DAYS

Reviewing



2

LH FRONT TYRE RIM (LOCAL REPAIR)

Reviewing

100

CUT





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$5,438.44

Claim Amount

\$5,438.44

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$4,308.44

\$4,308.44

Labour

\$1,430.00

\$1,430.00

Miscellaneous

\$100.00

\$100.00

Excess

-\$400.00

-\$400.00

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

FINAL
LUMP
SUM

Reviewing

4600





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$4,200.00

Claim Amount

\$4,200.00

CATEGORY

ESTIMATE

REVISED AMOUNT

Miscellaneous

\$4,600.00

\$4,600.00

Excess

-\$400.00

-\$400.00

Submit for Review