

VIC

# ST&T AUTOMOTIVE PTE LTD

48 Toh Guan Road East Enterprise Hub  
#05-139 Singapore 608536  
Tel: (65) 98779879 Fax: (65) 63585541

## Customer Vehicle detail

Car Number : SMJ8246Z Car Model : Honda Shutter 1.5A  
Chassis Number : GP72004070 Registration Year : 21-Mar-2019  
Engine Number : LEB7105287  
Insurance Company : NTUC Income Insurance Co-Operative Ltd

## Third Party Vehicle detail

Car Number : SKX8315H Car Model : Subaru  
Insurance Company :

## Estimation of repair cost

Item	Part Description	Qty	Unit Price	Price
1	Rear bumper <i>DE</i>	1	\$ 986.50	\$ 986.50 ✓
2	Rear bumper side bracket LH <i>NE</i>	1	\$ 39.60	\$ 39.60 ✓
4	Rear bumper side bracket RH <i>NE</i>	1	\$ 39.60	\$ 39.60 ✓
5	Rear bumper reflector garnish LH <i>? X SW</i>	1	\$ 35.60	\$ 35.60
6	Rear bumper reflector garnish RH <i>? X SW</i>	1	\$ 35.60	\$ 35.60
7	Rear bumper towing cover <i>X SW</i>	1	\$ 25.10	\$ 25.10
8	Clip, bumper <i>NE</i>	6	\$ 4.50	\$ 27.00 ✓
9	Rear end panel <i>M</i>	1	\$ 789.10	\$ 789.10 ✓
10	Rear end panel top garnish <i>DE</i>	1	\$ 181.20	\$ 181.20 ✓
11	Tailgate assy <i>RH</i>	1	\$ 1,062.80	\$ 1,062.80 ✓
12	Tailgate weathstrip <i>NE</i>	1	\$ 189.10	\$ 189.10 ✓
13	Tailgate lock <i>NE</i>	1	\$ 285.90	\$ 285.90 ✓
14	Emblem "Shuttle" <i>NE</i>	1	\$ 42.70 <i>PS. 10</i>	\$ 42.70 ✓
15	Emblem "Hybrid" <i>NE</i>	1	\$ 47.30 <i>79.90</i>	\$ 47.30 ✓
16	Tailgate windscreen <i>X SW</i>	1	\$ 1,050.00	\$ 1,050.00
17	Tailgate windscreen molding <i>NE</i>	1	\$ 175.80	\$ 175.80 ✓
18	Tail lamp inner LH <i>CA</i>	1	\$ 545.10	\$ 545.10 ✓
19	Tail lamp inner RH <i>SCB</i>	1	\$ 545.10	\$ 545.10 ✓
20	Tail lamp outer LH <i>SCB</i>	1	\$ 586.00	\$ 586.00 ✓
21	Tail lamp outer RH <i>CA</i>	1	\$ 586.00	\$ 586.00 ✓
			<u>4946.88</u>	Sub Total \$ 7,254.90 <i>6183.62</i>
				Less 20% \$ 1,450.98 <i>1236.72</i>
				Total \$ 5,803.92 <i>4946.88</i>

## Special Nett

1	Supply 1 set of reverse sensor <i>NE</i>	1	\$ 250.00	\$ <del>250.00</del> <i>220</i>
2	Supply windscreen sealant kit <i>NE</i>	1	\$ 45.00	\$ <del>45.00</del>
3	Supply joint/seam rubberised seal <i>NE</i>	1	\$ 60.00	\$ <del>60.00</del>
				Total \$ 355.00 <i>305.00</i>

## Labour

1	Remove, dismantling and replace damage parts. Pull, cut and weld on rear end panel. Repair and strengthen rear floor panel and towing hook panel, strengthen and repair side extension member, LH & RH rear fender, align body panel gap & fittings. Replace tail lamp panel LH & RH <i>(1500)</i>		\$ 1,500.00	<i>1000 700</i>
				<i>3350.00 200</i>

2	Supply paint and consumable material, carry out sanding, masking and cleaning on affected area. Conduct spray painting on tailgate (inner & outer), rear bumper, rear end panel, floor panel LH and RH rear fender. (2K metallic silver) <i>Tail lamp panel - \$250.00, 200</i>	\$ 1,500.00 1250 <del>800</del>
3	Set up and tightening vehicle on pulling work bench.	(photo) 105 <del>50</del> 150.00
4	Remove & reinstall rear upholstery to facilitate repair.	\$60 120.00
5	Remove and replace rear windscreen and conduct water leaking test.	\$ 120 180.00
6	Remove & transfer tailgate attachment parts and wiring onto new tailgate panel.	\$60 100.00
7	Remove and replace reverse sensor	\$ 50.00
8	Apply rust coating on underside accident affected area	\$ 60.00
9	Check lightings, wiring and light socket connection	\$ 40.00
	Total	\$ 3,700.00 <del>3340.00</del>
	Grand Total	\$ 10,964.90

Spare tyre bond cover ✓  
 Quarter panel garnish LH/RH - DE ✓ x2  
 Tailgate handle - DE ✓

RASUL  
 Hp 90010068  
 7 days  
 P/P  
 29/03/19 @ 1200hrs  
 Resurvey before paint

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey cost after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Authorised by Repairer  
 Signature  
 Date

# ST&T AUTOMOTIVE PTE LTD

48 Toh Guan Road East Enterprise Hub  
 #05-139, Singapore 608585  
 Tel: (65) 98779879 Fax: (65) 83565541

### Customer Vehicle detail

Car Number : SMJ8246Z Car Model : Honda Shutter 1.5A  
 Chassis Number : GP72004070 Registration Year : 21-Mar-2019  
 Engine Number : LEB7105267  
 Insurance Company : NTUC Income Insurance Co-Operative Ltd

### Third Party Vehicle detail

Car Number : SKX8315H Car Model : Subaru  
 Insurance Company :

### Supplementary repair list

Item	Part Description	Qty	Unit Price	Price
1	Spare tire board cover <del>DE</del>	1		\$ 257.90 ✓
2	Tailgate chrome garnish <del>CM</del>	1	\$ 373.70	\$ 373.70 ✓
4	Rear fender trim panel, LH <del>DE</del>	1	\$ 426.40	\$ 426.40 ✓
5	Rear fender trim panel, RH <del>DE</del>	1	\$ 426.40	\$ 426.40 ✓
6	Tailgate inner handle <del>DE</del>	1	\$ 67.30	\$ 67.30 ✓
7	Rear end side panel, LH <del>DM</del>	1	\$ 245.30	\$ 245.30 ✓
8	Rear end side panel, RH <del>DM</del>	1	\$ 245.30	\$ 245.30 ✓
	Rear license plate dent - <sup>35</sup> \$45.00 (special nett)			
	Spare tire top cover - \$296.50 ✓			
	<u>Labour</u>			
1	Carry out OBD scan, engine performance check, hybrid system test and functionality			\$ 350.00 ✓
				Total \$ 350.00
				Sub Total \$ 1,784.40
				Less 20% \$ 356.88
				Total \$ 1,427.52
				2351.04
				Grand Total \$ 1,777.52

Parts : 9122.40  
 less 20% : 1824.48  
7297.92 ✓

Special Nett: ~~350.00~~ 340  
 Labour : ~~3540.00~~ 3340

10,977.92 \$ 11,187.92 (part by part)

9 working days (7+2)

Replace tail lamp panel