

V/C

LKK
Steven ChenVEHICLE NO : SLN 2502PMODEL : VIA/CARBENS 1.7 A D EXWIP : 46339

Material	: \$	<u>2,176.00</u>
Labour	: \$	<u>3,740.00</u>
Sub-Total	: \$	<u>5,916.00</u>
Less 2% Disc	: \$	<u>-</u>
Less Excess	: \$	<u>-</u>
Total	: \$	<u>5,916.00</u>
GST 7%	: \$	<u>414.12</u>
Grand Total	: \$	<u>6,330.12</u>
Finalise By/Date :	<u>Larry on 18/06/19</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 5 WORKING DAYS + 2 days (wk.end)

* TP vehicle no: GBA8212Z (LONPAC)

* claim GA search fee \$2.00

* claim loss of use.

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : HR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NEBULAE ESERVICE	Cust No/Name /NEBULAE ESERVICE
BLK 170 GANGSA RD	Reg No/Reg Date SLN2502P / 27/04/2017
#02-40	Date In/Mileage 10/06/2019/ 237653
SINGAPORE 670170	Chassis/Package KNAH0815VH7172414 /KC17PKC17
Contact No Mobile: 96632763 Mr Ng	Engine No D4FDGH118106
10/06/	Make/Model KIA/CARENS 1.7 A D EX FL DY7
	Colour/Trim AJR INFERNO RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	18/06/2019/ 17:19	TLD	BB4 / Lauro Songcuan	46339
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER FACE				1650.00 ✓
E PNT88000	REMOVE AND INSTALL PARKING SENSOR				60.00 ✓
E PNT88000	REMOVE AND REPLACE REAR WINDSCREEN GLASS				240.00 ✓
M SUNDRY	SUPPLY REAR WINDSCREEN SEALANT				80.00 ✓
E PNT88000	TRANSFER REAR TAILGATE MECHANISM AND OTHER ATTACHMENT TO NEW PANEL				250.00 ✓
E PNT88000	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR				180.00 ✓
E PNT98000	SPRAY PAINT REAR BUMPER, REAR TAILGATE AND AFFECTED PORTIONS				840.00 ✓
M SUNDRY	SUPPLY C&C LOGO				50.00 ✓
M SUNDRY	APPLY BODY SEALANT ON AFFECTED AREAS				80.00 ✓
M SUNDRY	PERFORM RUST PREVENTION ON AFFECTED PANELS				60.00 ✓
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00 ✓
M SUNDRY	SUNDRIES				20.00 ✓
X PANEL ASSY-TAIL GATE ✓		1.00	1088.00	00.00	1088.00 ✓
X EMBLEM-CARENS ✓		1.00	36.00	00.00	36.00 ✓
X EMBLEM-CROI ✓		1.00	29.00	00.00	29.00 ✓
X BRACKET ASSY-RR BUMPER SIDE,LH ✓		1.00	25.00	00.00	25.00 ✓
X BRACKET ASSY-RR BUMPER SIDE,RH ✓		1.00	25.00	00.00	25.00 ✓

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NEBULAE ESERVICE	Cust No/Name /NEBULAE ESERVICE
BLK 170 GANGSA RD	Reg No/Reg Date SLH2502P / 27/04/2017
#02-40	Date In/Mileage 10/06/2019/ 237653
SINGAPORE 670170	Chassis/Package KNAHUB15VH7172414 /KC17PKC17
Contact No Mobile: 96632763 Mr Ng	Engine No D4FDGH11B106
10/06/	Make/Model KIA/CARENS 1.7 A D EX FL DY7
	Colour/Trim AJR INFERNO RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	18/06/2019/ 17:19	TLD	884 / Lauro Songcuan	46339

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RETAINER ✓	10.00	1.00	00.00	10.00 ✓
X BRACKET-FR BUMPER SIDE, LH ✓	1.00	4.00	00.00	4.00 ✓
X BRACKET-FR BUMPER SIDE, RH ✓	1.00	4.00	00.00	4.00 ✓
X COVER-RR BUMPER, UPR ✓	1.00	576.00	00.00	576.00 ✓
X COVER-RR BUMPER LWR ✓	1.00	201.00	00.00	201.00 ✓
X HOLDER-BACK WARING SYSTEM OTR ✓	2.00	4.00	00.00	8.00 ✓
X HOLDER-BACK WARING SYSTEM INR ✓	2.00	4.00	00.00	8.00 ✓
X ULTRASONIC SENSOR ASSY-P.A.S ✓	1.00	162.00	00.00	162.00 ✓

Z TEXT

TP LONPAC - GBAB212Z

DOA: 11.03.2019

SURVEYOR: STEVE CHEN (LKK) 26.03.19

05 DAYS

Cycle & Carriage celebrates 120 years.
 Visit www.cyclecarriage.com/120 for more info!

Parts	2,176.00			
Labour	3,450.00			
Standard Menu	0.00	7% GST on	Nett	5,916.00
Specialist Job	0.00			414.12
Diagnostics Job	0.00		Total Payable	6,330.12
Sundry/Others	290.00			
Total (w/o GST)	5,916.00			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NEBULAE ESERVICE	Cust No/Name LCV07824/NEBULAE ESERVICE
BLK 170 GANGSA RD	Reg No/Reg Date SLN2502P / 27/04/201
#02-40	Date In/Mileage / 0
SINGAPORE 670170	Chassis No KNAHUB15VH7172414
Contact No Mobile: 96632763 Mr Ng	Engine No D4FDGH118106
	Make/Model KIA/CARENS 1.7 A D EX FL DY7
	Colour/Trim AJR INFERNO RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	13/03/2019/ 19:43	QUD	247 / DonBong	46339
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR TAILGATE, REAR BUMPER FACE, REPAIR REAR END PANEL ST- REPAIR BOTH REAR FENDER	1650			2750.00
E PNT88000	REMOVE AND INSTALL PARKING SENSOR	60			80.00
E PNT88000	REMOVE AND REPLACE REAR WINDSCREEN GLASS	/			240.00
M SUNDRY	SUPPLY REAR WINDSCREEN SEALANT	/			80.00
M SUNDRY	SUPPLY REAR SOLAR FILM	X ?			220.00
E PNT88000	TRANSFER REAR TAILGATE MECHANISM AND OTHERS ATTACHMENT TO NEW PANEL	250			300.00
E PNT88000	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK	180			250.00
E PNT98000	PAINT WORK SPRAY REAR END PANEL, REAR BUMPER, REAR TAILGATE, REAR BOTH FENDER AND AFFECTED PORTION	840			2100.00
M SUNDRY	SUPPLY PARKING SENSOR	X			220.00
M SUNDRY	SUPPLY C&C LOGO	/			50.00
M SUNDRY	APPLY BODY SEALANT	80			160.00
M SUNDRY	PERFORM RUST PREVENTION	60			160.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	30			50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO USING HI-SCAN PRO TEST	/			200.00
Confirm & accepted by		LOOK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
Authorized signatory and company stamp					

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NEBULAE ESERVICE	Cust No/Name LCV07824/NEBULAE ESERVICE
BLK 170 GANGSA RD	Reg No/Reg Date SLN2502P / 27/04/201
#02-40	Date In/Mileage / 0
SINGAPORE 670170	Chassis No KNAHUB15VH7172414
Contact No Mobile: 96632763 Mr Ng	Engine No D4FDGH118106
	Make/Model KIA/CARENS 1.7 A D EX FL DY7
	Colour/Trim AJR INFERNO RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	13/03/2019/ 19:43	QUD	247 / DonBong	46339			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								20/50.00
M SUNDRIES								
M PANEL ASSY-TAIL GATE	✓ DO				1.00	1088.00	00.00	1088.00
M EMBLEM-CARENS	✓ NEX				1.00	36.00	00.00	36.00
M EMBLEM-CROTI	✓ NEX				1.00	29.00	00.00	29.00
M BRACKET ASSY-RR BUMPER SIDE, LH	✓ BR				1.00	25.00	00.00	25.00
M BRACKET ASSY-RR BUMPER SIDE, RH	✓ BR				1.00	25.00	00.00	25.00
M STAY-RR BUMPER LH	✓ NEX				1.00	159.00	00.00	159.00
M STAY-RR BUMPER RH	✓ NEX				1.00	159.00	00.00	159.00
M ANTENNA ASSY-SMARTKEY	✓ NEX				1.00	79.00	00.00	79.00
M BEAM-RR BUMPER	✓ NEX				1.00	367.00	00.00	367.00
M BRACKET-RR BUMPER RAIL, UPR	✓ NEX				1.00	5.00	00.00	5.00
M BRACKET-RR BUMPER RAIL, UPR	✓ NEX				1.00	5.00	00.00	5.00
M BRACKET-RR BUMPER RAIL, LWR	✓ NEX				2.00	5.00	00.00	10.00
M BRACKET-RR BUMPER LWR, CTR	✓ NEX				1.00	5.00	00.00	5.00
M WIRING HARNESS-R.P.A.S	✓ NEX				1.00	251.00	00.00	251.00
M RETAINER	✓ NEX				10.00	1.00	00.00	10.00
M BRACKET-FR BUMPER SIDE, LH	✓ NEX				1.00	4.00	00.00	4.00
M BRACKET-FR BUMPER SIDE, RH	✓ NEX				1.00	4.00	00.00	4.00
M LAMP ASSY-REAR FOG, RH	✓ NEX				1.00	116.00	00.00	116.00
M LAMP ASSY-REAR FOG, LH	✓ NEX				1.00	116.00	00.00	116.00
M COVER-RR BUMPER, UPR	✓ NEX				1.00	576.00	00.00	4608.00
M COVER-RR BUMPER LWR	✓ NEX				1.00	201.00	00.00	201.00
M BRACKET-RR BUMPER SIDE LWR, LH	✓ NEX				1.00	21.00	00.00	21.00
M BRACKET-RR BUMPER SIDE LWR, RH	✓ NEX				1.00	21.00	00.00	21.00
M HOLDER-BACK WARING SYSTEM OTR	✓ NEX				2.00	4.00	00.00	8.00
M HOLDER-BACK WARING SYSTEM INR	✓ NEX				2.00	4.00	00.00	8.00
M GLASS ASSY-TAIL GATE	✓ NEX				7.00	490.00	00.00	3430.00
M ULTRASONIC SENSOR ASSY-P.A.S	✓ NEX				1.00	162.00	00.00	162.00
M ULTRASONIC SENSOR ASSY-P.A.S	✓ NEX				1.00	162.00	00.00	162.00
M ULTRASONIC SENSOR ASSY-P.A.S	✓ NEX				1.00	162.00	00.00	162.00
M ULTRASONIC SENSOR ASSY-P.A.S	✓ NEX				1.00	162.00	00.00	162.00
SURVEYOR NAME: Store chin (LKK)					1.00	162.00	00.00	162.00
Confirm & accepted by								
DATE: 26/3/19 1.45 pm								
REMARKS:					2% GST on	18348.00		18,348.00
								1284.36
								19,632.36
Authorized signatory and company stamp								

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.