



LIM YEW BOO SPRAY PAINT CO.

Page 1 / 3

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645

No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721

Tel: 6453 4177 Fax: 6459 3724

Email: limyewboo@singnet.com.sg

Company Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP19/017

Date : 04/04/2019

Vehicle Num. : SLJ 3542M

Make/Model : TOYOTA SIENTA 1.5X LIMITED-201

Chassis/Eng#: MHFZ28H3800013632/2NRX07167

Accident Date : 21/04/2019

Claim No. :

Reference : LYB/SLJ3542M/AIG/tp/sl

Policy No. :

*Not Notified**Recovery BY paint & den*

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE <i>BT ✓</i>	<i>sm</i> 619.70	X
2.	2	REAR TAILGATE ABSORBER	<i>sm</i> X	
3.	2	REAR TAILGATE STOPPER	<i>Net</i> 396.57	X
4.	1	REAR TAILGATE LOCK /UPPER	<i>sm</i> 311.90	X
5.	1	REAR TAILGATE WEATHERSTRIP	<i>sm</i> 264.90	X
6.	1	REAR TAILGATE CHROME GARNISH		
7.	1	REAR EMBLEM <i>sm</i>	54.65	
8.	1	REAR EMBLEM 'SIENTA' <i>sm</i>	46.40	
9.	1	REAR EMBLEM 'V' <i>sm</i>	377.80	
10.	1	REAR TAILLAMP/LH <i>sm</i>	452.40	
11.	1	REAR BUMPER	<i>Net</i> 296.40	
12.	1	REAR BUMPER PAD (CENTRE)	<i>sm</i> 260.78	X
13.	1	REAR BUMPER PAD/LH	<i>mi</i>	
14.	1	REAR BUMPER PAD/RH	<i>sm</i> 84.62	
15.	1	REAR BUMPER TOWING COVER		
16.	1	REAR BUMPER REFLECTOR/LH		
17.	1	REAR BUMPER BRAKE LIGHT COVER <i>sm</i> X		
18.	2	REAR BUMPER RETAINER <i>sm</i> X		
19.	1	REAR BUMPER BEAM <i>sm</i> ?		
20.	2	REAR REVERSE PDC SENSOR	<i>Net</i> 226.00	452.00
List TotalS\$:				3,618.12
20.00% Discount S\$:				723.62
<i>25%</i>				2,894.50

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...

All cheques should be crossed and made payable to
Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department
 Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP19/017

Date : 04/04/2019
 Vehicle Num. : SLJ 3542M
 Make/Model : TOYOTA SIENTA 1.5X LIMITED-201
 Chassis/Eng# : MHFZ28H3800013632/2NRX07167
 Accident Date : 21/04/2019
 Claim No. :
 Reference : LYB/SLJ3542M/AIG/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	SPECIAL NETT ITEMS :		
2.	1	REAR W/SCREEN SEALANT		40.00
		REAR W/SCREEN INNER SEAL		40.00
		Special Nett Total S\$:		80.00
		LABOUR :		
		LABOUR TO REMOVE & REFIX REAR W/SCREEN		150.00
		LABOUR TO REMOVE/REFIX REAR SEAT,INTERIOR GARNISH..ETC		120.00
		TO CHECK WATER SEEPAGE		60.00
		TO TRANSFER TAILGATE PARTS & FITTING TO NEW TAILGATE		80.00
		TO CHECK & LABOUR REPLACE REAR REVERSE SENSOR		80.00
		TO CHECK & ALIGN ON AFFECTED EXHAUST		80.00
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS		120.00
		TO REPAIR,PANEL BEAT ON REAR TAILEND PANEL, RE-SHAPE & RE-STRAIGHTED ON REAR AFFECTED AREA & LABOUR TO REPLACE THE ABOVE PARTS		800.00

CONTINUE / ...

All cheques should be crossed and made payable to
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No. : 200514/00L

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 CHARTIS BUILDING SINGAPORE 079120

Attention : Motor Claim Department

Contact : 64191000 Fax No. : 64193727 Claims Dept

Estimate : TP19/017

Date : 04/04/2019
 Vehicle Num. : SLJ 3542M
 Make/Model : TOYOTA SIENTA 1.5X LIMITED-201
 Chassis/Eng# : MHFZ28H3800013632/2NRX07167
 Accident Date : 21/04/2019
 Claim No. :
 Reference : LYB/SLJ3542M/AIG/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO PUTTY,PRIMER & SPRAY PAINT ON REAR TAILGATE, REAR
 BUMPER,LEFT & RIGHT REAR TAILLAMP LOWER PANEL & REAR
 REVERSE SENSOR USING 2K PAINT (TOYOTA 040)

6602 800.00

Labour Total S\$:

2,290.00

E. & O. E.

Total S\$: 5,264.50

for LIM YEW BOO SPRAY PAINT CO.

All cheques should be crossed and made payable to
 Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.