

KAY MOTOR
BLOCK 9 SIN MING INDUSTRIAL ESTATE
#01-46
SINGAPORE 575644
Tel: 6458 2283 Fax: 6459 8863
Email: kayautosg@yahoo.com
Lim Chin Khoon

Not Authorized
Resurvey Bleeping
5 days

27 March 2019

Estimate To Repair Toyota Harrier – SFS 858X

1pc	rear boot lid
1pc	rear boot lid 'Harrier' emblem
1pc	rear boot 'Toyota' emblem
1pc	rear boot rubber
1pc	rear boot centre protector
2pcs	rear boot lamp @\$379.90
2pcs	rear tail lamp @\$561.50
1pc	rear boot lock
1pc	rear lock inner trim
1pc	rear end panel
1pc	rear bumper
2pcs	rear bumper bracket @\$171.45
1pc	rear bumper chrome moulding
1pc	rear bumper beam
1pc	rear wiper motor
1pc	rear windscreen moulding

Bu	\$ 1521.30	✓
Re	121.25	✓
Re	122.10	✓
Sn	343.60	X
Wap	374.45	✓
CM	759.80	✓
Sn	1123.00	X
Re	297.70	✓
Sn	731.31	X
	374.45	?
Bu	1271.45	✓
	342.90	?
Re	161.10	✓
	581.10	?
Sn	591.60	X
Re	172.60	✓

8889.71

2222.43

less 25%

6667.28

1set	rear bumper clips
1pc	rear number plate
1pc	rear windscreen sealant
1set	rear reverse sensor
1	rear boot sticker

Re	35.00sn	✓
Re	50.00 sn	45sn
Re	40.00 sn	✓
Re	380.00 sn	200sn
Re	120.00 sn	80sn
	150.00	1201
	60.00	✓
	750.00	6601

To remove & refit rear windscreen glass
To remove & fit rear wiper motor & wiring
To putty & spray painting

To repair & panelbeat rear inner panel, straighten rear chassis,
cut/weld rear end panel, rear fender, dismantle & fit the above parts

680.00 ?

Total: \$ 8932.28

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display detailed parts during resurvey
- Parts price list for confirmation
- Third party survey & "Without Prejudice" has been
- No illegal work
- Supplier of parts, labour, materials, and
- is subject to the company

Acknowledged by Repairer

Signature

Date: