

1/15/2019

INS. CASE OWNER:

Yale

CC

AXA1900

5596, R19/10/19

LKK
IDAC

Surveyor:

Rasul

DOI:

ASSIGNMENT

29/3/19

Date / Time:

29/3/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBF 5344U

Name of Insured:

THORNE LANDSCAPE & CONSTRUCTION

Insured Tel No.:

HP:

Claim No.:

SAM01163/107203

Policy No.:

PRU57048

Excess Sec II :\$S

D.O.A.:

29/3/19

Make / Model:

TOYOTA

Place of Accident:

HAWLEY LANE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

BLACKISTHAW NIMROMARY

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

GBF5344U

SUA296R

SME 935AB

INSRS:
WSP:
Tel:
Liability:
RMKS:

1

INSRS:
WSP:
Tel:
Liability:
RMKS:auto wheels
TpINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

28/3/19

* Sme claim

3VC 01 LAST

OBTAIN LOA.

called OZ
to inform TP claim

28/3/19

28/3/19

email sent to OZ to seek out ask for purpose
of usage.

23/10

24/10

25/10

w/ only agree UIC \$7000 for COR. ✓
Re-seek mandate of \$8103.45.
Sent to OZ \$8000 as per TP verbal propose. &
send (pending) ev in 2.

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI: 202011-202011-01

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Rasul

Repair Cost:

US

\$S 7300.00

(7 days)

Reduction: \$23,306.76

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

Gst

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia

100%

Repair Cost:

Gst

\$S -

(Agreed / Assessed)

BOLA S/N No.:

7490.00

(AXA instruction).

c.c. Col last

Loss of Rental (LOR):

\$S -

(days)

Loss of Use (LOU):

\$S 480

(S 60 x 8 days)

Loss of Income (LOI):

\$S -

(S x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]

GIA/LTA Search

\$S 7.45

Medical:

\$S 126.00

Disbursement:

\$S -

(e.g. Tow / Independent)

Legal Cost

\$S -

Total:

\$S 8103.45

Global Sum \$S:

\$8000.00

COPY SENT
9/11/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$4350/-

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$S 8000.00

Name 1:

Auto wheels motorworks Pte Ltd

Payee 2. (Strike if N.A.)

\$S -

Name 2:

Payee 3. (Strike if N.A.)

\$S -

Name 3:

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: AXA INSURANCE

DATE: 28/03/2019

VEHICLE NO: SLA2961R

MODEL: VOLKSWAGEN JETTA

YEAR: 2010

ACCIDENT DATE: 27/03/2019

CLAIM ADVISOR: LOUIS (97684247)

EMAIL:

ESTIMATION

DESCRIPTION

QTY

LIST PRICE

PARTS

BONNET <i>repair</i>	1	\$1,210.20 X
BONNET LOCK <i>X SVC</i>	1	\$365.10 X
FRONT EMBLEM <i>CRA</i>	1	\$95.40 ✓
FRONT LOGO-TSI <i>X SVC</i>	1	\$92.10 X
FRONT GRILLE <i>CRA</i>	1	\$967.30 ✓
FRONT GRILLE CLIPS <i>new</i>	10	\$50.00 ✓
FRONT BUMPER <i>DB</i>	1	\$1,156.30 ✓
FRONT BUMPER CLIPS <i>new</i>	10	\$50.00 ✓
FRONT BUMPER RETAINER <i>X SVC</i>	2	\$114.60 X
FRONT BUMPER BRACKET <i>X SVC</i>	2	\$188.40 X
FRONT BUMPER LOWER CENTRE GRILLE <i>X SVC</i>	1	\$355.20 X
FRONT BUMPER TOWING COVER <i>X SVC</i>	1	\$98.10 X
FRONT BUMPER PROTECTOR <i>X</i>	2	\$486.40 X
FRONT BUMPER LOWER SPOILER <i>cut</i>	1	\$574.10 ✓
FRONT NUMBER PLATE GARNISH <i>X SVC</i>	1	\$143.70 X
AIR DUCT <i>X</i>	1	\$453.10 X
RADIATOR TOP COVER <i>X</i>	1	\$365.10 X
RADIATOR TOP COVER CLIPS <i>X</i>	10	\$30.00 X
FRONT BUMPER SPONGE <i>? X SVC</i>	1	\$297.50 X
FRONT REINFORCEMENT BRACKET <i>? X SVC</i>	2	\$188.40 X
FRONT REINFORCEMENT <i>? X SVC</i>	1	\$576.30 X
SUPPORT PANEL - TOP <i>? X SVC</i>	1	\$474.10 X
SUPPORT PANEL <i>? X SVC</i>	1	\$896.30 X

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: AXA INSURANCE

DATE: 28/03/2019
 VEHICLE NO: SLA2961R
 MODEL: VOLKSWAGEN JETTA
 YEAR: 2010
 ACCIDENT DATE: 27/03/2019
 CLAIM ADVISOR: LOUIS (97684247)
 EMAIL:

ESTIMATION

HEADLAMP ? X
 HEADLAMP PANEL ?
 FOGLAMP X
 FOGLAMP COVER X
 INTERCOOLER X
 CONDENSER X
 CONDENSER AIR GUIDE X
 RADIATOR X
 LH FRONT FENDER X
 RH FRONT FENDER X
 BOOTLID H - ? X
 BOOTLID LAMP ? X
 BOOTLID HINGE X
 REAR LOGO - JETTA new
 BOOTLID LOCK cut
 REAR BUMPER DE
 REAR BUMPER CLIPS new
 REAR BUMPER DIFFUSER DE
 REAR BUMPER RETAINER X
 REAR BUMPER BRACKET X
 REAR BUMPER REFLECTOR X
 REAR NUMBER PLATE LAMP X
 REAR BUMPER SPONGE ?

2	\$1,978.80 X	} Xnn
2	\$298.40 X	
2	\$598.60 X	
2	\$288.40 X	
1	\$1,245.60 X	
1	\$894.10 X	
2	\$266.40 X	
1	\$911.30 X	
1	RESTORE X	}
1	RESTORE X	
1	\$1,342.10	} nn
2	\$698.40 X	
2	\$324.60 X	} nn
1	\$76.40	
1	\$299.50	
1	\$1,081.30	
10	\$50.00	
1	\$567.30	
2	\$114.60 X	
2	\$188.40 X	} nn
2	\$298.60 X	
2	\$366.20 X	
1	\$197.50 X	

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: AXA INSURANCE

DATE: 28/03/2019
 VEHICLE NO: SLA2961R
 MODEL: VOLKSWAGEN JETTA
 YEAR: 2010
 ACCIDENT DATE: 27/03/2019
 CLAIM ADVISOR: LOUIS (97684247)
 EMAIL:

ESTIMATION

REAR REINFORCEMENT *7/6t ✓*

END PANEL *repair*

SPARE TYRE PANEL *X*

END PANEL TOP GARNISH *?*

REAR WEATHER STRIP *new ✓*

REVERSE SENSOR *? new ✓*

REVERSE SENSOR HOLDER *new ✓*

REAR EXHAUST PIPE *X*

REAR EXHAUST PIPE FINISHER *X*

1	\$453.10 <i>✓</i>
1	\$569.20 <i>X</i>
1	RESTORE <i>X</i> } <i>nn</i>
1	\$299.60 <i>X</i>
1	\$287.90 <i>✓</i>
2	\$446.40 <i>200? 3/4</i>
2	\$64.20 <i>✓</i>
1	\$1,654.20 <i>X</i>
2	\$462.60 <i>X</i> } <i>nn</i>

TOTAL: \$25,551.40

DISCOUNT 10%: \$2,555.14

\$22,996.26

S/NET

REAR NUMBER PLATE *3 cr ✓*

FRONT NUMBER PLATE *cr ✓*

REAR END PANEL SEALANT *X*

COOLANT *X*

ATF OIL *X*

1	<i>35</i> \$100.00
1	<i>35</i> \$100.00
1	\$80.00
1	\$50.00
1	\$150.00 } <i>nn</i>

TOTAL: \$480.00

LABOUR

PRICE

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE
#04-142 SINGAPORE 608586

ATTN: AXA INSURANCE

DATE: 28/03/2019
VEHICLE NO: SLA2961R
MODEL: VOLKSWAGEN JETTA
YEAR: 2010
ACCIDENT DATE: 27/03/2019
CLAIM ADVISOR: LOUIS (97684247)
EMAIL:

ESTIMATION

LABOUR FOR FACILITATE REPAIR - FRONT PORTION
LABOUR FOR FACILITATE REPAIR - REAR PORTION
TO RESPRAY AFFECTED AREAS - BONNET
TO RESPRAY AFFECTED AREAS - FRONT BUMPER
TO RESPRAY AFFECTED AREAS - RH FRONT FENDER
TO RESPRAY AFFECTED AREAS - LH FRONT FENDER
TO RESPRAY AFFECTED AREAS - BOOTLID
TO RESPRAY AFFECTED AREAS - REAR BUMPER
TO RESPRAY AFFECTED AREAS - REAR BUMPER DIFFUSER
TO RESPRAY AFFECTED AREAS - END PANEL
TO RESPRAY AFFECTED AREAS - SPARE TYRE PANEL
TO REMOVE AND REFIT AC CONDENSER INCLUDING TOP UP AC GAS
TO REMOVE AND REFIT RADIATOR INCLUDING WATER PRESSURE TEST
TO REMOVE AND REFIT INTERCOOLER
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT REAR EXHAUST PIPE FOR FACILITATE REPAIR
TO REMOVE AND REFIT REVERSE SENSOR
TO CHECK AND RECONNECT ALL NECESSARY WIRING
SUNDRIES
RUST PROOFING

~~\$1,800.00~~ 300
~~\$1,500.00~~ X 400
~~\$300.00~~ 200
~~\$300.00~~ 200
~~\$250.00~~ X } 11
~~\$250.00~~ X } 11
~~\$300.00~~ 200
~~\$300.00~~ 200
~~\$250.00~~ X 11
~~\$250.00~~ 200
~~\$250.00~~ X
~~\$150.00~~ X } 11
~~\$150.00~~ X } 11
~~\$250.00~~ X } 11
~~\$150.00~~ 60
~~\$350.00~~ X 11
~~\$100.00~~ 60
~~\$100.00~~ 30
net \$50.00 20
~~\$80.00~~ 40

TOTAL: \$7,130.00

TOTAL: \$30,606.26
7% GST: \$2,142.44
\$32,748.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068

7 days

4/5

29/03/19 @ 1550

Resurvey after repair

AUTOWHEELS

MOTORWORKS PTE LTD

48 TON GILAN ROAD EAST 1111111111
#04-142 SINGAPORE 608584

ATTN: AXA INSURANCE

DATE: 28/03/2019
VEHICLE NO: 5LA2961R
MODEL: VOLKSWAGEN JETTA
YEAR: 2010
ACCIDENT DATE: 27/03/2019
CLAIM ADVISOR: LOUIS (97684247)
EMAIL:

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BONNET <i>repair</i>	1	R \$1,210.20
BONNET LOCK <i>X</i>	1	X \$365.10
FRONT EMBLEM <i>CR4</i>	1	- \$95.40
FRONT LOGO -TSI <i>X</i>	1	X \$92.10
FRONT GRILLE <i>CR4</i>	1	- \$967.30
FRONT GRILLE CLIPS <i>new</i>	10	- \$50.00
FRONT BUMPER <i>DB</i>	1	- \$1,156.30
FRONT BUMPER CLIPS <i>new</i>	10	X \$50.00
FRONT BUMPER RETAINER <i>X</i>	2	X \$114.60
FRONT BUMPER BRACKET <i>?</i>	2	X \$188.40
FRONT BUMPER LOWER CENTRE GRILLE <i>?</i>	1	X \$355.20
FRONT BUMPER TOWING COVER <i>X</i>	1	X \$98.10
FRONT BUMPER PROTECTOR <i>X</i>	2	X \$486.40
FRONT BUMPER LOWER SPOILER <i>cut</i>	1	- \$574.10
FRONT NUMBER PLATE GARNISH <i>X</i>	1	X \$143.70
AIR DUCT <i>X</i>	1	X \$453.10
RADIATOR TOP COVER <i>X</i>	1	X \$365.10
RADIATOR TOP COVER CLIPS <i>X</i>	10	X \$30.00
FRONT BUMPER SPONGE <i>?</i>	1	X \$297.50
FRONT REINFORCEMENT BRACKET <i>?</i>	2	X \$188.40
FRONT REINFORCEMENT <i>?</i>	1	X \$576.30
SUPPORT PANEL - TOP <i>?</i>	1	R \$474.10
SUPPORT PANEL <i>?</i>	1	R \$896.30

2,843.10

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE
PO4-102 SINGAPORE 618506

ATTN: AXA INSURANCE

DATE:

28/03/2019

VEHICLE NO:

SLA2961R

MODEL:

VOLKSWAGEN JETTA

YEAR:

2010

ACCIDENT DATE:

27/03/2019

CLAIM ADVISOR:

LOUIS (97584247)

EMAIL:

ESTIMATION

HEADLAMP ?	2	X \$1,978.80
HEADLAMP PANEL ?	2	X \$298.40
FOGLAMP X	2	X \$598.60
FOGLAMP COVER X	2	X \$288.40
INTERCOOLER X	1	X \$1,245.60
CONDENSER X	1	X \$894.10
CONDENSER AIR GUIDE X	2	X \$266.40
RADIATOR X	1	X \$911.30
LH FRONT FENDER X	1	R RESTORE
RH FRONT FENDER X	1	R RESTORE
BOOTLID H -	1	/ \$1,342.10
BOOTLID LAMP ?	2 (Cracked)	/ \$698.40
BOOTLID HINGE X	2	X \$324.60
REAR LOGO - JETTA per	1	/ \$76.40
BOOTLID LOCK cut	1	/ \$299.50
REAR BUMPER de	1	/ \$1,081.30
REAR BUMPER CLIPS per	10	/ \$50.00
REAR BUMPER DIFFUSER de	1	/ \$567.30
REAR BUMPER RETAINER X	2	X \$114.60
REAR BUMPER BRACKET X	2	X \$188.40
REAR BUMPER REFLECTOR X	2	X \$298.60
REAR NUMBER PLATE LAMP X	2	X \$366.20
REAR BUMPER SPONGE ?	1	X \$197.50

5,115

AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE
#04-142 SINGAPORE 08586

ATTN: AXA INSURANCE

DATE: 28/03/2019
VEHICLE NO: SLA2961R
MODEL: VOLKSWAGEN JETTA
YEAR: 2010
ACCIDENT DATE: 27/03/2019
CLAIM ADVISOR: LOUIS (97684247)
EMAIL:

ESTIMATION

REAR REINFORCEMENT ?
END PANEL *repair*
SPARE TYRE PANEL X
END PANEL TOP GARNISH ?
REAR WEATHER STRIP *new*
REVERSE SENSOR
REVERSE SENSOR HOLDER *new*
REAR EXHAUST PIPE X
REAR EXHAUST PIPE FINISHER X

1	✓	\$453.10	
1	R	\$569.20	805.20
		RESTORE	
1	X	\$299.60	
1	-	\$287.90	
1	✓	\$448.40	200? <i>200</i>
2	✓	\$64.20	
2			
1	X	\$1,654.20	
2	X	\$462.60	

TOTAL: \$25,551.40 *7,763.30*
DISCOUNT 10%: \$2,555.14 *10%*
\$22,996.26 *6,986.97*

S/NET
REAR NUMBER PLATE *3 car*
FRONT NUMBER PLATE *car*
REAR END PANEL SEALANT X
COOLANT X
ATF OIL X

1	- 35	\$100.00
1	- 35	\$100.00
1	X	\$80.00
1	X	\$50.00
1	+ 200 R/sewn	X \$150.00

TOTAL: \$480.00

270

PRICE

LABOUR

AUTOWHEELS

MOTORWORKS PTE LTD

42 TOM LUN ROAD EAST ENTERPRISE
204-142 SINGAPORE 600500

ATTN: AXA INSURANCE

DATE: 28/03/2019
VEHICLE NO: SLA2961R
MODEL: VOLKSWAGEN JETTA
YEAR: 2010
ACCIDENT DATE: 27/03/2019
CLAIM ADVISOR: LOUIS (97624247)
EMAIL:

ESTIMATION

LABOUR FOR FACILITATE REPAIR - FRONT PORTION
LABOUR FOR FACILITATE REPAIR - REAR PORTION
TO RESPRAY AFFECTED AREAS - BONNET
TO RESPRAY AFFECTED AREAS - FRONT BUMPER
TO RESPRAY AFFECTED AREAS - RH FRONT FENDER
TO RESPRAY AFFECTED AREAS - LH FRONT FENDER
TO RESPRAY AFFECTED AREAS - BOOTLID
TO RESPRAY AFFECTED AREAS - REAR BUMPER
TO RESPRAY AFFECTED AREAS - REAR BUMPER DIFFUSER
TO RESPRAY AFFECTED AREAS - END PANEL
TO RESPRAY AFFECTED AREAS - SPARE TYRE PANEL
TO REMOVE AND REFIT AC CONDENSER INCLUDING TOP UP AC GAS
TO REMOVE AND REFIT RADIATOR INCLUDING WATER PRESSURE TEST
TO REMOVE AND REFIT INTERCOOLER
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR
TO REMOVE AND REFIT REAR EXHAUST PIPE FOR FACILITATE REPAIR
TO REMOVE AND REFIT REVERSE SENSOR
TO CHECK AND RECONNECT ALL NECESSARY WIRING
SUNDRIES
RUST PROOFING

~~\$1,200.00~~ 300
~~\$1,500.00~~ 400
~~\$300.00~~ 200
~~\$300.00~~ 200
~~\$250.00~~ X
~~\$250.00~~ X
~~\$300.00~~ 200
~~\$300.00~~ 200
~~\$250.00~~ X
~~\$250.00~~ 200
~~\$250.00~~ X
~~\$150.00~~ 100 X
~~\$150.00~~ X
~~\$250.00~~ X
~~\$150.00~~ 60
~~\$350.00~~ X
~~\$100.00~~ 60
~~\$100.00~~ 30
~~\$50.00~~ 20
~~\$80.00~~ 40 1910

TOTAL: \$7,130.00

TOTAL: \$30,606.26 9,166.97

7% GST: \$2,142.44

\$32,748.70

LS: \$7,300

7 days

Rasul
Hp 90010068

7 days

L/S

29/03/19 @ 1550

Resurvey after repair

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

29/3 - auto wheels - VV in



Service Request Details

Claim

S9M01IG3

Reference

None

Loss Date

27 March 2019

Report Date

28 Mar 2019 4:51:00 PM

Request Date

29 March 2019

Due Date

29 March 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #

SLA2961R

Make

TPVD VOLKSWAGEN

Service Address

...

Primary Contact/Insured

THRONE LANDSCAPE & CONSTRUCTION PTE LTD
47 JALAN PEMIMPIN, #05-07 HALCYON 2, 577200, Singapore
67784018
BNCMSENQUIRY@AXA.COM.SG

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



THRONE LANDSCAPE & CONSTRUCTION PTE LTD

47 Jalan Pemimpin #05-07 Halcyon 2 Singapore 577200

Tel: +65 6778 4018 / +65 6250 9487 Reg. No.: 201001166R

Email: enquiry@throne.sg Web: www.throne.com.sg


11th Mar 2019

TO WHOM IT MAY CONCERN

Dear Sir/Mdm

This letter is to certify that **Mr Balakrishnan Dharmaraj**, holder of Fin No **G 2898455W**, is an employee of Throne Landscape & Construction Pte Ltd, and is allowed to drive the vehicle number **GBF 5344U** daily.

Yours Faithfully,


Sugumaran S/O Rethinam
Managing Director



Date: 28.3.19

To Whom It May Concern

Dear Sir/ Madam

This is authorize my Employee Name Bala Krishnan of
NRIC G2898455W to drive, report and claim for the accident dated 27.3.19 for
vehicle number GBF 53444

Sign & Chop

Sguru



28/3/19 @
2pm

Name of Manager/ In Charge/ Owner MR SUGU (BOSS)

NRIC Number: _____



Re:RE: Re:RE: Re:RE: Re:RE: Re:MANDATE IA - AUTO WHEELS - SLA 2961R

Type

🔔 Question

Message

Hi Pls proceed, tks-VO

Reply

AUTO WHEELS

MOTORWORKS PTE LTD

03th May 2019
AXA INSURANCE

Subject: Accident between SLA2961R and GBF5344U(TP) on 27/03/2019 Along Chancery Lane before Dunearn road Inter section.

We refer to the above case.

We are instructed by our client to file claim for the damages against your insured.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of vehicle No. SLA2961R.

We quantify our client's claim as follows:

1. Cost of Repair (\$7,300 + 7% GST)	S\$	7,811.00
2. Loss of Use (\$150 x 7 COR days + 1 Sunday)	S\$	1,200.00
3. Third Party Insurer Enquiry Fee (\$7.00 + 7% GST)	S\$	7.45
4. Medical Claim Receipt	S\$	126.00
	S\$	
Total	S\$	9144.45

We hereby append the following relevant documents for your perusal:

-  Repair Bill Tax Invoice
-  Third Party Insurer Enquiry Tax Invoice
-  Medical Claim Receipt

Please let us know within the next 7 days from the receipt of this letter, whether you are prepared to accept all the above amount.

Best regards,

Louis Ong
Motor Claims Officer
Auto Wheels Motorworks PTE LTD
Tel : 9192 8963
Email : louisongautowheels@yahoo.com

AUTO WHEELS MOTORWORKS PTE LTD
No 1 BUKIT BATOK CRESCENT
#02-40 WCEGA PLAZA
SINGAPORE 658064

TAX INVOICE

AXA INSURANCE PTE LTD

Invoice Date
2 May 2019

Tel & Fax: 6795 4101

Invoice Number
TG:16930

Reference
VW/JETTA - SLA 2961 R

UEN / GST Reg. No.
201226886H

Description	Quantity	Unit Price	Tax	Amount SGD
LUMPSUM REPAIR FOR SLA 2961 R	1.00	7,300.00	7%	7,300.00
Subtotal				7,300.00
TOTAL SALES GST 7%				511.00
TOTAL SGD				7,811.00

Due Date: 2 May 2019

Received In Good Order & Condition
Goods Sold Are Not Refundable/Return

- ** Any defects or unsatisfied conditions after servicing are to be informed within THREE (3) DAYS from DATE OF INVOICE.
- ** Services rendered will be taken as accepted if no feedback is received within THREE (3) DAYS from DATE OF INVOICE.
- ** Interest rate of 5% per month, calculated on a daily basis, is levied on payment for OVERDUE AMOUNT(s)/ACCOUNT(s) owing to Auto Wheels MotorWorks Pte Ltd after SEVEN (7) DAYS from DATE OF INVOICE.
- ** Cheque should be crossed and make payable to "AUTO WHEELS MOTORWORKS PTE LTD".

Customer's Signature/ Co. Stamp Auto Wheels Motorworks Pte Ltd
E. & O. E.





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19005596/R1gb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 18-11-2019



ATTN: VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 5344U	Veh. Inspected	SLA 2961R
Policy No.	P2053048	Coverage (\$)	0.00
Claim No.	S9M01IG3	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	29/03/2019

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN JETTA 1.4 (A)	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WVWZZZ1KZAM143412	Colour	BLACK
Odometer	201507	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40Z R18	MICHELIN	6 mm
L/H Front Tyre	225/40Z R18	MICHELIN	6 mm
R/H Rear Tyre	225/40Z R18	MICHELIN	6 mm
L/H Rear Tyre	225/40Z R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/03/2019	Inspection Date	29/03/2019
Survey held at	48 TOH GUAN ROAD EAST #04-142		
Repairer	AUTO WHEELS MOTORWORKS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 2961R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,210.20	-
1	BONNET LOCK (CONSISTENT)	SERVICEABLE	365.10	-
1	FRONT EMBLEM (CONSISTENT)	CRACKED	95.40	95.40
1	FRONT LOGO - TSI (CONSISTENT)	SERVICEABLE	92.10	-
1	FRONT GRILLE (CONSISTENT)	CRACKED	967.30	967.30
10	FRONT GRILLE CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,156.30	1,156.30
10	FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
2	FRONT BUMPER RETAINER (CONSISTENT)	SERVICEABLE	114.60	-
2	FRONT BUMPER BRACKET (CONSISTENT)	SERVICEABLE	188.40	-
1	FRONT BUMPER LOWER CENTRE GRILLE (CONSISTENT)	SERVICEABLE	355.20	-
1	FRONT BUMPER TOWING COVER (CONSISTENT)	SERVICEABLE	98.10	-
2	FRONT BUMPER PORTECTOR (CONSISTENT)	SERVICEABLE	486.40	-
1	FRONT BUMPER LOWER SPOILER (CONSISTENT)	CUT	574.10	574.10
1	FRONT NUMBER PLATE GARNISH (CONSISTENT)	SERVICEABLE	143.70	-
1	AIR DUCT (CONSISTENT)	SERVICEABLE	453.10	-
1	RADIATOR TOP COVER (CONSISTENT)	SERVICEABLE	365.10	-
10	RADIATOR TOP COVER CLIPS (CONSISTENT)	SERVICEABLE	30.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	297.50	-
2	FRONT REINFORCEMENT BRACKET (CONSISTENT)	SERVICEABLE	188.40	-
1	FRONT REINFORCEMENT (CONSISTENT)	SERVICEABLE	576.30	-
1	SUPPORT PANEL - TOP (CONSISTENT)	SERVICEABLE	474.10	-
1	SUPPORT PANEL (CONSISTENT)	SERVICEABLE	896.30	-
2	HEADLAMP (CONSISTENT)	NOT NECESSARY	1,978.80	-
2	HEADLAMP PANEL (CONSISTENT)	NOT NECESSARY	298.40	-
2	FOGLAMP (CONSISTENT)	NOT NECESSARY	598.60	-
2	FOGLAMP COVER (CONSISTENT)	NOT NECESSARY	288.40	-
1	INTERCOOLER (CONSISTENT)	NOT NECESSARY	1,245.60	-
1	CONDENSER (CONSISTENT)	NOT NECESSARY	894.10	-

Report Ref No. CC4/ASM19005596/R1gb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	CONDENSER AIR GUIDE (CONSISTENT)	NOT NECESSARY	266.40	-
1	RADIATOR (CONSISTENT)	NOT NECESSARY	911.30	-
1	LH FRONT FENDER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	RH FRONT FENDER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BOOTLID (CONSISTENT)	BENT	1,342.10	1,342.10
2	BOOTLID LAMP (CONSISTENT)	CRACKED	698.40	698.40
2	BOOTLID HINGE (CONSISTENT)	NOT NECESSARY	324.60	-
1	REAR LOGO- JETTA (CONSISTENT)	NECESSARY	76.40	76.40
1	BOOTLID LOCK (CONSISTENT)	CUT	299.50	299.50
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,081.30	1,081.30
10	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER DIFFUSER (CONSISTENT)	DEFORMED	567.30	567.30
2	REAR BUMPER RETAINER (CONSISTENT)	NOT NECESSARY	114.60	-
2	REAR BUMPER BRACKET (CONSISTENT)	NOT NECESSARY	188.40	-
2	REAR BUMPER REFLECTOR (CONSISTENT)	NOT NECESSARY	298.60	-
2	REAR NUMBER PLATE LAMP (CONSISTENT)	NOT NECESSARY	366.20	-
1	REAR BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	197.50	-
1	REAR REINFORCEMENT (CONSISTENT)	BENT	453.10	453.10
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	569.20	-
1	SPARE TYRE PANEL (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	299.60	-
1	REAR WEATHERSTRIP (CONSISTENT)	NECESSARY	287.90	287.90
2	REVERSE SENSOR HOLDER (CONSISTENT)	NECESSARY	64.20	64.20
1	REAR EXHAUST PIPE (CONSISTENT)	NOT NECESSARY	1,654.20	-
2	REAR EXHAUST PIPE FINISHER (CONSISTENT)	NOT NECESSARY	462.60	-
	LESS 10% DISCOUNT		-2,510.50	-781.33
			22,594.50	7,031.97
2	REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	446.40	200.00
	LESS 10% DISCOUNT		-44.64	-
			401.76	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	SCRATCHED	100.00	35.00
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	CRACKED	100.00	35.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	COOLANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	ATF OIL (SN) (CONSISTENT)	NOT NECESSARY	150.00	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	50.00	20.00
			530.00	90.00
<u>LABOUR</u>				
	LABOUR FOR FACILITATE REPAIR - FRONT PORTION. INCLUSIVE OF THE REPAIR OF BONNET.		1,800.00	300.00
	LABOUR FOR FACILITATE REPAIR - REAR PORTION. INCLUSIVE OF THE REPAIR OF END PANEL.		1,500.00	400.00
	TO RESPRAY AFFECTED AREAS - BONNET.		300.00	200.00
	TO RESPRAY AFFECTED AREAS - FRONT BUMPER.		300.00	200.00
	TO RESPRAY AFFECTED AREAS - RH FRONT FENDER.	NOT NECESSARY	250.00	-
	TO RESPRAY AFFECTED AREAS - LH FRONT FENDER.	NOT NECESSARY	250.00	-
	TO RESPRAY AFFECTED AREAS - BOOTLID.		300.00	200.00
	TO RESPRAY AFFECTED AREAS - REAR BUMPER.		300.00	200.00
	TO RESPRAY AFFECTED AREAS - REAR BUMPER DIFFUSER.	NOT NECESSARY	250.00	-
	TO RESPRAY AFFECTED AREAS - END PANEL.		250.00	200.00
	TO RESPRAY AFFECTED AREAS - SPARE TYRE PANEL.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIT AC CONDENSER INCLUDING TOP UP AC GAS.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT RADIATOR INCLUDING WATER PRESSURE TEST.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT INTERCOOLER.	NOT NECESSARY	250.00	-
	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR.		150.00	60.00
	TO REMOVE AND REFIT REAR EXHAUST PIPE FOR FACILITATE REPAIR.	NOT NECESSARY	350.00	-
	TO REMOVE AND REFIT REVERSE SENSOR.		100.00	60.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		100.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RUST PROOFING.		80.00	40.00
			7,080.00	1,890.00
GRAND TOTAL			30,606.26	9,211.97
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,300.00

Report Ref No. CC4/ASM19005596/R1gb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.