

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0429/2019/DY
Date : 4-Apr-19

Vehicle not in workshop. Kindly arrange for survey.

Your insured vehicle : **SLH 2381 C**

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Ms. Cheng Sok Khim
Address : Blk 225 Lorong 8 Toa Payoh
#05-66

Singapore 310225

Telephone : HP +65 92988611

Type of Claim : Third Party Claims

Policy No. : 2100508879-01

Vehicle No : **SLN 2885 J**

Model Code : A4 Sedan 1.4 TFSI S

Model / Year : 27/4/2017

Engine No : CVN 033370

Chassis No : WAUZZZF43HA128523

Mileage :

Date In :

Liability : -

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 25-Mar-19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Kah 97495789
WP
4/4/19 @ 12pm
Resurvey after repair
sure lkkauto.com
4 days

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 2885 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	s/n \$ 360.00	✓
2	To dismantle rear bumper. To repair rhs rear fender. Re-organize crash management components. Reinstall all parts removed.	600 \$ 1,200.00	900
3	To respray rear bumper and rhs rear fender.	\$ 1,500.00	1200-
4	To carry out diagnostic check.	s/n \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant