

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Date : 29/3/2019

To : AXA

Steve (LKK) WHL Repaired 2/4/19 3.30pm
8322 8813 P/P
Ry Dismantle & def spray
3 days

Dear Sir / Madam:

RE: VEHICLE REPAIR QUOTATION

Owner : CHRISTOPHER YAN

Policy : B27831179

Model : BMW 320i

Reg : SGJ5589U

Accident Date : 9/2/2019

We are please to submit our estimate of repairs to the abovemention vehicle.

		Parts	
		QTY	Net price
1	LH BI XENON HEADLIGHT X1	1	\$ 2,119.70 ?
2	RH BI XENON HEADLIGHT X1	1	\$ 2,119.70 X NN
3	FRT BUMPER PANEL PRIMED Dismantle	1	\$ 1,047.80 ?
4	FLAP TOWING EYE PRIMED	1	\$ 43.25 X NN
5	LH COVER SPRAY NOZZLE PRIMED	1	\$ 43.25 X NN
6	RH COVER SPRAY NOZZLE PRIMED	1	\$ 43.25 X NN
7	INSERT AIR INLET MIDDLE	1	\$ 119.65 X NN
8	MOUNTING SIDE PANEL FRT TOP LH	1	\$ 19.20 ?
8	MOUNTING SIDE PANEL FRT TOP RH	1	\$ 19.20 ?
10	MOUNTING SIDE PANEL FRT BOTTOM LH	1	\$ 19.20 ?
11	MOUNTING SIDE PANEL FRT BOTTOM RH	1	\$ 19.20 ?
12	MOUNTING SUPPORT	1	\$ 14.05 ?
13	SUPPORT CENTER	1	\$ 11.35 ?
14	RIVET	20	\$ 10.00 / NEC
15	SUPPORT FOG LAMP LH	1	\$ 41.85 ?
16	SUPPORT FOG LAMP RH	1	\$ 41.85 X NN
17	REPAIR KIT HOLDER BUMPER FRT	1	\$ 86.55 ?
18	LH FINISHER ROD	1	\$ 99.45 ?
19	RH FINISHER ROD	1	\$ 99.45 X NN
20	PARTIALLY OPEN GRID LH	1	\$ 77.10 ?
21	PARTIALLY OPEN GRID RH	1	\$ 77.10 X NN
22	GRILIE FRT LH	1	\$ 128.00 ?
23	GRILIE FRT RH	1	\$ 128.00 ?
24	LICENCE PLATE BASE	1	\$ 69.25 X NN
25	FRT BUMPER TOP CARRIER	1	\$ 415.50 ?
26	SHOCK ABSORBER FRT	1	\$ 45.00 ?
27	FRT LH DEFORMATION ELEMENT	1	\$ 111.90 ?
28	FRT RH DEFORMATION ELEMENT	1	\$ 111.90 X NN
29	FRT BUMOER BOTTOM CARRIER	1	\$ 147.50 ?
30	DEFORMATION ELEMENT FRT LH	1	\$ 94.95 ?
31	DEFORMATION ELEMENT FRT RH	1	\$ 94.95 X NN
32	DAMPER FOR CURB DESCENT	1	\$ 5.00 ?
33	FRT LH AXLE SUPPORT	1	\$ 32.20 ?
34	FRT RH AXLE SUPPORT	1	\$ 32.20 X NN
35	SUPPORT	1	\$ 9.75 X NN

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Total parts price: \$ 7597.70

	Labour
1 SUNDRIES	\$ 150.00 30
2 LABOUR TO REMOVE,REALIGN,REPLACE AND REPAIR FRONT BUMPER LH FRONT FENDER, LH HEADLAMP ASSY AND ALL AFFECTED AREAS . 340 hrs	\$2,400.00 340
3 LABOUR TO PUTTY AND RESPRAY FRONT BUMPER AND LH FRONT FENDER AND ALL AFFECTED AREAS 44	\$1,800.00 440
4 TUFF KOTE,ANTI RUST PRESERVATION, BODY CAVITY PRESERVATIONS. (PER PANEL \$60 NETT)	\$ 120.00 60
5 TO CONDUCT ECU PROGRAMMING CHECK & CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULE.(NETT)	\$ 600.00 ✓
6 HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR.(NETT)	\$ 200.00 ✓

TOTAL LABOUR \$ 5,270.00

Sub Total :	Parts + Labour	
GST 7%	7597.70 + 5270.00 =	\$12,867.70
Grand Total :		\$ 900.74 12,868.25#
		<u>\$ 13,768.44</u>

The above estimates are base on visual inspection and it is possible that further materials and labour may be required up dismantling. Should this occur, we will submit supplementary quotation for further approval.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: