

22/03/2002

ASS. REC. BY:

REF: CS/1CS 19005615 / EV d302

Special Instruction:

Sulvevor

Sulve

ASSIGNMENT (Office)

From (Person):

Desmond Lee

of

ECIS

Date/Time: 27.3.19 3.30p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 28784

Insured:

SJD 9198 P

at Workshop m/s

Kah motor

Tel:

65145481

of

255 Alexandra Road Singapore

Policy No:

Claim No:

DMP C1900087 H / DL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26.3.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time:

27.3.19 10.46 a.m

Person Contacted:

Sin Hui

Vehicle IN / OUT

Date/Time

Action/Instruction

( V ) Estimate

SJA 28784 - CS/TP 12009872 / R41

D.O.A - 24/3/2012

SJD 9198 P - X

16/4/19

Final fig \$ 7831.43 confirmed by email (Ref 890730, 5376)

Surveyor

Steve

REF: JCS

# ASSIGNMENT

From:

Date: 3/4/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJA 2878Y

at Workshop m/s

Kah Motor

of No 255 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11am

Jack

(Policy Condition)

8288 6309

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJA 2878Y

Yr Regn:

22/11/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HRV

c.c

1.5

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

43619

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHM R4 1830GX 200888

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

4

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

26/3/19

D.O.I.

3/4/19

Survey held at

Kah Motor, Alexandra rd

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 16 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 16/4 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

390

id

360

Report Format :

merimen

Lump Sum / I.B.I. (\$

7831.43

## Nivitha (LKK Auto)

---

**From:** Desmond Lee Ker Wen (ECICS, Claims) <Desmond\_Lee@ecics.com.sg>  
**Sent:** Wednesday, 27 March 2019 3:30 PM  
**To:** Jack Ng; assignments  
**Cc:** ECICS Claims  
**Subject:** RE: ACCIDENT BEWTEEN SJA 2878 Y AND YOUR INSURED SJD9198 P // Our Ref No: DMPC1900087H / DL  
**Attachments:** GIA REPORT.PDF

**Importance:** High

10.46 am @ 29/3/2019  
VNI  
Sin Hui

Without Prejudice

Dear Jack  
Liability is clear.

Dear LKK

Please assist with PRS of the above vehicle.

Thank you.

Best regards

Desmond Lee

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email [Desmond\\_Lee@ecics.com.sg](mailto:Desmond_Lee@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** ECICS Claims  
**Sent:** Wednesday, 27 March 2019 3:10 PM  
**To:** Desmond Lee Ker Wen (ECICS, Claims)  
**Cc:** Jack Ng; ECICS Claims  
**Subject:** RE: ACCIDENT BEWTEEN SJA 2878 Y AND YOUR INSURED SJD 9198 P

Dear Desmond

FYNA.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email [crystabelle\\_tan@ecics.com.sg](mailto:crystabelle_tan@ecics.com.sg) Web [www.ecics.com.sg](http://www.ecics.com.sg)

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

---

**From:** Jack Ng [mailto:[jackng@honda.com.sg](mailto:jackng@honda.com.sg)]

**Sent:** Tuesday, 26 March, 2019 7:00 PM

**To:** ECICS Claims

**Subject:** ACCIDENT BEWTEEN SJA 2878 Y AND YOUR INSURED SJD 9198 P

Dear all,

Kindly assist to register for direct settlement, attached is the GIA report.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

*Jack Ng*

*Hp: 8288 6309*

*Email: [jackng@honda.com.sg](mailto:jackng@honda.com.sg)*

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: [www.honda.com.sg](http://www.honda.com.sg)



Visit our  
Facebook page



*Please consider the environment before printing this email*

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4359F
<b>Vehicle Details</b>	
Vehicle No.:	SJA2878Y
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L15B4530888
Chassis No.:	JHMRU1830GX200888
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$23,790.00
Original Registration Date:	22 Nov 2016
First Registration Date:	22 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$20,306.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Nov 2026
PARF Rebate Amount:	\$15,229.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,334.00
COE Rebate Amount:	\$40,711.00
<b>Total Rebate Amount:</b>	<b>\$55,940.00</b>

The information contained herein is correct as at 03 Apr 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	26/03/2019 18:50
Date Of Accident	26/03/2019 08:05
Exact Location Of Accident	TOWARDS LOYANG (TPE/SLE)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJA2878Y
Insured/Policyholder	
Name Of Registered Owner	WONG WOON HENG
NRIC No	S1474359F
Email Address	KADEY.WONG@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-83833828
Alternative Phone No	OFFICE-83833828
Vehicle Particulars	
Manufacturer	HONDA
Model	HR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	WONG WOON HENG
NRIC No	S1474359F
Date Of Birth	22/11/1961
Occupation	INDOOR
Date Of Driving Pass	11/03/1983
Driving Experience	36 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83833828
Fax Number	
Contact Number	OFFICE-83833828
Email Address	KADEY.WONG@YAHOO.COM.SG

Address	6 JALAN PELEPAH
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD9198P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Sketch Plan Pg. 1

Vehicle Number: \_\_\_\_\_

## SKETCH PLAN




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


While driving along Loyang, my vehicle was stalled  
due to slow traffic. suddenly the vehicle No. SJD 9198P  
unable to stop in time. hit on my rear. no one is injured.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Steve [Signature] 4/4/19  
5 days  
p/p  
By bel spg

03/04  
LKK  
9am  
11.30am

Clear

**QUOTATION**

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: ECICS LIMITED	<b>Document No.</b>	: SQT19001380	<b>Page</b>	1
	7 TEMASEK BOULEVARD	<b>Date</b>	: 26. Mar 2019		
	#10-01 SUNTEC TOWER FIVE	<b>Customer No.</b>	: WZE001		
	SINGAPORE 038987	<b>Svc Advisor</b>	:		
<b>Registration No</b>	: SJA2878Y	<b>Engine No</b>	: L15B4530888		
<b>Chassis No</b>	: JHMRU1830GX200888	<b>Date   Time</b>	: 26. Mar 2019 4:52:35 PM		
<b>Model</b>	: HRV LX-SIN CVT YM 2016	<b>Surveyor Name</b>	:		
<b>Owner's Name</b>	: WONG WOON HENG	<b>Survey Date</b>	:		
<b>Ins Policy No.</b>	:	<b>Authorisation Date</b>	:		
<b>Date of Accident</b>	: 26/3/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
04715-T7A-900ZZ	FACE,RR.BUMPER / 00	1	463.70	25	347.77 ✓	24.34	372.11
71593-T7A-J00	SPACER R,RR.BPR S / N/C	1	16.90	25	12.67 ✓	0.89	13.56
71598-T7A-J00	SPACER,L,RR.BPR S / N/C	1	16.90	25	12.67 ✓	0.89	13.56
91505-TM8-003	CLIP,BUMPER / N/C	8	2.30	25	13.80 ✓	0.97	14.77
68100-T7A-J20ZZ	TAIL GATE COMP / 00	1	855.70	25	641.77 ✓	44.92	686.69
74440-T7A-003	WEATHERSTRIPTAILGATE ? X N/A	1	98.70	25	74.02	5.18	79.20
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER ? X N/A	1	105.30	25	78.97	5.53	84.50
74813-T5A-003	STRIKER ASSYTAILGATE ? X N/A	1	24.70	25	18.52	1.30	19.82
75722-T7W-A01	EMBLEMRR. / N/C	1	13.30	25	9.97 ✓	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC / N/C	1	14.50	25	10.87 ✓	0.76	11.63
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ? X N/A	1	320.00		320.00	22.40	342.40
74940-SZW-003	BUZZER ASSYSMART ? X N/A	1	61.30	25	45.97	3.22	49.19
66100-T7A-300ZZ	PANEL COMPRR. X R	1	373.10	25	279.82	19.59	299.41
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER / N/C	1	19.30	25	14.47 ✓	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 / N/C	1	8.50	25	6.37 ✓	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER / N/C	1	19.30	25	14.47 ✓	1.01	15.48
76711-T6A-003	CAPPVOT / N/C	1	4.80	25	3.60 ✓	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD / N/C	4	5.30	25	15.90 ✓	1.11	17.01
91502-S70-003	FASTENER B / N/C	2	5.30	25	7.95 ✓	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD / N/C	2	3.80	25	5.70 ✓	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / N/C	2	60.00		120.00 ✓	8.40	128.40
<b>Sum Item</b>					<b>2055.28</b>	<b>143.88</b>	<b>2,199.16</b>
BOSUN	SUNDRIES	1	100.00 / 50 ✓		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	150.00 / 100 ✓		150.00	10.50	160.50
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	150.00 X		150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00 / 280 ✓		380.00	26.60	406.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	380.00 / ✓		380.00	26.60	406.60
BOMISC1	REMOVE & RE-INSTALL REAR VIEW CAMERA (N)	1	450.00 / ✓		450.00	31.50	481.50

Printed on 27/3/2019 8:15:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: ECICS LIMITED	Document No.	: SQT19001380	Page	2
	7 TEMASEK BOULEVARD	Date	: 26. Mar 2019		
	#10-01 SUNTEC TOWER FIVE	Customer No.	: WZE001		
	SINGAPORE 038987	Svc Advisor	:		
Registration No	: SJA2878Y	Engine No	: L15B4530888		
Chassis No	: JHMRU1830GX200888	Date   Time	: 26. Mar 2019 4:52:35 PM		
Model	: HRV LX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: WONG WOON HENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 26/3/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	450.00	/ ✓	450.00	31.50	481.50
BODAMKIT	WINDSCREEN DAM KIT.	1	200.00	150 ✓	200.00	14.00	214.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00	/ ✓	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	/ ✓	560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	560 ✓	800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS	1	6000.00	1680 ✓	6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4500.00	1350 ✓	4500.00	315.00	4815.00
Sum Labor					14680.00	1,027.60	15,707.60

Survey By \_\_\_\_\_  
Date & Time \_\_\_\_\_  
Excess \_\_\_\_\_  
Status \_\_\_\_\_  
Signature \_\_\_\_\_

Total Amount 16,735.28 1,171.48 17,906.76  
Total (Inclusive of GST) 17,906.76  
16,738.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 27/3/2019 8:15:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer:** WZE001 / ECICS LIMITED  
**Chassis No:** JHMRU1830GX200888  
**License No:** SJA2878Y  
**Mileage:** 39072  
**Engine No:** L15B4530888

**Document No:** SVO19021251  
**Printed By:** JACKNG  
**Order Date:** 3. April 2019  
**Order Time:** 11:04:00 AM  
**Service Advisor:** JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incld GST
	SUPPLEMENTARY PART						
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
71593-T7A-J00	SPACER R,RR.BPR S	1	16.90	25	12.67	0.89	13.56
71598-T7A-000	SPACERL,RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
68100-T7A-J20ZZ	TAIL GATE COMP	1	855.70	25	641.77	44.92	686.69
75722-T7W-A01	EMBLEMRR.	1	13.30	25	9.97	0.70	10.67
75725-T8N-T00	EMBLEM,RR. I-VTEC	1	14.50	25	10.87	0.76	11.63
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
90661-SC7-003	GROMMET SCREW	2	2.30	25	3.45	0.24	3.69
	<b>SUM PARTS:</b>				<b>1,241.43</b>	<b>86.90</b>	<b>1,328.33</b>
BOSUN		1	50.00		50.00	3.50	53.50
	SUNDRIES						
BOJSE	1718	1	120.00		120.00	8.40	128.40
	BODY JOINT SEALANT FOR TAILGATE						
BML02I		1	280.00		280.00	19.60	299.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R	1729	1	380.00		380.00	26.60	406.60
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOMISC1	1729	1	450.00		450.00	31.50	481.50
	REMOVE & RE-INSTALL REAR VIEW CAMERA (N)						
BOMISC1		1	450.00		450.00	31.50	481.50
	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)						
BODAMKIT		1	150.00		150.00	10.50	160.50
	WINDSCREEN DAM KIT.						
BG02R	1438	1	560.00		560.00	39.20	599.20
	REPLACE RR. WINDSCREEN.(N)						
BKTG02R	1729	1	560.00		560.00	39.20	599.20
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BMI03D	1438	1	560.00		560.00	39.20	599.20
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BKRP02M	1729	1	1,680.00		1,680.00	117.60	1,797.60
	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.						



## SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** WZE001 / ECICS LIMITED  
**Chassis No:** JHMRU1830GX200888  
**License No:** SJA2878Y  
**Mileage:** 39072  
**Engine No:** L15B4530888

**Document No:** SVO19021251  
**Printed By:** JACKNG  
**Order Date:** 3. April 2019  
**Order Time:** 11:04:00 AM  
**Service Advisor:** JACK NG

BP06R	1718	1	1,350.00	1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)					
			<b>SUM LABOUR:</b>	<b>6,590.00</b>	<b>461.30</b>	<b>7,051.30</b>
			<b>TOTAL SGD</b>	<b>7,831.43</b>	<b>548.20</b>	<b>8,379.63</b>
<b>Total Payable (SGD)</b>						<b>8,379.63</b>

GST Amount is calculated from individual line(s)

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 16 April 2019 10:31 AM  
**To:** Jack Ng; Steve Chen (LKK Auto); SUR  
**Subject:** RE: FINALIZATION FOR SJA 2878 Y

Dear Jack,

WITHOUT PREJUDICE

Confirmed finalize amount \$7831.43 before GST @ 5 working days.

**Kindly send Final invoice and all supporting documents directly to ECICS INSURANCE**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jack Ng <jackng@honda.com.sg>  
**Sent:** Tuesday, 16 April 2019 9:26 AM  
**To:** Steve Chen (LKK Auto) <SteveChen@lkkauto.com>  
**Subject:** FINALIZATION FOR SJA 2878 Y  
**Importance:** High

Dear Steve,

We enclosed the total final repair costs for,

Vehicle No.	<b>SJA 2878 Y</b>
Final Repair Costs (exclude GST)	<b>S\$8,379.63</b>
Repair Period* (Days)	<b>5 WORKING DAYS</b>

**\*Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records

Thank you and have a great days ahead

Cheers !!!

Best Regards,

*Jack Ng*

*Hp: 8288 6309*

*Email: [Jackng@honda.com.sg](mailto:Jackng@honda.com.sg)*

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: [www.honda.com.sg](http://www.honda.com.sg)



Visit our  
Facebook page



**Please consider the environment before printing this email**

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)






















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Apr 2019 13:59 <a href="#">Edit Reg</a>		27 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$7,831.43</b> <a href="#">Edit Estimates</a>	<b>S\$7,831.43</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: <b>wong woon heng</b> , ID: S1474359F									
Vehicle Reg. No.:	<b>SJA2878Y</b>	Date of Loss:	26/03/2019 08:00 - :59 [28 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / DMPC1900087H/DL</b>	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SJD9198P</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Kah Motor Co Sdn Bhd (ALEXANDRA)</b> 255 ALEXANDRA ROAD, - Alexandra - Tel:								
Handling Insurer:	<b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Desmond Lee</b> - 6303 0167]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 09/04/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SJA2878Y (DMPC1900087H/DL)**  
**[SJD9198P]**  
**TP**  
**wong woon heng**  
**Mar 26 2019 8:00AM**  
**[-]**  
**Kah Motor Co Sdn Bhd**

Upload Documents	Upload Photos	Compose New Letter	<b>View</b> View in Browser <input type="button" value="v"/>	
<b>Photos/Images</b>			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
2	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
3	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/04/19 08:13	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
15	04/04/19 08:13	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/04/19 08:13	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
17	16/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
18	16/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
19	16/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
20	16/04/19 09:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/19 13:57	Supplementary	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			





## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19005615/EVD3E2

Date: 25/04/2019

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle  
No : SJA2878Y

Insured Vehicle No : SJD9198P

Date of Loss: 26/03/2019

Nature of Claim: TP

Claim No: DMPC1900087H/DL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJA2878Y

Make &amp; Model: HONDA HR-V, 1.5 (A)

Engine No: L15B4530888

Reg. Date: 22/11/2016 (Man. Year: 2016)

Chassis No: JHMRU1830GX200888

Colour: Black

Odometer: 43619 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,158.73	1,291.43	867.30	40.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,580.00	6,540.00	8,040.00	55.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,738.73</b>	<b>7,831.43</b>	<b>8,907.30</b>	<b>53.21</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,171.71</b>	<b>548.20</b>	<b>623.51</b>	<b>53.21</b>
<b>Nett Amount (S\$)</b>	<b>17,910.44</b>	<b>8,379.63</b>	<b>9,530.81</b>	<b>53.21</b>

INSPECTION

Date of Assignment: 27/03/2019

Date Inspected: 03/04/2019 Inspected At:

Kah Motor Co Sdn Bhd (ALEXANDRA)  
255 ALEXANDRA ROAD  
Singapore 159937

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2019)
<b>Parts:</b>	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJA2878Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,RR.BUMPER	Dented	347.77 FS	*347.77 FS
2	1		*SPACER R,RR.BPR S	Necessary	12.67 FS	*12.67 FS
3	1		*CLIP, BUMPER (8PCS)	Necessary	13.80 FS	*13.80 FS
4	1		*TAIL GATE COMP	Dented	641.77 FS	*641.77 FS
5	1		*WEATHERSTRIPTAILGATE	Not Necessary	74.02 FS	*- FS
6	1		*SWITCH ASSYTAILGATE OPENER	Not Necessary	78.97 FS	*- FS
7	1		*STRIKER ASSYTAILGATE	Not Necessary	18.52 FS	*- FS
8	1		*EMBLEMRR.	Necessary	9.97 FS	*9.97 FS
9	1		*EMBLEM,RR.I-VTEC	Necessary	10.87 FS	*10.87 FS
10	4		*ACT RR.SENSOR	Not Necessary	320.00 FS	*- FS
11	1		*BUZZER ASSYSMART	Not Necessary	45.97 FS	*- FS
12	1		*PANEL COMPRR.	Repair	279.82 FS	*- FS
13	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
14	1		*DAMPERSTD 5X5	Necessary	6.37 FS	*6.37 FS
15	1		*RUBBER CL/WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
16	1		*CAPPIVOT	Necessary	3.60 FS	*3.60 FS
17	1		*FASTENER BW/SHIELD (4PCS)	Necessary	15.90 FS	*15.90 FS
18	1		*FASTENER B (2PCS)	Necessary	7.95 FS	*7.95 FS
19	2		*FASTENER AW/SHIELD	Necessary	5.70 FS	*5.70 FS
20	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
21	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
22	1		*GROMMET SCREW (2PCS)	Necessary	3.45 FS	*3.45 FS
23	1		*SPACER,L.RR.BPR S	Necessary	12.67 FS	*12.67 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>2,158.73</b>	<b>1,291.43</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	BODY JOINT SEALANT FOR TAILGATE	New	150.00	120.00
2	BODY JOINT SEALANT FOR END PANEL	New	150.00	0.00
3	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	380.00	280.00
4	REMOVE & RENEW REVERSE SENSORS-4PCS	New	380.00	380.00
5	REMOVE & RE-INSTALL REAR VIEW CAMERA	New	450.00	450.00
6	RESET & CALLIBRATE SMART ENTRY SYSTEM	New	450.00	450.00
7	WINDSCREEN DAM KIT	New	200.00	150.00
8	REPLACE RR.WINDSCREEN	New	560.00	560.00
9	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	560.00	560.00
10	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	800.00	560.00
11	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS	New	6,000.00	1,680.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6p)	New	4,500.00	1,350.00
Gross Labour Cost (S\$)			<b>14,580.00</b>	<b>6,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >