

ASTECT AUTO PTE LTD
K1 KAKI BUKIT AVE 6
1-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO: SKW 7216Y

PARTICULAR	
FRONT BUMPER	
FRONT BUMPER LAMP N/S	
FRONT BUMPER FOG LAMP N/S	
FRONT BUMPER SIDE HOLDER	
FRONT BUMPER CLIPS	
FRONT BUMPER REINFORCEMENT	
FRONT BUMPER NOZZLE COVER	
FRONT BUMPER NOZZLE N/S	
FRONT GRILLE SPORT	
HEADLAMP N/S	
HEADLAMP TOP BRACKET N/S	
FRONT SUPPORT PANEL	
FRONT FENDER N/S	
FRONT FENDER INNER SHIELD	
FRONT FENDER INNER SHIELD	
FRONT FOG LAMP GARNISH N/S	
BONNET	
HEADLAMP BALLAST N/S	
FRONT SHOCK ABSORBER N/S	
FRONT KNUCKLE ARM N/S	
FRONT KNUCKLE ARM BEARING	
FRONT LOWER ARM N/S	
FRONT DCC CONTROL UNIT	
FRONT SPORT RIM N/S	
FRONT TYRE N/S	

LABOUR CHARGES:	
TO CHECK WIRING	
TO DISMANTLE & REPLACING F	
TO CONDUCT WHEEL ALIGNMENT	
TO REFILL AIR CON GAS	
TO DISMANTLE & REFIX DCC COIL	
TO SPRAY RUST PROOFING	
LABOUR FOR PANEL BEATING &	
TO PUTTY & SPRAY PAINTING	

1,031.7+

311.6+

398.5+

65.5+

50.0+

566.5+

28.5+

215.0+

3,598.6+

468.4+

456.2+

215.0+

50.0+

105.0+

485.0+

655.3+

225.0+

=

8,915.8*

8,915.8*

80.0%

7,132.64*

30.0+

120.0+

60.0+

100.0+

80.0+

30.0+

600.0+

750.0=

1,770.0*

1,770.0+

7,132.64=

8,902.64*

8,902.64*

80.0%

7,122.112*

L/S \$7,100

Not Authorized

Handwritten signature

h/s 7100

521

29/3/19

DIS	\$1,248.50	
CN	\$311.60	
CN	\$388.50	
CN	\$105.00	
ser	\$50.00	
ser	\$645.30	
380	\$28.50	
CN	\$315.60	
11	\$950.00	X
CN	\$3,850.00	
R	\$115.00	X
CN	\$866.10	
Buc	\$699.20	
2011	\$288.30	
my	\$50.00	
gnd	\$105.00	
R	\$1,266.20	X
shut	\$485.00	
11	\$615.00	X
381	\$655.30	
ser	\$350.00	
11	\$619.20	X
R	\$3,885.00	X
R	\$1,085.00	X
ser	\$250.00	X
	\$19,227.30	

97

\$80.00	30
\$180.00	120
\$150.00	60
\$150.00	100
\$250.00	80
\$80.00	30
\$1,080.00	600
\$1,500.00	750
TO	\$22,697.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey color after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

8902.64
7122