EACTECT AL	JTO PTE LTD	Not Adorisal
		1 1100
BLK1 KAKI B		1/25
#01-46,48,50 AUTOBAY		()
SINGAPORE	417883	, 34 (
VEHICLE NO:S	KW 7216Y	29/3/19
QTY		
1 PCS	FRONT BUMPER	7 /5 \$1,248.50
1 PCS	FRONT BUMPER LAMP N/S	(re \$311.60 _
1 PCS	FRONT BUMPER FOG LAMP N/S	(ne \$388.50_
PCS	FRONT BUMPER SIDE HOLDER N/S 65-10	cn \$105.00 -
1 SET	FRONT BUMPER CLIPS	re \$50.00
1 PCS	FRONT BUMPER REINFORCEMENT \$ 6.50	Sel \$645.30
1 PCS	FRONT BUMPER NOZZLE COVER N/S	3 Ro \$28.50
1 PCS	FRONT BUMPER NOZZLE N/S 215.00	cre \$315.60
1 PCS	FRONT GRILLE SPORT	1 1 \$950.00 €
1 PCS	HEADLAMP N/S 3598.60	CM \$3,850.00
1 PCS	HEADLAMP TOP BRACKET N/S	↑ \$115.00 ×
1 PCS	FRONT SUPPORT PANEL 46 & 40	C/L \$866.10
1 PCS	FRONT FENDER N/S 456- 20	Bu (\$699.20
1 PCS	FRONT FENDER INNER SHIELD N/S 2/5	Tom \$288.30
1 SET	FRONT FENDER INNER SHIELD CLIPS N/S	My \$50.00
1 PCS	FRONT FOG LAMP GARNISH N/S	gn-a \$105.00
1 PCS	BONNET	\$1,266.20 ×
1 PCS	HEADLAMP BALLAST N/S	8 hur \$485.00
1 PCS	FRONT SHOCK ABSORBER N/S	√ 1 \$615.00 ✓
1 PCS	FRONT KNUCKLE ARM N/S	\$655.30
1 PCS	FRONT KNUCKLE ARM BEARING N/S 2 25.00	Nu \$350.00
1 PCS	FRONT LOWER ARM N/S	\$619.20
1 PCS	FRONT DCC CONTROL UNIT	\$3,885.00 \$
1 PCS	FRONT SPORT RIM N/S	(U U , C W1,000.00 M
1 PCS	FRONT TYRE N/S	\$250.00 ×
		\$19,227.30
	LABOUR CHARGES:	
	TO CHECK WIRING	\$80.00 3
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	\$180.00 /2
	TO CONDUCT WHEEL ALIGNMENT	\$150.00
	TO REFILL AIR CON GAS	\$150.00
	TO DISMANTE & REFIX DCC CONTROL UNIT	\$250.00 80
	TO SPRAY RUST PROOFING	\$80.00 3
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1.080.00 \(\)
	TO PUTTY & SPRAY PAINTING	\$1,500.00 7 TO \$22,697.30
		TO \$22,697.30

LKK Auto Consultants hence notify the Recount of the following:

- To resorvey outere after spray painting
- To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation.
- Third party survey is a sal Vithout Prejudice" basis
- No illegal medification is allowed.
- Supplementary item(s, most be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8902.69 7122