

ASS. REC. BY:

REF: CS/CT119005618/R1td3n2 Special Instruction:

SUIVAJAY
MUMUN

Rahul

ASSIGNMENT (Office)

From (Person): Elaine cheong of CT1 Date/Time: 29.3.2019 15:14p.m

Estimated Cost: Bill to:

OD TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLR9771L Insured: SJP 78155

at Workshop m/s Hitachi Capital Asia Pacific Tel: 64663022

of M8 Fourth Lok yang Road

Policy No: DNPICV 1507131803 Claim No: SNM19D20133602

Sum Insured: Excess:

Make of Veh: D.O.A. 24.3.19
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement:

Date/Time: 29.3.19 3.50p.m Person Contacted: Voon Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 9771L - X
	SJP 78155 - CS/EQ115003330/T19bd1 DOA - 19/07/2015
	Part by part \$11477.50 (Red: 5210.95, 77%)

Surveyor

Passive

REF:

44723

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLR 9771L
 at Workshop n/s HITACHI
 of POWER Lorry 47
 Insured: CTI
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLR 9771L Yr Regn: 2017 / AU4
 Type: C M.Car / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: TOYOTA SIENNA HYBRID 1.5 c.c. 1496
 Colour: BLUE A/C: Insured / Std / NI / NA
 Sp. Reading: 26959 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: N4P1707089839
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: _____

C BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>24/03/19</u>	D.O.I. <u>25/05/19</u>

Survey held at HITACHI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 08 AUG 2019

Date/Time, File Pass to?

1) 18 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / (B): (\$) TP 1477.50

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

☐ S + RS. \$

☐ Photos

☐ Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Mar 2019		29 Mar 2019 15:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	CHEH HON KHEE, ID: S8574472J
Vehicle Reg. No.:	SLR9771L
Claim Type:	TP / SNM19D201336C02
Vehicle Reg. No. (Insured):	SJP7815S
	Excess: S\$800.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/04/2019]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All] [Search Tasks] [Create New Task] [Complete]

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 2 August 2019 9:26 AM
To: Vonn, LM Siow
Cc: Jamilah, Binte MohdKassim; JiongHow, Ng; Denise Tay (LKKAUTO)
Subject: RE: SLR9771L DOA: 24/3/2019 FINALIZATION

Hi Vonn,

Finalised amount confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Vonn, LM Siow [mailto:vonnlm.siow@hcspl.com.sg]
Sent: Thursday, 1 August, 2019 11:35 AM
To: Rasul (LKKAUTO); CS A Team; SUR
Cc: Jamilah, Binte MohdKassim; JiongHow, Ng
Subject: SLR9771L DOA: 24/3/2019 FINALIZATION

Dear Rasul,

We refer to the subject above and the attachments are for your reference.

Kindly confirm the COR for us at PP, \$1,477.50 before GST, 4 days.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
DID: 6833 6274 Mobile: 96435107
e: vonnlm.siow@hcspl.com.sg
w: www.hitachi-capital.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/03/2019 16:50
Date Of Accident	24/03/2019 22:55
Exact Location Of Accident	ENTRANCE OF JB MALAYSIA CHECKPOINT TWDS SINGAPORE
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR9771L
Insured/Policyholder	
Name Of Registered Owner	CHEH HON KHEE
NRIC No	S8574472J
Email Address	HONKHEE@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96524871
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01014414
Cover Note Number	

Driver

Name of Driver	CHEH HON KHEE
NRIC No	S8574472J
Date Of Birth	27/08/1985
Occupation	INDOOR
Date Of Driving Pass	22/01/2008
Driving Experience	11 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96524871
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	HONKHEE@HOTMAIL.COM

Address	BLK 673B JURONG WEST ST 65 #12-04
Postcode	642673
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	SJD1931S - -
Insurance Company of Driver's Own Vehicle	NTUC INCOME INSURANCE CO-OPERATIVE LTD - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : WIFE GENDER: : FEMALE
Passenger 2	NAME: : CHILD GENDER: : FEMALE
Passenger 3	NAME: : CHILD GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP7815S
Vehicle Make/Model/Colour	HONDA AIRWAVE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YU GAO FEI
NRIC/Passport Number	S9373385A

Contact Number

97881548

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 25/3/19
3.22pm

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:


SKETCH PLAN

Malaysia Checkpoint (JB)
Towards Singapore
At the Entrance.



A: SLR 9771 L
B: STP 7815 S

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- 1) 24 March 2019 around 10:55 pm
- 2) Malaysia checkpoint towards Singapore.
- 3) Car A travelling at centre lanes, merging ~~to~~ accordingly.
- 4) Car B on the right lane, ^{signal &} moving towards left. At Car A's blind spot.
- 5) While Car A concentrating on the merging traffic at the front, a screeching sound was heard. Car B ~~scared~~ front bumper scratched Car A right rear. 

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time: 25/3/19

3 22 ppm

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: _____

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4472J
Vehicle Details	
Vehicle No.:	SLR9771L
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5G CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	1NZR519665
Chassis No.:	NHP1707089839
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$27,876.00
Original Registration Date:	31 Aug 2017
First Registration Date:	31 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$36,035.00
Total Rebate Amount:	\$39,785.00

The information contained herein is correct as at 25 Mar 2019

OK

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 26/03/2019

CHINA TAIPING

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 24/03/2019 @ 22:55
 VRN : SLR9771L
 MODEL : TOYOTA SIENTA HYB 1.5
 TP VRN : SJP7815S

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 REAR BUMPER <i>repair</i>	1	\$ 455.00	\$ 455.00	
2 REAR BUMPER CLIP <i>X 2</i>	10	\$ 5.50	\$ 55.00	
3 REAR BUMPER SIDE RETAINER RH <i>X 1</i>	1	\$ 68.00	\$ 68.00	
4 REAR FENDER RH <i>repair</i>	1	\$ 1,500.00	\$ 1,500.00	
5 REAR FENDER GARNISH RH <i>scr</i>	1	\$ 45.00	\$ 45.00	
6 REAR DOOR RH <i>repair</i>	1	\$ 1,510.00	\$ 1,510.00	
7 REAR DOOR GARNISH RH <i>scr</i>	1	\$ 125.00	\$ 125.00	
8 REAR QUARTER GLASS W MOULDING <i>X 1</i>	1	\$ 507.00	\$ 507.00	
			\$ 4,265.00	
Discount -25%			\$ 1,066.25	
			\$ 3,198.75	
Special Nett				
9 REAR RH RIM <i>scr / s/n - 300</i>	1		\$ -	*pending price
PARTS TOTAL			\$ 3,198.75	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	\$ 1,500.00
Putty, Blend And Spray Paint on REAR Affected Area	\$ 1,250.00
Check Wiring and Ensure Proper Functioning	\$ 80.00
Remove & Reinstall Cushions, Seats, Backrests, Inner Trim, Garnish, Roof Lining and/or Upholstery to Facilitate Repair	\$ 180.00
Remove and Replace Rear RH Door & Rear RH Quarter Glass to Facilitate Repair	\$ 180.00
Dismantle and Transfer Door Fittings & Mechanisms to New Door	\$ 180.00
Conduct Water Seepage Test	\$ 120.00

LABOURS TOTAL

\$ 3,490.00

Grand Total : \$ 6,688.75
 Add 7% GST : \$ 468.21
Nett Total : \$ 7,156.96

No. of repair days: 8

30/5/19
4 days
P/P
29/05/19 @ 1515
Resurvey before paint



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 26/03/2019

CHINA TAIPING

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 24/03/2019 @ 22:55
 VRN : SLR9771L
 MODEL : TOYOTA SIENTA HYB 1.5
 TP VRN : SJP7815S

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 REAR BUMPER <i>repair</i>	1	\$ 455.00	\$ 455.00	
2 REAR BUMPER CLIP <i>X m</i>	10	\$ 5.50	\$ 55.00	
3 REAR BUMPER SIDE RETAINER RH <i>X m</i>	1	\$ 68.00	\$ 68.00	
4 REAR FENDER RH <i>repair</i>	1	\$ 1,500.00	\$ 1,500.00	
5 REAR FENDER GARNISH RH <i>sur</i>	1	\$ 45.00	\$ 45.00	
6 REAR DOOR RH <i>repair</i>	1	\$ 1,510.00	\$ 1,510.00	
7 REAR DOOR GARNISH RH <i>sur</i>	1	\$ 125.00	\$ 125.00	
8 REAR QUARTER GLASS W MOULDING <i>X m</i>	1	\$ 507.00	\$ 507.00	
			\$ 4,265.00	
Discount -25%			\$ 1,066.25	
			\$ 3,198.75	
Special Nett				
9 REAR RH RIM <i>sur s/n-300</i>	1		\$ -	*pending price
PARTS TOTAL			\$ 3,198.75	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	\$ 1,500.00
Putty, Blend And Spray Paint on REAR Affected Area	\$ 1,250.00 <i>750</i>
Check Wiring and Ensure Proper Functioning	\$ 80.00 <i>X</i>
Remove & Reinstall Cushions, Seats, Backrests, Inner Trim, Garnish, Roof Lining and/or Upholstery to Facilitate Repair	\$ 180.00 <i>X</i>
Remove and Replace Rear RH Door & Rear RH Quarter Glass to Facilitate Repair	\$ 180.00 <i>X</i>
Dismantle and Transfer Door Fittings & Mechanisms to New Door	\$ 180.00 <i>X</i>
Conduct Water Seepage Test	\$ 120.00 <i>X</i>

*P= 170.00
 -25%*

127.50

SN= 300.00

L= 1,050.00

T= 1,477.50

No. of repair days: 8

Rasul

Hp 90010068

4 days

p/p

29/05/19 @ 1515

Resumeny before paint

LABOURS TOTAL

\$ 3,490.00

Grand Total : \$ 6,688.75

Add 7% GST : \$ 468.21

Nett Total : \$ 7,156.96



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
 (MANAGER)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119005618/R1TD3N2

Date: 08/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1507131803	
Claimant Vehicle No :	SLR9771L	Insured Vehicle No :	SJP7815S	
Date of Loss:	24/03/2019	Nature of Claim:	TP	Claim No: SNM19D201336C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR9771L	Engine No:	1NZR519665
Make & Model:	TOYOTA SIENTA, 1.5 HYBRID (A)	Chassis No:	NHP1707089839
Reg. Date:	31/08/2017 (Man. Year: 2017)	Odometer:	26959 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,498.75	427.50	3,071.25	87.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,490.00	1,050.00	2,440.00	69.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,988.75	1,477.50	5,511.25	78.86
+ GST 7.00/7.00% (\$\$)	489.21	103.43	385.78	78.86
Nett Amount (\$\$)	7,477.96	1,580.93	5,897.03	78.86

INSPECTION

Date of Assignment:	29/03/2019	
Date Inspected:	29/05/2019	Inspected At:
		Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road Singapore 629705
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Aug 2019)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR9771L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	455.00 FL	*- FL
2	10		*REAR BUMPER CLIP	Not Necessary	55.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	68.00 FL	*- FL
4	1		*REAR FENDER RH	Repair	1,500.00 FL	*- FL
5	1		*REAR FENDER GARNISH RH	Scratched	45.00 FL	*45.00 FL
6	1		*REAR DOOR RH	Repair	1,510.00 FL	*- FL
7	1		*REAR DOOR GARNISH RH	Scratched	125.00 FL	*125.00 FL
8	1		*REAR QUARTER GLASS W MOULDING	Not Necessary	507.00 FL	*- FL
9	1		*REAR RH RIM	Scratched	300.00 FS	*300.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,565.00	470.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					1,066.25	42.50
Total Parts (\$\$)					3,498.75	427.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT,CUT,WELD,RE-ALIGN & REPLACE DAMAGED PARTS OF REAR AFFECTED AREA	New	1,500.00	300.00
2	PUTTY,BLEND AND SPRAY PAINT ON REAR AFFECTED AREA	New	1,250.00	750.00
3	CHECK WIRING AND ENSURE PROPER FUNCTIONING	New	80.00	0.00
4	REMOVE & REINSTALL CUSHIONS,SEATS,BACKRESTS,INNER TRIM,GARNISH,ROOF LINING AND/OR UPHOLSTERY TO FACILITATE REPAIR	New	180.00	0.00
5	REMOVE AND REPLACE REAR RH DOOR & REAR RH QUARTER GLASS TO FACILITATE REPAIR	New	180.00	0.00
6	DISMANTLE AND TRANSFER DOOR FITTINGS & MECHANISMS TO NEW DOOR	New	180.00	0.00
7	CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
Gross Labour Cost (\$\$)			3,490.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >