



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 30/03/2019

User ID : JeongCH

### Section A - Accident Details

Registration Number	SMB133K
Case Reference Number	BUS/03/19/5055
Registration Date	10/1/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Shamsuri Bin Selamat
Type of Accident	Side Swipe
Accident Date and Time	3/8/2019 11:00 AM
Accident Reported Date and Time	3/28/2019 11:22 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100831
Special Instruction to ARC, if any	SMB133K - LEFT FRONT PORTION GBD5298E (TP) - INSURED WITH AXA
Prepared Date and Time	3/28/2019 5:10 PM
Chassis Number	WEB63442021000263
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$530.00
Total Spray Cost	\$616.00	\$446.00
Total Spare Part Cost	\$887.48	\$1,109.35
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$2,563.48</b>	<b>\$2,085.35</b>
Lump Sum Total	\$0.00	\$2,100.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	Hwee jie
ARC / Surveyor Sign Off Date	28/03/2019 5:17 PM	30/03/2019 11:48 AM
Signature		
Remarks		L/S repair. After paint photo

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/03/2019

User ID : JeongCH

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL REPLACE ITEM & REPAIR LEFT SIDE PORTION	\$1,060.00	\$530.00
Total Labour	\$1,060.00	\$530.00

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$616.00	\$446.00
Total Spray Painting & Panel Beating	\$616.00	\$446.00

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009352	GLASS		WINDSCREEN FRT L/H, FOR MB OC500 BUS	1.00	\$931.50	10.00	\$838.35	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer- 206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006314	CONSUMABLE	Sikaflex-265	ADHESIVE DIRECT GLAZING	3.00	\$37.00	0.00	\$111.00	Replace	Replace
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
Total					\$1,128.50		\$1,109.35		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: