

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2018 10:57
Date Of Accident	27/02/2018 22:10
Exact Location Of Accident	CTE TOWARDS ANG MO KIO AVENUE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9538R
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	QUEK KOK KEE
NRIC No	S1666810I
Date Of Birth	30/01/1964
Occupation	OUTDOOR
Date Of Driving Pass	29/09/1981
Driving Experience	36 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96955832
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 383 BUKIT BATOK WEST AVENUE 5 #25-308
Postcode	650383
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 4	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 27.02.2018 at about 2210hours, I was travelling straight on the extreme right lane along CTE towards Ang Mo Kio Avenue 1 when Vehicle B (SJM1845K) in front of me E-brake. I immediately apply brake to avoid collision but to no avail my taxi had hit onto Vehicle B's rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM1845K
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category	PRIVATE CAR
Name of Driver	TAY YONG HOW
NRIC/Passport Number	S1502169A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ps see attach o/a report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

TAY YONG HOW

BLK 3 TOH YI DRIVE #08-183

SINGAPORE 590003

Contact : 97688183

TAX INVOICE

Date : 07/07/2018

Date in : 28/02/2018

Vehicle Num. : SJM1845K

Make/Model : TOYOTA ALLION 1.5 A-2008

Chassis/Eng# : NZT2603032976/1NZD195939

Accident Date : 27/02/2018

Claim No : CLM14021

Reference : FEB-15/2018

Policy No. : 5097439654 (22/12/2018)

LUMPSUM REPAIR BILL

AS PER SURVEYOR REPORT

REF : CAS/18-07/002 DATED 02/03/2018

BY CONSTANT APPRAISER SERVICES

Amount S\$

10,200.00

E. & O.E. Sub S\$: 10,200.00

Add GST (7 %) S\$: 714.00

Total Amount S\$: 10,914.00



for TWINCAR AUTOMOTIVE PTE LTD



WIN WIN CAR RENTAL

Invoice

SJM1845K
TAY YONG HOW
BLK 3 TOH YI DRIVE
#08-183
S(590003)

Invoice No : WWIN0001920
Invoice Date : 31/3/2018
Due Date : 31/3/2018
VHA No : 33964
Referral ID : T015

Description :	Amount
Rental for 6 Day/s @ \$120 per Day	\$720

Vehicle No : SJL 5242 D

Vehicle Description : Toyota Altis 1.6 A

Rental Period : 28/02/2018 to 06/03/2018

Total Amount Payable : \$720

WIN WIN CAR RENTAL







8 Kaki Bukit Ave 4 #06-04 Premier @ Kaki Bukit Singapore 415875

Tel: 6315 8479 H/P: 9833 0807

VHA No: 33964

ROC No: 52987763E

VEHICLE RENTAL AGREEMENT


HIRER'S PARTICULAR Name: (as in I/C) <u>JAY YONG HIOH</u> NRIC/PASSPORT No: <u>S 1502169 A</u> Address (Res): <u>BK 3 TOI YI DRIVE</u> <u>#08-183 S(190003)</u> Name & Address of Employer _____ Occupation: _____ Driving Exp: _____ Driving Licence No: _____ D/L Type: Local / International Issue Date: <u>25/06/2005</u> Date of Birth: <u>09/08/1961</u> Tel: (O) _____ (R) _____ HP <u>9169 8183</u>		Vehicle No: <u>SJL 5242D</u> Replace Veh No: _____ Mileage Out: <u>146417</u> Mileage Out: _____ Make & Model: <u>TOYOTA ALTIS</u> Auto / Manual Group: _____ Out : Date <u>23/12/18</u> Time: <u>15:00</u> HIRE / PERIOD EXPIRY _____ Time: _____ NON-WAIVER EXCESS=\$ <u>2000/-</u> <u>2000/-</u> SECTION I SECTION II																																											
ADDITIONAL DRIVER'S PARTICULARS Name: (as in I/C) _____ NRIC/PASSPORT No: _____ Address (Res): _____ Driving License No: _____ D/L Type: Local / International Issue Date: _____ Date of Birth: _____ Occupation: _____ Driving Exp: _____		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="4">CHARGES</th> </tr> <tr> <td>Daily</td> <td>6</td> <td>@\$ 120</td> <td>per day</td> </tr> <tr> <td>Weekly</td> <td></td> <td>@\$</td> <td>per week</td> </tr> <tr> <td>Monthly</td> <td></td> <td>@\$</td> <td>per month</td> </tr> <tr> <td>Hours</td> <td></td> <td>@\$</td> <td>per hour</td> </tr> <tr> <td>Others</td> <td></td> <td>@\$</td> <td></td> </tr> <tr> <td>CDW</td> <td></td> <td>@\$</td> <td>per day/month</td> </tr> <tr> <td>PAI</td> <td></td> <td>@\$</td> <td>per day/month</td> </tr> <tr> <td colspan="4">Delivery/Collection Service</td> </tr> <tr> <td colspan="4" style="text-align: right;">SUB-TOTAL \$</td> </tr> </table>		CHARGES				Daily	6	@\$ 120	per day	Weekly		@\$	per week	Monthly		@\$	per month	Hours		@\$	per hour	Others		@\$		CDW		@\$	per day/month	PAI		@\$	per day/month	Delivery/Collection Service				SUB-TOTAL \$					
CHARGES																																													
Daily	6	@\$ 120	per day																																										
Weekly		@\$	per week																																										
Monthly		@\$	per month																																										
Hours		@\$	per hour																																										
Others		@\$																																											
CDW		@\$	per day/month																																										
PAI		@\$	per day/month																																										
Delivery/Collection Service																																													
SUB-TOTAL \$																																													
VEHICLE CHECK LIST <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> <p style="writing-mode: vertical-rl; transform: rotate(180deg);">D - DENTS S - SCRATCHES</p>  <p>RIGHT</p> </div> <div style="text-align: center;"> <p>REAR</p>  <p>FRONT</p>  </div> <div style="text-align: center;">  <p>TOP</p> </div> <div style="text-align: center;">  <p>LEFT</p> </div> </div> <p>INDICATE: A - ACCIDENTS</p>		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th colspan="7">PETROL LEVEL</th> </tr> <tr> <td>Out</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> <td></td> </tr> <tr> <td>In</td> <td>E</td> <td>1/4</td> <td>1/2</td> <td>3/4</td> <td>F</td> <td></td> </tr> <tr> <th colspan="7">EXTENSION</th> </tr> <tr> <td colspan="7">Misc.</td> </tr> <tr> <td colspan="7" style="text-align: right;">TOTAL CHARGES \$</td> </tr> </table>		PETROL LEVEL							Out	E	1/4	1/2	3/4	F		In	E	1/4	1/2	3/4	F		EXTENSION							Misc.							TOTAL CHARGES \$						
PETROL LEVEL																																													
Out	E	1/4	1/2	3/4	F																																								
In	E	1/4	1/2	3/4	F																																								
EXTENSION																																													
Misc.																																													
TOTAL CHARGES \$																																													
ACCESSORIES CHECK <input type="checkbox"/> Ashtray <input type="checkbox"/> Cig Lighter <input type="checkbox"/> S/Tyre <input type="checkbox"/> STD Tools <input type="checkbox"/> Jack <input type="checkbox"/> Hub Caps <input type="checkbox"/> Radio/Cass <input type="checkbox"/> CD <input type="checkbox"/> Cartridges		<div style="text-align: center;">  </div> Hirer's Signature _____ Additional Driver's Signature _____																																											

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment. I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given WIN WIN CAR RENTAL in connection with this agreement is true.

* IMPORTANT

- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE. AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY. INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES. A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY WIN WIN CAR RENTAL.

RETURN OF VEHICLE. THE HIRER/DRIVER IS REQUIRED TO SIGN IN THE COLUMN " SINGAPORE OF HIRER / DRIVER " FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO WIN WIN CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	
<u>14/03/18</u>	<u>15:00</u>				 SIGNATURE OF HIRER/DRIVER

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 28 Feb 2018 / 15:23:19

Receipt Date/Time : 28 Feb 2018 / 15:23:19

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180228-001559

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHD9538R				
As at 27 Feb 2018/22:20:00				
Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - SHD9538R Enquiry Fee 20180228152242662257	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx2392	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire Vehicle & Owner Information (Vehicle No. SHD9538R As At 27 Feb 2018 / 22:20:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: T140-107315-18

Current Owner Details

Owner ID Type: Company

Owner ID: 200303878K

Owner Name: TRANS-CAB SERVICES PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 2

Registered Street Name: ANG MO KIO STREET 63

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 569111

Current Vehicle Details

Vehicle No.: SHD9538R

Make Description/Model: CHEVROLET / EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO

Insurance Company Name: AXA INSURANCE PTE LTD



Thank you

Ng Ching Boon Eric has successfully logged out.

Your last login date and time was 17 Aug 2018, 19:05:31.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SHD9538R	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	17 Aug 2018 / 19:05:55

AUTOBAY TOWING

1 Kaki Bukit Avenue 8
#01-05 AutoBay @ Kaki Bukit
Singapore 417883
Tel 9015 8686 (Ah Boon)

CASH SALE

No. _____

Date: 28/4/18

(TWINCAR)

Sold to: SJM 1845K

CROWN

Item	Quantity	Description	Unit Price	Amount
		Auto Hubs to Ubi 1DAZ		\$100
		Reporting Two Trips		
E. & O. E.			Sub Total :	
			GST Tax :	
			Total :	\$100

Issued by: _____

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: Tay Yong How
Blk 3 Toh Yi Drive
#08-183
Singapore 590003

Date : 02/07/2018

Invoice No : IV18-07002/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SJM 1845K (Inclusive Of Photographs And Transport Charges) Our reference : CAS/18-07/002	\$791.00
Total	\$791.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Tay Yong How
Blk 3 Toh Yi Drive
#08-183
Singapore 590003

Date : 02/07/2018

Reference No : CAS/18-07/002

General Information

Registration No. : SJM 1845K
Accident Date : 27/02/2018

Particulars of Damaged Vehicle

Colour	: Red	Make & Model	: Toyota Allion 1.5 A
Engine Capacity	: 1496 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 163030	Engine No.	: 1N2D195939
Chassis No.	: NZT2603032976	Steering	: In Order
Registration Date	: 23/12/2008	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	205/55R16	YOKOHAMA	90%
L/H Front Tyre	205/55R16	YOKOHAMA	90%
R/H Rear Tyre	205/55R16	YOKOHAMA	90%
L/H Rear Tyre	205/55R16	YOKOHAMA	90%

Inspection

Repairer : Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$12,895.82
Revised Amount : \$10,200.00
Less Excess : -
Nett Total : \$10,200.00

Remarks

- (A) Survey was done on 02/03/2018
- (B) Re-survey was done on 02/03/2018
- (C) Re-survey after repair was done on 06/03/2018
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : SJM 1845K

Our ref : CAS/18-07/002

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS</u>			
1	1pc	Rear bootlid	Dented/Buckled	781.20	781.20 ✓
2	1pc	Rear bootlid 'A15' emblem	Necessary	61.00	61.00 ✓
3	1pc	Rear bootlid 'allion' emblem	Necessary	56.60	56.60 ✓
4	1pc	Rear bootlid 'logo' emblem	Necessary	67.90	67.90 ✓
5	1pc	Rear bootlid chrome moulding	Broken	280.90	280.90 ✓
6	2pcs	Rear bootlid hinges L/R @ \$105.60	Bent	211.20	211.20 X R
7	1pc	Rear bootlid inner upholstery trim garnish	Deformed	781.10	781.10 X N/A
8	1pc	Rear bootlid mechanism lock	Bent/Jammed	387.25	387.25 ✓
9	1pc	Rear bootlid opener button sensor	Damaged	231.35	231.35 X N/A
10	1pc	Rear bootlid retainer garnish	Serviceable	174.45	- X
11	4pcs	Rear bootlid rubber guide stopper @ \$12.00	Necessary	48.00	48.00 X N/A
12	1pc	Rear bootlid weather strip	Distorted	231.70	231.70 ✓
13	1pc	Rear bumper	Broken	1,217.80	1,217.80 ✓ 985.40
14	2pcs	Rear bumper bracket L/R @ \$131.35	Dented	262.70	262.70 X N/A
15	2pcs	Rear bumper reflector L/R @ \$78.20	Cracked/Broken	156.40	156.40 ✓
16	2pcs	Rear bumper side retainer L/R @ \$57.70	Necessary	115.40	115.40 ✓
17	1pc	Rear end panel	Dented/Warped	779.00	779.00 ✓ 560
18	1pc	Rear end panel antenna sensor	Damaged	211.70	211.70 X N/A
19	1pc	Rear end panel inner top garnish	Deformed	281.50	281.50 ✓
20	1pc	Rear exhaust gasket	Necessary	63.91	63.91 X N/A
21	2pcs	Rear exhaust rubber mounting @ \$23.70	Distorted	47.40	47.40 X N/A
22	1pc	Rear exhaust silencer box	Dented/Bent	987.80	987.80 X N/A
23	2pcs	Rear fender inner upholstery trim garnish L/R @ \$581.10	Deformed	1,162.20	1,162.20 X N/A
24	2pcs	Rear spare tyre inner side trim board cover L/R @ \$371.45	Dented/Deformed	742.90	742.90 X N/A
25	1pc	Rear spare tyre inner trim board cover	Dented/Deformed	381.90	381.90 ✓
26	2pcs	Rear taillamp back rubber gasket L/R @ \$43.75	Necessary	87.50	87.50 X N/A
27	2pcs	Rear taillamp inner panel L/R @ \$189.25	Dented	378.50	378.50 X R
28	2pcs	Rear taillamp L/R @ \$489.25	Broken	978.50	978.50 ✓ 630
		Less 25%		11,167.76	10,993.31
				(2,791.94)	(2,748.33)
		Sub total		8,375.82	8,244.98

Vehicle No : SJM 1845K

Our ref : CAS/18-07/002

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1set	Rear bootlid chrome moulding clips - set	Necessary	30.00	30.00 10/
2	1set	Rear bootlid inner upholstery trim garnish clips - set	Necessary	50.00	50.00 10/
3	1set	Rear bumper clips - set	Necessary	50.00	50.00 35/
4	1set	Rear bumper reverse sensor - set	Broken	350.00	200 250.00 /
5	1set	Rear end panel inner top garnish clips - set	Necessary	30.00	30.00 10/
6	2sets	Rear fender inner upholstery trim garnish clips L/R – set @ \$50.00	Necessary	100.00	100.00 X NN
7	2sets	Rear taillamp clips L/R – set @ \$30.00	Necessary	60.00	60.00 20/
Sub total				9,045.82	8,814.98 335
<u>LABOUR & MISC. CHARGES</u>					
1		To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor		100.00	80.00 30/
2		To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)		150.00	100.00 50/
3		To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident		1,800.00	1,500.00 900/
4		To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident		180.00	100.00 X NN
5		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		1,500.00	1,300.00 900/
6		To apply anti-rust chemical on repaired and replaced panel		120.00	90.00 30/
Grand total				12,895.82	11,984.98 1910
Recommended cost of lump sum repair (To its pre-accident condition)					10,200.00

P - 3732.63
 M - 335
 L - 1910
 5977.63
 L/S - 4782.10
 = 4800 ✓ 5 days

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$10,200.00** on a contractual basis. Under normal circumstances, the repair period would be about **5 (Five)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 19.26197

Date: 08th April 2019

Our Ref: CS3/AXA18003956/Esd3s2-1

M/s AXA Insurance Pte Ltd

C/o: Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJM 1845K
INSURED VEHICLE: SHD 9538R ACCIDENT DATE: 27/02/2018**

We thank you for your instruction on 28/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJM 1845K from M/s Constant Appraiser Services.
- b) Final Repair Bill of SJM 1845K from M/s TwinCar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJM 1845K and SHD 9538R.
- d) Damaged vehicle photographs of SJM 1845K.

Pre-Repair Inspection Date : 01/03/2018 at M/s TwinCar Automotive Pte Ltd, 2 Kaki Bukit Ave 2
#01-17 Kaki Bukit Autohub Singapore 417921

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJM 1845K
Make & Model	: Toyota Allion
Year of Registration	: 2008
Chassis Number	: NZT26003032976
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 1845K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	DENTED / BUCKLED	781.20	781.20
1	REAR BOOTLID 'A15' EMBLEM	NECESSARY	61.00	61.00
1	REAR BOOTLID 'ALLION' EMBLEM	NECESSARY	56.60	56.60
1	REAR BOOTLID 'LOGO' EMBLEM	NECESSARY	67.90	67.90
1	REAR BOOTLID CHROME MOULDING	BROKEN	280.90	280.90
2	REAR BOOTLID HINGE L/R @ \$105.60	TO REPAIR SEE LABOUR	211.20	-
1	REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH	NOT NECESSARY	781.10	-
1	REAR BOOTLID MECHANISM LOCK	BENT / JAMMED	387.25	387.25
1	REAR BOOTLID OPENER BUTTON SENSOR	NOT NECESSARY	231.35	-
1	REAR BOOTLID RETAINER GARNISH	SERVICEABLE	174.45	-
4	REAR BOOTLID RUBBER GUIDE STOPPER @ \$12.00	NOT NECESSARY	48.00	-
1	REAR BOOTLID WEATHER STRIP	DISTORTED	231.70	231.70
1	REAR BUMPER	BROKEN	1,217.80	985.10
2	REAR BUMPER BRACKET L/R @ \$131.35	NOT NECESSARY	262.70	-
2	REAR BUMPER REFLECTOR L/R @ \$78.20	CRACKED / BROKEN	156.40	156.40
2	REAR BUMPER SIDE RETAINER L/R @ \$57.70	NECESSARY	115.40	115.40
1	REAR END PANEL	DENTED / WARPED	779.00	560.00
1	REAR END PANEL ANTENNA SENSOR	NOT NECESSARY	211.70	-
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	281.50	281.50
1	REAR EXHAUST GASKET	NOT NECESSARY	63.91	-
2	REAR EXHAUST RUBBER MOUNTING @ \$23.70	NOT NECESSARY	47.40	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	987.80	-
2	REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R @ \$581.10	NOT NECESSARY	1,162.20	-
2	REAR SPARE TYRE INNER SIDE TRIM BOARD COVER L/R @ \$371.45	NOT NECESSARY	742.90	-
1	REAR SPARE TYRE INNER TRIM BOARD COVER	DENTED / DEFORMED	381.90	381.90
2	REAR TAILLAMP BACK RUBBER GASKET L/R @ \$43.75	NOT NECESSARY	87.50	-
2	REAR TAILLAMP INNER PANEL L/R @ \$189.25	TO REPAIR SEE LABOUR	378.50	-
2	REAR TAILLAMP L/R @ \$489.25	BROKEN	978.50	630.00

Report Ref No. CS3/AXA18003956/Esd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,791.94	-1,244.22
			8,375.82	3,732.63
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BOOTLID CHROME MOULDING CLIPS (SN)	NECESSARY	30.00	10.00
1	SET REAR BOOTLID INNER UPHOLSTERY TRIM GARNISH CLIPS (SN)	NECESSARY	50.00	10.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	35.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	BROKEN	350.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
2	SETS REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R @ \$50.00 (SN)	NOT NECESSARY	100.00	-
2	SETS TAILLAMP CLIPS L/R @ \$30.00 (SN)	NECESSARY	60.00	20.00
			670.00	285.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	30.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		150.00	50.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,800.00	900.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	180.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID HINGE L/R AND REAR TAILLAMP INNER PANEL L/R.		1,500.00	900.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	30.00
			-	-
			-	-
			-	-
			3,850.00	1,910.00
	GRAND TOTAL		12,895.82	5,927.63



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,750.00
---	--	--	----------

Report Ref No. CS3/AXA18003956/Esd3s2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.