Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sq / claims@premiumauto.com.sq

Telefax

Estimate Accident Repairs Workshop Ubi Road 1 **Contact No** 6366 2323 Fax No 6841 1183

PA/OD/0378/2019/GW / NK Reference

Date 23-Mar-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name Ms. Liu ShaoMin

Address 60 Marine Parade road

#07-02

Singapore 449297 HP +65 90895808

Telephone Type of Claim Own Damage Claims

Policy No.

Vehicle No **SLZ 9228 Y**

Model Code Audi A3 SB 1.0 TFSI

Model / Year 23/5/2018 **Engine No** CHZ 439262

Chassis No WAUZZZ8V2JA098572

Mileage

Date In : Liability

Excess Cost

Estimated By Johnny Boo / Allan Wu

Accident Date 21-Mar-19

Place of Accident Marina Bay Sand Car Park

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 9228 Y

			Estimated	Surveyor's
S/n	Nature of Jobs		Charges	Recommendation
1	To remove, check and reinstall front wire harness for headlihts, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	·.
2	To dismantle and renew front bumper and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.		\$ 1,200.00	500
3	To respray front bumper.		\$ 800.00	550
4	To carry out diagnostic check.	S/N	\$	
	SUB LABOUR CHARGES	:	\$ 2,192.00	•

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax Material List for Accident Vehicle Regn No. SLZ 9228 Y

S/N	Parts Description		Damaged Parts & Prices S/Nett Remark
1	FRONT BUMPER Of L	\$	1,698.00
		-	•
2	FRONT BUMPER FIXING PARTS	\$	170.00 🗜
3	FRONT BUMPER GUIDE SECTION -LH/RH	\$	70.00 X
4	FRONT BUMPER GRILLE-CENTER (and	\$	146.00 -
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE ~~~	\$	270.00 ⊀
6	FRONT BUMPER CLOSING ELEMENT-LH	\$	270.00 ⁴
7	RADIATOR GRILLE Cum L	\$	1,301.00
8	RADIATOR GRILLE CLOSING ELELEMT	\$	174.00
9	FRONT BUMPER AIR GUIDE GRILLE-LH	\$	171.00 🗡
10	FORNT BUMPER REINFORCEMENT BEAM ?	\$	670.00
11.	FOAM FILLER PIECE	\$	172.00 ?
12	FRONT BUMPER COVER	\$	111.00 +
13	AIR CONDITIONER STICKER 3	\$	7.00 ⊀
14	SIGN ' CAUTION '	\$	13.00 ⊀
15	HEADLIGHT LIFT CYLINDER-LH	\$	128.00 ⊀
16	LED HEADLIGHT-LH	\$	5,029.00 ←
17	FRONT AIR GUDIE-LH	\$	22.00 4
18	FRONT NO. PLATE S/N	\$	25.00 🗸
19	sundries ?	\$	500.00 ?
	TOTAL SPARE PARTS :	\$	10,947.00
	TOTAL LABOUR CHARGES	\$	2,192.00
	GRAND TOTAL	\$	13,139.00
	=		

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

Authorsed Pepis, 03 Pays.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant