

22/03/2001

ASS. REC. BY:

REF: CS31 LPC18018 617 / Uqj3-1

uction:

Surveyor: Marlus

ASSIGNMENT (Office)

From (Person): Org di li

of JPC

Date/Time: 29/03/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCV 822T

Insured: GBD 4061C

at Workshop m/s: ZOOM Autowerks

Tel: 9450 7920

of 15 kaki Bkt Rd 4 #01-53

Policy No:

Claim No: 17118/18/VCOO/021012

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/10/2018

CA / REV / REP. / REV 24 HRS lup

17110/2018

H.O.D. Endorsement:

Date/Time: 12:30pm @ 15/10/18

Person Contacted:

Elin

Vehicle-IN/OUT OUT

Date/Time	Action/Instruction (X) Estimate	
	SCV 822T - NA/INC/18018 489/24	DOA: 10/10/18
	GBD 4061C - NA/INC/18018 489/24	DOA: 10/10/18
04/11/18	submit msg. 2350	
	Sumup H/S 822T 2by (led \$3,100, 57%)	

RECEIVED 0 8 APR 2019

Signature

REF: JPC

ASSIGNMENT

From: _____ Date: 17/10/18

Veh No: SCV 8227 Yr Regn: 6.09

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or CA /

To Inspect Vehicle No: SCV 8227
at Workshop m/s ZOOM Autowerks
of Iskaki Bkt Rd 4 # 01-53

Make: Audi A4 c.c 1798

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 198904 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: WAUZZZ8K69A22904

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 245/35-22 19
R: _____

Bal. or Market Value: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

IDAC Accident Rpt: _____ Consistent?: Yes or No

Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

D.O.A. 10/10/18 D.O.I. 17/10/18

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at _____

CA / REV / REP. / 24 HRS (up) 3230Z
Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____

Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/1/19 No content LTA work according to Elin from zoom Autowerks they pass lawyer advice. * repairer didn't provide LTA report.

RECEIVED 04 JAN 2019

Date/Time, File Pass to?

: Prel. Report

Days Of Repair: _____

1) 04/1/19 Transit

: Final Report

Resurvey No. of Trip: _____

Survey Fee: 450

Date/Time, File Return to?

Transportation: _____

2) _____

Add Fee: : Site Insp (\$)

S + RS. St

: Interview (\$)

Photos

: Tech. Invs (\$)

Others

: Weekend (\$)

Report Format: PPS.

Lump Sum / I.B.I: (\$)

TOTAL

450

➤ [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3230F
Vehicle Details	
Vehicle No.:	SCV822T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8T FSI MU S-LINE CVT ABS D/AB HID
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	CDH050272
Chassis No.:	WAUZZZ8K69A229021
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$39,011.00
Original Registration Date:	15 Jun 2009
First Registration Date:	15 Jun 2009
Transfer Count:	4
Actual ARF Paid:	\$39,011.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jun 2019
PARF Rebate Amount:	\$19,505.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jun 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$12,901.00
COE Rebate Amount:	\$784.00
Total Rebate Amount:	\$20,289.00

The information contained herein is correct as at 17 Oct 2018

OK

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 29 March 2019 12:42 PM
To: Admin-D (LKKAuto); assignments
Cc: MT_Claim_SG; SUR
Subject: RE: Our Ref: 17/18/18/VC00/021012 URGENT: Accident involving SCV822T & GBD4061C on 10/10/18 (Our Ref: PD/DL/1801766 (Sp)) [External General]
Attachments: 21012 TP SURVEY REPORT.pdf

Lonpac External - General

Dear Nivitha

Attached is the TP survey report.

Please let us have your surveyor's review & report.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 15 October, 2018 12:33 PM
To: ONG LI LI; assignments
Cc: MT_Claim_SG; SUR
Subject: RE: Our Ref: 17/18/18/VC00/021012 RE: URGENT: Accident involving SCV822T & GBD4061C on 10/10/18 (Our Ref: PD/DL/1801766 (Sp))

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 17/10/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



ALLIN AUTOMOTIVE APPRAISERS

Block 805D, Keat Hong Close. #13-88 Singapore 684805

TIONG HIN YANG
c/o Zoom Autowerks Pte Ltd
130 Bedok Reservoir Road
#08-1339
Singapore 470130

Report No : ALLIN-11-0264

Date : 27.10.2018

Reference

Requested by : Workshop, owner's behalf
Date of Request : 27/10/2018
Date of Accident : 10/10/2018
Date of Inspection : 27/10/2018
Inspected at : Zoom Autowerks Pte Ltd
130 Bedok Reservoir Road
#08-1339
Singapore 470130

Vehicle Details

Vehicle No.	: SCV822T	Make & Model	: AUDI A4
Year Make	: 2009	Colour	: BLACK
Engine No.	: CDH050272	Chassis No.	: WAUZZZ8K69A229021
Engine Capacity	: 1,798cc	Mileage	:
Air-Con	: YES	Radio/CD/Cassette	: YES
Seat Belt	: YES	Rims	: SPORT

General Condition of Vehicle

General Condition	: GOOD	Modification	: NIL
Brakes	: SERVICEABLE	Handbrake	: SERVICEABLE
Steering	: SERVICEABLE		

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Rim</u>	<u>Tread Balance</u>
Front Right	GOODYEAR	245/35 R19	SPORT	70%
Front Left	GOODYEAR	245/35 R19	SPORT	70%
Rear Right	GOODYEAR	245/35 R19	SPORT	70%
Rear Left	GOODYEAR	245/35 R19	SPORT	70%

Assessment

	<u>Repairer's Estimate</u>	<u>Recommendation</u>
Spare Parts	: \$ 4,053.00	\$ 3,647.70
Labour Charges	: \$ 1,540.00	\$ 1232.00
Paint Work	: \$ 750.00	\$ 600.00
Towing Charges	: \$	
Total	: \$ <u>6,343.00</u>	\$ <u>5,479.70</u>

Recommend Lum Sum Repairs : \$ 5,450.00
Reduction : \$ 893.00

Estimated Period Required for Repair : 20 Days



ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SCV822T
Chassis No: WAUZZZ8K69A229021
Engine No: CDH050272

Report No : ALLIN-11-0264
Date : 27.10.2018

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Rear Bumper	Damaged	\$ 1,280.00	\$ 1,152.00
2	1	Rear Diffuser	Damaged	\$ 550.00	\$ 495.00
3	2	Rear Tail Lamps	Broken	\$ 420.00	\$ 378.00
4	1	Rear Bumper Bracket	Necessary	\$ 280.00	\$ 252.00
5	1	Rear Reverse sensor	Faulty	\$ 258.00	\$ 232.20
6	1	Rear Reinforcement	Impacted	\$ 545.00	\$ 490.50
7	1	Rear End panel	Impacted	\$ 720.00	\$ 648.00
				\$ 4,053.00	\$ 3,647.70

Total (Parts): \$ 4,053.00 Less 10% \$ 3,647.70

Labour Charges

8	To fix & dismantle and remove damaged parts and affected Front Left affected damaged portion.	\$ 500.00		\$ 400.00
9	To apply anti rust coat and affected areas	\$ 60.00		\$ 48.00
10	To check wiring	\$ 80.00		\$ 64.00
11	Welding and cutting of affected panels, including chassis alignment:	\$ 800.00		\$ 640.00
12	Spray painting for Front Left affected parts.	\$ 750.00		\$ 600.00
13	To apply waterproofing sealer on end panels	\$ 100.00		\$ 80.00
		Total Labour: \$ 2,290.00		Less 20% \$ 1,832.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 6,343.00 \$ 5,479.70

2131.20
1916.00
278.00
2100

2368
2131.2
2961.2



ALLIN AUTOMOTIVE APPRAISERS

Block 805D, Keat Hong Close. #13-88 Singapore 684805

Vehicle No: SCV822T

Report No.: ALLIN-11-0264

Point of Impact

Recommendation

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is **\$5,450.00**

Conclusion

The repairer has agreed to undertake repairs at a lump sum of **\$5,450.00** corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE



Appraiser Name:
Lim Chang Liang

ZOOM CAR LEASING

Zoom Car Leasing
Registration No.: 5339410M
e-mail : zoomcarleasing@gmail.com

Zoom Autowerks Pte Ltd
Tel: 9450 7920

RENTAL INVOICE

Invoice No. : **INV0000283**
Date : 6/11/2018
Ref : SLT 7974 T
Your Ref : SCV 822 T
Terms : 30Days

#	Rental Period	Rate	Quantity	Amount
1	Rental Charges for SLT 7974 X (18/10/2018 to 20/10/2018)	\$200.00	2 Days	\$400.00

C/O Tiong Hin Yang
Contact: 9221 2213

Total : \$400.00

(Customer's Signature/Stamp)

**ZOOM CAR
LEASING**

(For Zoom Car Leasing)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC18018617/Uqd3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 10-04-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 4061C	Veh. Inspected	SCV 822T
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VC00/021012	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	29/03/2019
2. Vehicle Particulars & Condition			
Make & Model	AUDI A4 (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WAUZZZ8K69A229021	Colour	BLACK
Odometer	198904	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/35 R19	GOODYEAR	6 mm
L/H Front Tyre	245/35 R19	GOODYEAR	6 mm
R/H Rear Tyre	245/35 R19	GOODYEAR	6 mm
L/H Rear Tyre	245/35 R19	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/10/2018	Inspection Date	17/10/2018
Survey held at	15 KAKI BUKIT RD 4# 01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCV 822T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	1,280.00	1,280.00
1	REAR DIFFUSER	GRAZED	550.00	550.00
2	REAR TAIL LAMPS	NOT NECESSARY	420.00	-
1	REAR BUMPER BRACKET	NECESSARY	280.00	280.00
1	REAR REVERSE SENSOR	SHORTED	258.00	258.00
1	REAR REINFORCEMENT	TO REPAIR SEE LABOUR	545.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	720.00	-
	LESS 10% DISCOUNT		-	-236.80
			4,053.00	2,131.20
LABOUR				
	TO FIX & DISMANTLE AND REMOVE DAMAGED PARTS AND AFFECTED FRONT LEFT AFFECTED DAMAGED PORTION.	NOT NECESSARY	500.00	-
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO CHECK WIRING.		80.00	30.00
	WELDING AND CUTTING OF AFFECTED PANELS. INCLUSIVE OF THE REPAIR OF REAR REINFORCEMENT AND REAR END PANEL.		800.00	400.00
	SPRAY PAINTING FOR FRONT LEFT AFFECTED PARTS.		750.00	400.00
	TO APPLY WATERPROOFING SEALER ON END PANELS.	NOT NECESSARY	100.00	-
			2,290.00	830.00
GRAND TOTAL			6,343.00	2,961.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CS3/LPC18018617/Uqd3e2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.