



SERVICE PRE-INVOICE

Page 1/4

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Attn: Marcus (L.K.K.)

20 days

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZE001 / ECICS LIMITED
Chassis No: JHMRC1880JC204566
License No: SME7108Y
Mileage: 10432
Engine No: K24W72402015

Document No: SVO19020246
Printed By: CSLIM
Order Date: 29. March 2019
Order Time: 5:28:42 PM
Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72449)						
	OWNER: GILBERT ANG YAU HENG						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 27/3/2019						
	SURVEYED BY: MARCUS (L.K.K.)						
	DATE: 29/03/2019 @ 09:30AM						
	REF NO: DMCV1900016H/02/CT						
	TP INSURER: ECICS LIMITED						
	TP VEH: YK8899S						
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD	1	1,011.00	25	758.25	53.08	811.33
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73226-SZW-000	DAMPERSTD 5X5	2	8.50	25	12.75	0.89	13.64
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.70	25	14.55	1.02	15.57
73850-T6A-003	SEALL.QUARTER GLASS	1	35.10	25	26.32	1.84	28.16
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	1	5.30	25	3.97	0.28	4.25
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
91501-SMA-003	CLIP AQTR.	1	3.00	25	2.25	0.16	2.41
91501-SYA-000	CLIPQUARTER WINDSHIELD A	1	3.80	25	2.85	0.20	3.05
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91513-S70-003	CLIPL	1	3.80	25	2.85	0.20	3.05
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	337.90	25	253.42	17.74	271.16
65594-T6A-300ZZ	FRAME DL.RR.UPPER	1	48.20	25	36.15	2.53	38.68
65597-T6A-300ZZ	EXTENTION L.RR.FRAME ENDSIDE	1	32.90	25	24.67	1.73	26.40
65673-T6A-300ZZ	FRAME DL.RR.LOWER	1	43.40	25	32.55	2.28	34.83
64700-T6A-405ZZ	PANEL COMPL.RR.INSIDE	1	895.20	25	671.40	47.00	718.40
04646-T6A-J01ZZ	PANEL SET L,RR OUTSIDE	1	993.90	25	745.42	52.18	797.60
63720-T6A-300ZZ	GUTTER COMPL.RR.PILLAR	1	131.70	25	98.77	6.91	105.68
66100-T6A-Q00ZZ	PANEL COMP,REAR	1	460.80	25	345.60	24.19	369.79
72841-SH3-315	OILSHEET	1	40.70	25	30.52	2.14	32.66
72585-T6A-000ZZ	COVER COMPL.SLIDE DR CTR RAIL	1	164.50	25	123.37	8.64	132.01
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE	1	185.40	25	139.05	9.73	148.78
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER	1	105.30	25	78.97	5.53	84.50
74820-T6A-013	STAY ASSYR.TAILGATE OPEN	1	164.50	25	123.37	8.64	132.01
74870-T6A-013	STAY ASSYL.TAILGATE OPEN	1	164.50	25	123.37	8.64	132.01
74890-T6A-N11ZA	GARNISH ASSY,RR.LICEION LID	1	164.20	25	123.15	8.62	131.77
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	175.50	25	131.62	9.21	140.83
33500-T6A-003	TAILLIGHT ASSYR.	1	838.10	25	628.57	44.00	672.57
33550-T6A-003	TAILLIGHT ASSYL.	1	838.10	25	628.57	44.00	672.57
34150-T6A-003	LIGHT ASSYR.LID	1	386.20	25	289.65	20.28	309.93
34155-T6A-003	LIGHT ASSYL.LID	1	386.20	25	289.65	20.28	309.93
38387-SLE-003	ANTENNA ASSY,L.RR.	1	60.60	25	45.45	3.18	48.63
74940-TR0-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZE001 / ECICS LIMITED
Chassis No: JHMRC1880JC204566
License No: SME7108Y
Mileage: 10432
Engine No: K24W72402015

Document No: SVO19020246
Printed By: CSLIM
Order Date: 29. March 2019
Order Time: 5:28:42 PM
Service Advisor: LIM CHOU SIONG

NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
84181-T6A-J81ZA	GARNISH ASSYL.QUARTER PILLAR	1	89.50	25	67.12	4.70	71.82
84615-T6A-N23ZD	LINING COMP,R.RR.SIDGATE	1	705.40	25	529.05	37.03	566.08
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	103.60	25	77.70	5.44	83.14
84665-T6A-N22ZD	LINING COMP,L.RR.SIDE	1	705.40	25	529.05	37.03	566.08
84666-T6A-912ZB	LID COMP,L.DAMPER	1	55.30	25	41.47	2.90	44.37
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	206.30	25	154.72	10.83	165.55
84435-T6A-J01ZA	GARNISH ASSYR.TAILGATE SIDE	1	41.20	25	30.90	2.16	33.06
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1	10.70	25	8.02	0.56	8.58
84485-T6A-J01ZA	GARNISH ASSYL.TAILGATE SIDE	1	41.20	25	30.90	2.16	33.06
75701-T6A-000	EMBLEMH	1	26.30	25	19.72	1.38	21.10
75722-T6A-901	EMBLEM,RR.	1	31.00	25	23.25	1.63	24.88
72955-T6A-003	MOLDING ASSYL.QTR WINDSHIELD	1	109.70	25	82.27	5.76	88.03
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84	456.06
71502-T6A-003ZL	FACE,R.RR.BUMPER	1	76.80	25	57.60	4.03	61.63
71507-T6A-003ZL	FACE,L.RR.BUMPER	1	76.80	25	57.60	4.03	61.63
71517-T6A-901ZN	SPOILER ASSY,L.RR.	1	93.00	25	69.75	4.88	74.63
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
91505-TM8-003	CLIP,BUMPER	5	2.30	25	8.62	0.60	9.22
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
90650-SYY-003	GROMMETTAIL LIGHT	2	1.90	25	2.85	0.20	3.05
90650-SZT-003	GROMMETRR.COMBINATION LIGHT	1	2.50	25	1.87	0.13	2.00
90001-T6A-003	BOLT TAIL LIGHT	1	3.80	25	2.85	0.20	3.05
			SUM PARTS:		9,539.76	667.79	10,207.55
BOSUN	0760	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BOBC		1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BA02R	EXT-YJ	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BP00R		1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BKOT00R	EXT-YJ	1	180.00		180.00	12.60	192.60
	REMOVE & RENEW RR FLOOR						
	INSULATOR.(N)						
BMF00D		1	250.00		250.00	17.50	267.50
	REMOVE & INSTALL FUEL TANK FUEL						
	PIPES.(N)						
BG51D	EXT-YJ	1	280.00		280.00	19.60	299.60
	REMOVE & INSTALL RR. L QTR GLASS.						
	(N)						
BG02R	EXT-YJ	1	300.00		300.00	21.00	321.00
	REPLACE RR. WINDSCREEN.(N)						
BOMISC1		1	280.00		280.00	19.60	299.60
	PERFORM SETTING AND ALIGNMENT						
	OF MULTI-VIEW CAMERA						
	AND PARKING-ASSIST SYSTEM.(N)						



SERVICE PRE-INVOICE

Page 3/4

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZE001 / ECICS LIMITED
Chassis No: JHMRC1880JC204566
License No: SME7108Y
Mileage: 10432
Engine No: K24W72402015

Document No: SVO19020246
Printed By: CSLIM
Order Date: 29. March 2019
Order Time: 5:28:42 PM
Service Advisor: LIM CHOU SIONG

BOMISC1	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY COMPONENT.(N)	1	280.00	280.00	19.60	299.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	350.00	350.00	24.50	374.50
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00	380.00	26.60	406.60
BKRP02B	EXT-YJ CUT OFF & RENEW RR PANEL FLOOR PANEL RR L W/HOUSE RR L FENDER REPAIR ROOF PANEL & OTHER DAMAGE PARTS	1	6,720.00	6,720.00	470.40	7,190.40
BP06R	EXT-YBH SPRAY PAINTING ON ROOF PANEL RR L SLIDING DOOR RR PANEL FLOOR PANEL BOTH RR W/HOUSE BOTH RR FENDER & 0760	1	3,150.00	3,150.00	220.50	3,370.50
BOJSE	BODY JOINT SEALANT.	1	80.00	240.00	16.80	256.80
SUM LABOUR:				12,940.00	905.80	13,845.80
BO-3M-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	1	300.00	300.00	21.00	321.00
SUM EXT SERVICE:				300.00	21.00	321.00
TOTAL SGD				22,779.76	1,594.59	24,374.35

Total Payable (SGD) 24,374.35

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Page 4/4

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: ECICS LIMITED 7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER FIVE SINGAPORE 038987	Document No.	: SQT19001731	Page	1
Registration No	: SME7108Y	Date	: 17. Apr 2019		
Chassis No	: JHMRC1880JC204566	Customer No.	: WZE001		
Model	: ODYSSEY 2.4 EX-S 18YM (EURO 6)	Svc Advisor	: LIM CHOU SIONG		
Owner's Name	: GILBERT ANG YAU HENG	Engine No	: K24W72402015		
Ins Policy No.	:	Date Time	: 17. Apr 2019 12:43:23 PM		
Date of Accident	: 27/3/2019	Surveyor Name	: MARCUS (L.K.K.)		
		Survey Date	: 29/3/2019		
		Authorisation Date	: 29/3/2019		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72449) OWNER: GILBERT ANG YAU HENG OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L ACC DATE: 27/3/2019 SURVEYED BY: MARCUS (L.K.K.) DATE: 29/03/2019 @ 09:30AM REF NO: DMCV1900016H/02/CT TP INSURER: ECICS LIMITED TP VEH: YK8899S SUPPLEMENTARY LABOUR & PARTS						
90650-SYY-003	GROMMETTAIL LIGHT	2	1.90		3.80	0.27	4.07
90650-SZT-003	GROMMETRR.COMBINATION LIGHT	1	2.50		2.50	0.18	2.68
90001-T6A-003	BOLT TAIL LIGHT	1	3.80		3.80	0.27	4.07
Sum Item					10.10	0.72	10.82

Survey By	_____						
Date & Time	_____	Total Amount	10.10	0.72	10.82		
Excess	_____	Total (Inclusive of GST)			10.82		
Status	_____						
Signature	_____						

Printed on 17/4/2019 1:23:27 PM

This is a computer generated invoice, No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.