

ASS. REC. REV.

REF:

CS/ICS19005639/Und3er

Special Instruction

Sub Veyor

MURIS

ASSIGNMENT (Office)

Person

Crystabelle Ten

of

ICS

Date/Time:

28/3/19 6:44pm

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SME7108Y

Insured:

YK 8899S

at Workshop no:

1cuh Motor
15 ubi Road 4

Tel:

81006303

Policy No:

Claim No:

DMCV19000164/02/C7

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A

27/03/2019

CA / REV / REP. / REV 24 HRS

Date/Time:

9:47am 24/3/19

Person Contacted:

Mr Jim

Vehicle

IN / OUT

Date/Time

Action/Instruction



Estimate

(08/11/13) waf

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) *22,779.76*

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

350

10

360

RECEIVED 22 APR 2019

*Spare parts request 25% discount**22/4/19 confirmed final by #22779.76 (Ref 9536.24, 3019)*

Nivitha (LKK Auto)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Thursday, 28 March 2019 6:44 PM
To: assignments
Cc: ECICS Claims; Lim Chou Siong
Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO. SME7108Y AGAINST YK8899S - ECICS Ref : DMCV1900016H/02/CT
Attachments: 0399_001.pdf

WITHOUT PREJUDICE

Dear LKK

Refer to below email and arrange survey.

NOTE : Our insured has yet to report the accident.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Lim Chou Siong [mailto:cslim@honda.com.sg]
Sent: Thursday, 28 March, 2019 4:53 PM
To: ECICS Claims
Subject: DIRECT SETTLEMENT OF VEHICLE NO. SME7108Y AGAINST YK8899S

To Officer In Charge,

The Above Attachment For Your Reference,

Kindly Help To Arrange Surveyor To Survey This Vehicle SME7108Y,

Vehicle Is In Kah Motor Ubi Now,

Your Insure Vehicle Number YK8899S, Accident Date 27/03/19,

Thank for your help.

Best Regards,

Lim Chou Siong
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4

Singapore 408610
E-mail : cslim@honda.com.sg
Fax : 67480770 DID : 68465671 H/P : 81006303

From: Printer Service <printservice@honda.com.sg>
Sent: Thursday, 28 March, 2019 4:45 PM
To: Lim Chou Siong <cslim@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9112J
Vehicle Details	
Vehicle No.:	SME7108Y
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EX-S CVT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	K24W72402015
Chassis No.:	JHMRC1880JC204566
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$28,173.00
Original Registration Date:	12 Oct 2018
First Registration Date:	12 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$31,443.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2028
PARF Rebate Amount:	\$23,582.00
Intended COE Rebate Details	
COE Expiry Date:	11 Oct 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,000.00
COE Rebate Amount:	\$29,842.00
Total Rebate Amount:	\$53,424.00

The information contained herein is correct as at 29 Mar 2019

OK

- [Brexit - Remain or Leave EU?](#)
- [Selling Car through CARRO](#)
- [KBW Fractured Arm. In hospital](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)

[Advertiser Login](#)

[Ways of Selling](#)

Sporty & Powerful A5 For Sale!



Low Dep, All Audi Worries Done
up With Receipt to prove.
Hurry Before its Sold!
[StarAd](#)



Browse by Category

Sort by Date Posted

20 results/page

1 vehicles

Odyssey

Advanced Search [Submit](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Odyssey		Any	Any	2018	Any	Any	Any	Available
	Honda	Odyssey 2.4A EXV-S	\$132,888	\$12,670 /yr	02-May-2018	2,356 cc	4,500 km	MPV	Available
2.4L MPV 1-VTEC (EXV-S) - 2018 Facelift Model Exterior: Platinum White Interior: Black									
Posted: 14-Feb-2019 Tags: 2018 Honda Odyssey, 2018 honda odyssey, honda Odyssey, honda odyssey, honda, Odyssey, odyssey, Used Honda									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Odyssey, Odyssey Singapore, used Odyssey Singapore, used Odyssey, used vehicles Singapore or even buy used Odyssey Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel:+65 6841 3333 Fax:+65 6841 2611

255 Alexandra Road Singapore 159937. Tel:+65 6339 9880 Fax:+65 6471 5400

www.honda.com.sg

GST Reg No. : M20005022

Company Reg. : S60FC1380

Invoice No. : VINV18007018

Invoice Date : 19. Oct 2018

Order No. : VSO18006805

****9112J

GILBERT ANG YAU HENG

(GILBERT HONG YAOXING)

GILBERT ANG YAU HENG

(GILBERT HONG YAOXING)

33 PASIR RIS STREET 72

#14-27 SINGAPORE,518770

33 PASIR RIS STREET 72

#14-27 SINGAPORE,518770

Regn. No. : SME7108Y
Sales Exec : 1644 (CHARLES LAI SWEI)
Vehicle : ODYSSEY 2.4 EX-S 18YM (EURO 6)
Model : RC188JEN-B553P
Color : B553P COBALT BLUE P.

Customer No. : ****9112J
Reg. Date : 12. October 2018
Engine : K24W72402015
Chassis : JHMRC1880JC204566

VEHICLE'S PARTICULARS
AMOUNT

NETT ARF PRICE (including ARF, COE, Road Tax, GST, Reg Fee and Standard Accessories) 143,999.0

OPTIONAL ACCESSORIES: *warranty terms and conditions apply

ODYSSEY 18 FLR MAT WO HEATDUCT

ODYSSEY 18 STEP ILLUMI BLACK

CAR PLATE - ODYSSEY

EXT WTY (5YR) FOC

LTA IU

OPT-ODYSSEY EX-3M-SOLAR FILM-FOC

REAR 4PCS ACTIVE SENSORS

FOC 1K10K20K30K40K50K60K SVC - ODYSSEY

DVR, IROAD 2 CHANNELS NO SURVEILLANCE

VES DISCOUNT

-10,000.0

CAR INSURANCE - TOKIO MARINE

970.6

FLOOR MAT BLACK WO HEAT DUCT

STEP ILLUMI BLACK

DVR, IROAD 2 CHANNEL

428.0

TOTAL SGD INCL GST

135,397.6

DOWNPAYMENT BY CUSTOMER GILBERT ANG YAU HENG

135,397.6

AMOUNT FINANCED BY GILBERT ANG YAU HENG

0.0

VALUE OF OTHER SUPPLIES

75,448.6

VALUE OF STANDARD RATE SUPPLIES (SRS)

58,027.1

GST 7% ON STANDARD RATE SUPPLIES

3,921.8

135,397.6

CUSTOMER'S SRS AMOUNT

56,027.11

G.S.T

3,921.8

FINANCE CO'S SRS AMOUNT

0.00

G.S.T

0.0

REMARKS:

Printed by SGKAHMOTORICSLIM on 27/3/2019 7:47:20 PM

This is a computer generated invoice. No signature is required.

NOTE: PAYMENTS

(a) Our Official Receipt must be obtained from our Cashier for all payments made.

(b) Cheque/Cashier Order must be made payable to Kah Motor Co. Sdn. Bhd. and crossed 'Account Payee Only'.

(c) Under no circumstances should payments be made to our Salesman and/or any unauthorised persons.

(d) If no Official Receipt is forthcoming in acknowledgement of your payment(s) within 30 days, immediate enquiries should be made to our Accountant and request for receipt hitherto.

(e) Interest on late-payment 9.0% p.a. will be levied on this invoice's amount, if we fail to receive your payment within 14 days.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7429112J



Name

GILBERT ANG YAU HENG
(GILBERT HONG YAOXING)

洪耀兴

Race

CHINESE

Date of birth

27-08-1974

Sex

M

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S7429112J

Name: GILBERT ANG YAU HENG
(GILBERT HONG YAOXING)

Birth Date: 27 Aug 1974

Issue Date: 24 May 2003

000505962E

3749815

WMC No. S7429112J

Date of issue: 01-08-2005

Address:
33 PASIR RIS STREET 72
#14-27
SINGAPORE 518770

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	24 May 2003

NP 429A

License No: S7429112J

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2019 20:34
Date Of Accident	27/03/2019 15:50
Exact Location Of Accident	TANAH MERAH COAST ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME7108Y
Insured/Policyholder	
Name Of Registered Owner	GILBERT ANG YAU HENG (GILBERT HONG YAOXING)
NRIC No	S7429112J
Email Address	ANG.GILBERT@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90189801
Alternative Phone No	OFFICE-90189801

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 EX-S (A)
Exact Purpose for which vehicle was being used at time of accident	DROPPING OFF A FRIEND
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MT108035-R00
Cover Note Number	

Driver

Name of Driver	GILBERT ANG YAU HENG (GILBERT HONG YAOXING)
NRIC No	S7429112J
Date Of Birth	27/08/1974
Occupation	INDOOR
Date Of Driving Pass	24/05/2003
Driving Experience	15 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90189801
Fax Number	
Contact Number	OFFICE-90189801
Email Address	ANG.GILBERT@GMAIL.COM

Address	33 PASIR RIS STREET 72 #14-27
Postcode	518770
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YAP KERN LING GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YK8899S
Vehicle Make/Model/Colour	ISUZU / / WHITE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SIVALINGAM VENKATESAN
NRIC/Passport Number	G7780372L
Contact Number	81810141
Address	
Postcode	
Insurance Company Name	ECICS LIMITED
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	1

Vehicle Number: SME 7108Y

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 27/3/2018

17:15 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

A

SME 71084

B

UK 88993

Tanah merah
Coast Road.

was I was Stationary at a traffic light when the lorry rear ended the car

I/We declare the foregoing particulars are true in every respect.

Date & Time: 27/3/2019 @
17:15 hrs

CO

5



Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: 18-MT108035-R00 (Private Motor Car)

1. **Index Mark and Registration Number of Vehicle** SME7108Y **Chassis No.:** JHMRC1880JC204566
2. **Name of Policyholder** GILBERT ANG YAU HENG (GILBERT HONG YAOXING)
3. **Effective date of the Commencement of Insurance for the purposes of the Act** 12/10/2018
4. **Date of Expiry of Insurance** 11/10/2019
5. **Persons or Class of Persons entitled to drive***
 (a) The Policyholder.
 (b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. **Limitations as to use***

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: E2316DDA

Insurance Plan:	Comprehensive Approved Workshop Plan	
Limit for total loss or theft:	Prevailing Market Value	
Policy Excess:	Own Damage Claims	SGD 1,000
	Windscreen Excess	SGD 100

Tokio Marine Insurance Singapore Ltd.

Authorised Signature

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Vehicle-in

Kindly Help to Arrange
Surveyor to Survey this
Vehicle
Thanks**QUOTATION**GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: ECICS LIMITED	Document No.	: SQT19001400	Page	1
	7 TEMASEK BOULEVARD	Date	: 27. Mar 2019		
	#10-01 SUNTEC TOWER FIVE	Customer No.	: WZE001		
	SINGAPORE 038987	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SME7108Y	Engine No	: K24W72402015		
Chassis No	: JHMRC1880JC204566	Date Time	: 27. Mar 2019 5:54:41 PM		
Model	: ODYSSEY 2.4 EX-S 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: GILBERT ANG YAU HENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/3/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72449)						
	OWNER: GILBERT ANG YAU HENG						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 27/3/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: ECICS LIMITED						
	TP VEH: YK8899S						
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD 128.25 shift	1	1011.00		1011.00	70.77	1081.77
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE 27	2	18.00		36.00	2.52	38.52
73215-T6A-003	MOLDINGRR.WINDSHIELD CORNER 12.67	1	16.90		16.90	1.18	18.08
73216-T6A-003	MOLDINGLRR.WINDSHIELD CORNER 12.67	1	16.90		16.90	1.18	18.08
73221-SR4-000	SPACERRR.W/SHIELD 11.70	4	3.90		15.60	1.09	16.69
73226-SZW-000	DAMPERSTD 5X5 12.75	2	8.50		17.00	1.19	18.19
73525-SYY-000	RUBBERRR QTR W/SHIELD 14.55	2	9.70		19.40	1.36	20.76
73850-T6A-003	SEALLQUARTER GLASS 26.22	1	35.10		35.10	2.46	37.56
76711-T6A-003	CAPPVOT 3.60	1	4.80		4.80	0.34	5.14
91501-S70-003	FASTENER BW/SHIELD 3.97	1	5.30		5.30	0.37	5.67
BO-WS-SEALANT	WINDSCREEN SEALANT (N) 120	2	60.00		120.00	8.40	128.40
91501-SMA-003	CLIP AQTR. 2.25	1	3.00		3.00	0.21	3.21
91501-SYA-000	CLIPQUARTER WINDSHIELD A 2.85	1	3.80		3.80	0.27	4.07
91502-S70-003	FASTENER B 7.95	2	5.30		10.60	0.74	11.34
91513-S70-003	CLIPL 2.85	1	3.80		3.80	0.27	4.07
91536-SS0-J01	FASTENER AW/SHIELD 5.70	2	3.80		7.60	0.53	8.13
04656-T6A-310ZZ	PAN SET,3RD SEAT 253.42	1	337.90		337.90	23.65	361.55
65594-T6A-300ZZ	FRAME DL,RR,UPPER 36.15	1	48.20		48.20	3.37	51.57
65597-T6A-300ZZ	EXTENTION L,RR.FRAME ENDSIDE 24.67	1	32.90		32.90	2.30	35.20

Printed on 28/3/2019 4:41:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER FIVE
SINGAPORE 038987

Registration No : SME7108Y

Chassis No : JHMR1880JC204566

Model : ODYSSEY 2.4 EX-S 18YM (EURO 6)

Owner's Name : GILBERT ANG YAU HENG

Ins Policy No. :

Date of Accident : 27/3/2019

Document No. : SQT19001400 Page 2

Date : 27. Mar 2019

Customer No. : WZE001

Svc Advisor : LIM CHOU SIONG

Engine No : K24W72402015

Date | Time : 27. Mar 2019 5:54:41 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
65673-T6A-300ZZ	FRAME DL.RR.LOWER 30.55	1	43.40	✓	43.40	3.04	46.44
64700-T6A-405ZZ	PANEL COMPL.RR.INSIDE 671.40	1	895.20	✓	895.20	62.66	957.86
04646-T6A-J01ZZ	PANEL SET L.RR. OUTSIDE 745.43	1	993.90	✓	993.90	69.57	1063.47
63720-T6A-300ZZ	GUTTER COMPL.RR.PILLAR 98.77	1	131.70	✓	131.70	9.22	140.92
66100-T6A-Q00ZZ	PANEL COMP.REAR 345.60	1	460.80	✓	460.80	32.26	493.06
72841-SH3-315	OILSHEET 30.53	1	40.70	✓	40.70	2.85	43.55
72585-T6A-000ZZ	COVER COMPL.SLIDE DR CTR RAIL 123.37	1	164.50	✓	164.50	11.52	176.02
75450-SMA-003	OUTLET 11	1	27.70	X	27.70	1.94	29.64
68100-T6A-Q10ZZ	TAILGATE COMP 803.10	1	1070.80	✓	1070.80	74.96	1145.76
74440-T6A-003	WEATHERSTRIPTAILGATE 88.05	1	117.40	✓	117.40	8.22	125.62
74800-TF0-J02	LOCKTAILGATE 139.05	1	185.40	✓	185.40	12.98	198.38
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER 78.97	1	105.30	✓	105.30	7.37	112.67
74813-SEY-003	STRIKER ASSYTAILGATE 11	1	27.70	X	27.70	1.94	29.64
74820-T6A-013	STAY ASSYR.TAILGATE OPEN 123.37	1	164.50	✓	164.50	11.52	176.02
74827-T0A-A00	STOPPERTAILGATE 11	2	3.60	X	7.20	0.50	7.70
74870-T6A-013	STAY ASSYL.TAILGATE OPEN 123.37	1	164.50	✓	164.50	11.52	176.02
74890-T6A-N11ZA	GARNISH ASSY.RR.LICEION LID 123.15	1	164.20	✓	164.20	11.49	175.69
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN 81.62	1	175.50	✓	175.50	12.29	187.79
33500-T6A-003	TAILLIGHT ASSYR. 628.57	1	838.10	✓	838.10	58.67	896.77
33550-T6A-003	TAILLIGHT ASSYL 628.57	1	838.10	✓	838.10	58.67	896.77
34100-T5A-003	LIGHT ASSYLICENSE 11	2	31.80	X	63.60	4.45	68.05
34150-T6A-003	LIGHT ASSYR.LID 389.65	1	386.20	✓	386.20	27.03	413.23
34155-T6A-003	LIGHT ASSYL.LID 389.65	1	386.20	✓	386.20	27.03	413.23
38387-SLE-003	ANTENNA ASSY.LRR. 45.45	1	60.60	✓	60.60	4.24	64.84
74940-TR0-003	BUZZER ASSYSMART 45.07	1	60.10	✓	60.10	4.21	64.31
39530-T6A-J11	CAMERA ASSY.RR.VIEW 17	1	1061.90	X	1061.90	74.33	1136.23
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR 320	1	320.00	✓	320.00	22.40	342.40
76720-T4N-H01	ARM.RR.WIPER 11	1	42.60	X	42.60	2.98	45.58
76730-S3N-003	BLADEWINDSHIELD WIPER 11	1	42.80	X	42.80	3.00	45.80

Printed on 28/3/2019 4:41:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER FIVE
SINGAPORE 038987

Registration No : SME7108Y

Chassis No : JHMRC1880JC204566

Model : ODYSSEY 2.4 EX-S 18YM (EURO 6)

Owner's Name : GILBERT ANG YAU HENG

Ins Policy No. :

Date of Accident : 27/3/2019

Document No. : SQT19001400

Date : 27. Mar 2019

Customer No. : WZE001

Svc Advisor : LIM CHOU SIONG

Engine No : K24W72402015

Date | Time : 27. Mar 2019 5:54:41 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
76700-T6A-J01	WIPER MOTOR ASSY	1 1	240.40	X	240.40	16.83	257.23
84181-T6A-J81ZA	GARNISH ASSYL QUARTER PILLAR	67.12 647 1	89.50	✓	89.50	6.27	95.77
84615-T6A-N23ZD	LINING COMP,R.RR.SIDGATE	529.05 2.13 1	705.40	✓	705.40	49.38	754.78
84616-T6A-912ZB	LID COMP,R.DAMPER MAR SIDE	1 1	48.70	X	48.70	3.41	52.11
84640-T6A-003ZA	LINING ASSYRR.PANEL	17.70 1.13 1	103.60	✓	103.60	7.25	110.85
84643-T6A-Q01ZA	COMP LIDTOOL	1 1	61.40	X	61.40	4.30	65.70
84662-T6A-Q01ZA	LID,L.RR. SIDE LINING	1 1	21.10	X	21.10	1.48	22.58
84665-T6A-N22ZD	LINING COMP,L.RR.SIDE	529.05 2.13 1	705.40	✓	705.40	49.38	754.78
84666-T6A-912ZB	LID COMP,L.DAMPER	41.47 2.13 1	55.30	✓	55.30	3.87	59.17
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	154.72 2.13 1	206.30	✓	206.30	14.44	220.74
84433-T6A-J01ZA	GARNISH ASSYTAILGATE UPPER	1 1	42.60	X	42.60	2.98	45.58
84435-T6A-J01ZA	GARNISH ASSYR.TAILGATE SIDE	30.90 2 1	41.20	✓	41.20	2.88	44.08
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	8.02 1 1	10.70	✓	10.70	0.75	11.45
84485-T6A-J01ZA	GARNISH ASSYL.TAILGATE SIDE	30.90 2 1	41.20	✓	41.20	2.88	44.08
04828-T6A-M00ZA	OUTER SET,L.RR.SEAT	1 1	268.90	X	268.90	18.82	287.72
75701-T6A-000	EMBLEMH	19.72 1 1	26.30	✓	26.30	1.84	28.14
75722-T6A-901	EMBLEM,RR.	23.25 1 1	31.00	✓	31.00	2.17	33.17
72955-T6A-003	MOLDING ASSYL.QTR WINDSHIELD	80.27 1 1	109.70	✓	109.70	7.68	117.38
74591-T6A-000	FENDERL.RR INNER	1 1	116.30	X	116.30	8.14	124.44
83303-T6A-J02ZB	CARPET ASSY,RR.FLOOR	1 1	334.10	X	334.10	23.39	357.49
04715-T6A-900ZZ	FACERR.BUMPER	426.22 2.13 1	568.30	✓	568.30	39.78	608.08
33505-SLJ-013	REFLECTOR ASSYR.RR.	1 1	45.40	X	45.40	3.18	48.58
33555-SLJ-013	REFLECTOR ASSYL.RR.	1 1	45.40	X	45.40	3.18	48.58
71502-T6A-003ZL	FACE,R.RR.BUMPER	57.60 647 1	76.80	✓	76.80	5.38	82.18
71507-T6A-003ZL	FACE,L.RR.BUMPER	57.60 2.13 1	76.80	✓	76.80	5.38	82.18
71517-T6A-901ZN	SPOILER ASSY,L.RR.	69.75 2 1	93.00	✓	93.00	6.51	99.51
71593-T6A-003	SPACERR.RR.BUMPER SIDE	14.32 1 1	19.10	✓	19.10	1.34	20.44
71598-T6A-003	SPACERL.RR.BUMPER SIDE	14.32 1 1	19.10	✓	19.10	1.34	20.44
91505-TM8-003	CLIP,BUMPER	8.62 5	2.30	✓	11.50	0.81	12.31

Printed on 28/3/2019 4:41:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: ECICS LIMITED	Document No.	: SQT19001400	Page	4
	7 TEMASEK BOULEVARD	Date	: 27. Mar 2019		
	#10-01 SUNTEC TOWER FIVE	Customer No.	: WZE001		
	SINGAPORE 038987	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SME7108Y	Engine No	: K24W72402015		
Chassis No	: JHMRC1880JC204566	Date Time	: 27. Mar 2019 5:54:41 PM		
Model	: ODYSSEY 2.4 EX-S 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: GILBERT ANG YAU HENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/3/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) 45	1	45.00		45.00	3.15	48.15
Sum Item					15045.90	1,053.25	16,099.15
BO-3M-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	1	300.00		300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00	180	250.00	17.50	267.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (N)	1	250.00	180	250.00	17.50	267.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES (N)	1	250.00		250.00	17.50	267.50
BG51D	REMOVE & INSTALL RR. L QTR GLASS (N)	1	280.00		280.00	19.60	299.60
BG02R	REPLACE RR. WINDSCREEN (N)	1	300.00		300.00	21.00	321.00
BOMISC1	PERFORM SETTING AND ALIGNMENT OF MULTI-VIEW CAMERA	1	320.00	280	320.00	22.40	342.40
BOMISC1	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY	1	320.00	280	320.00	22.40	342.40
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00		350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	380.00		380.00	26.60	406.60
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	560.00	X	560.00	39.20	599.20
BKRP02B	CUT OFF & RENEW RR PANEL FLOOR PANEL RR L W/HOUSE 12	1	8500.00	6720	8500.00	595.00	9095.00
BP06R	SPRAY PAINTING ON ROOF PANEL RR L SLIDING DOOR, RR	1	4500.00	3150	4500.00	315.00	4815.00
BOJSE	BODY JOINT SEALANT	1	80.00		80.00	22.40	342.40
Sum Labor					16960.00	1,187.20	18,147.20

Printed on 28/3/2019 4:41:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



(A Member of the Oriental Holdings Berhad)

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No. M200050223

Company Ref. No.: S60FC1380G

Customer	: ECICS LIMITED 7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER FIVE SINGAPORE 038987
Registration No	: SME7108Y
Chassis No	: JHMRCL880JC204566
Model	: ODYSSEY 2.4 EX-S 18YM (EURO 6)
Owner's Name	: GILBERT ANG YAU HENG
Ins Policy No.	:
Date of Accident	: 27/3/2019

Document No. : SQT19001400
Date : 27. Mar 2019
Customer No. : WZE001
Svc Advisor : LIM CHOU SIONG
Engine No : K24W72402015
Date | Time : 27. Mar 2019 5:54:41 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 5

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	Marcus Hale	C 3 Lines					
Date & Time	29/3/18	81006303 (112)			Total Amount 32,305.90	2,261.45	34,567.35
Excess					Total (Inclusive of GST)		34,567.35
Status	Not Audited						
Signature	Tolson [Signature]				30,316		

Printed on 28/3/2019 4:41:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**

GST Reg No.: M200050223

Company Ref. No.: S80FC1380G

Attn: Marcus (L.K.K.)

20 days

Customer: WZE001 / ECICS LIMITED
 Chassis No: JHMRC1880JC204566
 License No: SME7108Y
 Mileage: 10432
 Engine No: K24W72402015

Document No: SVO19020246
 Printed By: CSLIM
 Order Date: 29. March 2019
 Order Time: 5:28:42 PM
 Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72449) OWNER: GILBERT ANG YAU HENG OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L ACC DATE: 27/3/2019 SURVEYED BY: MARCUS (L.K.K.) DATE: 29/03/2019 @ 09:30AM REF NO: DMCV1900016H/02/CT TP INSURER: ECICS LIMITED TP VEH: YK8899S						
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD	1	1,011.00	25	758.25	53.06	811.33
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	25	27.00	1.89	28.89
73216-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73226-SZW-000	DAMPERSTD 5X5	2	8.50	25	12.75	0.89	13.64
73526-SYY-000	RUBBERRR QTR W/SHIELD	2	9.70	25	14.55	1.02	15.57
73860-T6A-003	SEALL QUARTER GLASS	1	35.10	25	26.32	1.84	28.16
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	1	5.30	25	3.97	0.28	4.25
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
91501-SMA-003	CLIP AQTR.	1	3.00	25	2.25	0.16	2.41
91501-SYA-000	CLIPQUARTER WINDSHIELD A	1	3.80	25	2.85	0.20	3.05
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91513-S70-003	CLIPL	1	3.80	25	2.85	0.20	3.05
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
04856-T6A-310ZZ	PAN SET,3RD SEAT	1	337.90	25	253.42	17.74	271.16
66594-T6A-300ZZ	FRAME DL.RR.UPPER	1	48.20	25	36.15	2.53	38.68
66597-T6A-300ZZ	EXTENTION L.RR.FRAME ENDSIDE	1	32.90	25	24.67	1.73	26.40
66573-T6A-300ZZ	FRAME DL.RR.LOWER	1	43.40	25	32.55	2.28	34.83
64700-T6A-406ZZ	PANEL COMPL.RR.INSIDE	1	696.20	25	671.40	47.00	718.40
04846-T6A-J01ZZ	PANEL SET L.RR. OUTSIDE	1	993.90	25	745.42	52.18	797.60
63720-T6A-300ZZ	OUTTER COMPL.RR.PILLAR	1	131.70	25	98.77	6.91	105.68
66100-T6A-Q00ZZ	PANEL COMP,REAR	1	460.80	25	345.60	24.19	369.79
72841-SH3-315	OILSHEET	1	40.70	25	30.52	2.14	32.66
72585-T6A-000ZZ	COVER COMPL.SLIDE DR CTR RAIL	1	164.50	25	123.37	8.64	132.01
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE	1	117.40	25	88.05	6.16	94.21
74800-TF0-J02	LOCKTAILGATE	1	185.40	25	139.05	9.73	148.78
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER	1	105.30	25	78.97	5.53	84.50
74820-T6A-013	STAY ASSYR.TAILGATE OPEN	1	164.50	25	123.37	8.64	132.01
74870-T6A-013	STAY ASSYL.TAILGATE OPEN	1	164.50	25	123.37	8.64	132.01
74890-T6A-N11ZA	GARNISH ASSY,RR.LICEION LID	1	164.20	25	123.15	8.62	131.77
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	175.60	25	131.62	9.21	140.83
33500-T6A-003	TAILLIGHT ASSYR.	1	838.10	25	628.57	44.00	672.57
33550-T6A-003	TAILLIGHT ASSYL	1	838.10	25	628.57	44.00	672.57
34150-T6A-003	LIGHT ASSYR.LID	1	386.20	25	289.65	20.26	309.93
34165-T6A-003	LIGHT ASSYL.LID	1	386.20	25	289.65	20.26	309.93
36367-SLE-003	ANTENNA ASSY,L.RR	1	60.60	25	45.45	3.18	48.63
74940-TR0-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22

Page 2/4

**HONDA****SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5456 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S80FC1380G

Customer: WZE001 / ECICS LIMITED
 Chassis No: JHMRC1880JC204566
 License No: SME7108Y
 Mileage: 10432
 Engine No: K24W72402015

Document No: SVO19020246
 Printed By: CSLIM
 Order Date: 29. March 2019
 Order Time: 5:28:42 PM
 Service Advisor: LIM CHOU SIONG

NMRB-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
84181-T8A-J81ZA	GARNISH ASSYL QUARTER PILLAR	1	89.60	25	87.12	4.70	71.82
84615-T8A-N23ZD	LINING COMP.R.RR.SIDGATE	1	705.40	25	529.05	37.03	566.08
84640-T8A-003ZA	LINING ASSYRR PANEL	1	103.80	25	77.70	5.44	83.14
84666-T8A-N22ZD	LINING COMP.L.RR.SIDE	1	705.40	25	529.05	37.03	566.06
84668-T8A-912ZB	LID COMP.L.DAMPER	1	55.30	25	41.47	2.90	44.37
84431-T8A-J01ZA	LINING ASSYTAILGATE LOWER	1	206.30	25	154.72	10.83	165.55
84435-T8A-J01ZA	GARNISH ASSYR.TAILGATE SIDE	1	41.20	25	30.90	2.16	33.06
84441-T8A-J01ZA	POCKETTAILGATE LINING PULL	1	10.70	25	8.02	0.56	8.58
84485-T8A-J01ZA	GARNISH ASSYL.TAILGATE SIDE	1	41.20	25	30.90	2.16	33.06
75701-T8A-000	EMBLEM.H	1	26.30	25	19.72	1.38	21.10
75722-T8A-901	EMBLEM.RR.	1	31.00	25	23.25	1.63	24.88
72955-T8A-003	MOLDING ASSYL.QTR WINDSHIELD	1	109.70	25	82.27	5.76	88.03
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84	456.06
71602-T6A-003ZL	FACE.R.RR.BUMPER	1	76.80	25	57.60	4.03	61.63
71607-T6A-003ZL	FACE.L.RR.BUMPER	1	76.80	25	57.60	4.03	61.63
71617-T6A-901ZN	SPOILER ASSY.L.RR.	1	93.00	25	69.75	4.66	74.63
71693-T6A-003	SPACERR.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
71698-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
91606-TM8-003	CLIP.BUMPER	5	2.30	25	8.62	0.60	9.22
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
90650-SYY-003	GROMMETTAIL LIGHT	2	1.90	25	2.86	0.20	3.05
90650-SZT-003	GROMMETRR.COMBINATION LIGHT	1	2.60	25	1.87	0.13	2.00
90001-T8A-003	BOLT TAIL LIGHT	1	3.80	25	2.85	0.20	3.05
	SUM PARTS:				9,639.76	667.79	10,207.56
BOSUN	0780	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	100.00		100.00	7.00	107.00
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BOBC		1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BA02R	EXT-YJ	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BP00R		1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BKOT00R	EXT-YJ	1	180.00		180.00	12.60	192.60
	REMOVE & RENEW RR FLOOR						
	INSULATOR.(N)						
BMA000		1	250.00		250.00	17.50	267.50
	REMOVE & INSTALL FUEL TANK FUEL						
	PIPES.(N)						
BG51D	EXT-YJ	1	280.00		280.00	19.60	299.60
	REMOVE & INSTALL RR. L.QTR GLASS.						
	(N)						
BG02R	EXT-YJ	1	300.00		300.00	21.00	321.00
	REPLACE RR. WINDSCREEN.(N)						
BOMISC1		1	280.00		280.00	19.60	299.60
	PERFORM SETTING AND ALIGNMENT						
	OF MULTI-VIEW CAMERA						
	AND PARKING-ASSIST SYSTEM.(N)						

Page 3/4



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1360G

Customer: WZE001 / ECICS LIMITED
 Chassis No: JHMRC1880JC204568
 License No: SME7108Y
 Mileage: 10432
 Engine No: K24W72402015

Document No: SVO19020246
 Printed By: CSLIM
 Order Date: 29 March 2019
 Order Time: 5:28:42 PM
 Service Advisor: LIM CHOU SIONG

BOMISC1	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY COMPONENT.(N)	1	280.00	280.00	19.60	299.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	350.00	350.00	24.50	374.50
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	380.00	380.00	26.60	406.60
BKRP02B	EXT-YJ CUT OFF & RENEW RR PANEL FLOOR PANEL RR L W/HOUSE RR L FENDER REPAIR ROOF PANEL & OTHER DAMAGE PARTS	1	6,720.00	6,720.00	470.40	7,190.40
BP05R	EXT-YBH SPRAY PAINTING ON ROOF PANEL RR L SLIDING DOOR RR PANEL FLOOR PANEL BOTH RR W/HOUSE BOTH RR FENDER & 0760	1	3,150.00	3,150.00	220.60	3,370.50
BOJSE	BODY JOINT SEALANT.	1	80.00	240.00	16.80	266.80
SUM LABOUR:				12,940.00	905.80	13,845.80
BO-3M-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	1	300.00	300.00	21.00	321.00
SUM EXT SERVICE:				300.00	21.00	321.00
TOTAL SGD				22,779.76	1,594.59	24,374.35
Total Payable (SGD)						24,374.35

GST Amount is calculated from individual line(s)

Page 4/4



HONDA

QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER FIVE
SINGAPORE 038987

Registration No : SME7108Y

Chassis No : JHMR1880JC204568

Model : ODYSSEY 2.4 EX-S 18YM (EURO 8)

Owner's Name : GILBERT ANG YAU HENG

Document No. : SQT19001731
Date : 17. Apr 2019
Customer No. : WZE001
Svc Advisor : LIM CHOU SIONG
Engine No : K24W72402015
Date | Time : 17. Apr 2019 12:43:23 PM
Surveyor Name : MARCUS (L.K.K.)
Survey Date : 29/3/2019
Authorisation Date : 29/3/2019

Page 2 of 1

ins Policy No. :
Date of Accident : 27/3/2019

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 72449)						
	OWNER: GILBERT ANG YAU HENG						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 27/3/2019						
	SURVEYED BY: MARCUS (L.K.K.)						
	DATE: 29/03/2019 @ 09:30AM						
	REF NO: DMCV1900016H/02/CT						
	TP INSURER: ECICS LIMITED						
	TP VEH: YK8899S						
	SUPPLEMENTARY LABOUR & PARTS						
90650-SYY-003	GROMMETTAIL LIGHT	2	1.90		3.80	0.27	4.07
90650-SZT-003	GROMMETRIL COMBINATION LIGHT	1	2.50		2.50	0.18	2.68
90601-T6A-003	BOLT TAIL LIGHT	1	3.80		3.80	0.27	4.07
	Sum Item				10.10	0.72	10.82

Survey By

Date & Time

Excess

Status

Signature

Total Amount	10.10	0.72	10.82
---------------------	--------------	-------------	--------------

Total (Inclusive of GST)	10.82
---------------------------------	--------------

Printed on 17/4/2019 1:23:27 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual lines.

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

Veron Chen (LKKAUTO)

From: Lim Chou Siong <cslim@honda.com.sg>
Sent: Thursday, 18 April 2019 11:39 AM
To: Marcus Chua (LKKAUTO)
Cc: SUR
Subject: Pre-Invoice Of Vehicle No: SME7108Y For Finalising
Attachments: 1013_001.pdf

Dear,

We enclosed the total final repair costs of...

Vehicle No. SME7108Y
Final Repair Costs (include GST) \$24,374.35
Repair Period*(Working Day) 20
*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong
Contact No: 81006303 HP
KAH MOTOR CO. SDN. BHD.
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
15 Ubi Road 4 Singapore 408610
Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you

From: Printer Service <printservice@honda.com.sg>
Sent: Thursday, 18 April, 2019 11:29 AM
To: Lim Chou Siong <cslim@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Apr 2019 11:42 Edit Reg		28 Mar 2019 00:00 Edit Adj Rpt	S\$22,779.76 Edit Estimates	S\$22,779.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	-, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM		
Main Claimant:	GILBERT ANG YAU HENG (GILBERT HONG YAOXING)		
Vehicle Reg. No.:	SME7108Y	Date of Loss:	27/03/2019 15:00 - :59 [5 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / DMCV1900016H/CT	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	YK8899S	Policy No. (Claimant):	
		Excess:	
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Crystabelle Tan - 6303 0190]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 09/04/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME7108Y (DMCV1900016H/CT)
[YK8899S]

TP

GILBERT ANG YAU HENG (GILBERT HONG YAOXING)

Mar 27 2019 3:00PM

[-]

Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	22/04/19 11:18	General View								Load JPG	☒	
2	22/04/19 11:18	General View								Load JPG	☒	
3	22/04/19 11:18	General View								Load JPG	☒	
4	22/04/19 11:18	General View								Load JPG	☒	
5	22/04/19 11:18	General View								Load JPG	☒	
6	22/04/19 11:18	General View								Load JPG	☒	
7	22/04/19 11:18	General View								Load JPG	☒	
8	22/04/19 11:18	General View								Load JPG	☒	
9	22/04/19 11:18	General View								Load JPG	☒	
10	22/04/19 11:18	General View								Load JPG	☒	
11	22/04/19 11:18	General View								Load JPG	☒	
12	22/04/19 11:18	General View								Load JPG	☒	
13	22/04/19 11:18	General View								Load JPG	☒	
14	22/04/19 11:18	General View								Load JPG	☒	
15	22/04/19 11:18	General View								Load JPG	☒	
16	22/04/19 11:18	General View								Load JPG	☒	
17	22/04/19 11:18	General View								Load JPG	☒	
18	22/04/19 11:18	General View								Load JPG	☒	
19	22/04/19 11:18	General View								Load JPG	☒	
20	22/04/19 11:18	General View								Load JPG	☒	
21	22/04/19 11:18	General View								Load JPG	☒	
22	22/04/19 11:18	General View								Load JPG	☒	
23	22/04/19 11:18	General View								Load JPG	☒	
24	22/04/19 11:18	General View								Load JPG	☒	
25	22/04/19 11:18	General View								Load JPG	☒	
26	22/04/19 11:18	General View								Load JPG	☒	
27	22/04/19 11:18	General View								Load JPG	☒	
28	22/04/19 11:18	General View								Load JPG	☒	
29	22/04/19 11:18	General View								Load JPG	☒	
30	22/04/19 11:18	General View								Load JPG	☒	
31	22/04/19 11:18	General View								Load JPG	☒	
32	22/04/19 11:18	General View								Load JPG	☒	
33	22/04/19 11:18	General View								Load JPG	☒	
34	22/04/19 11:18	General View								Load JPG	☒	
35	22/04/19 11:18	General View								Load JPG	☒	
36	22/04/19 11:18	General View								Load JPG	☒	
37	22/04/19 11:18	General View								Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/04/19 11:18	General View	 Load JPG	☒
39	22/04/19 11:18	General View	 Load JPG	☒
40	22/04/19 11:18	General View	 Load JPG	☒
41	22/04/19 11:18	General View	 Load JPG	☒
42	22/04/19 11:18	General View	 Load JPG	☒
43	22/04/19 11:18	General View	 Load JPG	☒
44	22/04/19 11:18	General View	 Load JPG	☒
45	22/04/19 11:18	General View	 Load JPG	☒
46	22/04/19 11:18	General View	 Load JPG	☒
47	22/04/19 11:18	General View	 Load JPG	☒
48	22/04/19 11:18	General View	 Load JPG	☒
49	22/04/19 11:18	General View	 Load JPG	☒
50	22/04/19 11:18	General View	 Load JPG	☒
51	22/04/19 11:18	General View	 Load JPG	☒
52	22/04/19 11:18	General View	 Load JPG	☒
53	22/04/19 11:18	General View	 Load JPG	☒
54	22/04/19 11:18	General View	 Load JPG	☒
55	22/04/19 11:18	General View	 Load JPG	☒
56	22/04/19 11:18	General View	 Load JPG	☒
57	22/04/19 11:18	General View	 Load JPG	☒
58	22/04/19 11:18	General View	 Load JPG	☒
59	22/04/19 11:18	General View	 Load JPG	☒
60	22/04/19 11:18	General View	 Load JPG	☒
61	22/04/19 11:18	General View	 Load JPG	☒
62	22/04/19 11:18	General View	 Load JPG	☒
63	22/04/19 11:18	General View	 Load JPG	☒
64	22/04/19 11:18	General View	 Load JPG	☒
65	22/04/19 11:18	General View	 Load JPG	☒
66	22/04/19 11:18	General View	 Load JPG	☒
67	22/04/19 11:18	General View	 Load JPG	☒
68	22/04/19 11:18	General View	 Load JPG	☒
69	22/04/19 11:18	General View	 Load JPG	☒
70	22/04/19 11:18	General View	 Load JPG	☒
71	22/04/19 11:18	General View	 Load JPG	☒
72	22/04/19 11:18	General View	 Load JPG	☒
73	22/04/19 11:18	General View	 Load JPG	☒
74	22/04/19 11:18	General View	 Load JPG	☒
75	22/04/19 11:18	General View	 Load JPG	☒
76	22/04/19 11:18	General View	 Load JPG	☒
77	22/04/19 11:18	General View	 Load JPG	☒
78	22/04/19 11:18	General View	 Load JPG	☒
79	22/04/19 11:18	General View	 Load JPG	☒
80	22/04/19 11:18	General View	 Load JPG	☒
81	22/04/19 11:18	General View	 Load JPG	☒
82	22/04/19 11:18	General View	 Load JPG	☒
83	22/04/19 11:18	General View	 Load JPG	☒
84	22/04/19 11:18	General View	 Load JPG	☒
85	22/04/19 11:18	General View	 Load JPG	☒
86	22/04/19 11:18	General View	 Load JPG	☒
87	22/04/19 11:18	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	22/04/19 11:18	General View	 Load JPG	☒
89	22/04/19 11:18	General View	 Load JPG	☒
90	22/04/19 11:18	General View	 Load JPG	☒
91	22/04/19 11:18	General View	 Load JPG	☒
92	22/04/19 11:18	General View	 Load JPG	☒
93	22/04/19 11:18	General View	 Load JPG	☒
94	22/04/19 11:18	General View	 Load JPG	☒
95	22/04/19 11:18	General View	 Load JPG	☒
96	22/04/19 11:18	General View	 Load JPG	☒
97	22/04/19 11:18	General View	 Load JPG	☒
98	22/04/19 11:18	General View	 Load JPG	☒
99	22/04/19 11:18	General View	 Load JPG	☒
100	22/04/19 11:18	General View	 Load JPG	☒
101	22/04/19 11:18	General View	 Load JPG	☒
102	22/04/19 11:18	General View	 Load JPG	☒
103	22/04/19 11:18	General View	 Load JPG	☒
104	22/04/19 11:18	General View	 Load JPG	☒
105	22/04/19 11:18	General View	 Load JPG	☒
106	22/04/19 11:18	General View	 Load JPG	☒
107	22/04/19 11:18	General View	 Load JPG	☒
108	22/04/19 11:18	General View	 Load JPG	☒
109	22/04/19 11:18	General View	 Load JPG	☒
110	22/04/19 11:18	General View	 Load JPG	☒
111	22/04/19 11:18	General View	 Load JPG	☒
112	22/04/19 11:18	General View	 Load JPG	☒
113	22/04/19 11:18	General View	 Load JPG	☒
114	22/04/19 11:18	General View	 Load JPG	☒
115	22/04/19 11:18	General View	 Load JPG	☒
116	22/04/19 11:18	General View	 Load JPG	☒
117	22/04/19 11:18	General View	 Load JPG	☒
118	22/04/19 11:18	General View	 Load JPG	☒
119	22/04/19 11:18	General View	 Load JPG	☒
120	22/04/19 11:18	General View	 Load JPG	☒
121	22/04/19 11:18	General View	 Load JPG	☒
122	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
123	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
124	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
125	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
126	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
127	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
128	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
129	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
130	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
131	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
132	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
133	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
134	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
135	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
136	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
137	22/04/19 11:18	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
139	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
140	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
141	22/04/19 11:18	Reinspection Photo	 Load JPG	☒
142	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
143	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
144	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
145	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
146	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
147	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
148	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
149	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
150	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
151	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
152	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
153	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
154	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
155	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
156	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
157	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
158	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
159	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
160	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
161	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
162	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
163	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
164	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
165	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
166	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
167	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
168	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
169	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
170	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
171	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
172	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
173	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
174	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
175	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
176	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
177	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
178	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
179	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
180	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
181	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
182	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
183	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
184	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
185	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
186	22/04/19 11:19	Reinspection Photo	 Load JPG	☒
187	22/04/19 11:19	Reinspection Photo	 Load JPG	☒

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
188	22/04/19 11:19	Reinspection Photo		Load JPG	☒
189	22/04/19 11:19	Reinspection Photo		Load JPG	☒
190	22/04/19 11:19	Reinspection Photo		Load JPG	☒
191	22/04/19 11:19	Reinspection Photo		Load JPG	☒
192	22/04/19 11:19	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/04/19 11:44	Supplementary		Load PDF	
2	25/04/19 12:15	Supplementary		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19005639/UVD3E2

Date: 25/04/2019

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle
No :

SME7108Y

Insured Vehicle No :

YK8899S

Date of Loss:

27/03/2019

Nature of Claim:

TP

Claim No:

DMCV1900016H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SME7108Y

Make & Model:

HONDA ODYSSEY, 2.4 EX-S (A)

Engine No:

K24W72402015

Reg. Date:

12/10/2018 (Man. Year: 2018)

Chassis No:

JHMRC1880JC204566

Colour:

Blue

Odometer:

10432 km

Engine Capacity:

2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side:

Dunlop 8 mm

Rear Left Side:

Dunlop 8 mm

Front Right Side:

Dunlop 8 mm

Rear Right Side:

Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,406.00	9,859.76	5,546.24	36.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,910.00	12,920.00	3,990.00	23.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	32,316.00	22,779.76	9,536.24	29.51
+ GST 7.00/7.00% (S\$)	2,262.12	1,594.58	667.54	29.51
Nett Amount (S\$)	34,578.12	24,374.34	10,203.78	29.51

INSPECTION

Date of Assignment:

28/03/2019

Date Inspected:

29/03/2019

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)

15 Ubi Road 4

Singapore 408610

Estimated Period of Repair:

20.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2019)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 EX-S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME7108Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*MOLDINGRR.WINDSHIELD SIDE	Necessary	36.00 FS	*27.00 FS
2	1		*MOLDINGR.RR.WINDSHIELD CORNER	Necessary	16.90 FS	*12.67 FS
3	1		*MOLDING.RR.WINDSHIELD CORNER	Necessary	16.90 FS	*12.67 FS
4	1		*SPACERRR.W/SHIELD (4PCS)	Necessary	15.60 FS	*11.70 FS
5	1		*DAMPERSTD 5X5 (2PCS)	Necessary	17.00 FS	*12.75 FS
6	1		*RUBBERRR QTR W/SHIELD (2PCS)	Necessary	19.40 FS	*14.55 FS
7	1		*SEALL.QUARTER GLASS	Necessary	35.10 FS	*26.32 FS
8	1		*CAPPIVOT	Cut	4.80 FS	*3.60 FS
9	1		*FASTENER BW/SHIELD	Necessary	5.30 FS	*3.97 FS
10	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
11	1		*CLIP AQTR.	Necessary	3.00 FS	*2.25 FS
12	1		*CLIPQUARTER WINDSHIELD A	Necessary	3.80 FS	*2.85 FS
13	1		*FASTENER B (2PCS)	Necessary	10.60 FS	*7.95 FS
14	1		*CLIPL	Necessary	3.80 FS	*2.85 FS
15	2		*FASTENER AW/SHIELD	Necessary	7.60 FS	*5.70 FS
16	1		*PAN SET, 3RD SEAT	Necessary	337.90 FS	*253.42 FS
17	1		*FRAME DL.RR.UPPER	Bent	48.20 FS	*36.15 FS
18	1		*EXTENTION L.RR.FRAME ENDSIDE	Bent	32.90 FS	*24.67 FS
19	1		*FRAME DL.RR.LOWER	Bent	43.40 FS	*32.55 FS
20	1		*PANEL COMPL.RR.INSIDE	Badly Dented	895.20 FS	*671.40 FS
21	1		*PANEL SET L.RR. OUTSIDE	Badly Dented / Buckled	993.90 FS	*745.42 FS
22	1		*GUTTER COMPL.RR.PILLAR	Bent	131.70 FS	*98.77 FS
23	1		*PANEL COMP. REAR	Badly Dented	460.80 FS	*345.60 FS
24	1		*OILSHEET	Necessary	40.70 FS	*30.52 FS
25	1		*COVER COMPL.SLIDE DR CTR RAIL	Warped	164.50 FS	*123.37 FS
26	1		*OUTLET	Not Necessary	27.70 FS	*- FS
27	1		*TAILGATE COMP	Distorted	1,070.80 FS	*803.10 FS
28	1		*WEATHERSTRIPTAILGATE	Twisted	117.40 FS	*88.05 FS
29	1		*LOCKTAILGATE	Dented / Jammed	185.40 FS	*139.05 FS
30	1		*SWITCH ASSYTAILGATE OPENER	Damaged	105.30 FS	*78.97 FS
31	1		*STRIKER ASSYTAILGATE	Not Necessary	27.70 FS	*- FS
32	1		*STAY ASSYR.TAILGATE OPEN	Damaged	164.50 FS	*123.37 FS
33	2		*STOPPERTAILGATE	Not Necessary	7.20 FS	*- FS
34	1		*STAY ASSYL.TAILGATE OPEN	Damaged	164.50 FS	*123.37 FS
35	1		*GARNISH ASSY, RR.LICEION LID	Cracked	164.20 FS	*123.15 FS
36	1		*MOLDING ASSYRR.LICENSE GARN	Cracked	175.50 FS	*131.62 FS
37	1		*TAILLIGHT ASSYR.	Cut	838.10 FS	*628.57 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*TAILLIGHT ASSYL.	Broken	838.10 FS	*628.57 FS
39	2		*LIGHT ASSYLICENSE	Not Necessary	63.60 FS	*- FS
40	1		*LIGHT ASSYR.LID	Broken	386.20 FS	*289.65 FS
41	1		*LIGHT ASSYL.LID	Broken	386.20 FS	*289.65 FS
42	1		*ANTENNA ASSY,L.RR	Cracked	60.60 FS	*45.45 FS
43	1		*BUZZER ASSYSMART	Cracked	60.10 FS	*45.07 FS
44	1		*CAMERA ASSY,RR.VIEW	Not Necessary	1,061.90 FS	*- FS
45	4		*ACT RR.SENSOR	Shorted	320.00 FS	*320.00 FS
46	1		*ARM,RR.WIPER	Not Necessary	42.60 FS	*- FS
47	1		*BLADEWINDSHIELD WIPER	Not Necessary	42.80 FS	*- FS
48	1		*WIPER MOTOR ASSY	Not Necessary	240.40 FS	*- FS
49	1		*GARNISH ASSYL.QUARTER PILLAR	Cut	89.50 FS	*67.12 FS
50	1		*LINING COMP,R.RR.SIDGATE	Distorted	705.40 FS	*529.05 FS
51	1		*LID COMP,R.DAMPER MAR SIDE	Not Necessary	48.70 FS	*- FS
52	1		*LINING ASSYRR.PANEL	Distorted	103.60 FS	*77.70 FS
53	1		*COMP LIDTOOL	Not Necessary	61.40 FS	*- FS
54	1		*LID,L.RR. SIDE LINING	Not Necessary	21.10 FS	*- FS
55	1		*LINING COMP,L.RR.SIDE	Distorted	705.40 FS	*529.05 FS
56	1		*LID COMP,L.DAMPER	Damaged	55.30 FS	*41.47 FS
57	1		*LINING ASSYTAILGATE LOWER	Distorted	206.30 FS	*154.72 FS
58	1		*GARNISH ASSYTAILGATE UPPER	Not Necessary	42.60 FS	*- FS
59	1		*GARNISH ASSYR.TAILGATE SIDE	Deformed	41.20 FS	*30.90 FS
60	1		*POCKETTAILGATE LINING PULL	Twisted	10.70 FS	*8.02 FS
61	1		*GARNISH ASSYL.TAILGATE SIDE	Deformed	41.20 FS	*30.90 FS
62	1		*OUTER SET,L.RR.SEAT	Not Necessary	268.90 FS	*- FS
63	1		*EMBLEMH	Necessary	26.30 FS	*19.72 FS
64	1		*EMBLEM,RR.	Necessary	31.00 FS	*23.25 FS
65	1		*MOLDING ASSYL.QTR WINDSHIELD	Necessary	109.70 FS	*82.27 FS
66	1		*FENDERL.RR INNER	Not Necessary	116.30 FS	*- FS
67	1		*CARPET ASSY,RR.FLOOR	Not Necessary	334.10 FS	*- FS
68	1		*FACERR.BUMPER	Distorted	568.30 FS	*426.22 FS
69	1		*REFLECTOR ASSYR.RR.	Not Necessary	45.40 FS	*- FS
70	1		*REFLECTOR ASSYL.RR	Not Necessary	45.40 FS	*- FS
71	1		*FACE,R.RR.BUMPER	Cut	76.80 FS	*57.60 FS
72	1		*FACE,L.RR.BUMPER	Distorted	76.80 FS	*57.60 FS
73	1		*SPOILER ASSY,L.RR.	Deformed	93.00 FS	*69.75 FS
74	1		*SPACERR.RR.BUMPER SIDE	Necessary	19.10 FS	*14.32 FS
75	1		*SPACERL.RR.BUMPER SIDE	Necessary	19.10 FS	*14.32 FS
76	1		*CLIP, BUMPER (5PCS)	Necessary	11.50 FS	*8.62 FS
77	1		*NUMBER PLATE WITH CASING	Bent	45.00 FS	*45.00 FS
78	1		*SOLAR FILM ON REAR WINDSCREEN	Necessary	300.00 FS	*300.00 FS
79	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
80	1		*GLASS SET, RR.WINDSHIELD	Shorted	1,011.00 FS	*758.25 FS
81	1		*GROMMET TAIL LIGHT (2PCS)	Necessary	3.80 FS	*2.85 FS
82	1		*GROMMETRR.COMBINATION LIGHT	Necessary	2.50 FS	*1.87 FS
83	1		*BOLT TAILLIGHT	Necessary	3.80 FS	*2.85 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	15,406.00	9,859.76
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	100.00	100.00
2	BODY UNDERSIDE COATING	New	100.00	100.00
3	REMOVE & RENEW REVERSE SENSORS - 4PCS	New	130.00	130.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	180.00
5	REMOVE & RENEW RR FLOOR INSULATOR	New	250.00	180.00
6	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	250.00	250.00
7	REMOVE & INSTALL RR.L QTR GLASS	New	280.00	280.00
8	REPLACE RR.WINDSHIELD	New	300.00	300.00
9	PERFORM SETTING AND ALIGNMENT OF MULTI-VIEW CAMERA	New	320.00	280.00
10	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY	New	320.00	280.00
11	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	350.00	350.00
12	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	380.00	380.00
13	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	New	560.00	0.00
14	CUT OFF & RENEW RR PANEL FLOOR PANEL RR L W/HOUSE	New	8,500.00	6,720.00
15	SPRAY PAINTING ON ROOF PANEL RR L SLIDING DOOR RR	New	4,500.00	3,150.00
16	BODY JOINT SEALANT	New	320.00	240.00
Gross Labour Cost (\$\$)			16,910.00	12,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >