

Hwee Jie

REF: NTUC NS/INC19005664 / Jvd357

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop mis: _____
 of _____
 Insured: SGF 74852
 Policy No: 5107895335 (9/3/19 - 20/4/19)
 Claims No: MT/1038004-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHB5158R Yr Regn: 28/11/17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius c.c. 1798
 Colour: maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 181375 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKB3FU903574626
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65 R15
 R: _____

/	
N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 28/3/19 D.O.I. 29/3/19

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Survey held at Smrt
 Des. of Damages: Frt / Rear / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHB5158R - CC3 / RBE18023000 / Jh93 D.O.A - 20/12/2018
	SGF 74852 - X
9/4/19	Final fig \$ 2562.39 Confirmed by email (Red 6573.25, 728)
RECEIVED 10 APR 2019	

Date/Time. File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time. File Return to?
 2) 9/4 - typist
 Report Format: TP
 Lump Sum / I.B.I. (\$) 2562.39

Days Of Repair: 4
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)
 Survey Fee: _____
 Transportation: _____
) \$ + PS. \$ _____
) Photos _____
) Other _____
 TOTAL _____

Veron Chen (LKKAUTO)

From: MTCL@income.com.sg
Sent: Tuesday, 9 April 2019 3:59 PM
To: Veron Chen (LKKAUTO)
Subject: RE: REQUEST FOR CLAIM NUMBER

Hi all,

Claims created.

With Regards

Junainah
Senior Admin Assistant
Motor Insurance
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 9 April 2019 3:48 PM
To: MTCL@income.com.sg
Subject: RE: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Re-send

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No
1	MT/1038004-002	SMRT TAXIS PTE LTD	SHB 5158R	SGF 7485Z
2	MT/1034440-003	SMRT TAXIS PTE LTD	SHF 287M	SKB 2437U
3	MT/1037208-002	SMRT TAXIS PTE LTD	SHB 5008R	FG 9852R

D.O.A	Time of Accident	Estimate	Tentative repair cost
28/3/2019	15:25	\$9,135.64	\$2,562.39
3/3/2019	14:30	\$13,714.90	\$4,116.48

24/3/2019	15:50	\$3,325.18	\$650.00
-----------	-------	------------	----------

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 9 April 2019 10:57 AM

To: MTCL@income.com.sg

Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us the claim number

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No
1		SMRT TAXIS PTE LTD	SHB 5158R	SGF 7485Z
2		SMRT TAXIS PTE LTD	SHF 287M	SKB 2437U
3		SMRT TAXIS PTE LTD	SHB 5008R	FG 9852R

D.O.A	Time of Accident	Estimate	Tentative repair cost
15:25	15:25	\$9,135.64	\$2,562.39
3/3/2019	14:30	\$13,714.90	\$4,116.48
24/3/2019	15:50	\$3,325.18	\$650.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

My Desktop
Notice of Loss

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="28/03/2019 11:34"/>
Vehicle No.(For Motor)	<input type="text" value="SGF7485Z"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5107895335		A S ABDUL MALIK	S7098107F	GPC	drivo CLASSIC	SGF7485Z	SGF7485Z	09/03/2019	20/04/2020

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/03/2019 17:00
Date Of Accident	28/03/2019 15:25
Exact Location Of Accident	HOOT KIAM ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5158R
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	LIM KAY LEE
NRIC No	S1823874H
Date Of Birth	02/03/1967
Occupation	OUTDOOR
Date Of Driving Pass	05/03/1987
Driving Experience	32 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 26
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - RELIEF
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : FEMALE
 Passenger 2
 NAME: : UNKNOWN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG HOOT KIAM ROAD AT THE LEFT MOST LANE WITH TWO PASSENGERS ON BOARD WHEN THE VEHICLE SGF7485Z FROM MY RIGHT LANE CUT INTO MY LANE AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO LARGE
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGF7485Z
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE HIRE
 Name of Driver
 NRIC/Passport Number
 Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

5

Passenger 1

NAME: :

GENDER: :

Passenger 2

NAME: :

GENDER: :

Passenger 3

NAME: :

GENDER: :

Passenger 4

NAME: :

GENDER: :

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Rayth 28/3/2019.
Driver's Signature
(If driver is not the policyholder)
Date & Time:

ale 28/3/19
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB5158R
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS105736
Chassis No.:	JTDKB3FU903574626
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	28 Nov 2017
First Registration Date:	28 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$27,950.00
Total Rebate Amount:	\$31,700.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Apr 2019

OK



Case Details

Case Reference Number : TAX/03/19/2140
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5158R

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6277-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Accident Date and Time : 28/03/2019 07:25 AM
 Vehicle Age(In Months) : 16

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	DEF
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	WEL
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace	BUC
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	NEC
One Time Key In	Main			PROTECTOR, FR FENDER RH	1	90.40	90.40	25.00	67.80	Replace	0	0	Check	
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Check	
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	0	Repair	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	NEC
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	nn
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair	

Total Spare Part Cost 4,990.20

Surveyor Total 1,162.38

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 4,990.20

Final Sur Total 1,162.38

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks	
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	0	0	Not Give	✓	nn
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	0	Repair	✓	
Total Spare Part Cost									4,990.20	Surveyor Total		1,182.38			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0			
Final Spare Part Cost									4,990.20	Final Sur Total		1,182.38			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	845.00	600	
Total:			845.00	600.00	


Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	50	
4	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
5	Main	TO RESPRAY VIEW MIRROR	180.00	50	
Total:			1,494.00	700.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			480.00	80.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,990.20	1,182.38
Total Labour Cost	845.00	600.00
Total Spray Painting	1,494.00	700.00
Other	480.00	80.00
Overall Total	7,809.20	2,562.38
Lump Sum Repair Option		
Lump Sum Total	0.00	2,562.38
Surveyor Approved Amount		2,562.38
No of Repair Days*	6	4
Remarks		P/P REPAIR, PHOTO BEFORE PAINT.
Surveyor Name		Hwee Jie
Signature		 14/19
Survey Date	29/03/2019	

Save Clear

LKK Auto Consultant - Repairing
the Repairer of [unclear]

- To resurvey before and after repairing
- To display damage - [unclear] repair
- Parts of [unclear] [unclear]
- The party who [unclear] [unclear] [unclear]
- Not a [unclear] [unclear]
- Supplemental [unclear] [unclear] and [unclear] [unclear] approval from insurance company

Acknowledged by Repairer
 Sign: _____
 Date: _____

Section A - Accident Details

Registration Number	SHB5158R
Case Reference Number	TAX/03/19/2140
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LIM KAY LEE
Type of Accident	Side Swipe
Accident Date and Time	28/3/2019 3:25 PM
Accident Reported Date and Time	28/3/2019 5:01 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100812
Special Instruction to ARC, if any	TP
Prepared Date and Time	29/3/2019 11:18 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	





Diagram illustrating the accident location on the vehicle.

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$600.00
Total Spray Cost	\$1,494.00	\$700.00
Total Spare Part Cost	\$4,990.20	\$1,182.39
Total Other Cost	\$480.00	\$80.00
TOTAL COST	\$7,809.20 <i>9135.64</i>	\$2,562.39 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	29/03/2019 11:58 AM	29/03/2019 1:04 PM
Signature		
Remarks		P/P REPAIR, PHOTO BEFORE PAINT.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park East, Singapore 757705
 FAX Number : 65655592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 88662672

Date Generated : 07/04/2019
 User ID : PehSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0090	Invoice Number	
Quotation Date	06.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$845.00	\$600.00
Total Labour	\$845.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$1,494.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$480.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119479 62	COVER, FR BUMPER	1.00	\$495.50 ✓	25.00	\$371.63	Replace	Replace ✓	DEF
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50 ✓	25.00	\$11.25	Replace	Replace ✓	NEC
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90 ✓	0.00	\$0.00	Replace	Check X	nn
		53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10 ✓	25.00	\$699.83	Replace	Replace ✓	BUL
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90 ✓	25.00	\$39.68	Replace	Replace ✓	NEC
		53827470 50	PROTECTOR, FR FENDER RH	0.00	\$90.40 ✓	0.00	\$0.00	Replace	Check X	nn
		53875470 70	LINER, FR FENDER, RH	0.00	\$196.40 ✓	0.00	\$0.00	Replace	Check X	nn
		67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60 ✓	100.00	\$0.00	Replace	Repair P	Repair
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00 ✓	0.00	\$60.00	Replace	Replace ✓	NEC
			TYRE	0.00	\$126.74 ✓	0.00	\$0.00	Replace	Not Given X	nn
		42611- 47450	WHEEL, DISC FRONT	1.00	\$1,555.10 ✓	100.00	\$0.00	Replace	Repair P	Repair
		87910474 50	MIRROR ASSY, OUTER REAR VIEW, RH	0.00	\$1,373.50 ✓	0.00	\$0.00	Replace	Not Given X	nn



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
88 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63965592
Estimator Telephone Number: 65622233
Accident Reporting Number: 6862272

Date Generated : 07/04/2015

User ID : PohSuan

		87915470 70A1	COVER, OUTER MIRROR, RH	1.00	\$89.50 ✓	100.00	\$0.00	Replace	Repair ✓	Repair
Total					\$6,303.14		\$1,182.39			
Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total										

9135.64

1182.39
+ 600.00
+ 780.00

2562.39

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Tuesday, 9 April 2019 10:22 AM
To: Hwee Jie (LKK Auto)
Cc: Veron Chen (LKKAuto)
Subject: RE: SHB5158R

Follow Up Flag: Follow up
Flag Status: Flagged

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Hwee Jie (LKK Auto) [mailto:hweejie@lkkauto.com]
Sent: Tuesday, 9 April 2019 10:07 AM
To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)
Cc: Veron Chen (LKKAuto)
Subject: RE: SHB5158R

Hi poh suan,

Finalized P/P \$2,562.39/- 4days.

Best Regards,
Hwee Jie | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 8 April, 2019 9:34 AM
To: Hwee Jie (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB5158R

Hi Hwee Jie,

Attached herewith the repair estimate of SHB 5158R having Case No: TAX/03/19/2140.

There is no change to the approved amount of \$2,562.39 @ 4 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19005664/Jvd3s2			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 12-04-2019	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGF 7485Z	Veh. Inspected	SHB 5158R
Policy No.	5107895335	Coverage (\$)	0.00
Claim No.	MT/1038004-002	Excess (\$)	0.00
Assign From		Assign Date	29/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU903574626	Colour	MAROON
Odometer	181375	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	6 mm
L/H Front Tyre	195/65R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65R15	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/03/2019	Inspection Date	29/03/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5158R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, FR BUMPER (DISC 25%)	DEFORMED	495.50	371.63
10	CLIPS PIECE, FRT & RR BUMPER @ \$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	FENDER SUB-ASSY, FR, RH (DISC 25%)	BUCKLED	933.10	699.83
1	EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.68
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	SUPPORT, FR BUMPER RH	NOT NECESSARY	76.90	-
1	PROTECTOR, FR FENDER RH	NOT NECESSARY	90.40	-
1	LINER, FR FENDER, RH	NOT NECESSARY	198.40	-
1	TYRE	NOT NECESSARY	126.74	-
1	MIRROR ASSY, OUTER REAR VIEW, RH	NOT NECESSARY	1,373.50	-
1	PANEL SUB-ASSY, FRONT DOOR RH	TO REPAIR SEE LABOUR	1,249.60	-
1	WHEEL, DISC FRONT	TO REPAIR SEE LABOUR	1,555.10	-
1	COVER, OUTER MIRROR, RH	TO REPAIR SEE LABOUR	89.50	-
			6,316.64	1,182.39
LABOUR				
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, FRONT DOOR RH; WHEEL, DISC FRONT AND COVER, OUTER MIRROR, RH. SPRAY PAINT.		845.00	600.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		1,494.00	700.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		80.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	100.00	30.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)		120.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	120.00	30.00
			60.00	-
			2,819.00	1,380.00
GRAND TOTAL			9,135.64	2,562.39

Report Ref No. NS/INC19005664/Jvd3s2

RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,562.39
----------------------------------------------------	--	--	-----------------

Report Ref No. NS/INC19005664/Jvd3s2

ONG HWEE JIE
Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.