

16p AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : HOW TEOH TONG
BLK 250A COMPASSVALE ST
#04-77
SINGAPORE 541250

Claim No: MC1900247
No: MF1900536
Date: 29 Aug 2019
Policy No: PNPV2018-00000434
Veh Reg No: SKZ1456U
Make/Model: MAZDA BIANTE 5-DOOR

ATTN:

Your Ref No: SKZ1456U
Claim Type: Third Party
Accident Date: 19/03/2019
TP Veh Reg No: SJA1125T

Repair Cost to Vehicle No (For Finalization):SKZ1456U

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	1,114.70	* price in estimate wrong, was cost price.
2 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	92.80	
3 REAR BUMPER CLIPS	15 PC	60.00	
4 REAR BUMPER CHROME MOULDING CTR	1 PC	123.90	
5 REAR BUMPER CHROME MOULDING SIDE LH & RH	2 PC	163.80	
		1,555.20	
	Less 20%	311.04	1,244.16
LABOUR			
6 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	15.00	
7 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
8 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	
9 TO SPRAY REAR BUMPER	1 PC	220.00	
		485.00	485.00
INSURANCE			
10 MERIMEN CHARGES	1 EA	10.00	
		10.00	10.00
Total			S\$ 1,739.16 ✓/ok
Less Excess			S\$ 0.00
Amount Before GST			S\$ 1,739.16
Add GST @ 7%			121.74
Total Amount Payable			S\$ 1,860.90

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHT HUNDRED SIXTY AND CENTS NINETY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 02/04/2019

For AH LIM MOTOR COMPANY
AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Mar 2019)
 Parts: M1-MPV MAZDA BIANTE 2.0 BIANTE 5-DOOR WAGON SP.6E (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Ah Lim Motor Company/SKZ1456U/29/03/2019 16:42
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE <i>mc (B7)</i>	20:00	0:00	*1,618.70 FL X
2	2		*TAILGATE HINGE LH & RH <i>mc</i>	20:00	0:00	*68.20 FL X
3	1		*TAILGATE CTR REFLECTOR <i>mc (C.R.1)</i>	20:00	0:00	*1,922.40 FL X
4	1		*TAILGATE NO. PLATE GARNISH (CHROME) <i>mc</i>	20:00	0:00	*528.80 FL X
5	1		*TAILGATE SKY ACTIVE TECHNOLOGU LOGO <i>mc</i>	20:00	0:00	*111.50 FL X
6	1		*TAILGATE INNER LOCK <i>mc</i>	20:00	0:00	*252.00 FL X
7	1		*TAILGATE INNER TRIMBOARD <i>mc</i>	20:00	0:00	*406.00 FL X
8	1		*TAILGATE RUBBER <i>mc</i>	20:00	0:00	*207.90 FL X
9	1		*TAILAMP RH <i>mc</i>	20:00	0:00	*1,064.00 FL X
10	1		*REAR BUMPER <i>mc 1 Rd.</i>	20:00	0:00	*540.00 FL X
11	2		*REAR BUMPER SIDE RETAINERS LH & RH <i>old DMS</i>	20:00	0:00	*92.80 FL X
12	15		*REAR BUMPER CLIPS <i>mc</i>	20:00	0:00	*60.00 FL X
13	1		*REAR BUMPER CHROME MOULDING CTR <i>mc</i>	20:00	0:00	*123.90 FL X
14	2		*REAR BUMPER CHROME MOULDING SIDE LH & RH <i>mc</i>	20:00	0:00	*163.80 FL X
15	1		*REAR BUMPER REFLECTOR RH <i>mc</i>	20:00	0:00	*118.50 FL X
16	1		*INNER SEAL <i>mc</i>	0	0:00	*20.00 FS X
17	1		*WINDSCREEN SEALANT <i>mc</i>	0	0:00	*40.00 FS X
18	1		*REVERSE SENSOR <i>mc</i>	0	0:00	*200.00 FS X

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 7,538.50
 - List Item Discount on L Items (S\$) 1,455.70
 Total Parts (S\$) 6,082.80

Ah Lim Motor Company/SKZ1456U/29/03/2019 16:42. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 ^{15/}
2	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	New	na 150.00 X
3	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	na 120.00 X
4	TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	New	na 80.00 X
5	TO REMOVE & REINSTALL REVERSE CAMERA	New	na 80.00 X
6	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	New	80.00 ^{50/}
7	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	na 120.00 X
8	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD. TO KNOCK & REPAIR END PANEL; REAR FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	2000 1,000.00
9	TO SPRAY TAILOATE REAR BUMPER; END PANEL REAR FENDER RH.	New	2200 1,000.00
Gross Labour Cost (S\$)			2,670.00

Ah Lim Motor Company/SKZ1456U/29/03/2019 16:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >