

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5528B****AAD1903-213***Not Authorized  
L/Sing & Food*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHC 5528B**

VF1ABL15AUC278869

RENAULT

LATITUDE

27.3.2019

**AXA**

15/8/2014

|   | <b>PART</b>                          |    | <b>LIST</b>         |
|---|--------------------------------------|----|---------------------|
| 1 | DOOR PANEL REAR RH                   | \$ | <i>R</i> 2,844.66 ✓ |
| 1 | DOOR GUIDE REAR RH                   | \$ | <i>S</i> 176.82     |
| 1 | DOOR HINGE UPPER RH                  | \$ | <i>N</i> 274.50     |
| 1 | DOOR HINGE LOWER RH                  | \$ | <i>N</i> 300.55     |
| 1 | DOOR CHECK REAR LH/RH L70Y           | \$ | <i>S</i> 203.06     |
| 1 | DOOR LOCK REAR RH                    | \$ | <i>N</i> 908.75     |
| 1 | DOOR HANDLE OUTER REAR RH            | \$ | <i>S</i> 126.49     |
| 1 | DOOR HANDLE CAP REAR RH              | \$ | <i>S</i> 35.52      |
| 1 | DOOR HANDLE SEAL REAR RH             | \$ | <i>S</i> 7.89       |
| 1 | DOOR HANDLE COVER REAR RH            | \$ | <i>S</i> 13.22      |
| 1 | DOOR HANDLE MODULE REAR RH           | \$ | <i>S</i> 133.60     |
| 1 | DOOR REGULATOR REAR RH               | \$ | <i>S</i> 1,135.10   |
| 1 | DOOR REGULATOR MOTOR REAR RH         | \$ | <i>S</i> 893.75     |
| 1 | DOOR REGULATOR NUT REAR L70Y         | \$ | <i>S</i> 12.43      |
| 1 | DOOR REGULATOR MOTOR SCREW REAR L70Y | \$ | <i>S</i> 6.31       |
| 1 | DOOR FINISHER REAR RH                | \$ | <i>S</i> 423.10     |
| 1 | DOOR MOULDING REAR RH                | \$ | <i>S</i> 176.82     |
| 1 | DOOR MOULDING CLIP L70Y              | \$ | <i>N</i> 5.92       |
| 1 | DOOR MOULDING SCREW L70Y             | \$ | <i>S</i> 6.91       |
| 1 | DOOR CASING REAR RH                  | \$ | <i>S</i> 1,509.06   |
| 1 | DOOR WATER SHIELD REAR RH            | \$ | <i>S</i> 30.39      |
| 1 | DOOR CASING CLIP                     | \$ | <i>N</i> 12.63      |
| 1 | DOOR CASING LIGHT L70Y               | \$ | <i>S</i> 48.74      |
| 1 | DOOR FINISHER INNER REAR RH          | \$ | <i>S</i> 323.44     |
| 1 | DOOR FINISHER BRACKET INNER REAR RH  | \$ | <i>N</i> 46.97      |
| 1 | DOOR FINISHER BRACKET INNER REAR RH  | \$ | <i>N</i> 20.33      |
| 1 | DOOR FINISHER BRACKET INNER REAR RH  | \$ | <i>N</i> 20.33      |
| 1 | DOOR FINISHER BRACKET INNER REAR RH  | \$ | <i>N</i> 20.33      |
| 1 | DOOR GRAB HANDLE REAR RH             | \$ | <i>S</i> 210.96     |

X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5528B**

**AAD1903-213**

|   |                                |        |      |                  |     |
|---|--------------------------------|--------|------|------------------|-----|
| 1 | DOOR BLIND REAR RH             | \$     | Sm   | 741.80           | X   |
| 1 | DOOR WHEATHESTRIIP REAR RH     | \$     | Sm   | 410.66           | X   |
| 1 | DOOR SEAL REAR RH              | \$     | Sm   | 162.02           | X   |
| 1 | DOOR GLASS RUNNER SEAL REAR RH | \$     | Sm   | 229.31           | X   |
| 1 | DOOR WAIST SEAL OUTER REAR RH  | \$     | Sm   | 334.69           | X   |
| 1 | DOOR WAIST SEAL INNER REAR RH  | \$     | Sm   | 115.64           | X   |
| 1 | FENDER PANEL REAR RH           | \$     | Bt   | 3,299.13         | ✓   |
| 1 | FENDER PANEL INNER TRIM REAR   | \$     | Sm   | 671.45           | X   |
| 1 | WHEELARCH REAR RH              | \$     | R    | 543.47           | X   |
| 1 | DOOR MIRROR ASSY RH            | \$     | Sm   | 1,483.40         | X   |
| 1 | ROCKER PANEL INNER GARNISH RH  | \$     | Sm   | 466.51           | X   |
| 1 | ROCKER PANEL INNER RH          | \$     | R    | 1,024.79         | X   |
| 1 | ROCKER PANEL CENTER RH         | \$     | R    | 990.25           | X   |
| 1 | BUMPER COVER REAR              | \$     | Bu/R | 1,108.46         | ✓   |
| 1 | BUMPER LOWER REAR              | \$     | Sm   | 768.84           | } X |
| 1 | BUMPER BRACKET CTR REAR        | \$     | Sm   | 113.47           |     |
| 1 | BUMPER BRACKET SIDE RH REAR    | \$     | Sm   | 135.97           |     |
| 1 | BUMPER RETAINER RH REAR        | \$     | Sm   | 44.99            |     |
| 1 | REAR TAILAMP RH                | \$     | Sm   | 552.55           |     |
|   |                                | \$     |      | <b>23,125.98</b> |     |
|   |                                | 10% \$ |      | <b>2,312.60</b>  |     |
|   |                                | \$     |      | <b>20,813.38</b> |     |

**Special Nett**

|   |                               |    |    |       |      |
|---|-------------------------------|----|----|-------|------|
| 1 | REAR DOOR STICKER '6555-3333" | \$ | na | 80.00 | base |
| 1 | DOOR CHECK BOLT               | \$ | na | 22.69 | } X  |
| 1 | DOOR GUIDE SCREW              | \$ | na | 10.85 |      |
| 1 | DOOR HINGE BOLT               | \$ | na | 10.85 |      |
| 1 | DOOR HINGE NUT RH             | \$ | na | 14.60 |      |
| 1 | DOOR CHECK BOLT               | \$ | na | 22.69 |      |
| 1 | DOOR CHECK NUT                | \$ | na | 3.75  |      |
| 1 | DOOR LOCK SCREW L70Y          | \$ | na | 6.12  |      |
| 1 | DOOR CATCH SCREW L70Y         | \$ | na | 10.06 |      |

**TOTAL \$ 181.63**

**Trans-cab Auto Services Pte Ltd**

AAD1903-213

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5528B

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>20,995.01</b> |
|--------------------|-----------|------------------|

**LABOUR**

|   |    |          |          |
|---|----|----------|----------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 4,500.00 | 8001     |
| Putty and spray painting of the affected portion.   | \$ | 4,200.00 | 6601     |
| To rust-proofing of the affected areas.   | \$ | 170.00   | 601      |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | 380.00   | 1001     |
| To check steering geometry and computer wheel alignment   | \$ | 220.00   | 601      |
| To transfer of tire, rim and on wheel balancing.  | \$ | 170.00   | 201      |
| To Check Electrical Lighting Concerned.   | \$ | 170.00   | 201      |
| To transfer of front fender fittings, attachment and perform water seepage test.  | \$ | 380.00   | nn 601 X |
| To transfer of front door fittings, attachment and perform water seepage test.  | \$ | 380.00   | nn 601 X |
| To transfer of Rear door fittings, attachment and perform water seepage test.   | \$ | 380.00   | 601      |
| To transfer of Rear fender fittings, attachment and perform water seepage test.   | \$ | 380.00   | nn 601 X |
| To transfer of Rear bumper fittings, attachment and perform water seepage test.   | \$ | 380.00   | nn 601 X |
| Towing Fees.  | \$ | 120.00   | nn 601 X |

**Trans-cab Auto Services Pte Ltd**

**AAD1903-213**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5528B**

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *~ 380.00 X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *~ 380.00 X*

**TOTAL** \$ 12,590.00

**Over All Total** \$ 33,585.01

**LUMP SUM ( REPAIR DAY)**

*15 DAYS  
5 day,*