



Jia Le

Section A - Accident Details	
Registration Number	5HF489Y
Case Reference Number	TAX003/19/2132
Registration Date	30/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	MOHAMED ZAHRI BIN ONAN
Type of Accident	Head to Rear
Accident Date and Time	26/3/2019 4:33 PM
Accident Reported Date and Time	27/3/2019 10:32 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100762
Special Instruction to ARC, if any	TP/AIG-LKK
Prepared Date and Time	26/3/2019 10:31 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Jia Le

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,475.00	\$500.00
Total Spare Part Cost	\$5,226.86	\$1,151.72
Total Other Cost	\$500.00	\$40.00
TOTAL COST	\$8,047.88	\$2,091.72
Lump Sum Total	\$8,050.00	\$2,100.00 (L/S)
Number of Repair Days	8.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	29/03/2019 2:31 PM	29/03/2019 12:03 PM
Signature		
Remarks	initial estimated 6 days request number of extend 2 days	L/S REPAIR , PHOTO AFTER PAINT.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 55 Woodlands Industrial Park EA, Singapore 737703
 FAX Number: 63985382
 Estimator Telephone Number: 64482033
 Quotation Reporting Number: 88025672

Date Generated: 21/07/2019
 User ID: Fatimah

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1907-0289	Invoice Number	
Quotation Date	18.07.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$1,476.00	\$500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
Total Other Costs	\$500.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$206.70	0.00	\$0.00	Replace	Check ✗
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check ✗
		52013-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check ✗
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check ✗
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check ✗
			PXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given ✗
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given ✗
		78891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given ✗



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 20 Woodlands Industrial Park EA, Singapore 731102
 FAX Number: 63925522
 Estimate/Telephone Number: 68822021
 Accident Reporting Number: 68822073

Date Generated: 31/07/2016
 Year #: Full Year


Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
52592-47021			BUMPER SEAL, RR LH	1.00	\$88.90	25.00	\$66.68	Replace	Replace ✓
52591-47021			BUMPER SEAL, RR RH	1.00	\$65.70	25.00	\$49.28	Replace	Replace ✓
52576-47020			BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
52575-47020			BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
58308-47011			UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given X
67005-47241			TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair ✓
69350-47030			TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Not Given X
69415-47020			TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given X
69431-47010			STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given X
67981-47022			TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Check X
75374-47051			NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
58307-47060			END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check X
64716-47031B0			END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Not Given X
64716-47031B0			END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Not Given X
58336-12090			REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check X
4006314			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check X
58311-47071			SPARE TYRE PANEL	0.00	\$967.70	0.00	\$0.00	Replace	Not Given X
64993-47020			BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given X
58416-47030B3			BOX, RR FLOOR, BOARD	0.00	\$879.60	0.00	\$0.00	Replace	Not Given X
Total					\$7,380.21		\$630.92		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
52023-12240			BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace ✓
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
67881-47022			TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace ✓
Total					1,018.30		808.73		

1439.65
 - 208
 + 1151.72
 + 400.00
 + 540.00

 2091.72
 48 \$2100/-



Case Details

Case Reference Number : TAX05/19/2132
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF489Y

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6261-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 26/03/2019 08:33 AM
 Vehicle Age(In Months) : 54

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Parts Cost Detail

SOM Type	Coating Type	Position	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.00	458.00	25.00	343.50	Replace	1	343.50	Replace *	DEF ✓
One Time Key In	Main			BUMPER CLIPS	10	1.81	18.10	25.00	13.58	Replace	10	13.58	Replace *	rec ✓
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	35.00	134.27	Replace	0	0	Check *	X NM
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	129.80	129.80	25.00	104.70	Replace	0	0	Check *	X NM
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	129.80	129.80	25.00	104.70	Replace	0	0	Check *	Y NM
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.56	Replace	0	0	Check *	X NM
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check *	Y NM
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace *	/ rec
One Time Key In	Main			BUMPER LIP COVER RRLH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give *	X NM
One Time Key In	Main			BUMPER LIP COVER RRHH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give *	X NM
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give *	X NM

Total Spare Part Cost	5,724.80	Surveyor Total	550.91
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	4,579.36	Final Sur Total	504.73

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	1	88.88	Replace	/ REC
One Time Key In	Main			BUMPER SEAL, RR RH	1	45.70	45.70	25.00	34.28	Replace	1	44.28	Replace	/ REC
One Time Key In	Main			BUMPER SIDE RETAINER RRLH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	X N/A
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	X N/A
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair	X R
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	332.08	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.78	Replace	0	0	Not Give	X N/A
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.68	Replace	0	0	Not Give	X N/A
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Check	X N/A
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.93	Replace	/ REC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	X N/A
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	X N/A
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Not Give	X N/A
One Time Key In	Main			REINFORCEMENT, RR	2	54.80	109.60	25.00	81.90	Replace	0	0	Check	X
One Time Key In	Main		4006314	SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	X

Total Spare Part Cost	5,724.88	Surveyor Total	630.91
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	4,579.90	Final Sur Total	504.73

SMART Recommendation											Surveyor Approval			
SOB Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SPARE TYRE PANEL	1	867.70	867.70	25.00	650.78	Replace	0	0	Not Give	X hu
One Time Key In	Main			BOX, DECK FLOOR, RR	1	648.70	648.70	25.00	486.53	Replace	0	0	Not Give	X hu
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Give	X hu
Total Spare Part Cost									5,724.85	Surveyor Total		630.91		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									4,579.88	Final Sur Total		604.73		

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY REAR PANEL	180.00	0	
5	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
Total:			1,296.00	400.00	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
3	Main	TO REMOVE AND REPT WIRE HARDESS	120.00	0	
4	Main	TO WASH AND VACUUM	80.00	0	
Total:			400.00	40.00	

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
Total:			900.00	40.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spent Part Detail	4,572.88	504.73
Total Labour Cost	845.00	400.00
Total Spray Painting	1,296.00	400.00
Other	500.00	40.00
Owed Total	7,213.88	1,344.73
Lump Sum Repair Option	-	-
Lump Sum Total	7,213.88	1,344.73
Surveyor Approved Amount		1,350.00
No of Repair Days*	6	4
Remarks		L/S REPAIR , PHOTO AFTER PAINT.
Surveyor Name		Hasee ja
Signature		
Survey Date	23/03/2018	

Save Clear

REQUEST FOR SUPPLYMENT PARTS

Contractor:		Date of Collection	1 / 1
Accident Case Number	TAX 03/19/2012	Date of Request	01/04/2019
Vehicle No	SHE 489Y	Number of Days to Extend (If any)	12
Vehicle Model	TOYOTA PRIUS		

S/N	Part Number	Part Description	Quantity	Unit Price	
		REAR BUMPER REINFORCEMENT	1pc	BT	\$154.28
		ARM SUB ASSY, REAR BUMPER LH	1pc	BT	\$104.70
		ARM SUB ASSY, REAR BUMPER RH	1pc	BT	\$104.70
		REVERSE SENSOR	1 SET	Shorted	\$150
		TAILGATE DOOR WEATHERSTRIP	1pc	CUT	\$265.95
		LABOR TO SPRAY REAR BUMPER REINFORCEMENT		\$150	100

<<Please submit photographs for damaged parts>>

3/4/19

I, (Name) _____
 (Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
 (to be signed in front of an authorized witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission