



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk C #01-41 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

29/03/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP ALG
Jin Ce, MK053REH104547079.

Accident date: 27/03/2019

Estimated repair cost for vehicle no: SLC1627C TOYOTA ALTIS 1.6 A '16

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Buckled</i>		\$655.80	✓
2	2	Rear Boot Lid Hinge <i>Not new</i>	\$77.80	\$155.60	+
3	1	Rear Boot Lid Emblem Logo		\$66.70	✓
4	1	Rear Boot Lid Corolla Logo <i>for</i>		\$45.70	✓
5	1	Rear Boot Lid Altis Logo		\$39.40	✓
6	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00	+
7	1	Rear Boot Lid Centre Chrome Moulding <i>Not new</i>		\$267.90	+
8	2	Rear Boot Lid Side Reflector <i>Not RH cancelled</i>	\$280.50	\$561.00	✓
9	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$382.00	✓
10	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$166.40	✓
11	1	Rear Boot Lid Inner Trim Board <i>2 new</i>		\$385.10	+
12	10	Rear Boot Lid Inner Trim Board Clip <i>for</i>	\$6.50	\$65.00	+
13	1	Rear Boot Lid Camera (Special Nett) <i>Not new</i>		\$680.00	+
14	2	Rear Tail Lamp <i>cut</i>	\$463.10	\$926.20	✓ 736
15	2	Rear Tail Lamp Panel <i>Repair</i>	\$176.90	\$353.80	+
16	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	✓
17	1	Rear Bumper <i>Deformed</i>		\$482.00	✓
18	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00	30
19	2	Rear Bumper Side Retainer <i>new</i>	\$104.40	\$208.80	✓
20	2	Rear Bumper Side Reflector <i>Not new</i>	\$35.10	\$70.20	+
21	1	Rear Bumper Reinforcement <i>Best</i>		\$381.70	✓
22	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$380.00	200(SW)
23	1	Rear End Panel <i>Dented</i>		\$581.10	✓
24	1	Rear End Panel Top Garnish <i>Deformed</i>		\$229.40	✓
25	2	Rear Fender <i>Repair</i>	\$972.45	\$1,944.90	+
26	2	Rear Fender Inner Trim Board <i>for</i>	\$415.10	\$830.20	+
27	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00	+
28	1	Rear Spare Tyre Panel <i>Repair</i>		\$802.90	+
29	1	Rear Spare Tyre Panel Top Cover <i>Deformed</i>		\$348.20	✓

30	1	Rear Spare Tyre Panel & End Panel Sealant <i>3 AP</i>	\$450.00 +
31	1	Rear Windscreen Seal	\$125.10 +
32	1	Rear Exhaust <i>Bert.</i>	\$781.10 ✓
33	1	Rear Centre Exhaust <i>3 AP</i>	\$2,835.70 +
34	4	Rear Exhaust Mounting	\$33.70 \$134.80 +

5727.30
4295.47 *SN: 200*

Subtotal :- \$15,587.70

Labour charges

To remove & refit reverse sensor	\$100.00 <i>50</i>
To remove & refit rear & centre exhaust	\$380.00 <i>80</i>
To remove & refit boot lid camera	\$180.00 <i>60</i>
To remove & refit rear windscreen	\$120.00 +
Gum	\$50.00 +
To check wiring	2750 \$100.00 <i>30</i>
Tuff Kote	\$150.00 <i>60</i>
Panel beating	\$1,400.00 <i>1100</i>
Spray painting	\$1,600.00 <i>1200</i>

To remove upholstery *150 80*

To transfer bootlid fittings *150 80*

Subtotal :- \$4,080.00

Total:- \$19,667.70

total 7245.47

H/S: 5.8K

06 days.

5.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: