

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 931Y**AAD1903-219***Not Authored**Resurvey B4 painting*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 931Y

VF1ABL15AUC283294

RENAULT

LATITUDE

27.3.2019

III

8/12/2017

PART**LIST**

1	1	BUMPER COVER FRT
2	1	BUMPER SPOILER FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT LH
5	1	BUMPER SUPPORT FRT
6	1	BUMPER RETAINER FRT RH
7	1	BUMPER SUPPORT FRT
8	1	BUMPER UNDERTRAY FRT
9	1	BUMPER GRILLE LOWER FRT
10	1	BUMPER FOG LAMP GRILLE LH
11	1	BUMPER FOG LAMP GRILLE RH
12	1	BUMPER BEAM FRT
13	1	TOW COVER FRT
14	1	RADIATOR GRILLE
15	1	RADIATOR GRILLE BADGE 'RENAULT'
16	1	RADIATOR GRILLE FRAME
17	1	FRAME FULL SUPPORT PANEL
18	1	FRAME FULL SUPPORT BRACKET
19	1	FRONT BRACE PANEL
20	1	HORN
21	1	HORN BRACKET
22	1	HEADLAMP RH
23	1	HEADLAMP HARNESS
24	1	HEADLAMP PANEL FRT RH
25	1	BONNET
26	1	BONNET INSULATOR
27	1	BONNET STRUT LH
28	1	BONNET STRUT RH
29	1	BONNET HINGE LH

\$	<i>B₁</i>	1,259.42	✓
\$	<i>S_L</i>	181.75	X
\$	<i>CM</i>	394.68	✓
\$	<i>D₁</i>	151.41	✓
\$	<i>S_L</i>	123.88	X
\$	<i>D₁</i>	150.77	✓
\$	<i>S_L</i>	123.88	X
\$	<i>S_L</i>	472.83	X
\$	<i>CM</i>	266.80	✓
\$	<i>S_L</i>	207.21	X
\$	<i>S_L</i>	207.21	X
\$	<i>B₁</i>	914.08	✓
\$	<i>S_L</i>	28.61	X
\$	<i>CM</i>	1,707.78	✓
\$	<i>CM</i>	225.36	✓
\$	<i>CM</i>	1,353.75	✓
\$	<i>CM</i>	615.90	✓
\$	<i>B₁</i>	89.79	✓
\$	<i>B₁</i>	177.22	✓
\$	<i>S_L</i>	314.17	X
\$	<i>R</i>	40.45	X
\$	<i>ntjem S₂</i>	1,184.43	✓
\$	<i>S_L</i>	928.29	X
\$	<i>B₁</i>	152.15	✓
\$	<i>B₁</i>	1,941.63	✓
\$	<i>S_L</i>	405.73	X
\$	<i>S_L</i>	88.61	X
\$	<i>S_L</i>	88.61	X
\$	<i>R</i>	348.31	X

Trans-cab Auto Services Pte Ltd**AAD1903-219**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 931Y

30	1	BONNET HINGE RH	\$	R	348.31	X
31	1	BONNET LOCK	\$	DIT	305.48	✓
32	1	BONNET CABLE	\$	SL	119.19	}
33	1	BONNET CABLE COVER	\$	SL	161.03	
34	1	BONNET SEAL OUTER	\$	SL	92.36	
35	1	BONNET SEAL INNER	\$	SL	157.28	
36	1	FENDER PANEL FRT LH	\$	R	783.83	
37	1	WHEELARCH FRT LH	\$	SL	278.84	
38	1	FENDER BRACKET LOWER LH	\$	SL	15.79	
39	1	FENDER PANEL FRT LH	\$	R	783.83	
40	1	FENDER INSULATOR LH	\$	SL	130.84	
41	1	FENDER PANEL INNER FRT LH	\$	R	1,693.77	
42	1	FENDER PANEL FRT RH	\$	R	783.83	}
43	1	FENDER INSULATOR RH	\$	SL	130.84	
44	1	FENDER PANEL INNER FRT RH	\$	R	1,693.77	
45	1	TURBO DUCT	\$	SL	1,027.80	
46	1	A/C HEATER VALVE	\$	SL	484.50	
47	1	SUBFRAME OUTER FRT	\$	SL	2,652.45	
48	1	SUBFRAME BRACKET OUTER LH	\$	SL	92.36	
49	1	SUBFRAME BRACKET OUTER RH	\$	SL	92.36	
50	1	ENGINE UNDERTRAY	\$	SL	564.98	
51	1	A/C CONDENSER	\$	R	2,020.37	✓
52	1	A/C CONDENSER GARNISH LH UPPER	\$	SL	39.67	}
53	1	A/C CONDENSER GARNISH RH UPPER	\$	SL	39.67	
54	1	A/C CONDENSER GARNISH LH	\$	SL	58.81	
55	1	A/C CONDENSER GARNISH RH	\$	SL	59.60	
56	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	SL	208.39	
57	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	SL	658.72	
74	1	A/C PIPE COMPRESSOR	\$	SL	334.29	
75	1	A/C PIPE	\$	SL	658.72	
76	1	A/C COMRPRESSOR	\$	SL	2,684.61	
77	1	AIR COOLER	\$	SVC	792.60	X
78	1	AIR INTERCOOLER HOSE (LONG)	\$	SL	1,014.13	X
79	1	AIR INTERCOOLER HOSE (Short)	\$	SL	375.14	X
80	1	TRANSMISSION COOLER	\$	SL	1,219.30	X
81	1	TRANSMISSION COOLER PAD	\$	SL	17.96	X
82	1	RADIATOR	\$	SVC	1,202.20	X
83	2	RADIATOR STUD UPPER	\$	SL	14.41	X

Trans-cab Auto Services Pte Ltd

AAD1903-219

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 931Y

84	2	RADIATOR BUSH UPPER	\$	<i>Sn</i>	50.12	X
85	2	RADIATOR MTG LOWER	\$	<i>Sn</i>	55.85	X
86	1	RADIATOR FAN COWLING	\$	SVC	820.54	X
87	1	RADIATOR FAN MOTOR LH	\$	SVC	967.36	X
88	1	RADIATOR FAN MOTOR RH	\$	SVC	1,479.46	X
89	1	RADIATOR TANK	\$	<i>Sn</i>	324.62	X
90	1	RADIATOR HOSE UPPER	\$	<i>Sn</i>	240.56	X
91	1	RADIATOR HOSE LOWER	\$	<i>Sn</i>	491.18	X
92	1	RADIATOR TANK HOSE	\$	<i>Sn</i>	61.18	X

TOTAL	\$	42,427.59
10%	\$	4,242.76
	\$	38,184.83

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>Sn</i>	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	<i>Sn</i>	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i>	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i>	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	<i>nn</i>	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	<i>nn</i>	10.50	
7	1	TOW COVER FRT	\$	<i>Sn</i>	14.50	
8	1SET	RADAIOR GRILLE SCREW	\$	<i>nn</i>	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i>	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i>	70.00	} X
11	2	FRAME FULL SUPPORT PANEL NUT	\$	<i>nn</i>	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nn</i>	30.00	
13	1	Windscreen moulding	\$	<i>nn</i>	100.00	} X
14	1	FRONT NUMBER PLATE WITH HOLDER	\$	<i>Bz</i>	200.00	

TOTAL	\$	682.50
TOTAL PARTS	\$	38,867.33

Panel beating, knocking and straightening the
 necessary portion, remove and renewal of parts,
 adjust and realign the same

\$ 4,000.00 *500/*

Trans-cab Auto Services Pte Ltd**AAD1903-219**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 931Y

Towing Fees.	\$	120.00	50/
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
Putty and spray painting of the affected portion.	\$	4,000.00	660/
To rust-proofing of the affected areas.	\$	170.00	60/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To lift-up engine with gear box and refit.	\$	nn 440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00	X
To remove and refit air bag system and reset.	\$	nn 480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	100/
To replace, refix and top up coolant for radiator	\$	170.00	50/

Trans-cab Auto Services Pte Ltd**AAD1903-219**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 931Y

To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	11 X
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	11 X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	11 X

TOTAL \$ 13,000.00**Over All Total \$ 51,867.33****Repair Days (Part-by-Part)**~~20 days~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: