



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)

UNKNOWN

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/03/2019
Vehicle Reg. No.:	SKS7095A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	WANG XIAOYU		
Make/Model:	BMW 218I, 1.5 ACTIVE TOURER D/AB LED DSC AB (A)	Vehicle Reg. Date:	30/04/2015
Vehicle Colour:	WHITE		
Engine No:	33569191B38A15A	Chassis No:	WBA2A32060VZ53249
Odometer:	0 KM		
Paint Type:			
List Item Discount:	5.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	1,083.00
Miscellaneous Items	10.00
Labour	1,000.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	2,093.00
+ GST 7.00% (\$)	146.51
Nett Amount (\$)	2,239.51

This claim is handled by: JACELYN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Mar 2019)

Parts: M1-MPV BMW 218I 1.5 ACTIVE TOURER D/AB LED DSC AB (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Nova Automotive Pte Ltd/SKS7095A/29/03/2019 13:23

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR RH <i>DD</i>	5.00	0.00	*1,140.00 FI
2	1		*REAR DOOR HANDLE RH - REPAIR <i>x</i>	5.00	0.00	-
3	1		*REAR FENDER RH - REPAIR <i>x R</i>	5.00	0.00	-
4	1		*ROCKER GARNISH RH - REPAIR <i>x R</i>	5.00	0.00	-

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)

1,140.00

- List Item Discount on L Items (\$\$)

57.00

Total Parts (\$\$)

1,083.00

Nova Automotive Pte Ltd/SKS7095A/29/03/2019 13:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

5 fee (LKK) w2 Pdk
10/4/19 10.11 am
3 days
L/S
Rug AR spj

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK & STRAIGHTEN ON REAR FENDER RH. TO REMOVE & REPLACE DAMAGED ITEMS. REALIGN CONNECTION	New	300 400.00
2	TO SPRAY PAINT ON REPAIRED AREAS	New	/ 600.00
Gross Labour Cost (\$\$)			1,000.00

Mova Automotive Pte Ltd/SKS7095A/29/03/2019 13:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >