



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SKM 5651 P

AUDI A3

WAUZZZ8V3E1041836

No of Amt
LH/LR
2/59
4/59
3/4/19

ATTN:	NO.	DESCRIPTION - PARTS	QTY	PRICE
LH/LR Joy		REAR BUMPER	1	\$1,101.80
		REAR BUMPER SIDE RETAINER L+R	2	\$ 46.80
		REAR BUMPER BRACKET L+R	2	\$ 109.20
		REAR BUMPER LOWER	1	\$ 140.40
		REAR BUMPER REFLECTOR L+R	2	\$ 89.30
417-12		REAR BUMPER SENSOR SET 208.56x22=417.12 2 pcs. \$1248	4	\$ 2496.00
		REAR BUMPER SENSOR HOLDER	1	NIL
		REAR BUMPER SENSOR WIRE HARNESS	1	\$ 429.00
		REAR BUMPER BUZZER SENSOR	1	\$ 74.10
		REAR BUMPER REINFORCEMENT	1	\$ 335.40
		REAR BUMPER SPONGE	1	NIL
		REAR BUMPER CARRIER	1	\$ 191.10
		REAR END PANEL	1	\$ 549.90
		REAR END PANEL TOP GARNISH	1	\$ 117.00
		REAR SPARE WHEEL PANEL	1	\$ 640.70
		REAR SPARE WHEEL PANEL TOP BOARD	1	\$ 409.50
		REAR SPARE WHEEL PANEL CONTAINER	1	\$ 516.80
		REAR SPARE WHEEL PANEL FOAM	1	\$ 575.30
		REAR FENDER INNER TRIM L+R	2	\$ 366.60
		TAILLAMP L+R	2	\$ 1029.60
		TAILLAMP CLIPS L+R	2	\$ 16.40
		TAILLAMP PANEL L+R	2	\$ 240.00
		P = \$3,016.70		
		P = 2185.82		
		10% SUBTOTAL		\$ -
		10% LESS 10%		\$ -
		1967.23 PARTS TOTAL		\$ -
		SPECIAL NETT	QTY	PRICE
		REAR NUMBER PLATE	1	\$ 80.00
		REAR BUMPER CLIPS	1	\$ 100.00
		REAR FENDER INNER TRIM CLIPS	1	\$ 100.00
		REAR FENDER COWLING CLIPS	1	\$ 100.00
		SPECIAL NETT TOTAL		\$ 380.00
		LABOUR	QTY	PRICE
		TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1	\$ 2,600.00
		TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$ 2,400.00
		TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$ 160.00
		TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	1	\$ 800.00
		TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION	1	\$ 100.00
		TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	1	\$ 800.00
		L = \$1180		
		3197.23		
		TOTAL = \$3650		
		LABOUR TOTAL		\$ 6,860.00