

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883
 Email: SM_AUTOMOTIVE@HOTMAIL.COM
 Tel: (65) 6747 9241 Fax: (65) 6741 7276
 RCE No.: 53231488C

29/03/2019

Blk 1 Kaki Bukit Ave 6
 # 01-43
 Singapore 417883

TP china
 Asher.

JTFAT35Y90K209454

Accident date: 28/03/2019

Estimated repair cost for vehicle no: GBG9505R TOYOTA DYNA 150 3.0 M '17

CHASSIS: JTFAT35Y90K209454

S/n	Qty	Items	U/price	Amount
1	1	Rear Tailgate <i>Dented.</i>		\$1,714.40 ✓
2	1	Rear Tailgate Toyota Sticker <i>new</i>		\$85.00 ✓
3	1	Rear Tailgate Dyna Sticker <i>new</i>		\$40.00 ✓
4	2	Rear Tailgate Top Side Handle <i>new new</i>	\$187.30	\$374.60 X
5	2	Rear Tailgate Lower Side Lock <i>RH Bent</i>	\$171.40	\$342.80 <i>171.40</i>
6	4	Rear Tailgate Lower Side Hinge <i>new</i>	\$131.70	\$726.80 X
7	2	Rear Tailgate Lower Side Bracket <i>RH Bent</i>	\$168.60	\$337.20 <i>168.60</i>
8	2	Rear Tailgate Lower Side Rubber Stopper <i>RH w.</i>	\$31.20	\$62.40 <i>31.20</i>
9	1	Rear Tailgate Lower Member <i>Dented</i>		\$750.00 X <i>480</i>
10	2	Rear Tail Lamp <i>RH cut</i>	\$327.50	\$555.00 <i>532</i>
11	2	Rear Tail Lamp Panel <i>RH Bent</i>	\$374.45	\$748.90 <i>115</i>
12	1	Rear Number Plate Lamp <i>new</i>		\$131.35 X
13	1	Rear Number Plate Panel <i>Bent</i>		\$127.30 ✓
14	1	Rear Spare Tyre Lock <i>Damaged</i>		\$283.00 ✓
15	1	Rear Exhaust <i>Bent</i>		\$980.10 <i>585.20</i>
16	2	Rear Exhaust Mounting <i>new</i>	\$61.10	\$122.20 X
17	1	Rear Centre Exhaust <i>new</i>		\$678.10 X
18	1	Rear Floor Panel <i>Repair</i>		\$10,000.00 X

Subtotal: \$18,159.15

4333.10

3249.82

S/N	QTY	ITEMS / Special Net	U/PRICE	AMOUNT
19	1	Rear Tailgate 70km/H Sticker <i>3 New</i>		\$30.00 15
20	1	Rear Tailgate 13Pax Sticker		\$30.00 15
21	1	Rear Tailgate Aluminium Cover <i>Not New</i>		\$850.00 X
22	100	Rear Tailgate & Floor Panel Aluminium Rivet <i>Not New</i>	\$3.50	\$350.00 X 60
23	1	Rear Number Plate <i>Bent</i>		\$50.00 30
24	1	Rear Step Panel Bracket <i>Bent</i>		\$380.00 150
25	1	Rear Spare Tyre <i>Not New</i>		\$350.00 X
26	1	Rear Spare Tyre Lock Member <i>Not New</i>		\$380.00 X
27	1	Rear Floor Panel Aluminium Cover <i>Not New</i>		\$1,500.00 X
			270	Subtotal:- \$3,920.00

Labour charges

To remove & refit rear & centre exhaust		\$380.00 80
To check wiring		\$100.00 30
Towing fee		\$150.00 X
Tuff kote	2110	\$150.00 X
Panel beating		\$1,600.00 1000
Spray painting		\$1,600.00 900
To remove and replace reverse sensor	100 50	Subtotal:- \$3,980.00
To remove and replace tailgate aluminium panel	100 50	Total:- \$26,059.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 5629.82
L/S 45K.
05 Days.

45K