

INSURANCE

INS. CASE OWNER:

CC 6/LPC1900 5699, A/P 2012

LKK
IDAC

Surveyor:

Adrian

DOI:

ASSIGNMENT

20/12/19

Date / Time:

20/12/19

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLU 3460H

Name of Insured:

RISHIP BIN AUI

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

26/12/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

10/11/19/405/0495

Policy No.:

21940602175

Make / Model:

FIAT

Place of Accident:

KARI MUKIT K0

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SFE 2541K



INSRS:
WSP:
Tel:
Liability:
RMKS:

KANG



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

20/12/19

SLU 3460H-10

STAGE

DATE / PIC

Non-Reporting in (1st)
Non-Reporting in (2nd)
Non-Reporting in (Final)
Notification in (if non-pickup)
Call OI:
After call in to OI:

04/10/19

MANAGED
TP LOD IN BY EMAIL

FILE REQUESTED. OI REAR BUDGET TP.
TP REPORT FOR WARRANTS APPROVAL
REPORT DONE

20/10/19

BOOK WARRANTS TO LPC BY EMAIL

20/10/19

LPC APPROVED WARRANTS
SEND ACCEPTANCE EMAIL TO TP
BU DOCS IN ORDER
TO CLOSE

Documentation Check List: Handler Typist

Notification in (if non-pickup)
After call in to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

US

SS 2,550.00

5

days) Reduction:

43

%

Email

Call

FINAL SETTLEMENT

Date/Time:

08/11/19

Confirm with:

SHARON

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

IF NO or B 28, Ass. Lia

Repair Cost (w/Car)

SS 2,728.50

COI REAR BUDGET TP

Loss of Rental (LOR):

SS

-

(days)

Loss of Use (LOU):

SS

720.00

720

x 6

days)

UNREPAIR CAR

Loss of Income (LOI):

SS

-

(\$)

x

days)

LOR only

☐

LOU only

☒

LOR + LOU

☐

LOR + LOU

☐

[Tick only one]

GIA/TA Search

SS

2.00

Medical:

SS

-

1) Claim status: ☒ Non-Report/Private Settle

Disbursement:

SS

-

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

-

3) Survey fee:

450.00

Total:

SS

3,450.50

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3,450.50

Name 1:

KANG CAR REPAIRERS PTB USD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SKE2541K Yr Regn: 2012 / Feb.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Uios c.c. 1497Colour: Silver A/C: Insured / Std / Nil / NASp. Reading: 138781 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MROS3HY9305288484Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / SIRip / STD A/Rim orTyre Size: F: 185/60R15R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 29/03/19Survey held at Keny

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Len Pac

LH 2,550.00

CRAB: 4,955.76 (40%)

mv:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: 199601882C
Owner ID Type: Company
Owner Name: COMFORTDELGRO DRIVING CENTRE PTE. LTD.
Registered Address: 205 BRADDELL ROAD SINGAPORE 579701
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SKE2541K
Previous Vehicle No.: -
Effective Date of Ownership: 20 Feb 2012
Original Regn Date: 20 Feb 2012
Registration Date: 20 Feb 2012
Year of Manufacture: 2012
Vehicle Type: For Instruction (Co) Car With 10 Years Lifespan
Vehicle Scheme: -
Vehicle Attachment 1: No Attachment
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: TOYOTA
Vehicle Model: VIOS E MANUAL
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: MR053HY9305288484
Engine No.: 1NZY461869
Engine Capacity / Power Rating: 1497 cc / -
Maximum Power Output: 80.0 kW (107 bhp)
Propellant: Petrol
Max Unladen Weight: 1075 kg
Maximum Laden Weight: 1485 kg
Open Market Value: \$10,216.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Feb 2022
Minimum PARF Benefit: \$5,108.00
No. of Transfers: 0
IU Label No.: 1124333228
COE No.: 2011080101000670C
COE Expiry Date: 19 Feb 2022
COE Category: A - Car (1600cc & below)
COE Registration Category: A - Car (1600cc & below)
Quota Premium (QP) / Prevailing Quota Premium: \$56,002.00 / -
Actual QP Paid: \$56,002.00
QP (Regn Cat): \$56,002.00
OPC Cash Rebate Eligibility: No
QP during COE Bidding Exercise: \$56,002.00
Additional Registration Fee Rate: 100.00 %
Actual ARF Paid: \$10,216.00
Vehicle Lifespan Expiry Date: 19 Feb 2022
CO2 Emission: -
CO Emission: -
HC Emission: -
NOx Emission: -
PM Emission: -
Message: -

Print

OK

Save as PDF

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

TEL: 62507388 FAX: 62962706
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 28/03/2019
TP Veh Reg No: SLU3460H

Estimate No: EST1900083
Date: 29 Mar 2019

Veh Reg No: SKE2541K
Make/Model: TOYOTA VIOS E
MANUAL
Chasis No: MR053HY9305288484
Reg. Date: 20/02/2012
Your Ref No: SLU3460H

Joy

Estimate Repair Cost to Vehicle No :SKE2541K

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC REAR BUMPER <i>Deformed</i>	487.50 ✓	
2	1 PC REAR BUMPER BRACKET RH <i>new</i>	69.70 ✓	
3	1 PC REAR BUMPER SIDE RETAINER <i>new</i>	113.90 ✓	
4	1 PC REAR BUMPER RETAINER (SMALL) RH <i>new</i>	36.20 ✓	
5	1 PC REAR BUMPER REFLECTOR - RH <i>could</i>	94.70 ✓	
6	1 PC REAR PANEL <i>vented</i>	688.10 ✓	
7	1 PC TAIL LAMP - RH <i>could</i>	409.90 ✓	
8	1 PC REAR FENDER MUDFLAP <i>new</i>	65.20 ✓	
9	1 PC BOOT LID RUBBER <i>new</i>	186.50 ✓	
10	1 PC BOOT LID LOCK <i>new</i>	162.60 ✓	
		2,314.30	72
	Less 25%	578.58	1,735.76
	Special Net		
11	1 SET REAR BUMPER STICKER <i>new</i>	195.00 ✓	
12	1 PC REAR FENDER STICKER <i>new</i>	195.00 ✓	
13	2 PCS "L" PLATE BRACKET <i>new</i>	70.00 ✓	
	<i>Rear End Panel Sealant. New</i>	460.00	460.00
	Labour		
14	1 TO CHECK WIRING	50.00 ✓	
15	1 TO SPRAY UNDERSEAL	80.00 ✓	
16	1 TO REPLACE STICKER	100.00 ✓	
17	1 (REAR) TO SPRAY PAINTING	1,000.00 ✓	
18	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 ✓	
		2,230.00	2,230.00

1560.50

1170.67

520

190.60

1440

539

289.60

70.50

600

700

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S: LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

TEL: 62507388 FAX: 62962706
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 28/03/2019
TP Veh Reg No: SLU3460H

Estimate No: EST1900083
Date: 29 Mar 2019

Veh Reg No: SKE2541K
Make/Model: TOYOTA VIOS E
MANUAL
Chasis No: MR053HY9305288484
Reg. Date: 20/02/2012
Your Ref No: SLU3460H

Estimate Repair Cost to Vehicle No :SKE2541K

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	Total		S\$ 4,425.76
	Add GST @ 7%		309.80
	Total Amount Payable		S\$ 4,735.56
			<u>4,505.76</u>

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED THIRTY FIVE AND CENTS FIFTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
1/s 29/03/19.
05 days. Supplement: 80
Total 3210.67
1/s 2550

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

TEL: 62507388 FAX: 62962706
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 28/03/2019
TP Veh Reg No: SLU3460H

Estimate No: EST1900083
Date: 30 Mar 2019

Veh Reg No: SKE2541K
Make/Model: TOYOTA VIOS E
MANUAL
Chasis No: MR053HY9305288484
Reg. Date: 20/02/2012
Your Ref No: SLU3460H

Estimate Repair Cost to Vehicle No :SKE2541K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Supplementary Parts to Repair		
	Special Net		
1	1 PC "L" PLATE Bent	80.00	
		80.00	80.00
	Total		S\$ 80.00
	GST Amount		S\$ 5.60
	Total Amount Payable		<u>S\$ 85.60</u>

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

80

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 2 April 2019 1:13 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving SLU3460H (OI : LPC - TBA) AND SKE2541K (TP : LKK REF - CC6/LPC19005699/Ajb3) on 28.03.2019 [External Confidential]
Attachments: 02042019130913.pdf

Lonpac External - Confidential

Our Ref : 19/19/19/VP05/021595

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 1 April, 2019 7:23 PM
To: GERALD POH WEE BIN; 'ERIC WOO JUN KIAT'; ONG LI LI
Cc: MT_Claim_SG; Admin A; Joy Irene (LKKAUTO)
Subject: Direct Settlement - Accident Involving SLU3460H (OI : LPC - TBA) AND SKE2541K (TP : LKK REF - CC6/LPC19005699/Ajb3) on 28.03.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SKE 2541K at M/s Kang Car Repairers Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409 .

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 2 July 2019 6:18 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Vic (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SLU3460H (OI : LPC - TBA) AND SKE2541K (TP : LKK REF - CC6/LPC19005699/Ajb3) on 28.03.2019 [External Confidential]
Attachments: PA-LONPAC.pdf; TP ESTIMATE_MARKED.pdf

REF: 19/19/19/VP05/021595

Dear Gerald,

We attach herewith our PA and marked estimate for your records.

We will be requesting for mandate shortly.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 2 April 2019 1:13 PM
To: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Direct Settlement - Accident Involving SLU3460H (OI : LPC - TBA) AND SKE2541K (TP : LKK REF - CC6/LPC19005699/Ajb3) on 28.03.2019 [External Confidential]

Lonpac External - Confidential

Our Ref : 19/19/19/VP05/021595

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC6/LPC19005699/Ahb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 25-11-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY (FOLLOW THROUGH INSPECTION)				
	Insured Veh.	SLU 3460H	Veh. Inspected	SKE 2541K
	Policy No.	Z19VP05022178	Coverage (\$)	0.00
	Claim No.	19/19/19/VP05/021595	Excess (\$)	0.00
	Assign From		Assign Date	29/03/2019
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	MR053HY9305288484	Colour	SILVER
	Odometer	138781	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/03/2019	Inspection Date	29/03/2019
	Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 2541K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	487.50	487.50
1	REAR BUMPER BRACKET RH	NOT NECESSARY	69.70	-
1	REAR BUMPER SIDE RETAINER	NECESSARY	113.90	113.90
1	REAR BUMPER RETAINER (SMALL) RH	NECESSARY	36.20	36.20
1	REAR BUMPER REFLECTOR -RH	CRACKED	94.70	94.70
1	REAR PANEL	DENTED	688.10	539.00
1	TAIL LAMP -RH	CRACKED	409.90	289.60
1	REAR FENDER MUDFLAP	NOT NECESSARY	65.20	-
1	BOOT LID RUBBER	NOT NECESSARY	186.50	-
1	BOOT LID LCOK	NOT NECESSARY	162.60	-
	LESS 25% DISCOUNT		-578.58	-390.23
			1,735.72	1,170.67
SPECIAL NETT ITEMS				
1	SET REAR BUMPER STICKER (SN)	NECESSARY	195.00	195.00
1	REAR FENDER STICKER (SN)	NECESSARY	195.00	195.00
2	'L' PLATE BRACKET (SN)	NECESSARY	70.00	70.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	60.00
1	'L' PLATE (SN) (ADDITIONAL)	BENT	80.00	80.00
			640.00	600.00
LABOUR				
	TO CHECK WIRING .		50.00	30.00
	TO SPRAY UNDERSEAL.		80.00	60.00
	TO REPLACE STICKER .		100.00	50.00
	(REAR) TO SPRAY PAINTING.		1,000.00	600.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS.		1,000.00	700.00
			2,230.00	1,440.00
GRAND TOTAL			4,605.72	3,210.67



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00
---	--	--	----------

Report Ref No. CC6/LPC19005699/Ahb3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.