

INS2010

INS. CASE OWNER

Joe1

CC 6 /EQI1900

5 for 2, A<sup>P</sup> h<sup>S</sup>

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

21/7/19

Date / Time:

21/7/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

PC 1355P

Name of Insured:

ET BUEZ LLC

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

26/7/19

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

AN Bw Ismaru

Driver Tel No.:

(V/L: YES / NO )

Claim No.:

0M1910000904

Policy No.:

0M1910000904

Make / Model:

MITSUBISHI

Place of Accident:

Rmk Ave 3 TOWNS AND LO

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SKH 4897E

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:Hua  
mengINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

5/4/19

4/6/19

SKH 4897E - X

PC 1355P - X

CALLED OI TO INFORM ALL DETAILS AND OI AWARE NCD ISSUES.

- File -&gt; type mandate.

After paint photo ✓

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

0510119 - JC

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 7,500.00

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

29/8/2019

Confirm with:

Jing Yee

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

S\$ 7,500.00

Loss of Rental (LOR):

S\$

-

( days)

Loss of Use (LOU):

S\$

420.00

(S 60.00 x 7 days)

Loss of Income (LOI):

S\$

-

(S x days)

LOR only

☐

LOU only

☒

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$ 7,927.49

Global Sum S\$: 7,920.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7,920.00

Name 1:

Hua Meng spray painting workshop

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$400.00

ASS. REC. BY:

REF:


Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 09 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKH4897E Yr Regn: 2012 / Dec.  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598

Colour Silver A/C: Insured / Std / NI / NA

Sp. Reading 73084 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053REE104150644

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Giti

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 29/03/19

Survey held at Hua Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                   |
|-------------|----------------------------------------|
|             | <u>TP EQ</u>                           |
|             | <u>US \$ 750 Cred \$ 9015.25 / 550</u> |
|             | <u>MV: 42K</u>                         |
|             | <u>PV: 31.5K</u>                       |
|             | <u>Nett: 10.5K</u>                     |
|             | <u>58000</u>                           |

| Date/Time, File Pass to? | Date/Time, File Return to? | Part Prices Check: |     | Survey Fee:        | Date: |
|--------------------------|----------------------------|--------------------|-----|--------------------|-------|
| 1)                       | 2)                         | IN                 | OUT | Basic & Add.       |       |
| 3)                       | 4)                         |                    |     | ___ S + RS, ___ SI |       |
| 5)                       | 6)                         |                    |     | Photos             |       |
| Prel. Report             |                            |                    |     | Others             |       |
| Final Report             |                            |                    |     | TOTAL              |       |

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1

S 798125

TPER

Xiao Tony

Date

:26.04.2019

Make/Model

:SKH 4897 E

Accident date

:TOYOTA ALTIS

:28.03.2019

| No                | DESCRIPTION                                              | Qty | Amount (\$)               |
|-------------------|----------------------------------------------------------|-----|---------------------------|
| <u>List Items</u> |                                                          |     |                           |
| 1                 | Rear windscreen <i>Moulding. New</i>                     | 1   | \$ 89.3 ✓                 |
| 2                 | Rear boot lid <i>Distorted</i>                           | 1   | \$ 754.7 ✓                |
| 3                 | Rear boot lid hinges @ \$56.40 <i>Best</i>               | 2   | \$ 112.8 ✓                |
| 4                 | Rear boot lid upper lock <i>Damaged</i>                  | 1   | \$ 105.6 ✓                |
| 5                 | Rear boot lid lower lock                                 | 1   | \$ 29.6 ✓                 |
| 6                 | Rear boot lid insulation <i>torn</i>                     | 1   | \$ 174.1 ✓                |
| 7                 | Rear boot lid centre logo <i>new</i>                     | 1   | \$ 58.3 ✓                 |
| 8                 | Rear boot lid handle <i>crushed</i>                      | 1   | \$ 350.5 ✓                |
| 9                 | Rear boot lid 1.6 emblem                                 | 1   | \$ 32.5 ✓                 |
| 10                | Rear boot lid COROLLA emblem <i>new</i>                  | 1   | \$ 46.6 ✓                 |
| 11                | Rear boot lid ALTIS emblem                               | 1   | \$ 46.6 ✓                 |
| 12                | Rear boot lid reflector @ \$161.50 <i>crushed</i>        | 2   | \$ 323.7 ✓                |
| 13                | Rear boot lid weather strip <i>cut</i>                   | 1   | \$ 205.2 ✓                |
| 14                | Rear number plate lamp @ \$58.20 <i>new</i>              | 2   | \$ 116.4 X                |
| 15                | Rear lamp @ \$480.00 <i>crushed</i>                      | 2   | \$ 960.0 ✓ <i>570.20</i>  |
| 16                | Rear lamp housing @ \$84.10 <i>Buckled</i>               | 2   | \$ 168.2 ✓                |
| 17                | Rear lamp bracket @ \$88.90 <i>crushed</i>               | 2   | \$ 177.8 ✓ <i>96</i>      |
| 18                | Rear end panel <i>Distorted</i>                          | 1   | \$ 668.9 ✓                |
| 19                | Rear end panel inner top garnish <i>behind</i>           | 1   | \$ 202.7 ✓                |
| 20                | Rear bumper <i>Distorted</i>                             | 1   | \$ 486.5 ✓                |
| 21                | Rear bumper side holder @ \$70.40 <i>new</i>             | 2   | \$ 140.8 ✓                |
| 22                | Rear bumper bracket @ \$87.10 <i>Dented</i>              | 2   | \$ 174.2 ✓                |
| 23                | Rear bumper sponge <i>crushed</i>                        | 1   | \$ 123.5 ✓                |
| 24                | Rear bumper reflector @ \$37.20 <i>crushed</i>           | 2   | \$ 74.4 ✓                 |
| 25                | Rear bumper clips (1set) <i>new</i>                      | 1   | \$ 46.0 ✓ <i>30</i>       |
| 26                | Rear fender @ \$927.20 <i>LH Buckled</i>                 | 2   | \$ 1854.4 ✓ <i>927.20</i> |
| 27                | Rear fender inner trim @ \$351.70 <i>torn</i>            | 2   | \$ 703.4 ✓                |
| 28                | Rear fender inner shield @ \$47.30 <i>new</i>            | 2   | \$ 94.6 X                 |
| 29                | Rear fender lower air vent <i>new</i>                    | 1   | \$ 158.7 ✓                |
| 30                | Rear spare tyre top board <i>torn</i>                    | 1   | \$ 276.6 ✓                |
| 31                | Rear spare tyre well <i>Repair</i>                       | 1   | \$ 780.9 X                |
| 32                | Rear spare tyre well insulation @ \$279.60 <i>new</i>    | 3   | \$ 838.8 X                |
| 33                | Rear spare tyre well top side board @ \$69.80 <i>new</i> | 2   | \$ 139.7 X                |
| 34                | Rear spare tyre screw <i>Damaged</i>                     | 1   | \$ 46.7 ✓                 |
| 35                | Rear exhasut pipe <i>Not New</i>                         | 1   | \$ 926.3 X                |

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

DAWN ENTERPRISES  
21 SELETAR WEST FARMWAY 1  
S 798125

Date :26.04.2019  
:SKH 4897 E  
Make/Model :TOYOTA ALTIS  
Accident date :28.03.2019

| No | Description                               | Qty           | Amount (\$)     |
|----|-------------------------------------------|---------------|-----------------|
| 36 | Rear exhaust pipe mounting <i>Not new</i> | 1             | \$ 158 <i>x</i> |
|    | Bootlid Inner Trim Board <i>for 204</i>   |               | \$ 11647        |
|    |                                           | Less 25% Disc | \$ 2911.75      |
|    |                                           | Total         | \$ 8735.25      |

7381.5  
5536.12

### Special Nett Items

|   |                                           |       |                   |
|---|-------------------------------------------|-------|-------------------|
| 1 | Rear boot lid camera <i>damaged</i>       | 1     | \$ 800 <i>380</i> |
| 2 | Rear number plate <i>Best</i>             | 1     | \$ 50 <i>30</i>   |
| 3 | rear number plate holder <i>del</i>       | 1     | \$ 50 <i>30</i>   |
| 4 | Rear bumper reverse sensor <i>damaged</i> | 1     | \$ 380 <i>200</i> |
|   |                                           | Total | \$ 1280           |

640

### Labour Cost

|    |                                                     |                      |
|----|-----------------------------------------------------|----------------------|
| 1  | To supply rear windscreen sealant                   | net \$ 50 <i>✓</i>   |
| 2  | To supply rear end panel inner sealant              | net \$ 200 <i>60</i> |
| 3  | Remove & reinstall rear windscreen                  | \$ 150 <i>120</i>    |
| 4  | Remove & reinstall cushion & roof lining            | \$ 200 <i>60</i>     |
| 5  | Remove & reinstall petrol tank                      | \$ 150 <i>80</i>     |
| 6  | Remove & reinstall reverse sensor                   | \$ 150 <i>50</i>     |
| 7  | Remove & reinstall exhaust pipe                     | \$ 150 <i>x</i>      |
| 8  | Remove & reinstall camera                           | \$ 100 <i>50</i>     |
| 9  | Remove, replace & repair consistent to the accident | \$ 3000 <i>1300</i>  |
| 10 | Respray painting                                    | \$ 2200 <i>1400</i>  |
| 11 | Tuff kote                                           | \$ 150 <i>60</i>     |
|    | Total                                               | \$ 6500              |

3230

Grand total \$ 16515.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

total 9406.12  
4/5 7.5k  
09 Days  
7.5K 16668.25

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                               |                          |
|-------------------------------|--------------------------|
| Owner ID Type:                | Business                 |
| Owner ID:                     | 5800D                    |
| Vehicle No.:                  | SKH4897E                 |
| Vehicle to be Exported:       | Yes                      |
| Intended Deregistration Date: | 29 Mar 2019              |
| Vehicle Make:                 | TOYOTA                   |
| Vehicle Model:                | COROLLA ALTIS 1.6 AUTO   |
| Primary Colour:               | Silver                   |
| Manufacturing Year:           | 2012                     |
| Engine No.:                   | 1ZRX233049               |
| Chassis No.:                  | MR053REE104150644        |
| Maximum Power Output:         | 90.0 kW (120 bhp)        |
| Open Market Value:            | \$14,944.00              |
| Original Registration Date:   | 12 Dec 2012              |
| First Registration Date:      | 12 Dec 2012              |
| Transfer Count:               | 1                        |
| Actual ARF Paid:              | \$14,944.00              |
| PARF Eligibility:             | Yes                      |
| PARF Eligibility Expiry Date: | 11 Dec 2022              |
| PARF Rebate Amount:           | \$9,713.00               |
| COE Expiry Date:              | 11 Dec 2022              |
| COE Category:                 | A - Car (1600cc & below) |
| COE Period(Years):            | 10                       |
| QP Paid:                      | \$59,003.00              |
| COE Rebate Amount:            | \$21,825.00              |
| <b>Total Rebate Amount:</b>   | <b>\$31,538.00</b>       |

The information contained herein is correct as at 29 Mar 2019

OK



## ANNOUNCING Autolink Holdings

as sgCarMart Premium Dealer 2019



**SEARCH** 






[Advanced Search](#)

Used Car Comparison

--- Comparing 4 Vehicles ---



**Toyota Corolla Altis 1.6A**

[Add to Shortlist](#)



**Toyota Corolla Altis 1.6A**

[Add to Shortlist](#)



**Toyota Corolla Altis 1.6A**

[Add to Shortlist](#)



**Toyota Corolla Altis 1.6A**

[Add to Shortlist](#)

[Clear All](#)
[Add all to Shortlist](#)
[Back to search result](#)

| CAR DETAILS        |                                                                                                                                                                 |                                                                                                                                                                                       |                                                                                                                                         |                                                                                                                                                                                                                                         |
|--------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Price              | \$37,800                                                                                                                                                        | \$40,500                                                                                                                                                                              | \$39,800                                                                                                                                | \$39,998                                                                                                                                                                                                                                |
| Instalment         | \$844                                                                                                                                                           | \$837                                                                                                                                                                                 | \$766                                                                                                                                   | \$752                                                                                                                                                                                                                                   |
| Registration Date  | 27-Feb-2012                                                                                                                                                     | 24-May-2012                                                                                                                                                                           | 23-Aug-2012                                                                                                                             | 19-Sep-2012                                                                                                                                                                                                                             |
| Manufactured       | 2012                                                                                                                                                            | 2012                                                                                                                                                                                  | 2012                                                                                                                                    | 2012                                                                                                                                                                                                                                    |
| Mileage            | -                                                                                                                                                               | 58,400 km                                                                                                                                                                             | -                                                                                                                                       | 125,000 km                                                                                                                                                                                                                              |
| Transmission       | Auto                                                                                                                                                            | Auto                                                                                                                                                                                  | Auto                                                                                                                                    | Auto                                                                                                                                                                                                                                    |
| Engine Cap         | 1,598 cc                                                                                                                                                        | 1,598 cc                                                                                                                                                                              | 1,598 cc                                                                                                                                | 1,598 cc                                                                                                                                                                                                                                |
| Road Tax           | \$742 /yr                                                                                                                                                       | \$742 /yr                                                                                                                                                                             | \$742 /yr                                                                                                                               | \$742 /yr                                                                                                                                                                                                                               |
| Power              | 90.0 kW (120 bhp)                                                                                                                                               | 90.0 kW (120 bhp)                                                                                                                                                                     | 90.0 kW (120 bhp)                                                                                                                       | 90.0 kW (120 bhp)                                                                                                                                                                                                                       |
| Curb Weight        | 1,195 kg                                                                                                                                                        | 1,195 kg                                                                                                                                                                              | 1,195 kg                                                                                                                                | 1,195 kg                                                                                                                                                                                                                                |
| Features           | -                                                                                                                                                               | Powered By Toyota's 1.6L 4 Cylinders Inline 16 Valves DOHC VVT-I Engine Producing 120BHP Coupled With A 4 Speed Automatic Transmission.                                               | Powered By Toyota's 1.6L 4 Cylinders Inline 16 Valves DOHC VVT-I Engine Producing 120BHP Coupled With A 4 Speed Automatic Transmission. | Powered By Toyota's 1.6L 4 Cylinders Inline 16 Valves DOHC VVT-I Engine Producing 120BHP Coupled With A 4 Speed Automatic Transmission.                                                                                                 |
| Accessories        | -                                                                                                                                                               | Leather Seats, Built In Audio System, Steering Control, Retractable Side Mirrors With Light Indicators, Reverse Sensors, Eco Mode.                                                    | Leather Seats, Built In Audio System, Steering Control, Retractable Side Mirrors With Light Indicators, Reverse Sensors, Eco Mode.      | Leather Seats, Built In Audio System, Steering Control, Retractable Side Mirrors With Light Indicators, Reverse Sensors, Eco Mode.                                                                                                      |
| Description        | One Owner Only. Agent Maintained From First Day. Low Mileage And Low Maintenance With Very Low Fuel Consumption. No More Repairs Needed. Call Us To Own It Now. | Only 1 Owner And Genuine Low Mileage. Original Condition. Low Maintenance And Easy On Fuel. View To Appreciate This Beautiful Car. Welcome Trade In And Flexible Financing Available. | New Arrival, One Of The Most Popular Car, Good For Family Needs, Call To View This Unit Before Is Gone.                                 | Be Our Next Happy Customer. This Quality Pre-Owned Car. Reasonable And Affordable. Well Kept Interior. No Knocking Sounds. Low Fuel Consumption. House Loan Up To Professional And Financial Obligations Discussed. Will Be Considered. |
| COE                | \$54,887                                                                                                                                                        | \$58,501                                                                                                                                                                              | \$59,003                                                                                                                                | \$66,889                                                                                                                                                                                                                                |
| OMV                | \$14,432                                                                                                                                                        | \$15,045                                                                                                                                                                              | \$14,885                                                                                                                                | \$14,885                                                                                                                                                                                                                                |
| ARF                | \$14,432                                                                                                                                                        | \$15,045                                                                                                                                                                              | \$14,885                                                                                                                                | \$14,885                                                                                                                                                                                                                                |
| Depreciation       | \$10,480 /yr                                                                                                                                                    | \$10,460 /yr                                                                                                                                                                          | \$9,510 /yr                                                                                                                             | \$9,360 /yr                                                                                                                                                                                                                             |
| No. of Owners      | 1                                                                                                                                                               | 1                                                                                                                                                                                     | 2                                                                                                                                       | 4                                                                                                                                                                                                                                       |
| Type of Vehicle    | Sedan                                                                                                                                                           | Sedan                                                                                                                                                                                 | Sedan                                                                                                                                   | Sedan                                                                                                                                                                                                                                   |
| Category           | PARF Car, Premium Ad Car                                                                                                                                        | PARF Car, Low Mileage Car                                                                                                                                                             | PARF Car                                                                                                                                | PARF Car                                                                                                                                                                                                                                |
| Availability       | Available                                                                                                                                                       | Available                                                                                                                                                                             | Available                                                                                                                               | Available                                                                                                                                                                                                                               |
| SELLER INFORMATION |                                                                                                                                                                 |                                                                                                                                                                                       |                                                                                                                                         |                                                                                                                                                                                                                                         |

## Shu Pei (LKKAUTO)

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Tuesday, 2 April 2019 9:35 AM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** Vic (LKKAUTO); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving PC1355P (OI : EQI - DM19HO00904-JG) and SKH4897E (TP : LKK REF - CC6/EQI19005702/Ahb3) on 28.03.2019  
**Attachments:** PC1355P.pdf

Dear Shu Pei

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh

Executive Director



EQ Insurance Company Limited

11 Maxwell Road #11/00 Tower Block MND Complex Singapore 069110

did 65 6500 4772 | tel 65 6223 9433 ext 772 | fax 65 6723 4100

www.eqinsurance.com.sg

A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

**Sent:** Monday, April 1, 2019 6:26 PM

**To:** Joel Goh

**Cc:** Vic (LKKAUTO); Admin A

**Subject:** Direct Settlement - Accident Involving PC1355P (OI : EQI - TBA) and SKH4897E (TP : LKK REF - CC6/EQI19005702/Ahb3) on 28.03.2019

### WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

We have inspected TP vehicle SKH 4897E at M/s Hua Meng Spray Painting Workshop on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank You.

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Poh Kin (LKKAUTO)**

---

**From:** Hua Meng <huameng@live.com.sg>  
**Sent:** Thursday, 29 August 2019 6:21 PM  
**To:** Poh Kin (LKKAUTO)  
**Subject:** Re: EQ INSURED: PC 1355 P OUR REF: SKH 4897 E D.O.A: 28.03.2019

Dear Poh Kin

Kindly let us have your DV.

Thank You.

Regards,  
Jing Yee  
Hua Meng Spray Painting Workshop  
Tel : 6746 5519 Fax : 6743 4896

---

**From:** Poh Kin (LKKAUTO) <pohkin@lkkauto.com>  
**Sent:** Wednesday, August 28, 2019 4:39 PM  
**To:** Hua Meng <huameng@live.com.sg>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: EQ INSURED: PC 1355 P OUR REF: SKH 4897 E D.O.A: 28.03.2019

**"Without Prejudice"**  
**"Save As To Costs"**

Our Ref: CC6/EQI19005702/Apb3  
Your Ref: SKH 4897E

Dear Jing Yee,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. PC 1355P AND SKH 4897E ON 28.03.2019**

We refer to the above matter and your letter of demand.

Purely towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement at global sum of **\$ 7,920.00(all in)** on this matter.

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

**Poh Kin (LKKAUTO)**

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Wednesday, 28 August 2019 11:27 AM  
**To:** 'Joel Goh'  
**Cc:** Hsiao Tong (LKKAUTO); Admin A  
**Subject:** SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. PC 1355P (OI) AND SKH 4897E (TP) ON 28-03-2019; LKK ref : CC6/EQI19005702/Apb3; EQ ref: DM19HO00904-JG  
**Attachments:** LKK Adjustment report.pdf; LKK Inspection report.pdf; LKK Resurvey Photo.pdf; LKK Survey Photo.pdf; TP LOD.pdf  
**Importance:** High

Your ref : DM19HO00904-JG  
Our ref : CC6/EQI19005702/Apb3

Dear Joel,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. PC 1355P (OI) AND SKH 4897E (TP) ALONG ANG MO KIO AVENUE 3 ON 28/03/2019**

We refer to the above matter.

Liability: OID collided into the rear of TP vehicle. Liability is down against our insured.

We did clarify with PIC (Ms Emily) the nature of the accident and They are agree to settle, aware that NCD (if any) is affected.

We seek your approval to offer Third Party repairer "**Hua Meng Spray Painting Workshop**" at **\$ 7,927.49 (all-in).**

The summary is as follows: -

|                   | Claimed Amount                | Revised Amount               |
|-------------------|-------------------------------|------------------------------|
| 1. Cost of Repair | \$ 16,668.25                  | \$ 7,500.00                  |
| 2. Loss of Use    | \$ 840.00 (7 days x \$120.00) | \$ 420.00 (7 days x \$60.00) |
| 3. LTA search fee | \$ <u>7.49</u>                | \$ <u>7.49</u>               |
| Total             | \$ 17,515.74                  | \$ <b><u>7,927.49</u></b>    |

**\*\*9 days recommendation for repair**

Enclosed here with all the relevant documents for your perusal.

**For your approval/instruction please.**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                          |                             |            |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|-----------------------------|------------|--|
| EQ INSURANCE COMPANY LTD                                                                                                               |                                                                                          | Ref : CC6/EQ19005702/Apb3s2 |            |  |
| 5 MAXWELL ROAD<br>#17-00 TOWER BLOCK<br>MND COMPLEXSINGAPORE 069110                                                                    |                                                                                          | Date : 11-09-2019           |            |  |
|                                                                                                                                        |                                                                                          | Code : EQI                  |            |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                          |                             |            |  |
| Insured Veh.                                                                                                                           | PC 1355P                                                                                 | Veh. Inspected              | SKH 4897E  |  |
| Policy No.                                                                                                                             | DMCFHQ18-000079                                                                          | Coverage (\$)               | 0.00       |  |
| Claim No.                                                                                                                              | DM19HO00904-JG                                                                           | Excess (\$)                 | 0.00       |  |
| Assign From                                                                                                                            |                                                                                          | Assign Date                 | 29/03/2019 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                          |                             |            |  |
| Make & Model                                                                                                                           | TOYOTA ALTIS                                                                             | c.c                         | 1598       |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                   | Year of Reg.                | 2012       |  |
| Chassis No.                                                                                                                            | MR053REE104150644                                                                        | Colour                      | SILVER     |  |
| Odometer                                                                                                                               | 73084                                                                                    | Steering                    | IN ORDER   |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                 | Modification                | SPORTS RIM |  |
| General                                                                                                                                | GOOD                                                                                     |                             |            |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                          |                             |            |  |
|                                                                                                                                        | Size                                                                                     | Make                        | Balance    |  |
| R/H Front Tyre                                                                                                                         | 195/65 R15                                                                               | GITI                        | 6 mm       |  |
| L/H Front Tyre                                                                                                                         | 195/65 R15                                                                               | GITI                        | 6 mm       |  |
| R/H Rear Tyre                                                                                                                          | 195/65 R15                                                                               | GITI                        | 6 mm       |  |
| L/H Rear Tyre                                                                                                                          | 195/65 R15                                                                               | GITI                        | 6 mm       |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                          |                             |            |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                             |                                                                                          |                             |            |  |
| <b>5. General Information</b>                                                                                                          |                                                                                          |                             |            |  |
| Accident Date                                                                                                                          | 28/03/2019                                                                               | Inspection Date             | 29/03/2019 |  |
| Survey held at                                                                                                                         | HUA MENG SPRAY PAINTING WKSP<br>1 KAKI BUKIT AVE 6<br>#01-61 AUTOBAY<br>SINGAPORE 417883 |                             |            |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                          |                             |            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                          |                             |            |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                          |                             |            |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                          | <b>9 Working Days</b>       |            |  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 4897E

| Qty | Description of Parts               | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|---------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>        |               |                           |                   |
| 1   | REAR WINDSCREEN MOULDING           | NECESSARY     | 89.30                     | 89.30             |
| 1   | REAR BOOT LID                      | DISTORTED     | 754.70                    | 754.70            |
| 2   | REAR BOOT LID HINGES @ \$56.40     | BENT          | 112.80                    | 112.80            |
| 1   | REAR BOOT LID UPPER LOCK           | DAMAGED       | 105.60                    | 105.60            |
| 1   | REAR BOOT LID LOWER LOCK           | DAMAGED       | 29.60                     | 29.60             |
| 1   | REAR BOOT LID INSULATION           | TORN          | 174.10                    | 174.10            |
| 1   | REAR BOOT LID CENTRE LOGO          | NECESSARY     | 58.30                     | 58.30             |
| 1   | REAR BOOT LID HANDLE               | CRACKED       | 350.50                    | 350.50            |
| 1   | REAR BOOT LID 1.6 EMBLEM           | NECESSARY     | 32.50                     | 32.50             |
| 1   | REAR BOOT LID COROLLA EMBLEM       | NECESSARY     | 46.60                     | 46.60             |
| 1   | REAR BOOT LID ALTIS EMBLEM         | NECESSARY     | 46.60                     | 46.60             |
| 2   | REAR BOOT LID REFLECTOR @ \$161.50 | CRACKED       | 323.70                    | 323.70            |
| 1   | REAR BOOT LID WEATHER STRIP        | CUT           | 205.20                    | 205.20            |
| 2   | REAR NUMBER PLATE LAMP @ \$58.20   | NOT NECESSARY | 116.40                    | -                 |
| 2   | REAR LAMP @ \$480.00               | CRACKED       | 960.00                    | 570.20            |
| 2   | REAR LAMP HOUSING @ \$84.10        | BUCKLED       | 168.20                    | 168.20            |
| 2   | REAR LAMP BRACKET @ \$88.90        | CRACKED       | 177.80                    | 96.00             |
| 1   | REAR END PANEL                     | DISTORTED     | 668.90                    | 668.90            |
| 1   | REAR END PANEL INNER TOP GARNISH   | DEFORMED      | 202.70                    | 202.70            |
| 1   | REAR BUMPER                        | DISTORTED     | 486.50                    | 486.50            |
| 2   | REAR BUMPER SIDE HOLDER @ \$70.40  | NECESSARY     | 140.80                    | 140.80            |
| 2   | REAR BUMPER BRACKET @ \$87.10      | DENTED        | 174.20                    | 174.20            |
| 1   | REAR BUMPER SPONGE                 | CRACKED       | 123.50                    | 123.50            |
| 2   | REAR BUMPER REFLECTOR @ \$37.20    | CRACKED       | 74.40                     | 74.40             |
| 1   | SET REAR BUMPER CLIPS              | NECESSARY     | 46.00                     | 30.00             |
| 2   | REAR FENDER @ \$927.20             | N/S BUCKLED   | 1,854.40                  | 927.20            |
| 2   | REAR FENDER INNER TRIM @ \$351.70  | TORN          | 703.40                    | 703.40            |
| 2   | REAR FENDER INNER SHIELD @ \$47.30 | NOT NECESSARY | 94.60                     | -                 |
| 1   | REAR FENDER LOWER AIR VENT         | NECESSARY     | 158.70                    | 158.70            |
| 1   | REAR SPARE TYRE TOP BOARD          | TORN          | 276.60                    | 276.60            |

Report Ref No. CC6/EQI19005702/Apb3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

| Qty | Description of Parts                                                                                  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | REAR SPARE TYRE WELL                                                                                  | TO REPAIR SEE LABOUR | 780.90                    | -                 |
| 3   | REAR SPARE TYRE WELL INSULATION @ \$279.60                                                            | NOT NECESSARY        | 838.80                    | -                 |
| 2   | REAR SPARE TYRE WELL TOP SIDE BOARD @ \$69.80                                                         | NOT NECESSARY        | 139.70                    | -                 |
| 1   | REAR SPARE TYRE SCREW                                                                                 | DAMAGED              | 46.70                     | 46.70             |
| 1   | REAR EXHAUST PIPE                                                                                     | NOT NECESSARY        | 926.30                    | -                 |
| 1   | REAR EXHAUST PIPE MOUNTING                                                                            | NOT NECESSARY        | 158.00                    | -                 |
| 1   | BOOTLID INNER TRIM BOARD                                                                              | TORN                 | 204.00                    | 204.00            |
|     | LESS 25% DISCOUNT                                                                                     |                      | -2,962.75                 | -1,845.37         |
|     |                                                                                                       |                      | 8,888.25                  | 5,536.13          |
|     | <b>SPECIAL NETT ITEMS</b>                                                                             |                      |                           |                   |
| 1   | REAR BOOT LID CAMERA (SN)                                                                             | DAMAGED              | 800.00                    | 380.00            |
| 1   | REAR NUMBER PLATE (SN)                                                                                | BENT                 | 50.00                     | 30.00             |
| 1   | REAR NUMBER PLATE HOLDER (SN)                                                                         | DEFORMED             | 50.00                     | 30.00             |
| 1   | REAR BUMPER REVERSE SENSOR (SN)                                                                       | DAMAGED              | 380.00                    | 200.00            |
| 1   | REAR WINDSCREEN SEALANT (SN)                                                                          | NECESSARY            | 50.00                     | 50.00             |
| 1   | REAR END PANEL INNER SEALANT (SN)                                                                     | NECESSARY            | 200.00                    | 60.00             |
|     |                                                                                                       |                      | 1,530.00                  | 750.00            |
|     | <b>LABOUR</b>                                                                                         |                      |                           |                   |
|     | REMOVE & REINSTALL REAR WINDSCREEN.                                                                   |                      | 150.00                    | 120.00            |
|     | REMOVE & REINSTALL CUSHION & ROOF LINING.                                                             |                      | 200.00                    | 60.00             |
|     | REMOVE & REINSTALL PETROL TANK.                                                                       |                      | 150.00                    | 80.00             |
|     | REMOVE & REINSTALL REVERSE SENSOR.                                                                    |                      | 150.00                    | 50.00             |
|     | REMOVE & REINSTALL EXHAUST PIPE.                                                                      | NOT NECESSARY        | 150.00                    | -                 |
|     | REMOVE & REINSTALL CAMERA.                                                                            |                      | 100.00                    | 50.00             |
|     | REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE WELL. |                      | 3,000.00                  | 1,300.00          |
|     | RESPRAY PAINTING.                                                                                     |                      | 2,200.00                  | 1,400.00          |
|     | TUFF KOTE.                                                                                            |                      | 150.00                    | 60.00             |
|     |                                                                                                       |                      | 6,250.00                  | 3,120.00          |
|     | <b>GRAND TOTAL</b>                                                                                    |                      | <b>16,668.25</b>          | <b>9,406.13</b>   |

Report Ref No. CC6/EQ19005702/Apb3s2



|                                                                         |  |  |          |
|-------------------------------------------------------------------------|--|--|----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |  |  | 7,500.00 |
|-------------------------------------------------------------------------|--|--|----------|

Report Ref No. CC6/EQI19005702/Apb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.