

Arrange for rental car

Survey & repair
8.04 @ 10am

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Steve (LKK) m 8/4/19 2:30pm
3 days

GST REG. NO : M2 - 0020081 - X

01 APR 2019

ESTIMATE

P/P
Ry bet-spry

Estimate No. : b1 50675
Date Estimated : 01/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Kuah Woon Hua
28A JALAN LEMPENG
#28-16

Singapore 128808

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR3133E	WE60551	15/11/2018	520i	0

DESCRIPTION

To replace rear bumper, attachments and repair boot lid. X

VALUE

850 2,550.00

Painting rear bumper and boot lid. X

934 2,076.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

? 531.00

Sundries.

? 150.00

Total Labour 1: 5,484.00

DESCRIPTION

TAILPIPE TRIM CHROME

QTY PRIC

1 140.50

VALUE

140.50

REAR SILENCER

1 1,281.95

1,281.95

REAR BUMPER CARRIER

1 857.75

857.75

REAR BUMPER BOTTOM REINFORCEMENT

1 84.75

84.75

REAR BUMPER CENTRE GUIDE

1 61.55

61.55

REAR BUMPER TRIM STRIP

1 105.45

105.45

REAR BUMPER PANEL PRIMED (PDC/PMA)

1 1,578.85

1,578.85

SET MOUNTING PMA SENSOR

1 69.00

69.00

Total Parts : 4,179.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50675**
Date Estimated : **01/04/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR3133E	WE60551	15/11/2018	520i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	5,484.00
Parts	:	4,179.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	676.47
Grand Total	:	10,340.27

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **